



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBF9496M*M

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 35671
Reg No/Reg Date GBF9496M*M / 02/05/2017
Date In/Mileage 09/10/2017 / 17272
Chassis No WDF44760323273554
Engine No R9MA503C017056
Make/Model MBCV/Vito 109KA/ L 4X2 3200 Ma
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000007	Credit	11/12/2017/ 09:42		122 / Ng Wei Siang				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S-SUB								60.00
VEHICLE TOWING FROM 47, BUN BUKH RD TO 188 PANDAN LOOP								60.00
A 20114001 REPLACE COOLANT INCLUDING ANTIFREEZE, CHECK FOR LEAKS							28.57	60.00
A 20114301 DRAIN/FILL/CORRECT COOLANT							30.55	50.00
A 20400002 REPLACE RADIATOR							16.66	200.00
A 20646003 FAN ASSEMBLY REPLACE							16.66	200.00
A 88115501 BUMPER WITH INTEGRATED FRONT RADIATOR GRILLE REMOVE/INSTALL							28.57	60.00
A 88140001 FRONT BUMPER ADJUST							47.91	50.00
A 88194001 LOWER CROSSMEMBER REPLACE							33.33	200.00
A 68000099 REPLACE BOTH SIDE WHEEL HOUSING							16.66	100.00
A 82472001 LIGHT UNIT AT RIGHT FRONT REMOVE/INSTALL								84.00
X COOLANT RADIATOR					1.00	408.11	10.00	367.30
X RADIATOR ANTIFREEZE					2.00	45.18	10.00	81.32
X BRACKET					1.00	23.59	10.00	21.23
X BRACKET					1.00	23.59	10.00	21.23
X BLOWER					1.00	681.28	10.00	613.15
X TRIM PANEL WHEEL HOUSING					1.00	129.47	10.00	116.52
X TRIM PANEL WHEEL HOUSING					1.00	129.47	10.00	116.52
X *P NUT					10.00	1.91	10.00	17.19
X RIVET					10.00	4.16	10.00	37.44
X CROSS MEMBER					1.00	216.44	10.00	194.80
X SCREW					4.00	3.31	10.00	11.92
X SCREW					3.00	1.49	10.00	4.02
X NUT					2.00	11.73	10.00	21.11

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR GBF9496M*M

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 35671
Reg No/Reg Date GBF9496M*M / 02/05/2017
Date In/Mileage 09/10/2017 / 17272
Chassis No WDF44760323273554
Engine No R9MA503C017056
Make/Model MBCV/Vito 109KA/ L 4X2 3200 Ma
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WA000007	Credit	11/12/2017/ 09:42		122 / Ng Wei Siang

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BEAM	1.00	77.09	10.00	69.38
X HEADLAMP UNIT	1.00	536.38	10.00	482.74

AN OFFICIAL TAX INVOICE

ESTIMATE

Confirmed & accepted by

Nett 3,329.87
7% GST on 3329.87 233.09

Authorized signatory and company stamp

Total Payable 3,562.96

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg