

Labour charges

To remove & re-fix rear reverse sensor	<del>\$100.00</del> 50.
To Check Wiring System	<del>\$50.00</del> 30.
to underseal	<del>\$150.00</del> 50
to remove upholstery	<del>\$150.00</del> 60.
to remove & install rear camera	<del>\$100.00</del> 50
to remove & install rear video recorder	<del>\$100.00</del> 50
to Remove & install rear exhaust	<del>\$150.00</del> X
to remove & install rear windscreen	<del>\$180.00</del> 120.
to transfer tailgate fitting	<del>\$150.00</del> 80
to vacuum <sup>shattered</sup> shuttered glass & interior cleaning	2410. <del>\$180.00</del> 120.
Tuff kote	<del>\$150.00</del> X.
Panel beating	<del>\$1,400.00</del> 800
Spray painting	<del>\$1,400.00</del> 1000.

Subtotal :- \$4,260.00

Total:- \$20,198.35

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

total: 11847.41  
L/S. 9.4.12.  
07 Days.