

INS. CASE OWNER:

CC 4 / AXA1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

DATE / PIC

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Total Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Email

Call

If NO, B 28, Ass. Lia:

Repair Cost:

SS

(days)

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(days)

Loss of Income (LOI):

SS

(days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GI/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Total Cost

SS

Total:

SS

Global Sum SS:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
11/2/2020

\$350.00

ASS. REC. BY:

REF:

AKA

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 3076C Yr Regn: 10.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 14RV c.c. 1496

Colour:

M. Red A/C: Insured / Std / NI / NA

Sp. Reading

16763 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU1810G X 200384

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size:

F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

3/11/17

D.O.A.

16/1/19

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1

File pass to Car

B 1478.48 has on calculation

Low

(3 x 60)

(Reel # 350/197)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fuel/Pos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA17021489/zb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-11-2017



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 822R	Veh. Inspected	SLH 3076C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/11/2017	Inspection Date	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLH3076C
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1991053/YISHUN

Date: 16 Jan 2019

Policy No: 16-MV009797-R00

Veh Reg No: SLH3076C

Make/Model: HONDA HRV 1.5 DX
 CVT

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 03/11/2017

TP Veh Reg No: SJU822R

Chassis No: JHMRU1810GX200384

Engine No: L15B4530385

Reg. Date: 28/10/2016

Estimate Repair Cost to Vehicle No :SLH3076C

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	508.50	1 PC	508.50	—
2 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
3 TAILGATE EMBLEM (HRV)	43.80	1 PC	43.80	—
4 TAILGATE EMBLEM (E-TECH)	49.80	1 PC	49.80	—
			623.10	
		Less 20%	124.62	498.48
Special Net				
5 REVERSE SENSOR	200.00	1 PCSET	200.00	—
			200.00	200.00
Labour				
6 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TO KNOCK & REPAIR REAR PANEL, TAILGATE & REALIGN THE SAME	480.00	1 LA	480.00	300
7 PUTTY & RESPRAY TAILGATE PANEL & REAR BUMPER (TWO TONE)	600.00	1 LA	600.00	440
			1,080.00	1,080.00
			Total	SS 1,778.48
			Add GST @ 7%	124.49
			Total Amount Payable	SS 1,902.97

To remove and refit reverse camera and radar system

\$50 Add GST @ 7%

Total Amount Payable

For Cheng Hoe Motor Pte Ltd

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be itemized and subject to final approval from Link Auto Consultants

Authorised by Repairs:

AUTHORISED SIGNATURE

1828-48

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	1229E

Vehicle Details

Vehicle No.	SLH3076C
Vehicle to be Exported	Yes
Intended De-registration Date	03 Nov 2017
Vehicle Make	HONDA
Vehicle Model	HRV 1.5 DX CVT
Primary Colour	Red
Manufacturing Year	2016
Engine No.	L15B4530385
Chassis No.	JHMRU1810GX200384
Maximum Power Output	96.0 kW (128 bhp)
Open Market Value	\$20,928.00
Original Registration Date	28 Oct 2016
First Registration Date	28 Oct 2016
Transfer Count	0
Actual ARF Paid	\$16,300.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Oct 2026
PARF Rebate Amount	\$12,225.00

Intended COE Rebate Details

COE Expiry Date	27 Oct 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$55,200.00
COE Rebate Amount	\$44,160.00
Total Rebate Amount	\$56,385.00

The information contained herein is correct as at 03 Nov 2017

OK

Enquire Vehicle & Owner Information (Vehicle No. SJU822R As At 03 Nov 2017 / 12:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SLH3076

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S8361638E

Owner Name: SONG HAIJING

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 130

Registered Street Name: CANTONMENT ROAD

Registered Unit No.: # 20 - 04

Registered Building Name: -

Registered Postal Code: 089775

Current Vehicle Details

Vehicle No.: SJU822R

Make Description/Model: MERCEDES BENZ / C180K

Insurance Company Name: AXA INSURANCE PTE LTD





Print Sent Message

This mail is associated with :

***SLH3076C (C0458680)**

[SJU822R]

TP

HONG QI

Nov 3 2017 12:00PM

[SONG HAIJING]

Cheng Hoe Motor Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/11/2019 09:55 AM.
To stacey.ng@axa.com.sg
CC AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Seek Mandate> C0458680

Dear Sirs/Mdm,

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue.

We seek your mandate at \$1,769.97(all-in). TP-Mandate 1A had been uploaded in Merimen.

Kindly let us have your approval/instruction.

Hsiao Tong



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 01/11/2019

Survey Details:

Date of loss	3-Nov-17
Date of appointment	10-Nov-17
Date of survey	16-Jan-19
Location of survey	CHENG HOE MOTOR PL

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLH 3076C
Make and Model	MERCEDES BENZ C180K
Date of registration	28/10/2016
Excess	
Market Value	\$70,000
Parf Rebate	\$56,385
Nett Loss	\$13,615

Repair details:

Initial Estimate	\$ 1,778.48
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 698.48
Check items (estimate)	NIL
Labour	\$ 780.00
Total	\$ 1,478.48
Lump Sum(if applicable)	\$ -

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Of rear-ended third party.

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	1,581.97
Loss of use	\$	180.00 (3days x \$60)
Loss of rental		NIL no. of days
Loss of income		NIL no. of days
LTA search fees	\$	8.00
Others		NIL
Proposed Total	\$	1,769.97

Print Received Message

This mail is associated with :

***SLH3076C (C0458680)**

[SJU822R]

TP

HONG QI

Nov 3 2017 12:00PM

[SONG HAIJING]

Cheng Hoe Motor Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 28/11/2019 14:22 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1769.97) - SLH3076C - Claim Handler: Stacey Ng

Approved:1769.97.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 30 November 2019 12:25 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg)
Subject: Your Ref: SLH3076C *Our Ref: CC4/AXA17021489/Kpb3 [ACCIDENT INVOLVING SJU 822R(AXA) AND SLH 3076J ON 03/11/2017]

Your Ref: **SLH3076C** Without Prejudice
Our Ref: CC4/AXA17021489/Kpb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SJU 822R(AXA) AND SLH 3076J ON 03/11/2017

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,581.97
2. Loss of Use (3days x \$50.00)	\$ 150.00
3. LTA/GIA Search Fee	\$ 8.00
Total	\$ 1,739.97

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Saturday, 11 January 2020 4:52 AM
To: Hsiao Tong (LKKAUTO)
Subject: ACCEPTANCE- our Ref: SLH3076C *Our Ref: CC4/AXA17021489/Kpb3 [ACCIDENT INVOLVING SJU 822R(AXA) AND SLH 3076J ON 03/11/2017]

Hi Hsiao Tong,

Without Prejudice

Your offer as below is accepted.

Pls forward DV.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 30 November 2019 12:25 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg) <chmotor@singnet.com.sg>
Subject: Your Ref: SLH3076C *Our Ref: CC4/AXA17021489/Kpb3 [ACCIDENT INVOLVING SJU 822R(AXA) AND SLH 3076J ON 03/11/2017]

Your Ref: **SLH3076C** Without Prejudice
Our Ref: CC4/AXA17021489/Kpb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SJU 822R(AXA) AND SLH 3076J ON 03/11/2017

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,581.97
2. Loss of Use (3days x \$50.00)	\$ 150.00
3. LTA/GIA Search Fee	\$ 8.00
Total	\$ 1,739.97

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice

engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."


Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date:

OCT 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SLH3076C & SJU822R ON 03/11/2017
WOODLANDS SQUARE.**

We are authorized by SLH3076C for their above matter.

Record reveals that you are the insurer of SJU822R. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 1581.97
2. Loss of Use (3 x 360/day)	S\$ 180.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 1769.97

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 03/11/2017

TP Veh Reg No: SJU822R

NO: CL8190876

Date: 21 Aug 2019

Policy No: 16-MV009797-R00

Veh Reg No: SLH3076C

Make/Model: HONDA HRV 1.5 DX
CVT

Job No: JC1600343

PAGE:1

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	S\$ 1,478.48	S\$ 1,478.48

Total	S\$ 1,478.48
Add GST @ 7%	103.49
Total Amount payable	<u>S\$ 1,581.97</u>

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Nov 2017		09 Nov 2017 15:47 Edit Adj Rpt	S\$1,478.48 Edit Estimates	S\$1,478.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	SONG HAIJING, ID: S8361638E, Tel: +6597529676		
Main Claimant:	HONG QI, Co. Reg. No.: S7481299E		
Vehicle Reg. No.:	SLH3076C	Date of Loss:	03/11/2017 12:00 - :59 [12 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0458680	Policy/Cover Note No.:	GA094440 (Comprehensive)
Vehicle Reg. No. (Insured):	SJUB22R	Policy No. (Claimant):	16-MVD09797-R00
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Stacey Ng - 6880 4351]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/11/2017]		
Adj Asg. Remarks:	ARC -YES		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (28/11/2019): Alert - Adj Mandate Approved (S\$1769.97) - SLH3076C - Claim Handler: Stacey Ng
- AXA_SG (22/03/2019): Hi Joy, pls proceed as per IA-VO
- AXA_SG (12/08/2018): REVIEW
- AXA_SG (02/01/2018): TP settlement - C0458680/GA094440
- AXA_SG (14/11/2017): Re: Direct Settlement - Accident Involving SJUB22R (OI : AXA - C0458680) and SLH...
- AXA_SG (09/11/2017): WP / New TP Assignment - C0458680/GA094440

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH3076C (C0458680)
[SJU822R]
TP
HONG QI
Nov 3 2017 12:00PM
[SONG HAIJING]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 17:48	Video - Accident FROM TP ->HEAD ->TD-REAR	 Load WMV	☐
Photos/Images			3 per page ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 12:12	General View	 Load JPG ☒	☒
2	12/02/19 12:12	General View	 Load JPG ☒	☒
3	12/02/19 12:12	General View	 Load JPG ☒	☒
4	12/02/19 12:12	General View	 Load JPG ☒	☒
5	12/02/19 12:12	General View	 Load JPG ☒	☒
6	12/02/19 12:12	General View	 Load JPG ☒	☒
7	12/02/19 12:12	General View	 Load JPG ☒	☒
8	12/02/19 12:12	General View	 Load JPG ☒	☒
9	12/02/19 12:12	General View	 Load JPG ☒	☒
Documentation			1 per page ☒	
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	09/11/17 09:44	Email_ABS	 Load PDF	☐
2	09/11/17 09:44	SLH3076C TP GIA REPORT	 Load PDF	☐
3	09/11/17 09:50	EMAIL TO WORKSHOP_ABS	 Load PDF	☐
4	09/11/17 15:42	TP - Kenneth Kong (LKK Auto Consultants Pte Ltd) Get TP video	 Load TIF	☐
5	02/01/18 09:11	PH GIA.pdf	 Load PDF	☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/19 17:29	TP ESTIMATE- MARKED	 Load PDF	☐
2	12/02/19 12:13	IA	 Load PDF	☐
3	21/10/19 09:05	LTA SEARCH	 Load PDF	☐
4	01/11/19 09:54	LKK Survey Photos	 Load PDF	☐
5	01/11/19 09:54	LKK Resurvey Photos 1	 Load PDF	☐
6	01/11/19 09:54	LKK Resurvey Photos 2	 Load PDF	☐
7	01/11/19 09:54	TP-MANDATE IA dd 011119	 Load PDF	☐
8	12/02/20 10:15	AUTHORISATION TO ACT FORM	 Load PDF	☐
9	12/02/20 10:15	PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM	 Load PDF	☐
10	12/02/20 10:15	LETTER TO OI	 Load PDF	☐

Documents Checklist

Reset Save Print		
DOCUMENTS CHECKLIST There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17021489/KPA3Q2

Date: 12/02/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA094440

Claimant

Vehicle No : SLH3076C

Insured Vehicle No :

SJU822R

Date of Loss: 03/11/2017

Nature of Claim:

TP

Claim No: C0458680

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH3076C

Make & Model: HONDA HR-V, 1.5 (A)

Engine No: L15B4530385

Reg. Date: 28/10/2016 (Man. Year: 2016)

Chassis No: JHMRU1810GX200384

Colour: Metallic Red

Odometer: 16763 km

Engine Capacity: 1496 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	698.48	698.48	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	780.00	350.00	30.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,828.48	1,478.48	350.00	19.14
+ GST 7.00/7.00% (S\$)	127.99	103.49	24.50	19.14
Nett Amount (S\$)	1,956.47	1,581.97	374.50	19.14
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		1,739.97		

INSPECTION

Date of Assignment: 09/11/2017

Date Inspected: 16/01/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2019)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH3076C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Buckled / Dented	508.50 FL	*508.50 FL
2	6		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	21.00 FL	*21.00 FL
3	1		*TAILGATE EMBLEM (HRV) (CONSISTENT)	Necessary	43.80 FL	*43.80 FL
4	1		*TAILGATE EMBLEM (E-TECH) (CONSISTENT)	Necessary	49.80 FL	*49.80 FL
5	1		*SET REVERSE SENSOR (CONSISTENT)	Shorted	200.00 FS	*200.00 FS
					Sub Total (S\$)	823.10 823.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	124.62 124.62
					Total Parts (S\$)	698.48 698.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TO KNOCK & REPAIR REAR PANEL, TAILGATE & REALIGN THE SAME	New	480.00	300.00
2	PUTTY & RESPRAY TAILGATE PANEL & REAR BUMPER (TWO TONE)	New	600.00	440.00
3	TO REMOVE AND REFIT REVERSE CAMERA AND RESET SYSTEM	New	50.00	40.00
Gross Labour Cost (S\$)			1,130.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >