

ASS. REC. BY:

REF:

CS/EGN13021602/Gtbn2

Special Instruction:

Supervisor:

GR

ASSIGNMENT (Office)

From (Person):

Siti

of

EGL

Date/Time:

13-11-2017 11:32am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 711B

Insured:

GBF 5116L

at Workshop m/s

Trans Eurocars

Tel:

63957874

of

5 Ubi Close

Policy No:

Claim No:

GBF5116L/SE/SA

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31-10-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

14.11.2017 @ 2:30pm

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Jess

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 711B - X
	GBF 5116L - X
15/11-	Permit preli advise
	Confirm CoR: \$7842.74 before GST. (Red: 3702.42 : 32%)

REF: EGI

ASSIGNMENT

From: _____ Date: 14/11/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKS711B

at Workshop m/s Trans Eurokars

of S ubi close

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

2.30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKS711B Yr Regn: 24 Mar 2015

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.C. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 34260 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6BM 42A 8G0303570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 14-11-17

Survey held at w/s

2:30pm

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 19 MAR 2018

Date/Time, File Pass to?

1) 19/11/17 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

350

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B. (\$) 7848.74



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI17021602/Gtb	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 13-11-2017	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 5116L	Veh. Inspected	SKS 711B	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBF5116L/SE/sa	Excess (\$)	0.00	
Assign From	SITI	Assign Date	13/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/10/2017	Inspection Date	13/11/2017	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBF5116L/SE/sa
Our Ref: CS/EG17021602/Gtb

Date: 15/11/2017

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SKS 711B.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/11/2017 at the premises of M/s Trans Eurokars and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,551.16</u>
Revised Estimate Amount	: S\$ <u>7,848.74</u>
"Check" Items Amount	: S\$ <u>563.22</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
At front portion.



Repair days: 5 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Guo Qiang
Automotive Assessor

Catherine Chong (LKK Auto)

From: Siti A Thikah AB Rahman <siti.rahman@ergo.com.sg>
Sent: Monday, 13 November, 2017 11:32 AM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com)
Subject: OI: GBF 5116L | TP: SKS 711B | LKK | DOA: 31.10.2017 - PRS | OUR REF: GBF5116L/SE/sa
Attachments: PRS FORM.pdf; YOUR REF: GBF5116L / OUR REF: SKS711B THIRD PARTY CLAIM (REQUESTING FOR S... (553 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK Auto Consultants Pte Ltd to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and to try finalise with the repairer on the repairs. (Note: Our insured has yet to lodge the accident report to us).

Please fill up the necessary on ERGO PRS Form and return to us together on your update of the survey status.

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest regards
Siti A'thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9170
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]
Sent: Monday, 6 November, 2017 2:16 PM
To: Siti A Thikah AB Rahman; eric.pau@eurokars.com.sg
Cc: ronald.yap@eurokars.com.sg; kevin.lee@eurokars.com.sg; Survey Report (ERGO Insurance Pte. Ltd.); admin-d@lkkauto.com
Subject: RE: GBF 5116L | TP: SKS711B | DOA: 31.10.2017 - OUR REF:GBF5116L/SE/sa

Hi Sitti,

We choose LKK Auto for this case.

Kindly arrange the necessary.

Thanks & regards.

Jess Francis Carlos
Insurance Claim Executive
TRANS EUROKARS PTE LTD
5 Ubi Close
Singapore 408605
DID: +6563957874

From: Siti A Thikah AB Rahman [mailto:siti.rahman@ergo.com.sg]
Sent: Friday, 3 November 2017 5:09 PM
To: Eric Pau <eric.pau@eurokars.com.sg>; Jess Francis <jess.francis@eurokars.com.sg>
Cc: Ronald Yap <ronald.yap@eurokars.com.sg>; Vion Lim <vion.lim@eurokars.com.sg>; Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>; Kevin Lee <kevin.lee@eurokars.com.sg>; Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Subject: OI: GBF 5116L | TP: SKS 711B | DOA: 31.10.2017 - OUR REF:GBF5116L/SE/sa

WITHOUT PREJUDICE

Dear Sir,

We refer to your email below.

Attached our template for your input.

Kindly let us have your reply.

Thank you.

Warmest regards
Siti A'thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 65 6829 9170
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

From: eric.pau@eurokars.com.sg [mailto:eric.pau@eurokars.com.sg]
Sent: Friday, 3 November, 2017 12:01 PM
To: ERGO Insurance Pte. Ltd. (Claims Department); jess.francis@eurokars.com.sg
Cc: ronald.yap@eurokars.com.sg; vion.lim@eurokars.com.sg; catherinechua@eurokars.com.sg; kevin.lee@eurokars.com.sg
Subject: YOUR REF: GBF5116L / OUR REF: SKS711B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

YOUR REF: GBF5116L / OUR REF: SKS711B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Liaise with Jess for survey arrangement.

Best Regards,

Eric Pau

Insurance Claims Officer

TRANS EUROKARS PTE LTD

5 Ubi Close, Singapore 408605

D: (65) 6395 8685 H: (65) 9618 5991

E: eric.pau@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]

Sent: Friday, November 3, 2017 12:10 PM

To: Eric Pau <eric.pau@eurokars.com.sg>

Subject: Attached Image

Date: 03.11.2017
 Our Reference: GBF5116L/SE/sa
 Your Reference: SKS711B

Sent via Fax

or

Email

To: EUROKARS GROUP OF COMPANIES

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKS 711B
 Insured's Vehicle: GBF 5116L
 Date Of Accident: 31.10.2017


We acknowledge receipt of your request for PRS on: 02.11.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK AUTO**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	LKK	LKK Auto Consultants Pte Ltd
JPk	JP Knights Pte Ltd	PS	Priority Services
		VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>We are therefore not in a position to discuss on liability at this juncture.</u>

Prepared by:		Siti	6829 9170	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
 Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
 Time: _____
 Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	6389G
Vehicle Details	
Vehicle No.	SKS711B
Vehicle to be Exported	No
Intended De-registration Date	15 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour	Grey
Manufacturing Year	2015
Engine No.	P520267606
Chassis No.	JM6BM42A8G0303570
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$17,507.00
Original Registration Date	24 Mar 2015
First Registration Date	24 Mar 2015
Transfer Count	0
Actual ARF Paid	\$7,507.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Mar 2025
PARF Rebate Amount	\$5,630.00
Intended COE Rebate Details	
COE Expiry Date	23 Mar 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$64,700.00
COE Rebate Amount	\$47,585.00
Total Rebate Amount	\$53,215.00

The information contained herein is correct as at 15 Nov 2017

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Erik Low Kim Lee ADDRESS : Bkl 212 Jurong East Street 21 #20-289 Singapore 600212 TEL : 96356716		WIP : 42082 EXCESS : DATE: 3-Nov-17	
VEH NO :	SKS711B	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BM42A8G0303570	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	24-Mar-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	FRONT BUMPER / <i>Cut</i>	1	MBHR3-50-031BBB		\$ 1,031.70 ✓
2	RETAINER(RHS), FRONT BUMPER / <i>MBL</i>	1	MBHN1-50-0T1F		\$ 18.70 ✓
3	BRACKET(RHS), FRONT BUMPER X <i>NA</i>	1	MBHN1-50-152		\$ X 15.10
4	FRONT REINFORCEMENT X	1	MB45A-50-070A		\$ X 444.50
5	GROMMET, FRONT BUMPER /	2	MGHP9-50-0Z5		\$ 5.40 ✓
6	CLIP, FRONT BUMPER / <i>MBL</i>	12	MC274-50-133		\$ 42.00 ✓
7	FASTENER, FRONT BUMPER /	2	MB45A-56-146A		\$ 5.60 ✓
8	GRILLE TOP / <i>Cut</i>	1	MBHN1-50-033 27		\$ 335.00 ✓
9	RIVET, GRILLE TOP / <i>MBL</i>	6	MS51S-51-833		\$ 22.80 ✓
10	RIVET, GRILLE TOP / <i>MBL</i>	4	MTK21-50-355		\$ 34.80 ✓
11	BRACKET TOP, GRILLE X <i>NN</i>	1	MBHN1-50-717D		\$ 102.40
12	CHROME(RHS), FRONT BUMPER / <i>Cut</i>	1	MBHN1-50-7J1A		\$ 176.70 ✓
13	GRILLE:BLACK (GLOSS) ? <i>NN</i>	1	MBJE1-50-712B		\$ X 581.60
14	MASCOT,FRONT ? <i>NN</i>	1	MC235-51-731A		\$ X 44.20
15	BRACKET(RHS), GRILLE X <i>NN</i>	1	MBHN1-50-153		\$ 15.10
16	PIN LOCATOR, GRILLE /	2	MKD45-50-1K5A		\$ 5.40 ✓
17	GROMMET, GRILLE / <i>MBL</i>	2	MKD45-50-ES1		\$ 5.40 ✓
18	RIVET, GRILLE /	2	MEA01-50-037		\$ 15.20 ✓
19	FASTENER, GRILLE /	8	MGD7A-50-EA1		\$ 24.00 ✓
20	BONNET / <i>BT</i>	1	MBHY0-52-31XA		\$ 1,067.30 ✓
21	WEATHERSTRIP, BONNET / <i>Cut</i>	1	MBHN9-56-770A		\$ 63.60 ✓
22	HEADLAMP RHS / <i>Cut</i>	1	MBHT6-51-031A		\$ 2,245.00 ✓
23	CLIP, HEADLAMP X <i>NA</i>	2	MFB01-50-133C		\$ X 7.60
24	RIVET, HEADLAMP X <i>NA</i>	1	MB092-51-833		\$ X 3.30
TOTAL PARTS					\$ 6,312.40
LESS 10%					\$ 631.24
TOTAL PARTS COST					\$ 5,681.16
Labour Description					

1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,260.00	\$ 2,520.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET.	\$ 1,500.00	\$ 2,400.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES. <i>new</i>	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 3,260.00	\$ 5,870.00
TOTAL PARTS			\$ 4,588.74	\$ 5,681.16
TOTAL			\$ 7,848.74	\$ 11,551.16
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 7,848.74	
GST 7%			\$ 549.41	\$ -
GRAND TOTAL			\$ 8,398.15	\$ -

REMARKS: SKS711B

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIR



ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Erik Low Kim Lee ADDRESS : Bkl 212 Jurong East Street 21 #20-289 Singapore 600212 TEL : 96356716	WIP : 42082 EXCESS : DATE: 3-Nov-17
VEH NO :	SKS711B	DATE IN :	CONTACT PERSON : JESS 6395 7874
CHASSIS NO :	JM6BM42A8G0303570	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.: 24-Mar-15	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MBHR3-50-031BBB	\$ 1,031.70	\$ 1,031.70
2	1	MBHN1-50-0T1F	\$ 18.70	\$ 18.70
3	1	MBHN1-50-152		\$ 15.10
4	1	MB45A-50-070A		\$ 444.50
5	2	MGHP9-50-025	\$ 5.40	\$ 5.40
6	12	MC274-50-133	\$ 42.00	\$ 42.00
7	2	MB45A-56-146A	\$ 5.60	\$ 5.60
8	1	MBHN1-50-033 27	\$ 335.00	\$ 335.00
9	6	MS515-51-833	\$ 22.80	\$ 22.80
10	4	MTK21-50-355	\$ 34.80	\$ 34.80
11	1	MBHN1-50-717D		\$ 102.40
12	1	MBHN1-50-7J1A	\$ 176.70	\$ 176.70
13	1	MBJE1-50-712B		\$ 581.60
14	1	MC235-51-731A		\$ 44.20
15	1	MBHN1-50-153		\$ 15.10
16	2	MKD45-50-1K5A	\$ 5.40	\$ 5.40
17	2	MKD45-50-ES1	\$ 5.40	\$ 5.40
18	2	MEA01-50-037	\$ 15.20	\$ 15.20
19	8	MGD7A-50-EA1	\$ 24.00	\$ 24.00
20	1	MBHY0-52-31XA	\$ 1,067.30	\$ 1,067.30
21	1	MBHN9-56-770A	\$ 63.60	\$ 63.60
22	1	MBHT6-51-031A	\$ 2,245.00	\$ 2,245.00
23	2	MFB01-50-133C		\$ 7.60
24	1	MB092-51-833		\$ 3.30
TOTAL PARTS			\$ 5,098.60	\$ 6,312.40
LESS 10%			\$ 509.86	\$ 631.24
TOTAL PARTS COST			\$ 4,588.74	\$ 5,681.16

Labour Description



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI17021602/Gtbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 20-03-2018	
Code : EGI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 5116L	Veh. Inspected	SKS 711B
Policy No.		Coverage (\$)	0.00
Claim No.	GBF5116L/SE/sa	Excess (\$)	0.00
Assign From	SITI	Assign Date	13/11/2017
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0303570	Colour	GREY
Odometer	34260	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/10/2017	Inspection Date	14/11/2017
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 711B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	1,031.70	1,031.70
1	RETAINER (RHS),FRONT BUMPER	NECESSARY	18.70	18.70
1	BRACKET (RHS),FRONT BUMPER	NOT NECESSARY	15.10	-
1	FRONT REINFORCEMENT	NOT NECESSARY	444.50	-
2	GROMMET,FRONT BUMPER	NECESSARY	5.40	5.40
12	CLIP,FRONT BUMPER	NECESSARY	42.00	42.00
2	FASTENER,FRONT BUMPER	NECESSARY	5.60	5.60
1	GRILLE TOP	CUT	335.00	335.00
6	RIVET,GRILLE TOP	NECESSARY	22.80	22.80
4	RIVET,GRILLE TOP	NECESSARY	34.80	34.80
1	BRACKET TOP,GRILLE	NOT NECESSARY	102.40	-
1	CHROME (RHS),FRONT BUMPER	CUT	176.70	176.70
1	GRILLE BLACK (GLOSS)	NOT NECESSARY	581.60	-
1	MASCOT,FRONT	NOT NECESSARY	44.20	-
1	BRACKET (RHS),GRILLE	NOT NECESSARY	15.10	-
2	PIN LOCATOR,GRILLE	NECESSARY	5.40	5.40
2	GROMMET,GRILLE	NECESSARY	5.40	5.40
2	RIVET,GRILLE	NECESSARY	15.20	15.20
8	FASTENER,GRILLE	NECESSARY	24.00	24.00
1	BONNET	BENT	1,067.30	1,067.30
1	WEATHERSTRIP,BONNET	CUT	63.60	63.60
1	HEADLAMP RHS	CRACKED	2,245.00	2,245.00
2	CLIP,HEADLAMP	NOT NECESSARY	7.60	-
1	RIVET,HEADLAMP	NOT NECESSARY	3.30	-
	LESS 10% DISCOUNT		-631.24	-509.86
			5,681.16	4,588.74
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00

Report Ref No. CS/EG117021602/Gtbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE FRONT BUMPER,FRONT REINFORCEMENT,GRILLE TOP AND BONNET,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		2,520.00	1,260.00
	TO RESPRAY FRONT BUMPER,FRONT REINFORCEMENT,GRILLE TOP AND BONNET.		2,400.00	1,500.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			5,770.00	3,240.00
	GRAND TOTAL		11,551.16	7,848.74
RECOMMENDED COST OF REPAIRS				7,848.74

Report Ref No. CS/EG117021602/Gtbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.