

REPAIR DETAILS

Reference. --

Supplementary

Part Source: (Last Synchronised: 24 Nov 2017)

Parts: N/A MERCEDES-BENZ 3336K/6X4 11.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD8602E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT CORNER PANEL GRILLE(LH)	0.00	0.00	*230.00 F
2	1		*FRT SIDE MIRROR COVER(LH)	0.00	0.00	*55.00 F
3	1		*FRT STEP ASSY(LH)	0.00	0.00	*620.00 F
Sub Total (S\$)						905.00
+ Margin on L,N Items 15.00% (S\$)						135.75
Total Parts (S\$)						1,040.75

F=Franchise part.

(H) der
(H) m/s
*(H) bt*Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS