

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ernest Tay

Date: 21 Nov 2017

Preliminary Advice

Insured Vehicle No	: SJC8765P	Accident Date	: 16/11/2017
TP Vehicle No	: GBF3174G	Assignment Date	: 17/11/2017
Make	: MITSUBISHI CANTER FEA01BR2SDEB (CBU)	Est. Duration of Repair	: 3 days
Date of Inspection	: 20/11/2017		
Inspection At	: Super-zee Motor Service (HQ) BLK 14 DEFU LANE 10, #01-402 Singapore 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,245.90
Revised Amount	:S\$	1,710.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,710.08

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.