

22

ASS-REC BY:

REF: CS/FCI17022076/Kvb

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Luren Jaw

of FCI

Date/Time: 18/11/17 @ 1:38pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 9458L

Insured: SHA 9919R

at Workshop m/s: Lai Huat (Mong Kee)

Tel: 64538110

of 160 Sin Ming Drive #01-01 & 07-03

Policy No:

Claim No: D17010704MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 15/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 9:45am @ 20/11/17

Person Contacted:

Jenny

Vehicle: IN OUT

Date/Time	Action/Instruction
	(✓) Estimate Got Footage from Workshop
	SJN 9458L - CC3 / AIG16024716 / Geb392 - D.O.A.: 25/12/2016
	SHA 9919R - CS / FCI14009580 / Rqm3u2 - D.O.A.: 18/05/2014

21/11/17 Email preli revised to FCI

4/5 LI Pp 821K Cg firm by email (Ref 8388.82, 29/11)

REF: FCI

ASSIGNMENT

From: Date: 20/11/2017

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ CD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No:

SIN 9458L

at Workshop with:

Lai Hui (Meng Kee)

of 160 Sin Ming Drive #04-01/0230703

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel on Market Value:

B 48k

IDAO Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

24

days

Res: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP / 24 HRS

wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SIN 9458L

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover

Truck / Trailer or

Make:

Volkswagen

R36

3597

Colour:

m. Blade

Insured / Std / Nil / NA

Sp Reading:

163765

T. Pass: Insured / Std / Nil / NA

Eng No:

C/No:

WVWZ 783089E C69140

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orMod: ☒ Nil ☐ S/Rim ☐ STD A/Rim or

Tyre Size:

F:

R:

235/408R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front:

Rear:

R. Bal:

6

mm

R. Bal:

7

mm

L. Bal:

6

mm

L. Bal:

7

mm

D.O.A:

15/11/17

D.O.A:

20/11/17

Survey held at:

Des. of Damages: ☐ Frt ☐ Rear ☐ O/S ☐ N/S ☐ U/O ☐ Rooftop or

O/S Rear body, Frt & N/S

The U/O / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

21/11 Fk pass to Caravan
4 Jason asking for \$23k.

Note: MV: \$48K (Est) LTA: \$26,375 NV: \$21,625

RECEIVED 06 MAY 2018 RECEIVED 1 MAY 2018

Date/Time File Pass to:



Prel. Report

Days Of Repair:

24

Date/Time File Return to:



Final Report

Resurvey No. of Trip:

3

Survey Fee

4/3- typist

Add Fee:



Site Insp:



Interview:



Tech. Insp:



Witnessing:

Report Format:

MS

Lump Sum (L.S.):

LS \$21000k

19X15=285

170+285

50

50+50+50

54

158

05P

4/5/18

709

Survey Department Check List (Case Handler)

Reference No. : 05/FCI/7022076/Kvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

4/5/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022076/Kvb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 20-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9919R	Veh. Inspected	SJN 9458L
Policy No.		Coverage (\$)	0.00
Claim No.	D17010704MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	20/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/11/2017	Inspection Date	20/11/2017
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	16-11-2017	Our Ref No. D17010704MFSH
Accident Date	15-11-2017	Claim Type. Third Party
Insured Vehicle	SHA9919R	Third Party Vehicle. SJN9458L
Survey Location	160 Sin Ming Drive #04-01/02 and #07-03 Sin Ming Autocity	
Contact Person.	JENNY LIM	
Contact No.	64538110/ 0	Fax No. 64596267
Survey Type	WITHOUT PREJUDICE: KINDLY ASK LAI HUAT (MENG KEE) TO FWD US THEIR CLIENT'S VIDEO FOOTAGE FOR OUR VIE	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230338)



PRI Documents



Close X

PRI Header Details

Claim No	D17010704MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & LAI HUAT LTD
Workshop Name	LAI HUAT (MENG KEE) MOTOR PTE LTD (Contact Person : JENNY LIM)	Survey Location & Contact Details	160 Sin Ming Drive #04-01/02 and #07-03Sin Ming Auto Mobile: 0 , Phone: 64538110 , Fax: 64596267 EmailId: JENNY.LIM@LAIHUAT.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: KINDLY ASK LAI HUAT (MENG KEE) CLIENT'S VIDEO FOOTAGE FOR OUR VIEW		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9919R	TP Vehicle No	SJN9458L
PRI Recieved Date	17-11-2017 06:37:03 PM	Surveyor Appointed Date	18-11-2017 01:37:41 PM	Surveyor Accept Date	20-11-2017 11:00:00 AM

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 21 November, 2017 2:48 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010704MFSH/1, SJN 9458L
Attachments: SJN 9458L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJN 9458L
Date of survey: 20/11/2017

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 20 November, 2017 9:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010704MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Saturday, 18 November, 2017 1:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010704MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010704MFSH
Our ref: CS/FCI17022076/Kvb

Date : 21/11/2017

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJN 9458L


We thank for your instruction on 18/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2017 at the premises of M/s LAI HUAT (MENG KEE) MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$29,388.82
Revised Estimate Amount	: S\$26,749.77
"Check" Items Amount	: S\$1,572.50
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear body, front and n/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6321E

Vehicle Details

Vehicle No.	SJN9458L
Vehicle to be Exported	No
Intended De-registration Date	15 Nov 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	PASSAT R36 3.6 V6 A 4WD
Primary Colour	Black
Manufacturing Year	2008
Engine No.	BWS005083
Chassis No.	WVWZZZ3CZ9E069140
Maximum Power Output	220.0 kW (295 bhp)
Open Market Value	\$46,751.00
Original Registration Date	05 Mar 2009
First Registration Date	05 Mar 2009
Transfer Count	0
Actual ARF Paid	\$46,751.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	04 Mar 2019
PARF Rebate Amount	\$25,713.00

Intended COE Rebate Details

COE Expiry Date	04 Mar 2019
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$5,101.00
COE Rebate Amount	\$662.00
Total Rebate Amount	\$26,375.00

The information contained herein is correct as at 15 Nov 2017

OK

Thank you



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 15 Nov 2017, 11:34:44.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$\$)	Log Date/Time
1	Vehicle	SHA9919R	-	18.32 Insurance Enquiry (GIRO Payment)	5.35	15 Nov 2017 / 11:35:25

sgCARMART.COM
THE ONLY PLACE FOR SMART CAR BUYERS

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

FREE HELP
FOR DIRECT BUYERS & SELLER
100% FREE SETTLEMENT ON LOANS, INSURANCE & PAPERWORK



Username / Email Add

password

Submit Qu



Connect

Sign Up New Account

Forgot Password

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Lamborghini Gallardo LP560-4.



Cheapest And Most Value For
Money In The Market With All
Wear And Tear Done.
Direct Owner (Slovak)

Lake View
Credit Pte Ltd

view our cars

> Low prices guaranteed
> Specialist in Japanese cars
> Easy loan approval
> All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

1 vehicles

volkswagen passat r36

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	volkswagen	passat r36	Any	Any	Any	Any	Any	Any	Available
	Volkswagen	Passat R36	\$44,800	\$20,060 /yr	19-Dec-2008	3,597 cc	119,000 km	Luxury	Available DIRECT OWNER
Last Chance To Own This Subtle German Powerhouse. Not Many Left. Safe Buy With PARF And Body To Redeem. View To Appreciate.									
Posted: 12-Nov-2017 Tags: 2008 Volkswagen Passat, 2008 Volkswagen Passat, Volkswagen Passat, Volkswagen Passat, Volkswagen, Passat, Passat, Used Volkswagen									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads								

20 results/page

sgCarMart is the number one car classifieds for parallel import cars. Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used volkswagen passat r36, volkswagen passat r36 Singapore, used volkswagen passat r36 Singapore, used volkswagen passat r36, used vehicles Singapore or even buy used volkswagen passat r36 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8037948Z**

Name: **LI XIAOPING**

Birth Date: **01 Dec 1980**

Issue Date: **02 Aug 2006**

001435684C




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8037948Z



Name

LI XIAOPING

李 晓 平

Race

CHINESE

Date of birth

01-12-1980

Country of birth

SINGAPORE

Sex

M

S8037948Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B Motorcycles $\leq$ 200 CC
 Class 2A Motorcycles between 201 CC and 400 CC
 Class 2 Motorcycles $>$ 400 CC
 Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver; and motor tractors/vehicles $\leq$ 2500 kg

PASS DATE

11 Aug 2010

11 Aug 2010

11 Aug 2010

15 Aug 2006

S / No. 9000129276

S8037948Z



NP 428A

4793225



NRIC No: **S8037948Z**



Date of issue

15-11-2011

34 CLOVER CRESCENT
SINGAPORE 579203
 NRIC No: **S8037948Z**

Date: **27/02/2013**

No: **7246251**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/11/2017 11:37
Date Of Accident	15/11/2017 08:55
Exact Location Of Accident	REPUBLIC AVENUE TOWARDS ESPLANADE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN9458L
Insured/Policyholder	
Name Of Registered Owner	SEAH GEOK KEOW
NRIC No	S0006321E
Email Address	GKSEAH9@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98164736
Alternative Phone No	OTHERS-98164736
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	PASSAT R36 3.6 V6 A 4WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0081073-VDP-R006
Cover Note Number	
Driver	
Name of Driver	LI XIAOPING
NRIC No	S8037948Z
Date Of Birth	01/12/1980
Occupation	INDOOR
Date Of Driving Pass	15/08/2000
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96229730
Fax Number	
Contact Number	
EMail Address	XIAOPING.LI@APRO.COM.SG

Name	LI XIAOPING
Approximate Age	37
Injuries Sustain	GIDDINESS FROM THE IMPACT OF AIRBAG
Injured person in which vehicle?	SJN9458L
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	34 CLOVER CRESCENT
Postcode	579203

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0017849
Seah Geok Keow

Page 1 of 5
Your ref TP-SHA 9919R FC
Job No 68998
Our ref 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model .. Volkswagen Passat
Accident on 15/11/2017

Not Authorised
U/Ly S
Resony After Pging

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front bumper	<i>Acc/Meng</i> 2,220.00	10.00	1,998.00
1.00	Pc	Front bumper fog lamp cover LH	<i>Net/Ly</i> 276.00	10.00	248.40
1.00	Pc	Front bumper side holder LH	<i>D.Y</i> 41.40	10.00	37.26
1.00	Pc	Front bumper side holder RH	<i>D.Y</i> 41.40	10.00	37.26
1.00	Pc	Front number plate base	<i>Net</i> 72.00	10.00	64.80
1.00	Pc	Front signal lamp side garnish RH	<i>D.Y</i> 92.00	10.00	82.80
1.00	Pc	Front radiator grille	<i>Net/Ly</i> 2,105.00	10.00	1,894.50
1.00	Pc	Front fender inner shield LH (front)	<i>CM</i> 149.50	10.00	134.55
1.00	Pc	Front fender inner shield RH (front)	<i>CM</i> 149.50	10.00	134.55
1.00	Pc	Rear door RH	<i>Bz</i> 1,530.00	10.00	1,377.00
1.00	Pc	Rear door weatherstrip RH	<i>Net</i> 391.00	10.00	351.90
1.00	Pc	Rear door chrome moulding RH	<i>Bz</i> 230.00	10.00	207.00
1.00	Pc	Rear door lower garnish RH	<i>Bz</i> 230.00	10.00	207.00
1.00	Pc	Rear fender RH	<i>Bz</i> 2,220.00	10.00	1,998.00
1.00	Pc	Rear fender arch garnish RH	<i>D.Y/D.Y</i> 490.00	10.00	441.00
1.00	Pc	Side skirt jack cover RH	<i>Net</i> 345.00	10.00	310.50
1.00	Pc	Rear sport rim RH (18")	<i>Net</i> 2,450.00	10.00	2,205.00
1.00	Pc	Rear bumper reflector RH	<i>CM</i> 92.00	10.00	82.80

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

3527

EST. No EST0017849
Seah Geok Keow

Page 163765 2 of 5
Your ref. TP-SHA 9919R FC
Job No. 68998
Our ref. WVWZ 73 19 11 26 069140
Payment
Date 17/11/2017

Attn

Vehicle No ... SJN 9458L
Vehicle Model Volkswagen Passat
Accident on ... 15/11/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Pc	Front door LH	As 1,760.00	10.00	1,584.00	✓ 175.95
1.00	Pc	Front door weatherstrip LH	Mc 391.00	10.00	351.90	506.50
1.00	Pc	Front door chrome moulding LH	oc 276.00	10.00	248.40	—
1.00	Pc	Front door lower garnish LH	As 299.00	10.00	269.10	—
1.00	Pc	Front door wing mirror LH (complete)	CM 1,210.00	10.00	1,089.00	✓
1.00	Pc	Battery positive cable (SRS)	276.00	10.00	248.40	✓
1.00	Pc	Roof top lining	Return 1,570.00	10.00	1,413.00	✓
1.00	Pc	RH head curtain airbag	As 1,415.00	10.00	1,273.50	✓
1.00	Pc	Front passenger safety belt	Turn 620.00	10.00	558.00	✓
1.00	Pc	Front driver safety belt	Th 620.00	10.00	558.00	✓
1.00	Pc	Body undercover RH	mi 207.00	10.00	186.30	✓
1.00	Pc	Front driver seat airbag	As 995.00	10.00	895.50	✓
1.00	Pc	Front engine oil pan	CM 880.00	10.00	792.00	✓
1.00	Pc	Rear top arm RH	As 345.00	10.00	310.50	✓
1.00	Pc	Rear shock absorber RH	As 452.00	10.00	406.80	✓
1.00	Pc	Rear knuckle arm RH	As 620.00	10.00	558.00	✓
1.00	Pc	Rear control arm RH	su 452.00	10.00	406.80	✓
1.00	Pc	Rear wheel bearing with hup RH	As 452.00	10.00	406.80	✓

Special nett item:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

3527

EST. No EST0017849
Seah Geok Keow

Page 163165 3 of 5
Your ref. TP-SHA 9919R FC
Job No. 68998
Our ref. MVWZ 92 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No ... SJN 9458L
Vehicle Model Volkswagen Passat
Accident on ... 15/11/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Front number plate	35.00		35.00 ✓
5.00	Litre	Engine oil	21.50	53.75	107.50 ✓
1.00	Litre	Brake fluid	18.00		18.00 ✓
5.00	Litre	Gearbox fluid	40.00		200.00 ✓
		Labour & Misc.			
1.00		Towing (4 wheel)	120.00		120.00 ✓
1.00		To check 4 wheel alignment (computerised)	80.00		80.00 ✓
1.00		To check + erase fault codes + reset SRS system, etc	180.00		180.00 ✓
1.00		To remove + renew rear suspension part RH	180.00		180.00 ✓
1.00		To renew roof upholstery	140.00		140.00 ✓
1.00		To remove + renew safety belts + airbags, etc	200.00		200.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679. Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0017849
Seah Geok Keow

Page 4 of 5
Your ref TP-SHA 9919R FC
Job No. 68998
Our ref 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model : Volkswagen Passat
Accident on ... 15/11/2017

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00		To remove + refix rear passenger seats, carpet, speaker board, etc	160.00		160.00 120
1.00		To remove + refix front and rear windscreen	320.00		320.00 280
1.00		To supply sealant (x2)	80.00		80.00 40
1.00		To remove + refix roof sunglass	150.00		150.00 120
1.00		To repair driver seat cushion and supply material	250.00		250.00 200
1.00		To straighten front body and renew of parts (front portion)	400.00		400.00 320
1.00		To straighten rear body including cutting and welding, to knock dents on rear fender inner panel RH, rear fender LH and renew of parts	1,600.00		1,600.00 1400

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No EST0017849
Seah Geok Keow

Page 5 of 5
Your ref TP-SHA 9919R FC
Job No 68998
Our ref 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model Volkswagen Passat
Accident on 15/11/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (front bumper only)	300.00		300.00
1.00		To spray paint	1,500.00		1,500.00

2601
1400

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub-Total 29,388.82
GST 7.00% 2,057.22
Total S\$ 31,446.04

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0017849
Seah Geok Keow

Page 1 of 5
Your ref. TP-SHA 9919R FC
Job No 68998
Our ref 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model . Volkswagen Passat
Accident on ... 15/11/2017

Not Authorised
11 Nov 8
Resony Ask Pain
\$21.00

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front bumper	2,220.00	10.00	1,998.00
1.00	Pc	Front bumper fog lamp cover	276.00	10.00	248.40
1.00	Pc	Front bumper side holder LH	41.40	10.00	37.26
1.00	Pc	Front bumper side holder RH	41.40	10.00	37.26
1.00	Pc	Front number plate base	72.00	10.00	64.80
1.00	Pc	Front signal lamp side garnish RH	92.00	10.00	82.80
1.00	Pc	Front radiator grille	2,105.00	10.00	1,894.50
1.00	Pc	Front fender inner shield LH (front)	149.50	10.00	134.55
1.00	Pc	Front fender inner shield RH (front)	149.50	10.00	134.55
1.00	Pc	Rear door RH	1,530.00	10.00	1,377.00
1.00	Pc	Rear door weatherstrip RH	391.00	10.00	351.90
1.00	Pc	Rear door chrome moulding RH	230.00	10.00	207.00
1.00	Pc	Rear door lower garnish RH	230.00	10.00	207.00
1.00	Pc	Rear fender RH	2,220.00	10.00	1,998.00
1.00	Pc	Rear fender arch garnish RH	490.00	10.00	441.00
1.00	Pc	Side skirt jack cover RH	345.00	10.00	310.50
1.00	Pc	Rear sport rim RH (18")	2,450.00	10.00	2,205.00
1.00	Pc	Rear bumper reflector RH	92.00	10.00	82.80

11460.42

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0017849
Seah Geok Keow

Page 2 of 5
Your ref. TP-SHA 9919R FC
Job No. 68998
Our ref 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model : Volkswagen Passat
Accident on ... 15/11/2017

Quantity	Unit	Description	Unit price	Disc pct	Amount
			<i>Pr</i> 1,760.00	10.00	1,584.00 ✓
1.00	Pc	Front door LH	<i>Mr</i> 391.00	10.00	175.95 ✓
1.00	Pc	Front door weatherstrip LH	<i>Od</i> 276.00	10.00	248.40 ✓
1.00	Pc	Front door chrome moulding LH	<i>Pr</i> 299.00	10.00	269.10 ✓
1.00	Pc	Front door lower garnish LH	<i>CM</i> 1,210.00	10.00	1,089.00 ✓
1.00	Pc	Front door wing mirror LH (complete)	276.00	10.00	248.40 ✓
1.00	Pc	Battery positive cable (SRS) relay	<i>McLarn</i> 1,570.00	10.00	1,413.00 ✓
1.00	Pc	Roof top lining	<i>Burn</i> 1,415.00	10.00	1,273.50 ✓
1.00	Pc	RH head curtain airbag	<i>Tu</i> 620.00	10.00	558.00 ✓
1.00	Pc	Front passenger safety belt	<i>Tu</i> 620.00	10.00	558.00 ✓
1.00	Pc	Front driver safety belt	<i>A.1</i> 207.00	10.00	186.30 ✓
1.00	Pc	Body undercover RH	<i>Pr</i> 995.00	10.00	895.50 ✓
1.00	Pc	Front driver seat airbag	<i>CM</i> 880.00	10.00	792.00 ✓
1.00	Pc	Front engine oil pan	345.00	10.00	310.50 ✓
1.00	Pc	Rear top arm RH	452.00	10.00	406.80 ✓
1.00	Pc	Rear shock absorber RH	<i>A1</i> 620.00	10.00	558.00 ✓
1.00	Pc	Rear knuckle arm RH	452.00	10.00	406.80 ✓
1.00	Pc	Rear control arm RH	<i>A1</i> 452.00	10.00	406.80 ✓
1.00	Pc	Rear wheel bearing with hup RH			

Special nett item.

10548.90

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0017849
Seah Geok Keow

Page 3 of 5
Your ref. TP-SHA 9919R FC
Job No. 68998
Our ref. 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model : Volkswagen Passat
Accident on ... 15/11/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Front number plate	35.00		35.00 ✓
5.00	Litre	Engine oil	21.50		53.75 ✓
1.00	Litre	Brake fluid	18.00		18.00 ✓
5.00	Litre	Gearbox fluid	40.00		200.00 ✓
		Labour & Misc.			106.75 SN
1.00		Towing (4 wheel)	120.00		120.00 ✓
1.00		To check 4 wheel alignment (computerised)	80.00		80.00 ✓
1.00		To check + erase fault codes + reset SRS system, etc	180.00		180.00 120 ✓
1.00		To remove + renew rear suspension part RH	180.00		180.00 ✓
1.00		To renew roof upolstery	140.00		140.00 120 ✓
1.00		To remove + renew safety belts + airbags, etc	200.00		200.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0017849
Seah Geok Keow

Page 5 of 5
Your ref. TP-SHA 9919R FC
Job No 68998
Our ref. 17.11.26
Payment
Date 17/11/2017

Attn

Vehicle No SJN 9458L
Vehicle Model : Volkswagen Passat
Accident on ... 15/11/2017

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (front bumper only)	300.00		300.00 261
1.00		To spray paint	1,500.00		1,500.00 1400
					4920

Sub-Total 29,388.82
GST 7.00% 2,057.22
Total S\$ 31,446.04

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



24 HOURS TOWING SERVICES

KAO LIN MOTOR TRADING CO

Thomson Road Post Office, P.O. Box 95, Singapore 915704

Tel: 6452 0716, 6458 4013

Registration No. 21645200K

CASH SALE
JOB ORDER

No. 7007067

Messrs

Lai Hung

Date

15/11/17

Vehicle No.

S2H94086

Model

Vollagen

Destination

Singapore

Plyer

Time In

10:00

Time Out

11:00

Remarks

Amount \$

150

- ☐ Change Spare Tyre / Jumpstart
- ☐ Basement / Multi Carpark
- ☒ Accident
- ☒ Using King Dolly (Extra Trailer)
- ☐ Lowered Bodykit / Suspension

- ☐ Loaded With Goods
- ☐ Dismantle Shaft / Brake / Equipment
- ☐ Open Door
- ☒ Crane up / Winch out

Driver

Received By

1N4541

7

bizSAFE

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 3 May 2018 4:18 PM
To: Kenneth Kong (LKKAUTO)
Subject: FW: Finalisation - SJN 9458L / Volkswagen Passat
Attachments: SJN 9458L.pdf; SJN 9458L-Towing receipt.pdf; IMG_1909.jpg; IMG_1910.jpg; IMG_1911.jpg; IMG_1912.jpg; IMG_1913.jpg; IMG_1914.jpg; IMG_1915.jpg; IMG_1947.jpg; IMG_1948.jpg; IMG_1949.jpg; IMG_2923.jpg; IMG_2924.jpg; IMG_2925.jpg; IMG_2926.jpg; IMG_2927.jpg; IMG_2928.jpg; IMG_2929.jpg; IMG_2930.jpg; IMG_2931.jpg; IMG_5626.jpg; IMG_5627.jpg; IMG_5628.jpg; IMG_5629.jpg; IMG_5630.jpg; IMG_5631.jpg; IMG_5632.jpg

Dear Kenneth,

CS/FCI17022076/Kvb

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Thursday, 3 May 2018 3:39 PM
To: SUR <sur@lkkauto.com>
Subject: FW: Finalisation - SJN 9458L / Volkswagen Passat

Dear Veron

For your kind attention.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Thursday, 4 January, 2018 3:03 PM
To: Kenneth Kong
Subject: Finalisation - SJN 9458L / Volkswagen Passat

Dear Sir

For your confirmation, please:

- Parts: \$22,009.32
- SN: \$ 498.65
- L&P: \$ 4,920.00

Sub-total: \$27,427.97

LS(-20%): \$ 5,485.60 = \$21,942.37

Lump sum: \$21,000.00 / 33 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022076/Kvbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9919R	Veh. Inspected	SJN 9458L
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17010704MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	18/11/2017

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN R36 (A)	c.c	3597
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WVWZZZ3CZ9E069140	Colour	METALLIC BLACK
Odometer	163765	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40Z R18	MICHELIN	6 mm
L/H Front Tyre	235/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	235/40Z R18	MICHELIN	7 mm
L/H Rear Tyre	235/40Z R18	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY, FRONT AND N/S FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/11/2017	Inspection Date	20/11/2017
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	24 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 9458L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / MTG CRACKED	2,220.00	2,220.00
1	FRONT BUMPER FOG LAMP COVER LH	DENTED / CUT	276.00	276.00
1	FRONT BUMPER SIDE HOLDER LH	DISTORTED	41.40	41.40
1	FRONT BUMPER SIDE HOLDER RH	DISTORTED	41.40	41.40
1	FRONT NUMBER PLATE BASE	DENTED	72.00	72.00
1	FRONT SIGNAL LAMP SIDE GARNISH RH	DISTORTED	92.00	92.00
1	FRONT RADIATOR GRILLE	DENTED / CUT	2,105.00	2,105.00
1	FRONT FENDER INNER SHIELD LH (FRONT)	CRACKED	149.50	149.50
1	FRONT FENDER INNER SHIELD RH (FRONT)	CRACKED	149.50	149.50
1	REAR DOOR RH	BENT	1,530.00	1,530.00
1	REAR DOOR CHROME MOULDING RH	BUCKLED	230.00	230.00
1	REAR DOOR LOWER GARNISH RH	BENT	230.00	230.00
1	REAR FENDER RH	BENT	2,220.00	2,220.00
1	REAR FENDER ARCH GARNISH RH	DISTORTED / DENTED	490.00	490.00
1	SIDE SKIRT JACK COVER RH	MISSING	345.00	345.00
1	REAR SPORT RIM RH (18)	DENTED	2,450.00	2,450.00
1	REAR BUMPER REFLECTOR RH	CRACKED	92.00	92.00
1	FRONT DOOR LH	BENT	1,760.00	1,760.00
1	FRONT DOOR CHROME MOULDING LH	DENTED	276.00	276.00
1	FRONT DOOR LOWER GARNISH LH	BENT	299.00	299.00
1	FRONT DOOR WING MIRROR LH (COMPLETE)	CRACKED	1,210.00	1,210.00
1	BATTERY POSITIVE CABLE (SRS)	SERVICEABLE	276.00	-
1	ROOF TOP LINING	DEFORMED	1,570.00	1,570.00
1	RH HEAD CURTAIN AIRBAG	BURST	1,415.00	1,415.00
1	FRONT PASSENGER SAFETY BELT	JAMMED	620.00	620.00
1	FRONT DRIVER SAFETY BELT	JAMMED	620.00	620.00
1	BODY UNDERCOVER RH	MISSING	207.00	207.00
1	FRONT DRIVER SEAT AIRBAG	BURST	995.00	995.00
1	FRONT ENGINE OIL PAN	CRACKED	880.00	880.00

Report Ref No. CS/FCI17022076/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TOP ARM RH	BENT	345.00	345.00
1	REAR SHOCK ABSORBER RH	BENT	452.00	452.00
1	REAR KNUCKLE ARM RH	BENT	620.00	620.00
1	REAR CONTROL ARM RH	SERVICEABLE	452.00	-
1	REAR WHEEL BEARING WITH HUB RH	BENT	452.00	452.00
	LESS 10% DISCOUNT		-2,518.28	-2,445.48
			22,664.52	22,009.32
1	REAR DOOR WEATHERSTRIP RH (50%) (SN)	NECESSARY	391.00	195.50
1	FRONT DOOR WEATHERSTRIP LH (50%) (SN)	NECESSARY	391.00	195.50
	LESS 10% DISCOUNT		-78.20	-
			703.80	391.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	35.00	35.00
5	LITRE ENGINE OIL @\$21.50 (SN) (50%)	NECESSARY	107.50	53.75
1	LITRE FLUID (SN)	NECESSARY	18.00	18.00
5	LITRE GEARBOX FLUID @\$40.00(SN)	NOT NECESSARY	200.00	-
2	SEALANT (SN)	NECESSARY	80.00	40.00
			440.50	146.75
	<u>LABOUR</u>			
	TOWING (4 WHEEL)		120.00	120.00
	TO CHECK 4 WHEEL ALIGNMENT (COMPUTERISED)		80.00	80.00
	TO CHECK & ERASE FAULT CODES + RESET SRS SYSTEM, ETC.		180.00	120.00
	TO REMOVE + RENEW REAR SUSPENSION PART RH.		180.00	180.00
	TO RENEW ROOF UPHOLSTERY.		140.00	120.00
	TO REMOVE + RENEW SAFETY BELTS + AIRBAGS, ETC.		200.00	200.00
	TO REMOVE + REFIX REAR PASSENGER SEATS, CARPETS, SPEAKER BOARD, ETC.		160.00	120.00
	TO REMOVE + REFIX FRONT AND REAR WINDSCREEN.		320.00	280.00
	TO REMOVE + REFIX ROOF SUNGLASS.		150.00	120.00
	TO REPAIR DRIVER SEAT CUSHION AND SUPPLY MATERIAL.		250.00	200.00

Report Ref No. CS/FCI17022076/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO STRAIGHTEN FRONT BODY AND RENEW OF PARTS (FRONT PORTION)		400.00	320.00
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING, TO KNOCK DENTS ON REAR FENDER INNER PANEL RH, REAR FENDER LH AND RENEW OF PARTS.		1,600.00	1,400.00
	TO SPRAY PAINT (FRONT BUMPER ONLY)		300.00	260.00
	TO SPRAY PAINT.		1,500.00	1,400.00
			5,580.00	4,920.00
	GRAND TOTAL		29,388.82	27,467.07
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,000.00

Report Ref No. CS/FCI17022076/Kvbe2

MARKET VALUE: \$48,000.00(EST)-LTA REIMBURSEMENT VALUE:\$26,375.00=NETT VALUE: \$21,625.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.