

Not Authorized
1-B-1
Recovery B4 party

6 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer:

AIG

Vehicle No: SGX7Y

Third Party Veh No:

SKW1572H

Model: MERCEDES BENZ E200

Date of Accident:

10/11/17

Chassis: WDD2130422A102884

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR RH DOOR		\$2,118.00
1	REAR RH DOOR RUBBER SEAL		\$135.00
1	REAR RH DOOR WEATHER STRIP		\$274.00
1	REAR RH DOOR POWER WINDOW MOTOR		\$478.00
1	REAR RH DOOR POWER WINDOW REGULATOR		\$702.00
1	REAR RH DOOR POWER WINDOW CHANNEL		\$172.00
1	REAR RH DOOR POWER WINDOW CHANNEL WEATHER STRIP		\$129.00
1	REAR RH DOOR INNER SUPPORT BOARD		\$1,224.00
1	REAR RH DOOR MECHANISM LOCK		\$380.00
14	REAR RH DOOR INNER TRIM BOARD CLIPS	\$9.00	\$126.00
1	ROCKER RH SIDE SKIRTING		\$630.00
1	ROCKER RH SIDE SKIRTING CHROME MOULDING FRONT		\$160.00
1	ROCKER RH SIDE SKIRTING CHROME MOULDING REAR		\$78.00
10	ROCKER RH SIDE SKIRTING CLIPS	\$9.00	\$90.00
1	REAR BUMPER		\$1,872.00
10	REAR BUMPER CLIPS	\$9.00	\$90.00
10	REAR BUMPER RIVET	\$11.50	\$115.00
1	REAR BUMPER RH SIDE RETAINER		\$60.00
1	REAR SUSPENSION RH UPPER ARM		\$178.00
1	REAR SUSPENSION RH KNUCKLE ARM		\$1,592.00
1	REAR SUSPENSION RH KNUCKLE ARM BEARING		\$230.00
1	REAR SUSPENSION RH LOWER ARM		\$242.00
1	REAR SUSPENSION RH TRAILING ARM		\$220.00
1	REAR SUSPENSION RH TORSION ARM		\$210.00
1	REAR RH 17" SPORT RIM ORIGINAL		\$660.00
12	REAR RH FENDER INNER SHIELD CLIPS	\$9.00	\$108.00

SUB TOTAL	\$12,273.00
Less 10%	-\$1,227.30
PARTS TOTAL	\$11,045.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer: AIG

Vehicle No: SGX7Y

Third Party Veh No: SKW1572H

Model: MERCEDES BENZ E200

Date of Accident: 10/11/17

Chassis: WDD2130422A102884

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR RH 225/55 R17 97Y TYRE		\$580.00
		S/N TOTAL	\$580.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,500.00	700
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,250.00	1100
TO TUFF KOTE / ANTI-RUST	\$60.00	300
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	\$60.00	200
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$280.00	7
TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	\$350.00	7
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$100.00	7
TO SEND VEHICLE FOR 3D COMPUTERISED WHEEL ALIGNMENT	\$80.00	✓
TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT TO FACILITATE REPAIR	\$180.00	800
	LABOUR TOTAL	\$3,860.00
WINSON	TOTAL	\$15,485.70