



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

FWD/AIG(SCU868S)

DOA: 12/11/2017@1915

AIG ASIA PACIFIC INSURANCE PTE LTD

18/11/2017

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJQ 2459 P - SUBARU FORESTER 2.0X AWD 4AT D/AIRBAGS

CHASSIS NO: JF1SH5KS59G018871 (2009)

1 pc	Front bumper	\$ 720.50
1 pc	Front bumper foglight chrome RH	\$ 90.40
1 pc	Front bumper foglight RH	\$ 425.10
1 pc	Front headlamp RH	\$ 1,157.90
		<u>\$ 2,393.90</u>
	LESS 25%	<u>\$ 598.48</u>
		<u>\$ 1,795.42</u>
	Check wiring function	\$ 40.00
	Remove necessary parts; jacking, panel beating, repair and straighten front headlamp panel RH, front fender RH and front bumper,	\$ 350.00
	Putty and respray front headlamp panel RH, front fender RH and front bumper.	<u>\$ 450.00</u>
		<u>\$ 2,635.42</u>
	ADD 7% GST	<u>\$ 184.48</u>
		<u><u>\$ 2,819.90</u></u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....
