

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1147/2017/JT
Date : 20-Nov-17

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle number :SLN 7568 S

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Riga Paul Maurits
Address : 31 Mandai Estate
#05-12
Singapore 729933
Telephone : HP +65 9685 5555
Type of Claim : Third Party Claim
Policy No. : 5093635094
Vehicle No : **SLR 7725 J**
Model Code : Audi Q2 1.4 TFSI S-tronic
Model / Year : Aug-17
Engine No : CZE 479683
Chassis No : WAUZZZGA7JA000800
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Nov-17
Place of Accident : Yio Chu Kang Road before Yio Chu Kang Road flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 7725 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper, lower spoiler and both wheel arch trims.	\$ 2,100.00 1300.	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 3,472.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

S/N are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 7725 J.

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	REAR BUMPER <i>delivered</i>	\$ 982.00	✓
2	REAR BUMPER MID PORTION <i>delivered</i>	\$ 792.00	✓
3	REAR BUMPER LOWER SPOILER TRIM <i>delivered</i>	\$ 378.00	+
4	REAR BUMPER LOWER SPOILER <i>delivered</i>	\$ 549.00	✓
5	REAR BUMPER REFLECTOR - LHS <i>delivered</i>	\$ 24.00	✓
6	REAR WHEEL ARCH TRIM - LHS/RHS <i>delivered</i>	\$ 776.00	✓
7	REAR PARKING AID <i>delivered</i>	\$ 208.00	+
8	SUNDRIES <i>delivered</i>	\$ 300.00	?
TOTAL SPARE PARTS		\$ 4,009.00	
TOTAL LABOUR CHARGES		\$ 3,472.00	
GRAND TOTAL		\$ 7,481.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 22/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant