

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Dec 2018)**Parts:** 143 BMW 316I 1.6 AT D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hua Hong Pte Ltd/SCM794M/17/12/2018 14:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper Undercover	0.00	0.00	CRA *175.00 F ✓
2	1		*Front Inner Shield LH	0.00	0.00	NN *160.00 F X
Sub Total (S\$)						335.00
+ Margin on L,N Items 5.00% (S\$)						16.75
Total Parts (S\$)						351.75

F=Franchise part.

**Hua Hong Pte Ltd/SCM794M/17/12/2018 14:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS**