

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

XE 2944C

ESTIMATE

DATE : 20/11/2017

VEHICLE NO : PLU 1588

MAKE/MODEL : MIT. ATTRAGE

ACC DATE : 18/11/2017

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR BUMPER	659.00	659.00 ✓
2	2 REAR BUPER SIDE RETAINER RH/LH	32.00	64.00 ✓
3	1 REAR FENDER RH	725.00	725.00 ✓
4	1 REAR FENDER LOWER SHIELD RH	46.00	46.00 X
5	1 REAR SPORT RIM RH	645.00	645.00 3005.00
6	1 REAR SHOCK ABSORBER RH	225.00	225.00 ?
7	1 REAR AXLE	939.00	939.00 X
8	1 REAR AXLE WHEEL BEARING RH	110.00	110.00 ?
9	1 REAR DOOR RH	845.00	845.00 ✓
10	1 REAR DOOR TOP HINGE RH	49.00	49.00 ✓
11	1 REAR DOOR BOTTOM HINGE RH	49.00	49.00 ✓
12	1 REAR DOOR CHECKER RH	52.00	52.00 ✓
13	1 REAR DOOR RUBBER RH	129.00	129.00 ✓
14	1 REAR DOOR LOCK RH	290.00	290.00 ?
15	1 REAR DOOR INNER SPEAKER RH	155.00	155.00 ?
16	1 REAR DOOR INNER TRIM BOARD RH	472.00	472.00 ?
17	1 REAR DOOR GLASS CHANNEL RH	101.00	101.00 X
18	1 REAR DOOR GLASS REGULATOR RH	119.00	119.00 ?
19	1 REAR DOOR GLASS REGULATOR MOTOR RH	352.00	352.00 ?
20	1 REAR DOOR BLACK TAPE RH	27.00	27.00 ✓
21	1 REAR DOOR OUTER HANDLE RH	92.00	92.00 X
22	1 DOOR CENTRE PILLAR RH	982.00	982.00 ✓
23	1 FRONT DOOR RH	752.00	752.00 ✓
24	1 FRONT DOOR RUBBER RH	168.00	168.00 ✓
25	1 FRONT DOOR INNER SPEAKER RH	155.00	155.00 X
26	1 FONT DOOR LOCK RH	290.00	290.00 ?
27	1 FRONT DOOR INNER TRIM BOARD RH	495.00	495.00 ?
28	1 FRONT DOOR GLASS RH	375.00	375.00 X
29	1 FRONT DOOR GLASS CHANNEL RH	113.00	113.00 X
30	1 FRONT DOOR GLASS REGULATOR RH	125.00	125.00 ?
31	1 FRONT DOOR GLASS REGULATOR MOTOR RH	352.00	352.00 ?
32	1 FRONT DOOR BLACK TAPE RH	27.00	27.00 ✓

Not Authorised
1/5
21/11/17

LEE BROTHERS AUTOMOTIVE PTE. LTD.

33	1	FRONT DOOR OUTER HANDLE RH	92.00	<i>cut</i>	92.00	✓
34	1	FRONT DOOR VIEW MIRROR RH	604.00	<i>510</i>	604.00	✓
35	1	FRONT DOOR VIEW MIRROR COVER RH	103.00	<i>cut</i>	103.00	✓
36	1	FRONT DOOR VIEW MIRROR SIGNAL LAMP RH	151.00	<i>17</i>	151.00	✗
	1	FRONT FENDER QUARTER GARNISH RH	32.00	<i>garnish</i>	32.00	✓
					10,961.00	
			LESS 10%		1,096.10	
					9,864.90	

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN SPONGE TAPE	20.00	<i>net</i>	20.00	✓
2	1	(SET) FRT WINDSCREEN SEALANT	80.00	<i>net</i>	80.00	40
3	1	(SET) REAR BOOT INNER TRIM CLIPS	45.00	<i>17</i>	45.00	✗
4	1	(SET) REAR BUMPER CLIP	35.00	<i>net</i>	35.00	✓
5	1	REAR TYRE RH	200.00	<i>gumb</i>	200.00	60%
6	1	FRONT FENDER EMBLEM RH	50.00	<i>net</i>	50.00	✓
			BALANCE B/F		430.00	

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR FENDER RH AND REPAIR FENDER INNER PANEL AND REPLACE ACCIDENT PARTS	<i>1000</i>	1,200.00	
2	TO SPRAY PAINTING ON ACCIDENT PARTS	<i>1000</i>	1,200.00	
3	TO REMOVE, REFIX REAR WINDSCREEN		120.00	✓
4	TO REMOVE, REFIX CUSHION AND INNER TRIM	<i>80</i>	120.00	
5	TO REMOVE, REPLACE REVERSE SENSOR	<i>50</i>	80.00	
6	TO REMOVE, REPLACE REAR UNDERCARRIGE	<i>120</i>	300.00	
7	4 WHEEL ALIGNMENT	<i>60</i>	80.00	
8	TO TRANSFER 2 DOOR PARTS	<i>120</i>	160.00	
9	TO TUFF KOTE		100.00	✓
10	TOWING		60.00	✓
				3,420.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,714.90