

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yvonne Ang Ching Ching

Date: 23 Nov 2017

Preliminary Advice

Vehicle No	: SLM2668A	Accident Date	: 16/11/2017
Make	: PORSCHE MACAN	Policy No.	: P1921331
Assignment Date	: 21/11/2017	Excess	: S\$3,000.00
Date of Inspection	: 22/11/2017	Est. Duration of Repair	: 6.00
Inspection At	: STUTTGART AUTO PTE LTD (HQ) 12 SUNGEI KADUT AVE SINGAPORE 729648		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,073.12
Revised Amount	:S\$	10,830.96
Check Items (Estimated)	:S\$	109.36
Total	:S\$	10,940.32

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	304,000.00
COE / PARF Rebate	:S\$	127,771.00
Salvage Value	:S\$	
Margin for Repair	:S\$	176,229.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Survey date and time: 22/11/2017 at 1.45pm
We have Not authorise repair.