



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 16:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012086 Date : 24/01/2018 Order : SLF0672L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF0672L (V 30949) Regn Date: 11/08/2016 Mileage: 14353 WIP No.: 45641
Model: A1 SB 1.0 TFSI S tronic 8XFCSG Chassis: WAUZZZ8X26B113544 Engine: CHZ 102401 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (11)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT AND BONNET. ALIGN TO POSITION. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL	1000.00	1.00	1,000.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 16:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012086 Date : 24/01/2018 Order : SLF0672L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF0672L (V 30949) Regn Date: 11/08/2016 Mileage: 14353 WIP No.: 45641
Model: A1 SB 1.0 TFSI S tronic 8XFCSE Chassis: WAUZZZ8X26B113544 Engine: CHZ 102481 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (11)

		Details	Qty	Unit Price	Amount
S	BODYWORK	UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURIS COOLING SYSTEM. (S/N)	1750.00	1.00	1,750.00
S	BODYWORK	M: TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REPAIR LHS A-PILLAR.	500.00	1.00	500.00
X	AN 90771002	TO RESPRAY LHS A-PILLAR.			
X	ABXA809961A	NUT (A)	Less 020%	7.00	3.80
X	AG A13A8JM1	WHEEL HOUS(A)	Less 020%	1.00	146.00
X	ABXA941043A	COOLANT ADDITIVE	Less 020%	4.00	32.90
X	ABXA807065A GRU	HEADLAMP	Less 020%	1.00	1616.00
X	ABX0823029	COVER	Less 020%	1.00	1280.00
X	ABXA807611	HOOD	Less 020%	1.00	1860.00
X	ABXA805594	PLATE	Less 020%	1.00	136.00
X	ABX0098629A	CARRIER(A)	Less 020%	1.00	885.50
X	ABXA805607	ATT.PARTS(A)	Less 020%	1.00	32.90
X	ABX0823126	MOUNTING	Less 020%	1.00	99.30
X		EDGING	Less 020%	2.00	15.20
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 16:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012086 Date : 24/01/2018 Order : SLF0672L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF0672L (V 30949) Regn Date: 11/08/2016 Mileage: 14353 WIP No.: 45641

Model: A1 SB 1.0 TFSI S tronic 8XFCSE Chassis: WAUZZZ8X26B113544 Engine: CHZ 102481 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (11)

		Details		Qty	Unit Price	Amount
X	ABXA807681B 9B9	GRILL	Less 020%	1.00	335.00	268.00
X	ABX0955101C	CYLINDER	Less 020%	1.00	122.50	98.00
X	ABXA010515	STICKER	Less 020%	1.00	31.90	25.52
X	AN 90817302	NUT	Less 020%	2.00	1.40	2.24

Parts 5,389.20
Labour 0.00
Sublet 6,702.00
Menus 0.00
Lubricant 0.00

Sub-Total 11,491.20

7% GST 804.38

Grand Total 12,295.58



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLF 672 L

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/1148/2017/KS
6 Dec 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A1 SB 1.4 TFSI S tronic
Vehicle Chassis No. : WAUZZZ8X2GB113544
Vehicle Regn No. : **SLF 672 L**
Vehicle Mileage : 14353 KM
Vehicle Owner : Ms. Deborah Khoo Wen Shi
Certificate No : 2100478645-01
Policy Excess : **S\$642.00 (inclusive GST)**
Accident Date : 17 November 2017
Place : General Hospital Multi Storey Carpark H Level 2B
Repair Cost : \$ 12,295.58
WIP No. : 45641
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 6/12/17

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1148/2017/JT 30-Nov-17 CHANG 1 SLF 672 L Audi A1 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system. (S/N)	\$ 1,000.00	\$ 1,000.00 ✓
2	To renew front lock carrier and align to position. Repair LHS A-pillar.	\$ 2,700.00	\$ 1,750.00 ✓
3	To respray LHS A-pillar.	\$ 800.00	\$ 500.00 ✓ <u>\$ 3,250.00</u>
<u>Parts</u>			
1	FRONT WHEEL HOUSING LINER - LH <i>Cracked.</i>	\$ 146.00	\$ 116.80 ✓
2	WHEEL HOUSING LINER ATTACHEMENT PARTS <i>me</i>	\$ 33.00	\$ 26.32 ✓
3	FRONT LOCK CARRIER <i>Cracked</i>	\$ 886.00	\$ 708.40 ✓
4	COOLANT <i>me</i>	\$ 132.00	\$ 105.28 ✓
			<u>\$ 956.80</u>
GRAND TOTAL		: \$ 5,697.00	\$ 4,206.80

For Premium Automobiles Pte Ltd

Authorised Signature