

maximen.

Policy No: **23-112017**
 Estimated Cost: **SLR 8480H**
 Vehicle No: **Vermogen**
 Location: **6 Beni Sector.**
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 Vehicle Record:
 Make of Veh:
 Policy Condition:
 Remarks: The veh had commenced its repair at the time of inspection.
 Date: Person Contacted:
 Vehicle IN/OUT:



Policy No: **SLR84804** Date: **2017** Agency: **Way**
 Type: **W** Car / Cycle / Bus / Van / Long / Truck / Home/Mover / Truck / Trailer
 Make: **Toyota Fielder** Year: **1996**
 Colour: **White** - Insured: Std: **NA**
 Seating: **6606** - Insured: Std: **NA**
 Eng No:
 Ch No: **NRE1618002824**
 Gen Cond: **G600** / Fair / Poor / Burnt
 Steering: Jammed / Leaked / Burnt or
 Brake: Jammed / Leaked / Burnt or
 Mod: **Nil** / SRim / ST Rim or
 Tyre Size: **FR 175/65R15**
 RR:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI / TOYO / YOKO or
 Front: Rear:
 R.Bal: **6** mm R.Bal: **6** mm
 L.Bal: **6** mm L.Bal: **6** mm
 D.O.A: D.O: **23/11/12 @ 170**
 Survey held at: **Vermogen Beni**
 Des of Damages: Fr: Rear: DS **(NS)** UO: Rooftop:
 The U.O / Chassis frame / Body Structure affected due to ... of

Date Time Action Instruction
21/11/2017 2300, 5 days - email to Paulo.
(Red: 11598.02 : 83%)

RECEIVED 21 FEB 2018 pass back to catheme (Amend d.o.a).
 RECEIVED 21 FEB 2018

Days Of Repair: **5**
 Resurvey No. of Trip: **1**
 Report Format: Prelim. Report
 Final Report
 Add Fee: Site Insp:
 ...
 ...
 ...
 Report Format: **TP**
2300
 Date Fee: **200**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022268/T1tb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 22-11-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJF 9337U	Veh. Inspected	SLR 8480H	
Policy No.	DMHCSN1744351700	Coverage (\$)	0.00	
Claim No.	SNM17D06709C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	21/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/11/2017	Inspection Date	22/11/2017	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2017		21 Nov 2017 17:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:

Main Claimant:	LCRF PTE LTD	Date of Loss:	20/11/2017 22:00 - :59
Vehicle Reg. No.:	SLR8480H	Policy/Cover Note No.:	DMHCSN1744351700
Claim Type:	TP / SNM17D06709C02	Policy No. (Claimant):	
Vehicle Reg. No. (Insured):	SJF9337U	Excess:	S\$0.00

Repairer: Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/11/2017]

Adj Asg. Remarks: PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION

ASSOCIATED MAIL RECEIVED [View All](#) | [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2017 14:23
Date Of Accident	16/11/2017 22:30
Exact Location Of Accident	CHANGI AIRPORT TERMINAL 3 DEPARTURE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8480H
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	FIELDER
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995170
Cover Note Number	

Driver

Name of Driver	MOHAMED SALEHIN BIN MOHD AMIN
NRIC No	S8040186H
Date Of Birth	25/12/1980
Occupation	OUTDOOR
Date Of Driving Pass	14/06/2003
Driving Experience	14 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO PHOTOS ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJF9337U
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver IRDAWATI BINTE ANWAR
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 		 
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

T3 Departure

SKETCH PLAN

A-SLR8480H
B-SJF9337U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along T3 Departure near to Door 2 and 3, I was driving straight and I saw vehicle B wanted to filter out from my left side. ^{Sheve but she still collided into my vehicle.} I stopped and dropped my passenger, after which I went to the 4th lane to take photos and exchange particulars and the cisco asked us to move towards the first lane after the last door, I received a message from the next day and she says that she does not have the money to do private settlement and asked me to proceed with insurance claim. I wish to add that before vehicle B collide to my car, I managed to sheve to the right to prevent more damage to the vehicle and also to the passenger.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

EDMOND

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

< +6586937893

if thats the case then i will just inform my car rental co and see what they say. bcos as u know i have the right of way and u just come out..gd thing i manage to swerve if not my passenger inside may got hurt...

14:27 So confirm u say 50 50?

14:28 If yes then i proceed for the insurance claim

If u want to claim insurance then ok lah cos i really don't have cash to pay u now.

14:32

Anyway wats yr car plate too?

14:50

Ok..I want to do personal settlement bcos claim insurance will be tough..if u noe how much excess u need to fork out

14:50 Sir8480h

Yup i know 14:51

Enter message



< +6586937893



Sorry wats ur car plate no? 14:23

I need to inform my car rent co...bcos need replacement car 14:24

SJF9337U 14:25

Ok noted. 14:27

If thats the case den i will just inform my car rental co and see what they say..bcos as u know i have the right of way and u just come out..gd thing i manage to swerve if not my passenger inside may got hurt...

So confirm u say 50 50? 14:27

If yes then i proceed for the insurance claim 14:28

If u want to claim insurance then ok lah cos i really don't have cash to pay u now. 14:32

Anyway wats yr car plate

Enter message



< +6586937893



Friday, 17 November 2017

Assalam...i am salehin,
the driver yest from
airport. Have u ask ur
workshop?

10:18



Salam brader... jap eh
I'm currently in meeting.
Get back to u during my
lunchtime yah.

10:49

11:21 Ok thank u

13:50 Hi there...so how?



Hi bro I already talk to my
workshop. He say our case
is 50-50 settlement. I signal
out but i might not see yr car
incoming & u nk masuk tapi
tk nmpk I nk kuar. Lagipun
block by cars & taxis. airport
is alway bz. Suggest we do
our own repair & close case.
Furthermore our damage is
not serious just s

VIEW ALL



14:22

Sorry wats ur car plate
no?

14:23

Enter message



< +6586937893



Fri, 17 Nov 2017 14:22

Hi bro I already talk to my workshop. He say our case is 50-50 settlement. I signal out but i might not see yr car incoming & u nk masok tapi tk nmpk i nk kuar. Lagipun block by cars & taxis. airport is alway bz. Suggest we do our own repair & close case. Furthermore our damage is not serious just some scratches. Kita pun sama2 cari mkn & I'm doing part time je. Seriously if u want to claim me cash I really don't have unless u want to claim insurance.







Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





SLR8480H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 16/11/2017

Vehicle Reg. No. : SLR8480H
Vehicle Reg. Date: 29-Aug-2017
Make / Model : COROLLA FIELDER HYBRID
Engine No. : 2NR8513773
Chassis No. : NRE1618002824

COST OF CLAIMS

Parts Cost / List Items : \$ 11,236.00
Plus/Less 20% \$ 2,247.20
Total Cost / List : \$ 8,988.80
Special Nett Items : \$ -
Total Parts Amount : \$ 8,988.80
Total Labour Amount : \$ 4,000.00
Gross Total : \$ 12,988.80
GST % : 7% \$ 909.22
Nett Amount : \$ 13,898.02

Surveyor Name and Company :

Tanjik 97475749 27/11/17

Date of survey : 23/11/17 @ 1700

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : suu@lkkauto.com

Fax No : _____

HP No : _____

This claim is handled by : EDMOND

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLR8480H
 Vehicle Reg. Date: 29/8/2017
 Make / Model : COROLLA FIELDER HYBRID 1.5G CVT
 Engine No. : 2NR8513773
 Chassis No. : NRE1618002824

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAIL LAMP LH	X NM	\$ 673.00		
2	1	REAR BUMPER	Rx	\$ 573.00		
3	1	REAR BUMPER SIDE RETAINER	Rx	\$ 73.00		
4	2	REAR BUMPER BRACKET	X } ana	\$ 67.00		
5	2	REAR BUMPER REFLECTOR	X } ana	\$ 85.00		
6	1	Front door LH	Rx	\$ 1,097.00		
7	1	Front door front rubber LH	X	\$ 107.00		
8	1set	Front door sticker LH	X	\$ 35.00		
9	1	Front door hinge upper LH	X	\$ 93.00		
10	1	Front door hinge lower LH	X	\$ 93.00		
11	1	Front door stopper LH	X } NM	\$ 25.00		
12	1	Front door moulding LH	X	\$ 187.00		
13	1	Front door weather strip LH	X	\$ 273.00		
14	1	Front door outer handle LH	X	\$ 83.00		
15	1	Front door trim LH	X	\$ 673.00		
16	1set	Front door trim clips LH	X	\$ 50.00		
17	1	Rear door LH	Rx	\$ 1,173.00		
18	1	Rear door front rubber LH	X NM	\$ 135.00		
19	1	Rear door sticker LH	hel	\$ 30.00		
20	1	Rear door hinge upper LH	Rx	\$ 93.00		
21	1	Rear door hinge lower LH	Rx	\$ 93.00		
22	1	Rear door stopper LH	X	\$ 25.00		
23	1	Rear door moulding LH	X	\$ 175.00		
24	1	Rear door weather strip LH	X } ana	\$ 297.00		
25	1	Rear door outer handle LH	X } ana	\$ 65.00		
26	1	Rear door trim LH	X	\$ 681.00		
27	1set	Rear door trim clips LH	X	\$ 50.00		
28	1	Rear fender LH	Rx	\$ 975.00		
29	1	Rear wheel hub cap LH	cut	\$ 187.00		
30	1	Rear shock absorber LH	X NM	\$ 175.00		
31	1	Rear fender LH	Rx	\$ 35.00		
32	1	Rear Rim LH	ana	\$ 2,317.00		
33	1	Rear wheel hub cap LH	ana	\$ 543.00		
34	1	Rear shock absorber LH				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

1465
 25% 1746.25
 1097.25



SLR8480H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 16/11/2017

Vehicle Reg. No. : SLR8480H
Vehicle Reg. Date: 29-Aug-2017
Make / Model : COROLLA FIELDER HYBRIC
Engine No. : 2NR8513773
Chassis No. : NRE1618002824

COST OF CLAIMS

Parts Cost / List Items : \$ 11,236.00
Plus/Less 20% \$ 2,247.20
Total Cost / List : \$ 8,988.80
Special Nett Items : \$ -
Total Parts Amount : \$ 8,988.80
Total Labour Amount : \$ 4,000.00
Gross Total : \$ 12,988.80
GST % : 7% \$ 909.22
Nett Amount : \$ 13,898.02

Surveyor Name and Company :

Tanjilun 97475749

Date of survey : 23/11/17 @ 1700

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : Suv@kkhant.com

Fax No : _____

HP No : _____

This claim is handled by : EDMOND

P = 1463
- 25%

1097.25
L = 1790

2887.25
- 20%

2309.80

45 = 2300

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLR8480H
 Vehicle Reg. Date: 29/8/2017
 Make / Model : COROLLA FIELDER HYBRID 1.5G CVT
 Engine No. : ZNR8513773
 Chassis No. : NRE1618002824

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAIL LAMP LH	X	\$ 673.00		
2	1	REAR BUMPER	Rp	\$ 573.00		
3	1	REAR BUMPER SIDE RETAINER	RF	\$ 73.00		
4	2	REAR BUMPER BRACKET	X	\$ 67.00		
5	2	REAR BUMPER REFLECTOR	X	\$ 85.00		
6	1	Front door LH	Rp	\$ 1,097.00		
7	1	Front door front rubber LH	X	\$ 107.00		
8	1set	Front door sticker LH	X	\$ 35.00		
9	1	Front door hinge upper LH	X	\$ 93.00		
10	1	Front door hinge lower LH	X	\$ 93.00		
11	1	Front door stopper LH	X	\$ 25.00		
12	1	Front door moulding LH	X	\$ 187.00		
13	1	Front door weather strip LH	X	\$ 273.00		
14	1	Front door outer handle LH	X	\$ 83.00		
15	1	Front door trim LH	X	\$ 673.00		
16	1set	Front door trim clips LH	X	\$ 50.00		
17	1	Rear door LH	Rp	\$ 1,173.00		
18	1	Rear door front rubber LH	X	\$ 135.00		
19	1	Rear door sticker LH	RF	\$ 30.00		
20	1	Rear door hinge upper LH	Rp	\$ 93.00		
21	1	Rear door hinge lower LH	Rp	\$ 93.00		
22	1	Rear door stopper LH	X	\$ 25.00		
23	1	Rear door moulding LH	X	\$ 175.00		
24	1	Rear door weather strip LH	X	\$ 297.00		
25	1	Rear door outer handle LH	X	\$ 65.00		
26	1	Rear door trim LH	X	\$ 681.00		
27	1set	Rear door trim clips LH	X	\$ 50.00		
28	1	Rear fender LH	Rp	\$ 975.00		
29	1	Rear wheel hub cap LH	cut	\$ 187.00		
30	1	Rear shock absorber LH	X	\$ 175.00		
31	1	Rear fender LH	Rp	\$ 35.00		
32	1	Rear Rim LH	X	\$ 2,317.00		
33	1	Rear wheel hub cap LH	X	\$ 543.00		
34	1	Rear shock absorber LH				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

P-1463

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2017		21 Nov 2017 17:20 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	LCRF PTE LTD			
Vehicle Reg. No.:	SLR8480H	Date of Loss:	16/11/2017 22:00 - :59	
Claim Type:	TP / SNM17D06709C02	Policy/Cover Note No.:	DMHCSN1744351700	
Vehicle Reg. No. (Insured):	SJF9337U	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza, 658064 Bukit Batok - Tel: 65155230			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/11/2017]			
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLR8480H (SNM17D06709C02)**
[SJF9337U]
TP
LCRF PTE LTD
Nov 16 2017 10:00PM
[-]
Vermogen Ace Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
18	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
19	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
20	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
21	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
22	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
23	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
24	01/02/18 15:12	General View		Load JPG	<input checked="" type="checkbox"/>
25	01/02/18 15:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	01/02/18 15:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	01/02/18 15:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	01/02/18 15:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/11/17 17:21	EMAIL FROM VA(1)		Load PDF	
2	21/11/17 17:21	EMAIL FROM VA(2)		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

///

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17022268/T1TBE2
Date: 23/02/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. **Policy No:** DMHCSN1744351700
Claimant Vehicle No : SLR8480H **Insured Vehicle No :** SJF9337U
Date of Loss: 16/11/2017 **Nature of Claim:** TP **Claim No:** SNM17D06709C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8480H
Make & Model: TOYOTA COROLLA FIELDER, 1.5 (A) **Engine No:** 2NR8513773
Reg. Date: 26/08/2017 (Man. Year: 2015) **Chassis No:** NRE1618002824
Colour: White **Odometer:** 6606 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 **Rear Tyre Size:** 175/65 R15
Front Left Side: Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,988.80	1,097.25	7,891.55	87.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,790.00	2,210.00	55.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,988.80	2,887.25	10,101.55	77.77
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	12,988.80	2,300.00	10,688.80	82.29
+ GST 7.00/7.00% (S\$)	909.22	161.00	748.22	82.29
Nett Amount (S\$)	13,898.02	2,461.00	11,437.02	82.29

INSPECTION

Date of Assignment: 21/11/2017
Date Inspected: 23/11/2017 **Inspected At:** 6 BENOI SECTOR
Estimated Period of Repair: 5.0 days **Repairer :** Vermogen Ace Pte Ltd (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 07 Feb 2018)**Parts:** N/A TOYOTA COROLLA FIELDER 1.5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLR8480H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP LH	Not Necessary	673.00 FL	*- FL
2	1		*REAR BUMPER	Repair	573.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER	Necessary	73.00 FL	*73.00 FL
4	2		*REAR BUMPER BRACKET	Not Necessary	67.00 FL	*- FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	85.00 FL	*- FL
6	1		*FRONT DOOR LH	Repair	1,097.00 FL	*- FL
7	1		*FRONT DOOR FRONT RUBBER LH	Not Necessary	107.00 FL	*- FL
8	1		*SET FRONT DOOR STICKER LH	Not Necessary	35.00 FL	*- FL
9	1		*FRONT DOOR HINGE UPPER LH	Not Necessary	93.00 FL	*- FL
10	1		*FRONT DOOR HINGE LOWER LH	Not Necessary	93.00 FL	*- FL
11	1		*FRONT DOOR STOPPER LH	Not Necessary	25.00 FL	*- FL
12	1		*FRONT DOOR MOULDING LH	Not Necessary	187.00 FL	*- FL
13	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	273.00 FL	*- FL
14	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	83.00 FL	*- FL
15	1		*FRONT DOOR TRIM LH	Not Necessary	673.00 FL	*- FL
16	1		*SET FRONT DOOR TRIM CLIPS LH	Not Necessary	50.00 FL	*- FL
17	1		*REAR DOOR LH	Bent	1,173.00 FL	*1,173.00 FL
18	1		*REAR DOOR FRONT RUBBER LH	Not Necessary	135.00 FL	*- FL
19	1		*REAR DOOR STICKER LH	Necessary	30.00 FL	*30.00 FL
20	1		*REAR DOOR HINGE UPPER LH	Repair	93.00 FL	*- FL
21	1		*REAR DOOR HINGE LOWER LH	Repair	93.00 FL	*- FL
22	1		*REAR DOOR STOPPER LH	Not Necessary	25.00 FL	*- FL
23	1		*REAR DOOR MOULDING LH	Not Necessary	175.00 FL	*- FL
24	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	297.00 FL	*- FL
25	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	65.00 FL	*- FL
26	1		*REAR DOOR TRIM LH	Not Necessary	681.00 FL	*- FL
27	1		*SET REAR DOOR TRIM CLIPS LH	Not Necessary	50.00 FL	*- FL
28	1		*REAR FENDER LH	Repair	975.00 FL	*- FL
29	1		*REAR WHEEL HUB CAP LH	Cut	187.00 FL	*187.00 FL
30	1		*REAR SHOCK ABSORBER LH	Not Necessary	175.00 FL	*- FL
31	1		*REAR FENDER LH	Repair	35.00 FL	*- FL
32	1		*REAR RIM LH	Not Necessary	2,317.00 FL	*- FL
33	1		*REAR WHEEL HUB CAP LH	Not Necessary	543.00 FL	*- FL
34	1		*REAR SHOCK ABSORBER LH (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	11,236.00	1,463.00
- List Item Discount on L Items 20.00/25.00% (S\$)	2,247.20	365.75
Total Parts (S\$)	8,988.80	1,097.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA	New	1,400.00	700.00
2	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA	New	1,600.00	900.00
3	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
4	TO RUST PROOF AFFECTED AREAS	New	200.00	40.00
5	TO REMOVE AND REFIT INTERIOR PARTS AND UPHOLSTERY TO ASSIST REPAIR	New	200.00	40.00
6	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New	350.00	0.00
7	TO DO WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$)			4,000.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >