

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Survey & repair
4/11/2017
10am

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

22 NOV 2017

Estimate No. : b1 44909
Date Estimated : 21/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
OSH Minishop
APT BLK 524 Bukit Batok Street 52
#04-761

Singapore 650524

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC422H	V259896	29/04/2016	216d CAT	0

DESCRIPTIONVALUETo replace front RH fender, front RH door and attachments
including knock out dent area cause by accident

1700 2,550.00

Painting on front RH fender & front RH door

1593 1,770.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

To carry out body cavity preservation.
(Per panel) x2

200 236.00

Sundries.

? 80.00

Total Labour 1: **5,344.00**DESCRIPTIONQTYPRICVALUE

FRT RH FENDER *Ry*
 RH EXTENSION WHEEL HOUSING STRUT ?
 RH CROSS SUPPORT SIDE PANAL ?
 Bracket, sid ?
 RH UPPER FRONT DOOR HINGE ?
 RH LOWER FRT DOOR HINGE ?
 FRT RH DOOR *dd* ✓
 FRT RH DOOR BRAKE ?
 FRONT DOOR EDGE PROTECTION ?
 RH SEAL A PILLAR ?
 FRT DOOR JOINT SEAL ?

1	559.30	559.30
1	135.75	135.75
1	41.95	41.95
1	31.35	31.35
1	53.30	53.30
1	53.30	53.30
1	1,076.75	1,076.75
1	70.30	70.30
1	149.60	149.60
1	48.40	48.40
1	29.65	29.65

Total Parts : **2,249.65**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44909
Date Estimated : 21/11/2017
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC422H	V259896	29/04/2016	216d CAT	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 4/12/17 0.42pm Excess S\$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 93495749 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjiah@lkk.com

No. of Working Days Recommend 4-5 days

Labour 1	:	5,344.00
Parts	:	2,249.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	531.56
Grand Total	:	8,125.21

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **