

ASS. REC. 501

REL

CS/AXA17022344 / member

Smart claim

Ma.

ASSIGNMENT (Office)

From (Report)

Kitty Teo

AXA

Date/Time 23/12/2017 12:19pm

Estimated Cost

Bill to

① ID / IP / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJF 8949K

Insured

at Workshop ins

BH Auto

Tel.

6559 8942

of

Blk 1 Sin Ming Ind Est #01-115

Policy No

Claim No

S7M004NQ

Sum Insured

Excess

\$600.00

Make of Veh:

(Client's Record)

D.O.A

10.11.2017

① REV / REP. / REV 24 HRS

R.O.D. Endorsement

Date/Time

23/12/2017 1:21pm

Person Connected

Jacelyn

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJF 8949K - x

24/11/17

Send preli revised by SMART claim

21/2/18

Final fig \$6410 confirmed by email (Ref 5813, 47 figs) (No LS)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s 251 AUTO
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$600
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$22k 23k ma 24/11/17
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJT 89 147K Yr Regn: JUL / 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC c.c. 2.4Colour: SILVER A/C: Insured / Std / NI / NASp. Reading: 116019 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHL RE 48508210482Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60/R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 10/4/2012 D.O.I. 22/11/2017Survey held at _____ @ 649pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

INFORMED WEN CHEN MAX \$6500/2

#6110k

8/3/2018

RECEIVED 03 FEB 2018

RECEIVED 03 FEB 2018

Date/Time. File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time. File Return to?

2)

9/3 - typist

Days Of Repair: 9Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format : SMART claim

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

TOTAL

250

Survey Department Check List (Case Handler)

Reference No. : **CS/AXA/7022344/MIVb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **8/3/18**
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17022344/M1vb

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 23-11-2017



Code : AXA2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJF 8949K
Policy No.	Coverage (\$)	0.00
Claim No. S7M004NQ	Excess (\$)	600.00
Assign From SMART CLAIM (KITTY TEO)	Assign Date	23/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 10/11/2017	Inspection Date 23/11/2017
Survey held at BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

LKK AUTO CONSULTANTS PTE LTD (OD) ▾

New Message

Type *

☒ Message

Subject *

PRELIMINARY ADVICE OF VEHICLE NO SJF 8949K

Message *

Repairer's Estimate (Gross) : S\$12,223.00

Revised Estimate Amount : S\$6,000.00

" Check" Items Amount : S\$ -

Total : S\$6,000.00

Market Value : S\$23,000.00

COE/PARF Rebate : S\$15,656.00

Nett Value : S\$7,344.00

The vehicle sustained damages at the rear portion.

Survey date and time: 23/11/2017 at 6.49PM

We have authorize repair.

No of days:9 days

Some of the parts pending for parts prices.

Best Regards,

Veron Chen

Cancel

Send

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	5110E

Vehicle Details

Vehicle No.	SJF8949K
Vehicle to be Exported	No
Intended De-registration Date	24 Nov 2017
Vehicle Make	HONDA
Vehicle Model	HONDA CRV 2.4L AT
Primary Colour	Silver
Manufacturing Year	2008
Engine No.	K24Z12758242
Chassis No.	JHLRE48508C210482
Maximum Power Output	125.0 kW (167 bhp)
Open Market Value	\$29,414.00
Original Registration Date	14 Jun 2008
First Registration Date	14 Jun 2008
Transfer Count	1
Actual ARF Paid	\$29,414.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	13 Jun 2018
PARF Rebate Amount	\$14,707.00

Intended COE Rebate Details

COE Expiry Date	13 Jun 2018
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$17,113.00
COE Rebate Amount	\$949.00
Total Rebate Amount	\$15,656.00

The information contained herein is correct as at 24 Nov 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

Username / Email Add password Connect	Sign Up New Account Forgot Password
--	--

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Year Coe Renewal 2007 Toyota Wish 1.8A



\$2800 Downpayment Monthly
 From \$688 Onwards. Lowest
 3.86% P.A. @ GV Car Financing.
 GV Credit Pte Ltd. Startd



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

10 vehicles

HONDA CRV

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	HONDA CRV		Any	Any	2008	Any	Any	Any	Available

**Honda CR-V 2.0A****\$24,800**

\$16,500 /yr

18-Aug-2008

1,997 cc

130,190 km

SUV

Available

1 Owner Only! Beautiful Black SUV! Best For Short Term Or Future COE Renewal! Well Maintained, Excellent Condition! Call For More Enquiries!

Posted: 11-Nov-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)**Honda CR-V 2.0A****\$20,500**

\$10,580 /yr

08-Aug-2008

1,997 cc

-

SUV

Available

Almost Brand New Condition, Price Can't Be Negotiable. If Find Any A Fault -\$200 Feel Free To Contact To View The Car At 60 Kaki Bukit Eunus Tech Park.

Posted: 10-Nov-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)**Honda CR-V 2.0A****\$21,800**

\$10,880 /yr

30-Sep-2008

1,997 cc

145,000 km

SUV

Available

Down Payment From 10%, Low Depreciation, Accident Free, Guarantee Condition, Road Tax Till 03/2017, View To Believe! Hurry! Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For Mor...

Posted: 10-Nov-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)**Honda CR-V 2.4A****\$20,000**

N/A

04-Apr-2008

2,354 cc

166,000 km

SUV

Available

Posted: 09-Nov-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)[Car Buying](#)[Car Selling](#)[Car Aftermarket](#)[Car Ownership](#)[On The Move](#)[Lifestyle](#)
[Buy Tyres Online!](#)
[Latest Special Offers from Tyrepack!](#)
**Honda CR-V 2.4A****\$22,000**

\$10,870 /yr

06-Nov-2008

2,354 cc

-

SUV

Available

Just In! Powerful Engine With Spacious Interior. Suitable For Family Or One That Requires Spacious Ride. Flexible Loan. Call Us For Viewing Appointment Before It's Gone!

Posted: 08-Nov-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)**Honda CR-V 2.4A Sunroof****\$25,000**

\$9,400 /yr

03-Dec-2008

2,354 cc

100,000 km

SUV

Available

Very Well Maintained, Comfortable And Spacious Storage Space, Clean And Neat Interior. New Tyres And Air Con Compressor. Spacious Leg Room And Huge Boot Space. Best For Short Term Or Future COE Renewa...

Posted: 07-Nov-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)**Honda CR-V 2.4A Sunroof****\$25,800**

\$13,110 /yr

25-Sep-2008

2,354 cc

173,000 km

SUV

Available

Car Is Well Maintain And Service Regularly. All Wear And Tear Replaced. Good To Go For Another 10 Years Of COE Renewal.

Posted: 28-Oct-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)**Honda CR-V 2.4A****\$22,800**

\$14,160 /yr

02-Jun-2008

2,354 cc

178,771 km

SUV

Available

One Owner, Road Tz

17, Low Mileage, Tip Top Condition, 4WD, When Scrap Body Worth \$3000, Short Term Use, Better Than Rental.

Posted: 20-Oct-17

2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

[Details](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2017 17:32
Date Of Accident	10/11/2017 23:30
Exact Location Of Accident	CTE LEADING TO JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF8949K
Insured/Policyholder	
Name Of Registered Owner	ONG SWEE KENG
NRIC No	S1495110E
Email Address	PETER@AIRPARTSCENTRE.COM
Mobile Phone No	(LOCAL) +65-97558186
Alternative Phone No	OFFICE-97558186

Vehicle Particulars

Manufacturer	HONDA
Model	HONDA CRV 2.4L AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA059385/1
Cover Note Number	

Driver

Name of Driver	ONG SWEE KENG
NRIC No	S1495110E
Date Of Birth	30/07/1961
Occupation	OUTDOOR
Date Of Driving Pass	23/05/1989
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97558186
Fax Number	
Contact Number	OFFICE-97558186
EMail Address	PETER@AIRPARTSCENTRE.COM

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP7058H
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver PERUMAL MUNIRAJ
 NRIC/Passport Number
 Contact Number 82855215
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Accident Sketch Plan

SKETCH PLAN

13.05.2014 11:00 AM
 12/11/14
 12.05.2014

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING IN THE FILTER FROM LITE TO
 TALAN EKEIT MOKAM WHEN VEHICLE B CRASHED INTO
 MY VEHICLE A FROM REAR. THIS CAUSED ME TO
 MOMENTARILY LOSE CONTROL OF MY VEHICLE AND I HAD TO
 CONTROL & STEER MY VEHICLE SAFELY FORWARD

DECLARATION

I hereby declare that the information provided is true and correct.

(Signature)

Name:
 Title:
 Date:
 11/11/14

Name:
 Title:
 Date:
 11/11/14

(Signature)

Name:
 Title:
 Date:
 11/11/14

11/11/14
 11/11/14

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
Attn: Motor Claim Department
Tel : 6338 7288 Fax : 6880 4838
Dear Sir/Madam,

Accident Repair On : SJF8949K

Model : HONDA CRV 2.4L AT

Policy No : GA059385/1

Chassis No : JHLRE48508C210482

Year Of Make : 2008

Date / Time Of Accident : 10/11/2017 at 1130Hrs

Location : CTE LEADING TO JALAN BUKIT MERAH

Date: 23/11/2017

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Tailgate	①	580.00	old	580.00
2	Tailgate moulding chrome	1	150.00	enc	150.00
3	Tailgate hinge LH	1	25.00	enc	25.00
4	Tailgate hinge RH	1	25.00	enc	25.00
5	Tailgate stand absorber LH	1	90.00	enc	90.00
6	Tailgate stand absorber RH	①	90.00	enc	90.00
7	Tailgate inner trim	1	125.00	enc	125.00
8	Tailgate lock assy	1	75.00	enc	75.00
9	Tailgate striker	1	18.00	enc	18.00
10	Tailgate weatherstrip	①	40.00	enc	40.00
11	Tailgate emblem	1	15.00	enc	15.00
12	Tailgate lettering "CRV"	①	15.00	enc	15.00
13	Tailgate lower cover	①	150.00	enc	150.00
14	Tailgate pull handle pocket	1	15.00	enc	15.00
15	Tailgate handle switch button	1	65.00	enc	65.00
16	Rear windscreen	①	650.00	enc	650.00
17	Rear windscreen moulding set	①	30.00	enc	30.00
18	Rear tail lamp assy RH	①	195.00	enc	195.00
19	Rear tail lamp panel RH	①	75.00	enc	75.00
20	Rear bumper	①	160.00	enc	160.00
21	Rear bumper side retainer LH	①	10.00	enc	10.00
22	Rear bumper side retainer RH	1	10.00	enc	10.00
23	Rear bumper reflector RH	①	15.00	enc	15.00
24	Rear bumper side cover RH	①	40.00	enc	40.00
25	Rear bumper under cover	1			
26	Rear fender RH	①	590.00		590.00
27	Rear fender inner RH	1			
28	Rear fender shield RH	1			
29	Rear fender quarter glass RH	①	250.00		250.00
30	Rear fender quarter glass moulding upper RH	①	20.00		
31	Rear fender quarter glass moulding lower RH	①	80.00		
32	Rear fender lower guard RH	1			
33	Rear fender wheel arch protector RH	1	35.00		35.00

34	Rear fender inner upper trim RH	X <i>ave</i>	1		
35	Rear fender inner lower trim RH	<i>ave</i>	①	125.00	125.00
36	Spare tyre cover board	X <i>ave</i>	1		
37	spare tyre box	X	1	250.00	250.00
38	Spare tyre panel	<i>ave</i>	1		
39	Rear door RH	X <i>ave</i>	1	520.00	520.00
40	Rear door weatherstrip RH	X <i>ave</i>	1	65.00	65.00
41	Rear door glass outer moulding chrome RH	X <i>ave</i>	1	55.00	55.00
42	Rear door pillar frame sticker RH	X <i>ave</i>	1	20.00	20.00
43	Rear exhaust assembly	X <i>ave</i>	1	320.00	320.00
44	Rear exhaust tips chrome	X <i>ave</i>	1	65.00	65.00
45	Rear end panel	<i>ave</i>	①	185.00	185.00
46	Rear end panel top garnish	<i>ave</i>	①	45.00	45.00
47	Rear wheel rim RH	X <i>ave</i>	1	720.00	720.00
48	Rear axle assembly	X <i>ave</i>	1	580.00	580.00
49	Rear absorber RH	X <i>ave</i>	1	120.00	120.00
50	Rear absorber mounting RH	X <i>ave</i>	1	35.00	35.00
				Sub-Total:	6,643.00

Total Parts : 6,643.00

Special Nett Items

1	Rear bumper sensors	1	250.00	<i>220</i>	250.00
2	Rear tail lamp holder clips	5	2.00		<i>10.00</i>
3	Rear bumper clips	10	1.00	<i>10</i>	<i>10.00</i>
4	Rear fender shield clips	10	1.00		<i>10.00</i>
5	Rear wheel arch protector clips	10	2.00		<i>20.00</i>
6	Rear number plate with casing	1	35.00	<i>35</i>	<i>35.00</i>
7	Rear tyre RH	1	185.00	<i>185</i>	<i>185.00</i>
				Total Nett Items:	<u>520.00</u>

Accident Vehicle Of : SJF8949K

Page : 2 of 2

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts.		<i>1500</i>	<i>1200</i>	2,200.00
2	Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities		<i>900</i>	<i>1600</i>	1600.00
3	Provide skill labour to disconnect & check electrical wiring, harness, wyre sockets, etc. test & rectify for proper functioning				30.00
4	Provide skill labour to check and re-adjust all wheel alignment.				X 60.00
5	Provide skill labour to dismantle and transfer tailgate fitting and facilitate repair				60.00
6	Provide skill labour to remove & refit cushions, seats, backrest, inner trim, garnish, rooflining and upholstery to facilitate repairs		<i>60</i>	<i>100</i>	100.00
7	Provide skill labour to remove and replace bumper sensors				40.00
8	Provide skill labour to remove and replace rear windscreen		<i>150</i>	<i>150</i>	150.00
9	Provide skill labour to remove and replace quarter glass				60.00
10	Provide skill labour to remove and replace/refit whole rear with axle undercarriage				X 250.00
11	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair				X 80.00
12	Provide skill labour to mount vehicle onto chassis alignment bench				X 250.00
13	Provide skill labour to remove and replace fuel tank fixture and attachment				X 50.00
13	Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair.				X 50.00
14	Provide skill labour to remove and refit spare tyre panel lining and garnish to facilitate repair.				X 80.00

Total Labour: 5,060.00

Acknowledged by Repairer

Signature:

Date:

- To resurvey before/after
- Parts prices are subject to
- Third party survey is on a "Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Total Parts:	6,643.00
Total Nett Items:	520.00
	<u>12,223.00</u>
GST 7%	855.61
Grand Total:	<u>13,078.61</u>

Estimate Repair Duration (include 1 day for re-survey & 1 day for parts ordering) 18 days

Remark: **Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

Contact No : _____

Email : _____

Estimator : Wen zheng

Veron Chen (LKKAUTO)

From: Ma C.F (LKKAUTO)
Sent: Wednesday, 21 February 2018 5:34 PM
To: BHAS - Janice Koh; Mei Kwan (LKKAUTO); BHAS - Kelvin Lim; Veron Chen (LKKAUTO)
Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau; BHAS - Bernard Kee; BHAS - Jacelyn Loh; BHG - Johnny Lim; Admin A; SUR
Subject: RE: FINALIZE FOR SJF 8949K *** LKK REF: CS/AXA17022344/M1vb

Dear Janice

COR \$6410.00 & 9 W/Days Confirmed

Warmest Regards,
Ma Chin Fook
LKKAUTO Consultants Pte Ltd
HP : 84028474
FAX: 6741 4108
EMAIL: macf@lkkauto.com

From: BHAS - Janice Koh [<mailto:janice.koh@bhauto.com.sg>]
Sent: Tuesday, 13 February, 2018 3:49 PM
To: Mei Kwan (LKKAUTO); BHAS - Kelvin Lim; Ma C.F (LKKAUTO); Veron Chen (LKKAUTO)
Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau; BHAS - Bernard Kee; BHAS - Jacelyn Loh; BHG - Johnny Lim; Admin A; SUR
Subject: RE: FINALIZE FOR SJF 8949K *** LKK REF: CS/AXA17022344/M1vb

Hi Veron,

Appreciate you can assist in this finalize ASAP.

Thank you

Warmest Regards,

Janice Koh

(W) 6559 8944 ext 108 (F) 6269 2404

(HP) 9159 3399

(Add) Blk 1 Sin Ming Industrail Estate Sector C #01-111-113-115-117 Singapore 575636

janice@bhauto.com.sg <http://www.bhauto.com.sg>

 BH AUTO SERVICES PTE LTD

From: Mei Kwan (LKKAUTO) [<mailto:Meikwan@lkkauto.com>]
Sent: Tuesday, February 13, 2018 12:06 PM
To: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Kelvin Lim <kelvin.lim@bhauto.com.sg>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau

<anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHG - Johnny Lim <johnny@bhglobal.com.sg>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZE FOR SJF 8949K *** LKK REF: CS/AXA17022344/M1vb

Dear Janice,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/AXA17022344/M1vb	Veron

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Janice Koh [<mailto:janice.koh@bhauto.com.sg>]

Sent: Tuesday, 13 February, 2018 10:45 AM

To: BHAS - Kelvin Lim <kelvin.lim@bhauto.com.sg>; Ma C.F (LKKAuto) <MaCF@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHG - Johnny Lim <johnny@bhglobal.com.sg>

Subject: RE: FINALIZE FOR SJF 8949K

Dear Ma,

Refer to our email dated on 30/12/2017, appreciate you can assist to finalize this case since it's been pending for almost 2 months.

Appreciate you can expedite to finalize ASAP.

Thank you

Warmest Regards,

Janice Koh

(W) 6559 8944 ext 108 (F) 6269 2404

(HP) 9159 3399

(Add) Blk 1 Sin Ming Industrail Estate Sector C #01-111-113-115-117 Singapore 575636

janice@bhauto.com.sg <http://www.bhauto.com.sg>

 **BH AUTO SERVICES PTE LTD**

From: BHAS - Kelvin Lim

Sent: Saturday, December 30, 2017 03:05 PM

To: MACF@LKKAUTO.COM

Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHG - Johnny Lim <johnny@bhglobal.com.sg>

Subject: FINALIZE FOR SJF 8949K

Dear Chee ,

Kindly refer to attached file to finalize our vehicle **SJF 8949K** FINALIZE AMOUNT **\$6410.00 B/GST/ PART BY PART**

PARTS	- \$3390.00
MISC	- \$2750.00
LABOUR	- \$270.00
TOTAL	- \$6410.00

Appreciate could you confirm the finalize amount ASAP.

Thank you and have a great day.

Best Regards,

Kelvin Lim

Kelvin Lim

BH AUTO SERVICES PTE LTD

(W) +65-6559 8945 (F) +65-6269 2404

(M) +65-9621 1984

Kelvin.lim@bhauto.com.sg <http://www.bhauto.com.sg>

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
Attn: Motor Claim Department
Tel: 6338 7288 Fax: 6880 4838
Dear Sir/Madam,

Accident Repair On : SJF8949K
Model : HONDA CRV 2.4L AT
Policy No : GA059385/1
Chassis No : JHLRE48508C210482
Year Of Make : 2008
Date / Time Of Accident : 10/11/2017 at 1130Hrs
Location : CTE LEADING TO JALAN BUKIT MERAH

Date: 23/11/2017
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Tailgate	1	580.00	old	580.00
2	Tailgate moulding chrome	1	150.00	new	150.00
3	Tailgate hinge LH	1	25.00	new	25.00
4	Tailgate hinge RH	1	25.00	new	25.00
5	Tailgate stand absorber LH	1	90.00	new	90.00
6	Tailgate stand absorber RH	1	90.00	new	90.00
7	Tailgate inner trim	1	125.00	new	125.00
8	Tailgate lock assy	1	75.00	new	75.00
9	Tailgate striker	1	18.00	new	18.00
10	Tailgate weatherstrip	1	40.00	new	40.00
11	Tailgate emblem	1	15.00	new	15.00
12	Tailgate lettering "CRV"	1	15.00	new	15.00
13	Tailgate lower cover	1	150.00	new	150.00
14	Tailgate pull handle pocket	1	15.00	new	15.00
15	Tailgate handle switch button	1	65.00	new	65.00
16	Rear windscreen	1	650.00	new	650.00
17	Rear windscreen moulding set	1	30.00	new	30.00
18	Rear tail lamp assy RH	1	195.00	new	195.00
19	Rear tail lamp panel RH	1	75.00	new	75.00
20	Rear bumper	1	160.00	new	160.00
21	Rear bumper side retainer LH	1	10.00	new	10.00
22	Rear bumper side retainer RH	1	10.00	new	10.00
23	Rear bumper reflector RH	1	15.00	new	15.00
24	Rear bumper side cover RH	1	40.00	new	40.00
25	Rear bumper under cover	1		new	
26	Rear fender RH	1	590.00	new	590.00
27	Rear fender inner RH	1		new	
28	Rear fender shield RH	1		new	
29	Rear fender quarter glass RH	1	250.00	new	250.00
30	Rear fender quarter glass moulding upper RH	1	30.00	new	30.00
31	Rear fender quarter glass moulding lower RH	1	85.00	new	85.00
32	Rear fender lower guard RH	1	30.00	new	30.00
33	Rear fender wheel arch protector RH	1	35.00	new	35.00

34	Rear fender inner upper trim RH <i>X one</i>	1		
35	Rear fender inner lower trim RH <i>OTS</i>	1	125.00	125.00
36	Spare tyre cover board <i>X one</i>	1		
37	spare tyre box <i>X</i>	1	250.00	250.00
38	Spare tyre panel <i>X</i>	1		
39	Rear door RH <i>X</i>	1	520.00	520.00
40	Rear door weatherstrip RH <i>X one</i>	1	65.00	65.00
41	Rear door glass outer moulding chrome RH <i>X one</i>	1	55.00	55.00
42	Rear door pillar frame sticker RH <i>X one</i>	1	20.00	20.00
43	Rear exhaust assembly <i>X one</i>	1	320.00	320.00
44	Rear exhaust tips chrome <i>X one</i>	1	65.00	65.00
45	Rear end panel <i>X one</i>	1	185.00	185.00
46	Rear end panel top garnish <i>X one</i>	1	45.00	45.00
47	Rear wheel rim RH <i>X one</i>	1	720.00	720.00
48	Rear axle assembly <i>X one</i>	1	580.00	580.00
49	Rear absorber RH <i>X one</i>	1	120.00	120.00
50	Rear absorber mounting RH <i>X one</i>	1	35.00	35.00
			Sub-Total:	6,643.00

Total Parts : 6,643.00

Special Nett Items

1	Rear bumper sensors	1	250.00	250.00
2	Rear tail lamp holder clips	5	2.00	10.00
3	Rear bumper clips	10	1.00	10.00
4	Rear fender shield clips	10	1.00	10.00
5	Rear wheel arch protector clips	10	2.00	20.00
6	Rear number plate with casing	1	35.00	35.00
7	Rear tyre RH	1	185.00	185.00
			Total Nett Items:	<u>520.00</u>

Accident Vehicle Of : SJF8949K

Page : 2 of 2

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts.	2,200.00
2	Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities	1,600.00
3	Provide skill labour to disconnect & check electrical wiring, harness, wyre sockets, etc. test & rectify for proper functioning	30.00
4	Provide skill labour to check and re-adjust all wheel alignment.	80.00
5	Provide skill labour to dismantle and transfer tailgate fitting and facilitate repair	60.00
6	Provide skill labour to remove & refit cushions, seats, backrest, inner trim, garnish, rooflining and upholstery to facilitate repairs	180.00
7	Provide skill labour to remove and replace bumper sensors	40.00
8	Provide skill labour to remove and replace rear windscreen	450.00
9	Provide skill labour to remove and replace quarter glass	100.00
10	Provide skill labour to remove and replace/refit whole rear with axle undercarriage	250.00
11	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	80.00
12	Provide skill labour to mount vehicle onto chassis alignment bench (and Fender pillar)	200.00
13	Provide skill labour to remove and replace fuel tank figure and attachment	50.00
13	Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair.	50.00
14	Provide skill labour to remove and refit spare tyre panel lining and garnish to facilitate repair.	80.00
		Total Labour: <u>5,060.00</u>

Total Parts:	6,643.00
Total Nett Items:	520.00
	<u>12,223.00</u>
GST 7%	855.61
Grand Total:	<u>13,078.61</u>

Estimate Repair Duration (include 1 day for re-survey & 1 day for parts ordering) 18 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Estimator : Wen zheng

Name : _____
Company : _____
Date : _____
Time : _____
Contact No : _____
Email : _____

Parts - 3390.00

Labour - 2750.00

MISC - 270.00

Total: 6410.00

Veron Chen (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 13 February 2018 12:06 PM
To: BHAS - Janice Koh; BHAS - Kelvin Lim; Ma C.F (LKKAUTO); Veron Chen (LKKAUTO)
Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau; BHAS - Bernard Kee; BHAS - Jacelyn Loh; BHG - Johnny Lim; Admin A; SUR
Subject: RE: FINALIZE FOR SJF 8949K *** LKK REF: CS/AXA17022344/M1vb
Attachments: FINALIZE FOR SJF 8949K

Dear Janice,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/AXA17022344/M1vb	Veron

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Janice Koh [mailto:janice.koh@bhauto.com.sg]

Sent: Tuesday, 13 February, 2018 10:45 AM

To: BHAS - Kelvin Lim <kelvin.lim@bhauto.com.sg>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHG - Johnny Lim <johnny@bhglobal.com.sg>

Subject: RE: FINALIZE FOR SJF 8949K

Dear Ma,

Refer to our email dated on 30/12/2017, appreciate you can assist to finalize this case since it's been pending for almost 2 months.

Appreciate you can expedite to finalize ASAP.

Thank you

Warmest Regards,

Janice Koh

(W) 6559 8944 ext 108 (F) 6269 2404

(HP) 9159 3399

(Add) Blk 1 Sin Ming Industrial Estate Sector C #01-111-113-115-117 Singapore 575636

janice@bhauto.com.sg <http://www.bhauto.com.sg>

BH AUTO SERVICES PTE LTD

From: BHAS - Kelvin Lim

Sent: Saturday, December 30, 2017 03:05 PM

To: MACF@LKKAUTO.COM

Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHG - Johnny Lim <johnny@bhglobal.com.sg>

Subject: FINALIZE FOR SJF 8949K

Dear Chee ,

Kindly refer to attached file to finalize our vehicle **SJF 8949K** FINALIZE AMOUNT **\$6410.00 B/GST/ PART BY PART**

PARTS	- \$3390.00
MISC	- \$2750.00
LABOUR	- \$270.00
TOTAL	\$6410.00

Appreciate could you confirm the finalize amount ASAP.

Thank you and have a great day.

Best Regards,

Kelvin Lim

Kelvin Lim

BH AUTO SERVICES PTE LTD

(W) +65-6559 8945 (F) +65-6269 2404

(M) +65-9621 1984

Kelvin.lim@bhauto.com.sg <http://www.bhauto.com.sg>

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
Attn: Motor Claim Department
Tel : 6338 7288 Fax : 6880 4838
Dear Sir/Madam,

Accident Repair On : SJF8949K
Model : HONDA CRV 2.4L AT
Policy No : GA059385/1
Chassis No : JHLRE48508C210482
Year Of Make : 2008
Date / Time Of Accident : 10/11/2017 at 1130Hrs
Location : CTE LEADING TO JALAN BUKIT MERAH

Date: 23/11/2017
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Tailgate	+	580.00	old	580.00
2	Tailgate moulding chrome	1	150.00	enc	150.00
3	Tailgate hinge LH	1	25.00	enc	25.00
4	Tailgate hinge RH	1	25.00	enc	25.00
5	Tailgate stand absorber LH	1	90.00	enc	90.00
6	Tailgate stand absorber RH	+	90.00	enc	90.00
7	Tailgate inner trim	1	125.00	enc	125.00
8	Tailgate lock assy	1	75.00	enc	75.00
9	Tailgate striker	1	18.00	enc	18.00
10	Tailgate weatherstrip	1	40.00	enc	40.00
11	Tailgate emblem	1	15.00	enc	15.00
12	Tailgate lettering "CRV"	1	15.00	enc	15.00
13	Tailgate lower cover	1	150.00	enc	150.00
14	Tailgate pull handle pocket	1	15.00	enc	15.00
15	Tailgate handle switch button	1	65.00	enc	65.00
16	Rear windscreen	+	650.00	enc	650.00
17	Rear windscreen moulding set	+	30.00	enc	30.00
18	Rear tail lamp assy RH	+	195.00	enc	195.00
19	Rear tail lamp panel RH	+	75.00	enc	75.00
20	Rear bumper	+	160.00	enc	160.00
21	Rear bumper side retainer LH	+	10.00	enc	10.00
22	Rear bumper side retainer RH	1	10.00	enc	10.00
23	Rear bumper reflector RH	+	15.00	enc	15.00
24	Rear bumper side cover RH	+	40.00	enc	40.00
25	Rear bumper under cover	1			
26	Rear fender RH	+	590.00		590.00
27	Rear fender inner RH	1			
28	Rear fender shield RH	+			
29	Rear fender quarter glass RH	+	250.00		250.00
30	Rear fender quarter glass moulding upper RH	+	30.00		30.00
31	Rear fender quarter glass moulding lower RH	+	85.00		85.00
32	Rear fender lower guard RH	+	30.00		30.00
33	Rear fender wheel arch protector RH	1	35.00		35.00

34	Rear fender inner upper trim RH	X ONE	1	125.00	125.00
35	Rear fender inner lower trim RH	2x5	1		
36	Spare tyre cover board	X ONE	1	250.00	250.00
37	spare tyre box	X	1		
38	Spare tyre panel	X	1	520.00	520.00
39	Rear door RH	1x2	1	65.00	65.00
40	Rear door weatherstrip RH	X ONE	1	55.00	55.00
41	Rear door glass outer moulding chrome RH	X ONE	1	20.00	20.00
42	Rear door pillar frame sticker RH	X ONE	1	320.00	320.00
43	Rear exhaust assembly	X ONE	1	65.00	65.00
44	Rear exhaust tips chrome	X ONE	1	185.00	185.00
45	Rear end panel	1x1	1	45.00	45.00
46	Rear end panel top garnish	1x1	1	720.00	720.00
47	Rear wheel rim RH	X ONE	1	580.00	580.00
48	Rear axle assembly	X ONE	1	120.00	120.00
49	Rear absorber RH	X ONE	1	35.00	35.00
50	Rear absorber mounting RH	X ONE	1		
				Sub-Total:	6,643.00

Total Parts : 6,643.00

Special Nett Items

1	Rear bumper sensors	1	250.00	250.00
2	Rear tail lamp holder clips	5	2.00	10.00
3	Rear bumper clips	10	1.00	10.00
4	Rear fender shield clips	10	1.00	10.00
5	Rear wheel arch protector clips	10	2.00	20.00
6	Rear number plate with casing	1	35.00	35.00
7	Rear tyre RH	1	185.00	185.00
				Total Nett Items: 520.00

Accident Vehicle Of : SJF8949K

Page : 2 of 2

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts.	2,200.00
2	Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities	1,600.00
3	Provide skill labour to disconnect & check electrical wiring, harness, wyre sockets, etc. test & rectify for proper functioning	30.00
4	Provide skill labour to check and re-adjust all wheel alignment.	60.00
5	Provide skill labour to dismantle and transfer tailgate fitting and facilitate repair	60.00
6	Provide skill labour to remove & refit cushions, seats, backrest, inner trim, garnish, rooflining and upholstery to facilitate repairs	100.00
7	Provide skill labour to remove and replace bumper sensors	40.00
8	Provide skill labour to remove and replace rear windscreen	100.00
9	Provide skill labour to remove and replace quarter glass	60.00
10	Provide skill labour to remove and replace/refit whole rear with axle undercarriage	250.00
11	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	80.00
12	Provide skill labour to mount vehicle onto chassis alignment bench	250.00
13	Provide skill labour to remove and replace fuel tank ficture and attachment	50.00
13	Provide skill labour to remove and refit rear end panel lining and garnish to facilitate repair.	50.00
14	Provide skill labour to remove and refit spare tyre panel lining and garnish to facilitate repair.	80.00
		Total Labour: 5,060.00

Total Parts:	6,643.00
Total Nett Items:	520.00
	<u>12,223.00</u>
GST 7%	855.61
Grand Total:	<u>13,078.61</u>

Estimate Repair Duration (include 1 day for re-survey & 1 day for parts ordering) 18 days

Remark: **Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

Estimator : Wen zheng

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

Contact No : _____

Email : _____



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)


WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6306 9610



Dept Direct: 6417 9794



Dept Direct: 6306 9611



Dept Direct: 6417 9795



Dept Direct: 6417 9792



Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/EUNICE

TAX INVOICE : AR201711-15336

DATE : 27/11/2017

CUSTOMER ID : BHA001

VEH REG. NO. : SJF8949K

TERMS : 60 days

PO NO. : 1848

PAGE NO. : Page 1 of 2

CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H68100-SWA-U00ZZ RE2 RE4	TAILGATE ASSY	PA PL1-H1-03B	1	580.00	580.00
2.	H74820-SWA-A01 RE2 RE4	BOOT ABSORBER RH 6	PA PL1-N1-10H	1	90.00	90.00
3.	H74440-SWE-Z01T RE2 RE4	W/STRIP, TAILGATE 10	PA PL1-M1-11C	1	40.00	40.00
4.	H75722-SWE-T01T RE2	"CRV" EMBLEM 12	PA PL1-L1-06K	1	15.00	15.00
5.	H74895-SWE-Z01ZKT RE2 RE4	GARNISH, TAILGATE LOWER 13	PA PL1-M1-040	1	150.00	150.00
6.	WH73211-SWA-A11 RE2 RE4 CRV 07"	RR W/S GLASS [GN] 16	PA PL1-Q1-06B	1	650.00	650.00
7.	H04733-SWA-000 CRV 07"	RR GLASS MLD 17	PA PL1-P1-110	1	30.00	30.00
8.	H33501-SWA-013 RE3	TAIL LAMP RH 18	PA PL1-J1-08A	1	195.00	195.00
9.	H63320-SWA-A00ZZ RE2 RE4	GUTTER, R.RR 19 (Tail Lamp Panel)	PA PL1-P1-05A	1	75.00	75.00
10.	H71501-SWA-000 RE2 RE4	BUMPER RR 20	PA PL4-A1-20	1	160.00	160.00
11.	H71502-SWA-J00ZQ RE2 RE4	BUMPER SIDE RH T99 21	PA PL1-L1-09S	1	40.00	40.00
12.	H33505-SWA-003 RE3	REFLECTOR, R.RR BUMPER 22	PA PL1-L1-04K	1	15.00	15.00
13.	H04636-SWE-Q00ZZT RE2 RE4	FENDER RR RH 23	PA PL1-G1-050	1	590.00	590.00
14.	73511-SWE-T10 RE2 RE4 CRV 07"	29 R/FIX GLASS RH 24	PA PL1-Q1-020	1	250.00	250.00
15.	H73510-SWA-003 RE3 RE2 RE4	QUATER MLD RH 25	PA PL1-M1-08A	1	80.00	80.00
16.	H66100-SWA-300ZZ RE3 RE2 RE4	PANEL RR 26	PA PL1-P1-03B	1	185.00	185.00

CONTINUE NEXT PAGE

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6385 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M



Dept Direct: 6417 8781 / 6745 9839



Dept Direct: 6305 9810

Dept Direct: 6308 9811

Dept Direct: 6417 8782



Dept Direct: 6417 8784

Dept Direct: 6417 8786

Dept Direct: 6417 8788

Dept Direct: 6417 8788

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/EUNICE

TAX INVOICE : AR201711-15336

DATE : 27/11/2017

CUSTOMER ID : BHA001

VEH REG. NO. : SJF8949K

TERMS : 60 days

PO NO. : 1848

PAGE NO. : Page 2 of 2

CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
17. H84640-SWA-013ZB RE3	LINING,RR PANEL 46	PA PL1-N1-110	1	45.00	45.00

SUB-TOTAL : 3,190.00
ADD GST 7.00 % 223.30

E & O E

TOTAL AMOUNT S\$: 3,413.30

[P] 27/11/2017 12:31:33PM

[E] 27/11/2017 11:17:03AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 7 1 1 - 1 5 3 3 6 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG NO.: M2-0119201-3 CO. REG NO.: 199307741M

BH AUTO SERVICES PTE LTD
BLK 1, #01-115
SIN MING IND EST SECTOR C
[MUST WRITE PO]
SINGAPORE 575636
TEL : 65598944 FAX : 62692404
ATTN : K.T.CHEONG 9101 3232 ERIC/EUNICE



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-15354
DATE : 27/11/2017
CUSTOMER ID : BILA001
VEH REG. NO. : SJF8949K
TERMS : 60 days
PO NO. : 1848
PAGE NO. : Page 1 of 1
CURR. : S\$

Q STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
H74410-SWA-A00 RE2 RE4	WHEEL ARCH RR RH 33	U1 I.2-J5-A	1	35.00	35.00

SUB-TOTAL : 35.00
ADD GST 7.00 % 2.45

E & O.E TOTAL AMOUNT S\$: 37.45

[P] 27/11/2017 11:25:09AM

[E] 27/11/2017 11:24:49AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

~~GST REG NO. M2-0149201-3 CO. REG NO. 100307741M~~

BH AUTO SERVICES PTE LTD

BLK 1, #01-115


SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/EUNICE



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-15702

DATE : 27/11/2017

CUSTOMER ID : BILA001

VEH REG. NO. : SJF8949K

TERMS : 60 days

PO NO. : 1848

PAGE NO. : Page 1 of 1

CURR. : S\$

Q STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
H71593-SWA-A01 RE3 RE2 RE4	BUMPER SPACER RH	U1 1.2-F8-F	1	10.00	10.00

SUB-TOTAL : 10.00
ADD GST 7.00 % 0.70

E. & O.E TOTAL AMOUNT S\$: 10.70

[P] 27/11/2017 2:56:19PM

[E] 27/11/2017 2:55:58PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAB Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 7 1 1 - 1 5 7 0 2 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

BH AUTO SERVICES PTE LTD CO. REG. NO.: 199307741M

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/EUNICE



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Spark plug: Bosch (Made in Germany)

DATE : 18/12/2017

CUSTOMER ID : BILA001

VEH REG. NO. : SJF8949K

TERMS : 60 days

PO NO. : 1897

PAGE NO. : Page 1 of 1

CURR : S\$

STOCKID

H84635-SWA-YOIZA

RE2 RE4

DESCRIPTION

FENDER TRIM RH

Stk Loc

PA

PL1-MI-000

QTY

1

UPPRICE

125.00

AMOUNT

125.00

SUB-TOTAL : 125.00

ADD GST 7.00 % 8.75

TOTAL AMOUNT S\$: 133.75

PJ 18/12/2017 2:11:13PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 18/12/2017 2:10:15PM

AE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.

No signature is required.



* AR 201712-10092 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG NO: M2-0119201-3 CO REG NO: 199307741M

BH AUTO SERVICES PTE LTD

BLK 1, #01-115

SIN MING IND EST SECTOR C

[MUST WRITE PO]

SINGAPORE 575636

TEL : 65598944 FAX : 62692404

ATTN : K.T.CHEONG 9101 3232 ERIC/EUNICE

WINDSCREEN GLASS
Dept Direct: 6417 9794 / 6745 9809



TOYOTA
GENUINE PARTS

LEXUS

DAIHATSU

Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso NGK (Made in Japan)

TAX INVOICE : AR201712-12132

DATE : 21/12/2017

CUSTOMER ID : BILA001

VEH REG. NO. : SJF8949K

TERMS : 60 days

PO NO. : 1903

PAGE NO. : Page 1 of 1

CURR. : S\$

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. H04733-SWA-000 CRV 07"	RR GLASS MLD 30	MO 1HS	1	30.00	30.00

SUB-TOTAL : 30.00
ADD GST 7.00 % 2.10

E. & O.E

TOTAL AMOUNT S\$: 32.10

[P] 21/12/2017 10:02:22AM

[E] 21/12/2017 10:02:08AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 7 1 2 - 1 2 1 3 2 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date