

XINYA AUTO SERVICES PTE LTD

BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719
Tel: 6270 3481 Fax: 6278 7522
E-mail: xinyauto@singnet.com.sg

Date : 16.11.17

Address : MR TAY CHIN SIONG
BLK 634 JURONG WEST ST. 65
10-320
SINGAPORE 640634

Reference : TP 1138/11/17
Vehicle No : SJE 773H
Make/Model : HYUNDAI AVANTE
Insurance Co. : ERGO

RE : QUOTATION REPAIRS TO SJE 773H FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

	QTY	COST	AMT \$
1) REAR R/H DOOR	1		\$916.40 <i>bb</i>
2) REAR R/H FENDER	1		\$1,605.30 <i>Rx</i>
3) REAR R/H DOOR LOCK	1		\$237.40 <i>mm</i>
4) REAR R/H DOOR WEATHERSTRIPE	1		\$85.80 <i>new</i>
5) DOOR HINGES	2		\$240.00 <i>Rx</i>
LIST PRICE TOTAL			\$3,084.90
LESS DISCOUNT 20%			\$616.98
LIST PRICE TOTAL AFTER LESS			\$2,467.92
NETT PRICE TOTAL			\$0.00

TOTAL PARTS COST

\$2,467.92

LABOUR AND MISCELLANEOUS CHARGES

1) TO REMOVE & REPLACE REAR DOOR AND TO PANEL BEAT REAR RH FENDER	\$1,000.00 (5 Days)
2) TO PUTTY & SPRAY PAINT TO REAR RH DOOR, FENDER REAR RH, ROCKER PANEL & OTHER AFFECTED AREA.	\$800.00 (4 Panel)
3) TO TRANSFER DOOR PARTS & ACESSORIES TO NEW DOOR	\$180.00
4) TUFF KOTE	\$180.00
5) TO CHECK & RECTIFY WIRING	\$60.00

801.76
1730
2531.76
15/2000 * 5 days

Tanjilun 97495749
28/11/17
-wp-