

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD341A -**AAD1711-239***Not Notified**Recovery Bepain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SHD341A - JHOW**VE1 ABL15AUC282722****RENAULT****LATITUDE****21.11.2017****TOKIO****PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu 1M</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84	} X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
5	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
8	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	
9	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49	
10	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
11	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	} X
12	1	TAILLAMP RH	\$	<i>Sn</i> 552.55	
13	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
14	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66	
15	1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82	
16	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50	
17	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	

TOTAL \$ 12,362.17**10% \$ 1,236.22****\$ 11,125.95****Specical Nett**

1	1SET	PARKING AID	\$	<i>Sn</i> 700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	} X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	
8	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	
9	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00	} X
10	1SET	WHEELARCH CLIP RR RH	\$	<i>na</i> 66.00	