

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022389/R1tbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 08-01-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9336C	Veh. Inspected	SHB 1280X	
Policy No.	5073987573-02	Coverage (\$)	0.00	
Claim No.	MT/0970787-002	Excess (\$)	0.00	
Assign From		Assign Date	22/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U205711272	Colour	MAROON	
Odometer	567020	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	5 mm	
L/H Front Tyre	195/65 R15	FALKEN	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2017	Inspection Date	22/11/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		