



Service Order Confirmation

SERVICE ORDER NO.: 17IP3173
 CUSTOMER NO.: CV038145
 CUSTOMER NAME: TAN BOON YONG KELLY
 TELEPHONE NO.:
 ADDRESS: 11 LORONG SARHAD
 Singapore

VEH No.: SLR2818H

Order Date: 23/11/17

Reg Date: 28/07/17

VIN NO.: WVVZZZAUZGW163361

MODEL: GOLF A7 1.2 TL 81 (DSG)

KM: 3,095

ENGINE NO:

MODEL NO.: 5G12BZ

SA: Kong Charmaine

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tamplin 97495749

Ex \$500

Revert 24/11/17 @ 1510

Resurvey before paint

Sur@lkhands.com

76 days

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	200		200 ✓
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		360 ✓
3	B&P MECH R&R RIM & BALANCE	1	TU	50		50 ✓
4	B&P WHEEL ALIGNMENT B&P WHEEL ALIGNMENT NETT	1	TU	360		360 ✓
5	B&P ALEX LABOUR LABOUR	6	UNIT	475		2,850 1425
6	B&P ALEX PAINT SPRAY PAINT	5	UNIT	500		2,500 1500
7	CINTURATO 205/55R16 Pirelli Cinturato P7 205/55R16	1	ST	680		680
Item						
8	5G0807217BNGRU FRT BUMPER de ✓	1	PCS	1,152.82	28	830.03
9	5G0807724D BUMPER INNER BRACKET RH new ✓	1	PCS	27.60	28	19.87
10	5G0807050A BUMPER SIDE BRACKET RH new ✓	1	PCS	19.54	28	14.07
11	5G0807049A BUMPER SIDE BRACKET LH ?	1	PCS	19.54	28	14.07
12	5G0807246F FOAM ?	1	PCS	40.17	28	28.92
13	5G0853212D 9B9 FOG LAMP GRILLE UPPER RH ?	1	PCS	29.07	28	20.93
14	5G0853666 9B9 FOG LAMP GRILLE LOWER RH ?	1	PCS	93.62	28	67.55
15	5G2941006E HEADLAMP RH new ✓	1	PCS	1,073.04	28	772.59
16	5G0805588AC LOCK CARRIER ?	1	PCS	892.50	28	642.60
17	5G0805705G BUMPER CENTRE BRACKET ?	1	PCS	40.21	28	28.95
18	5G0805932 H/LAMP TOP PANEL RH ?	1	PCS	34.83	28	25.08
19	5G0821106A FENDER RH ht ✓	1	PCS	406.99	28	293.03
20	N 90817302 NUT new ✓	4	PCS	1.78	28	5.13
21	5G0821136B RHS FENDER BRACKET new ✓	1	PCS	27.58	28	19.86
22	5G0805970N FENDER LINER UPPER RH de ✓	1	PCS	150.69	28	108.50
23	5G0805911AK FENDER LINER LOWER RH de ✓	1	PCS	66.06	28	47.56
24	6N0809966A NUT new ✓	6	PCS	1.03	28	4.45
25	5G0601025CE8Z8 16" 'ASPEN' RIM ONLY cut ✓	1	PCS	792.46	28	570.57
26	311601361 RUBBER VALVE new ✓	1	PCS	1.72	28	1.24



Service Order Confirmation

SERVICE ORDER NO: 17IP3173

CUSTOMER NO.: CV038145

CUSTOMER NAME: TAN BOON YONG KELLY

TELEPHONE NO.:

ADDRESS: 11 LORONG SARHAD

Singapore

VEH No.: SLR2818H

Order Date: 23/11/17

Reg Date: 28/07/17

KM: 3,095

VIN NO.: WVVZZZAUZGW163361

ENGINE NO:

SA: Kong Charmaine

MODEL: GOLF A7 1.2 TL 81 (DSG)

MODEL NO.: 5G12BZ

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	10,515.00
GST AMOUNT	736.05
TOTAL AMOUNT	11,251.05

On Behalf Of "COMPANY"



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT