

DING AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector G

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

23/11/2017 19:31

JOB-NO: 85007958

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLG1457E

TRANS: AUTO

CHASSIS: MR053REH104557995

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY332126

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN & PANEL BEAT ON ACCIDENT AREAS	1.00	1,200.00	0.00	1,200.00		Y	300
2 REFOCUS FRONT HEADLAMP	1.00	180.00	0.00	180.00		Y	30
3 FRONT WHEEL ALIGNMENT	1.00	180.00	0.00	180.00		Y	60
4 RUSH PROOFING	1.00	150.00	0.00	150.00		Y	30
5 SPRAY PAINTING FOR FRONT BUMPER & FRONT FENDER AND FRONT DOOR LHS	1.00	1,400.00	0.00	1,400.00		Y	400
TOTAL:		3,110.00	0.00	3,110.00			
MATERIALS							
1 FRONT BUMPER	1.00	511.20	127.80	383.40	L	Y	de
2 FRONT BUMPER SIDE RETAINER LHS	1.00	58.17	14.54	43.63	L	Y	ner
3 FRONT BUMPER LOWER GRILLE	1.00	138.70	34.68	104.02	L	Y	x
4 FRONT BUMPER SIDE FOGLAMP COVER LHS	1.00	121.75	30.44	91.31	L	Y	x
5 FRONT BUMPER BRACKET	1.00	135.70	33.93	101.77	L	Y	x
6 HEADLAMP LHS	1.00	794.10	198.53	595.57	L	Y	x
7 HEADLAMP LOWER BRACKET LHS	1.00	0.00	0.00	0.00	L	Y	x
8 HEADLAMP CLIPS	1.00	3.21	0.80	2.41	L	Y	x
9 HEADLAMP CHROME MOULDING	1.00	145.60	36.40	109.20	L	Y	x
10 HEADLAMP BULB	1.00	44.17	11.04	33.13	L	Y	x
11 HEADLAMP YELLOW BULB	1.00	18.90	4.73	14.17	L	Y	x
12 SUPPORT PANEL	1.00	1,074.00	268.50	805.50	L	Y	x
13 FRONT FENDER LHS	1.00	858.00	214.50	643.50	L	Y	bt
14 FRONT FENDER SPLASH SHIELD LHS	1.00	171.20	42.80	128.40	L	Y	de
15 FRONT FENDER SPLASH SHIELD CLIPS	10.00	22.10	5.53	16.57	L	Y	ner
16 FRONT FENDER VVTI BADGE	1.00	45.17	11.29	33.88	L	Y	ner
17 FRONT BUMPER CLIPS	1.00	35.00	0.00	35.00	S	Y	ner
TOTAL:		4,176.97	035.51	3,141.46			

TOTAL PARTS & LABOUR :

7,286.97

1,035.51

6,251.46

EXCESS/LOADING:\$S 0.00

No. Of Day: 3

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
DATE OF SURVEY: 24 / 11 / 17							
SURVEYED BY: Tanjun 'WP' sur@lklauto.com							
CONTACT NO: 97495749 FAX NO:							

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX: