

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Attn : Tel : Fax :

Not Aired
new
The photo taken
2017.

24/11/17
3 days
p/p 2477.60

req: LKK marcus.
24.11.2017 @ 1450hrs.

Quotation No : QO17/11-1118	Quotation Date : 22/11/2017	Terms : 30 DAYS
Vehicle No : SLK2973D	Chassis No : JM6BN22A8H0136560	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEHICLE NO: SGV1576A, DATE OF ACCIDENT: 21.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REFLECTOR	2	51.0000	102.00
3	REAR BUMPER CLIP	10	5.0000	50.00
4	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
5	REAR BUMPER SIDE RETAINER	2	46.0000	92.00
6	REAR BUMPER SIDE HOLDER	2	37.0000	74.00
7	REAR BUMPER SIDE HOLDER RIVETS	4	5.0000	20.00
8	REAR BUMPER TOW COVER	2	17.0000	34.00
9	REAR BUMPER SCREW SPACER	2	8.0000	16.00
10	REAR END PANEL	1	506.0000	506.00
11	REAR END PANEL INNER TRIM	1	86.0000	86.00
12	BOOTLID - MAZDA 3 BADGE	1	54.0000	54.00
13	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
14	BOOTLID EMBLEM BADGE	1	75.0000	75.00
15	LESS 20% ITEM (1-14)	1	-557.2000	-557.20
16	REAR BUMPER PARKING SENSOR	1	450.0000	450.00
17	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	150.0000	150.00
18	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	120.0000	120.00
19	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	100.0000	100.00
20	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
21	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	800.0000	800.00

P- 1697
202
1357.6

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO17/11-1118	Quotation Date : 22/11/2017	Terms : 30 DAYS
Vehicle No : SLK2973D	Chassis No : JM6BN22A8H0136560	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEHICLE NO: SGV1576A, DATE OF ACCIDENT: 21.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
22	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	850.0000	850.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	4,758.80
GST(7.00%)	333.12
Total (SGD)	5,091.92

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216