15/(2010	2 Desce 19	CC 4/ QBE170 22	1/		KK: DAC:
INS. CASE OWNER:	Syabada	Virtue autoritation and the control of the control		pass	
6 4		DOI: ASSIGNM	12	PARTO TIME	1/2
Surveyor:	_X6Q	DOI:	17	Date / Time :	24/11/17
	O Bill			Registered in Merime	n;
Pre-assign / CCU /	FTE				
Insured Vehicle No.	GT 7803	R	Claim No.	: VC010	890
					6264 - MUA
Name of Insured	CDS CAR REN	TAL PTE LID	Policy No.	8-0000	204 - MUM
Insured Tel No.	HP:		Make / Model	: NISSAN	CABSTAR
Excess Sec II :SS	D.O	A: 10/11/17	Place of Accide		MARYMOUNT ROAD
Is driver the owner?	Company of the compan	ure of Accident :		AND SIN	MING AVE
			OLGIA DEDGE	TOTAL AND THE	IA REPORT YES / NO
	e Age: LEE KOK PEW	414 (P) (NO.)			
Driver Tel N	No.: 84086348	(V/LYES/NO)	Insured Liability	y: % F	inal? Yes/No
SGA 6166C					•
	5	Location of	STATE OF THE PARTY.		Le de station de
INSRS: WSP: Treas - Euro	(ub) INSRS:		INSRS:		INSRS:
Tel:	WSP:	1	WSP: Tel :	15 7	WSP: Tel:
Liability:	Liability:		Liability:	R-S	Liability:
RMKS:	RMKS:		RMKS:		RMKS:
Date/ Time					
	SaA 6166C - X :	GT 7303 R - X		STAGE	DATE / PIC
15/12/17 (HT)				Non-Reporting ltr (1st)	
				Non-Reporting ltr (2nd	
American Construction Construction				Non-Reporting ltr (Fin Notification ltr (if non-	
19/12/12/04.02pm	Called Ol company	at 64527127.	Spoken to	A 11 A 1	erula 19/14
141110 11	Sandra Contin	rear-ended TP.	Agreed to	After call ltr to Of:	10 20122617.
	settle and aware in	up) com.		Documentation Chec	k-List: Handler Typist
	by	is a dat		Notification ltr (if non-	pickup)
17/18 -	File puss to te	gre monovorte		After call ltr to OI:	
1 ,	1	31		Authorisation To Act: Release Voucher:	
	REC	EIVED 9 5 FEB	2018	Final Repair Bill:	
	4		4010	Car Rental Invoice:	
29/3/18 -	DVsent REC	EIVED 1 0 ADD	2040	Towing Invoice	
20/1/10	V V XOIT	CIVEU IS AFA	2010	LTA / GIA :	
	-XTP had submit	ted all the on	suldous	Medical Bill:	
	-to QRF	9	,	PIR:	
191418 -	- Flerasity Nei	Wan to close	2,	Mandate/Reject Inst	ruction:
	<u> </u>			LOD	
				Payment Breakdown	Form:
DELIMINADV ADVICE					
RELIMINARY ADVICE	Date/Time: 06/12/17	Sent By: Shide	Hirw	Post-Repair Photos:	
			Hew	Others:	
FINALIZATION	Date/Time:	Confirm with:		Others: Confirm by:	Email Call
FINALIZATION Repair Cost:	Date/Time:	Confirm with: days) Reduction:	, H,εω %	Others: Confirm by:	Email Call Call
FINALIZATION Repair Cost: FINAL SETTLEMENT	Date/Time: S\$ (Date/Time: 29 3 6 Co	Confirm with: days) Reduction: nfirm with Tervu	%	Others: Confirm by:	
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability:	Date/Time: S\$ (Date/Time: 29 3 6 Co	Confirm with: days) Reduction: infirm with Termy cosed) BOLA S/N No.	%	Others: Confirm by: Email Call	
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: W/657	Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Co	Confirm with: days) Reduction: nfirm with Tervu	%	Others: Confirm by: Email Call	
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: VI 65T Loss of Rental (LOR) W/66	Date/Time: S\$ (Date/Time: D\$ 7 6 Co % (W) (Agreed / Ass \$\$ 0.76 , 20 \$\$ 8.56.00 (8 S\$ - (8 - x -	Confirm with: days) Reduction: Infirm with Tevny Cosed) BOLA S/N No.	%	Others: Confirm by: Email Call	
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): Loss of Income (LOD)	Date/Time: 39 3 16 Co % (W) (Agreed / Ass SS 10361, 20 SS 256.00 (& SS - (S - x - SS - (S - x	Confirm with: days) Reduction: Infirm with Termy Cosed) BOLA S/N No.	%	Others: Confirm by: Email Call	
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): Loss of Income (LOD) LOR only LOU only	Date/Time: S\$ (Date/Time: D\$ 3 6 Co % (W) (Agreed / Ass S\$ 036 , 20 S\$ 856.00 (Confirm with: days) Reduction: Infirm with Tevny Cosed) BOLA S/N No.	%	Others: Confirm by: Email Call	
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): Loss of Income (LOU) LOR only LOU only GIA/LTA Search	Date/Time: S\$ (Date/Time: 29 3 6 Co % (W) (Agreed / Ass S\$ 036 , 20 S\$ 556 \cdot 00 (Confirm with: days) Reduction: Infirm with Termy Cosed) BOLA S/N No.	%	Others: Confirm by: Email Call If NO or B 28, Ass.	Lia:
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): LOR only LOU only GIA/LTA Search Medical:	Date/Time: S\$ (Date/Time: D\$ 7 6 Co % (W) (Agreed / Ass S\$ 0.76 , 20 S\$ 0.76 , 20 S\$ - (S - x - x) LOR + LOU LOR S\$ 2 · W S\$ -	Confirm with: days) Reduction: Infirm with Tenny Cosed) BOLA S/N No. days) LW days) days) + LOI Tick only one	%	Others: Confirm by: Email Call If No or B 28, Ass.	Lia :
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): Loss of Income (LOD) LOR only GIA/LTA search Medical: Disbursement:	Date/Time: S\$ (Date/Time: D\$ 3 1 Co % (W) (Agreed / Ass S\$ 036 , 20 S\$ 856.00 (Confirm with: days) Reduction: Infirm with Termy Cosed) BOLA S/N No.	%	Others: Confirm by: Email Call If No or B 28, Ass. 1) Claim status: No. 2) Report Format:	Lia :
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): LOR only LOU only GIA/LTA search Medical: Disbursement: Legal Cost	Date/Time: S\$ (Date/Time: D\$ 3 1 Co % (Confirm with: days) Reduction: Infirm with Tenny Cosed) BOLA S/N No. days) LW days) days) + LOI Tick only one	%	Others: Confirm by: Email Call If No or B 28, Ass. 1) Claim status: No. 2) Report Format:	Lia :
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): Loss of Income (LOU) LOR only GIA/LT/Search Medical: Disbursement: Legal Cost Total:	Date/Time: SS (Date/Time: DS 3 6 Co % (W) (Agreed / Ass SS 036 , 20 SS 876.00 (Confirm with: days) Reduction: Infirm with Termy Coscol BOLA S/N No. days) LOI Tick only one (e.g. Tow/ Independent	%	Others: Confirm by: Email Call If No or B 28, Ass. 1) Claim status: No. 2) Report Format:	Lia :
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Use (LOU): Loss of Income (LOU): LOR only LOU only GIA/LTA search Medical: Disbursement: Legal Cost Total: FINAL PAYMENT	Date/Time: 29 3 16 Co % (W) (Agreed / Ass SS 036 , 20 SS = (S - x - SS - (S - x - SS - SS - SS - S	Confirm with: days) Reduction: Infirm with Terwy Cessed) BOLA S/N No. days) days) days) + LOI Tick only one (e.g. Tow/ Independent lobal Sum SS:	%	Others: Confirm by: Email Call If NO or B 28, Ass. 1) Claim status: No. 2) Report Format: 3) Survey fee: Email Call	Lia :
FINALIZATION Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR) Loss of Income (LOU) Loss of Income (LOU) LOR only LOU only GIA/LT/Search Medical: Disbursement: Legal Cost Total: FINAL PAYMENT Payee 1: Payee 2: (Strike if N.A.)	Date/Time: 29 3 16 Co % (W) (Agreed / Ass SS 10361, 20) 1 SS 856.00 (8 SS - (S - x - x) LOR + LOU LOR SS 2.W SS - SS - SS - SS - SS - SS - SS 219.20 Gi Date/Time: 29 3 18 Co SS 1119.20 No	Confirm with: days) Reduction: Infirm with Terwy Cessed) BOLA S/N No. days) days) days) + LOI Tick only one (e.g. Tow/ Independent lobal Sum SS:	%	Others: Confirm by: Email Call If NO or B 28, Ass. 1) Claim status: No. 2) Report Format: 3) Survey fee: Email Call	Lia :

XRD.

	20101211111	
FIOTING SEC	S6A6166C	17 Nov 2015
Estimad Cost	Type (I.C) IM Cycle Bus Van / Lorry / Taxi I	Prime Mover
OD TRIWS / TP RES / OD RES / EVA / INV / MV	Truck / Traller or	
To Inspect Vehicle No. SCA 6166C	Marda CX-5	2488
at Workshop mas Trans Eurokars		Insured / Std / NI / NA
5 Ub close		Insured / Std / NI / NA
insured	Eastle .	
Policy No.	CNO JM6KE 10326	70345043
Claims No.	Gen Cond. Ford / Fair / Poor / Burnt	
Sum Insured Excess:	Steering: In ofder / Jammed / Leaked / Burnt. cr	
(Client's Record)	Brake Ingreer / Jammed / Leaked / Burnt or	
Make of Veh	Mod Nil / Z/Rim / STD on or	/
10-45am	Tyre Size F: 245 225	155 R19
(Polley Candition)	R	11
Remark: The veh had commenced its N.S.	BS DUN EXNOVA GY FS LIZA MIC OH	'SU / PIR / SUMI /
repair at the time of inspection.	YOYGIYOKO ar	
Sal. cr Narket Velue	Eront Bear	7
IDAC Accident Room Consistent? Yes or No	R.Bal. 6 mm R.Bal.	b m
GIA PR Seen. Consistent? Yes or No	L'Bal 6 mm L'Bal	6
Est Repairs	D.O.A. , D.O.I.	24-11-17
Lum Sum % 3 Val. Yes or No	Survey held at W/S	10:45AM
CA / REV / REP. / 24 HRS	Des. of Damages Frt. / Read / O/S / N/S / U	IC / Roofton or
Vahide IN	/ OUT The U/C / Chassis frame / Body Structur	e affected the to collabor
	The Ord I Chassis Hame I body director	5 - 50,000,000,000,000,000,000,000,000,000,
Date Time Action Instruction	4	
P/P \$ 9683.36 (bed)	# 7289.887 464.)	
1 1		
(A)	<u> </u>	
	2212	
Cata Time File Pass 107 : Prelli. Report	Days Of Repair:	. 5
: Final Report		ey Reid
Cate Time Rie Return to? Add	promising	-11_1
	Transfer S Fig.	
Report Format		
Lump Sum / LB II / S	Webler 5 (\$	
	-	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inter	rnationale Des Experts En Autom			
BE INSURANCE (SIN	GAPORE) PTE LTD	Ref : CC4/QBE17022	461/Gpa3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date: 24-11-2017 Code: QBE			
	Policy Particu	lars :- THIRD PARTY CLAI	M		
Insured Veh.	GT 7803R	Veh. Inspected	SGA 6166C		
Policy No.	8-V0016264-MVA	Coverage (\$)	0.00		
Claim No.	VC010890	Excess (\$)	0.00		
Assign From		Assign Date	24/11/2017		
2.	Vehicle	Particulars & Condition	# 1		
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer		Steering			
Brakes		Modification			
General					
3.	Co	onditions of Tyres			
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre		4	mm		
4.	Des	cription of Damages			
5.		eneral Information	24/11/2017		
Accident Date	10/11/2017	Inspection Date	24/11/2017		
Survey held at	TRANS EUROKARS PTE	LID			
	NO 5 UBI CLOSE SINGAPORE 408605	3	V.		
5a.		Remarks			

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605 ESTIMATE OF REPAIRS



QBE INSURANCE (SINGAPORE) PTE LTD			NAME:	Mr Ng Ching	Fah	WIP:	44215
1 RAFFLES QUAY #29-10		ADDRESS :	DRESS: 542 SERANGOON NORTH AVE 4		EXCESS:		
оитн	TOWER			#07-03	N NORTH AVE 4	DATE:	11-Nov-17
INGAP	ORE 048583			Singapore 5505	12 741		
ATTN.	;	MOTOR CLAIMS	TEL:	97396094	- Her		
AX :	-46						
EH N	0:	SGA6166C	DATE IN :	/	CONTACT PERSON:	JESS 6395 787	4
CHASS	IS NO :	JM6KE1032G0345043	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY	CLAIM
MODE	L:	MAZDA CX5 2.5L	DATE REG.:	17-Nov-15	POLICY NO. :		
			N/	ATURE OF WORKS	<u> </u>		
			j	Parts Description			
NO				QTY		REVISED	PRICES
1	REAR BUMPER	re .		1	MKDY3-50-22XFBB		\$ 1,218.00
2	SENSOR,ULTRASC		<i>JN</i>	2	MGMK6-67-UC1 E4		\$ 344.4
3	SENSOR,ULTRASC	TA A S	MUCH AV	2	MKD49-67-UC1		\$ 385.8
4	RETAINER CENTE	R, SENSOR ?	IN	2	MKD45-67-UC5AE4		\$ 34.6
5	RETAINER SIDE, S	ENSOR X NN		2	MKD49-67-UC5A		\$ 19.4
6	TAPE PROTECTOR	11		5	MG001-67-061		\$ 37.0
7	CORD, SHORT (SE			1	MKA3B-67-290		\$ 127.8
8	RETAINER(LHS), F		N/N	1	MKD53-50-2J1A		\$ 32.4
9	RETAINER(RHS), I		1110	1	MKD53-50-2H1A		\$ 32.4
10		R, REAR BUMPER / KL		1	MKD53-50-251		\$ 5.1
11	REFLECTOR LHS	X (n/n/		1	MKD31-51-5M0		\$ 101.2
12	REFLECTOR RHS	XYN		1	MKD31-51-5L0		\$ 101.2
13	COVER(LHS), TOV	WING / 1 . I		1	MKD53-50-EL1A		\$ 2.5
14	COVER(RHS), TO	. 100		1	MKD53-50-EK1A		\$ 2.5
15	REAR REINFORCE	7 11		1	MKD53-50-260D		\$ 495.2
11000	Charles and the agency	FORCEMENT / Met .		2	MKD53-52-B22A		\$ 32.8
16		R, REAR BUMPER /		2	MG043-62-864A		\$ 6.6
17	FASTENER, REAR		1.	2	MB45A-56-146A		\$ 5.6
19	CLIP, REAR BUM		MEC	2	MC274-50-133		\$ 7.0
20	RIVET, REAR BUN			4	ML33X-13-209		\$ 11.2
21	GROMMET, REA	THE CITY 1		6	MBHN1-50-0Z1A		\$ 15.0
10000	PANEL, REAR ENI	O CIA I		1	MK0Y0-70-75Z		\$ 473.9
22	TAILGATE	BUC		1	MKDZ1-62-02XD		\$ 1,321.4
23	TRIM LOWER, TA	7 / /	^1	1	MKA0G-68-960		\$ 267.
24	WEATHERSTRIP,	0 5 M	V	1	MKD53-62-761A		\$ 174.5
25	47-1000 NOV. 12-100 NOV.	TAILOATE .		2	MGHP9-58-867		\$ 22.8
26	VALVE ONEWAY	0	X.	1	MG33M-62-310B		\$ 256.4
27	TAPE PROTECTO			2	MBR5S-56-994		\$ 14.
28		- 1N	tc.	2	MG043-62-864A		\$ 6.
30		7 NN		1	MKD53-62-4B0A		\$ 94.

31	GARNISH, TAILGA	TE / 25		1	MKD46-50-810AE4		\$	363.20
32	MAZDA, EMBLEM	/	1	1	MKD53-51-721		\$	45.30
33	SKYACTIV, EMBLEI	м /		1	MKD53-51-771		\$	71.60
34	200000000000000000000000000000000000000	WINDSCREEN /	MC	2	MC513-50-896		\$	15.60
35		WINDSCREEN /	1,00	2	MD204-50-896A		\$	5.20
36	SPACER, REAR WII	ACTIVE AND WATER TO SEE THE SECOND SE		3	MGJ6A-50-897		\$	36.30
37	PIN STUD, REAR W	CONTRACTOR STATE		1	MGR4B-63-938		\$	11.40
38	PROTECTOR, REAL			2	MKD53-51-954		\$	6.00
39	PROTECTOR, REAL	10.00000000000		2	MKD54-51-954		\$	5.00
40	PROTECTOR, REAL	on the second of		3	MD01G-51-979		\$	37.80
41	PROTECTOR, REAL	- Charles - Char		2	MKD53-51-979A		\$	5.00
42	PROTECTOR, REAL	SELECTION OF THE SELECT		2	MKD45-51-979		\$	5.00
43	PROTECTOR, REAL			4	MBBN9-51-972		\$	9.20
44	CLIP, REAR SPOILE			1	MKD53-51-0B6B		\$	2,50
-	CLIP, REAR SPOILE			2	MKDY3-51-0A6B		\$	21.60
45 46	FASTENER, REAR			3	MEG21-51-146		\$	17.70
47	CLIP, REAR SPOILE	escontant of the		2	MEG21-51-SJ3		\$	10.80
20	ANTENNA, KEYLES	0/ 0/4		1	MKD47-67-6NXA		\$	105.80
48	-			1	MKD45-67-6NYA		\$	2.50
49	CLIP, ANTENNA	A STORMONOWY TO THE COMMENT OF THE C	<u>c. </u>	1	MKD54-51-163A		\$	35.20
50	GASKET(LHS), TAI			100000	MKD54-51-153A	_	\$	35.20
51	GASKET(RHS), TAI	50-505-000 MC-0	SMC	1	MKD53-51-146B		\$	7.8
52	FASTENER, TAILLA		10	2	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		\$	29.8
53	GROMMET, TAILL			2	MGJ6A-51-14Y		-	1,000,00
54	GASKET(LHS), TAI		-	1	MKD53-51-3J8A		\$	43.70
55		ILGATE LAMP	,	1	MKD53-51-3H8A		\$	43.7
56	LAMP, LICENSE	X	SNN	2	MGJ6A-51-270C		\$	90.60
57	CAMERA-BACK M	ONITOR X	1	1	MK015-67-RC0A		\$	790.50
	land Ro	+lid / Cay	1 466.6	0 / .	TOTAL PARTS		\$	7,503.60
	(aut) 11°	1110/2 07	1,00.0		LESS 10%		\$	750.36
	1				TOTAL PARTS COST		\$	6,753.2
			<u>L</u> a	abour Descript	tion			
1	MZ-BR-REAR06	TO REPLACE REAR BU TAILGATE REPAIR ALL	IMPER, REAR REINF AREAS AFFECTED	FORCEMENT, I	REAR END PANEL AND DENT.	1890	\$	3,780.0
2	MZ-SP-SREAR6	TO RESPRAY REAR BU	JMPER, REAR REIN	FORCEMENT,	REAR END PANEL AND TAILGATE.	1500	\$	3,000.0
3	MZ-BR-SEALER	TO SUPPLY SPRAY TE	ROSTAT SEALANT	ON THE CUTTI	NG NM	3	\$	350.0
4	MZ-BR-CAVITY	TO CARRY-OUT BODY	CAVITY PRESERVA	ATION.		150	\$	250.0
				N THE BEAD O	ECTION TO GIVE WAY TO THE	315	\$	630.0

	10.5					
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	/	NETT	\$	560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	/	NETT	\$	120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		315	s	630.00
9	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.		315	\$	630.00
10	MZ-BR-PLATE1	TO SUPPLY-NUMBER PLATE. X	,	SNETT X	\$	70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150	\$	250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		180	\$	350.00
13	MZ-BR-SUNDRI	SUNDRIES.	ne 20	9 NETT	\$	100.00
	-	TO	OTAL LABOUR	\$ -	\$ 10	,720.00

\$ 6,753.24 \$ TOTAL PARTS \$ \$ 17,473.24 TOTAL Ś \$ LESS EXCESS \$ TOTAL AFTER EXCESS \$ GST 7% \$ \$ **GRAND TOTAL**

17843.18

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

7-(8) Days.

Nefore paint photos.

Cano Qiap - 82880282

24/11/17

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:



TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605 FINALISED OF REPAIRS



QBE INSURANCE (SINGAPORE) PTE LTD

NAME:

Mr Ng Ching Fah

WIP:

44215

1 RAFFLES QUAY #29-10

ADDRESS: 542 SERANGOON NORTH AVE 4

EXCESS:

SOUTH TOWER

#07-03

DATE:

SINGAPORE 048583

Singapore 550542

11-Nov-17

ATTN.:

MOTOR CLAIMS

TEL:

97396094

FAX:

SGA6166C

DATE IN:

CONTACT PERSON: TYPE OF CLAIM:

JESS 6395 7874

CHASSIS NO:

JM6KE1032G0345043

MILEAGE: DATE REG.:

POLICY NO. :

THIRD PARTY CLAIM

MODEL:

VEH NO :

MAZDA CX5 2.5L

17-Nov-15 NATURE OF WORKS

- Am - 20.		Parts Description	on				
NO		QTY			REVISED		PRICES
1	REAR BUMPER	1	MKDY3-50-22XFBB	\$	1,218.00	\$	1,218.00
2	SENSOR, ULTRASONIC (CENTER)	2	MGMK6-67-UC1 E4			\$	344.40
3	SENSOR,ULTRASONIC (SIDE)	2	MKD49-67-UC1			\$	385.80
4	RETAINER CENTER, SENSOR	2	MKD45-67-UC5AE4			\$	34.60
5	RETAINER SIDE, SENSOR	2	MKD49-67-UC5A			\$	19.40
6	TAPE PROTECTOR, SENSOR	5	MG001-67-061	\$	37.00	5	37.00
7	CORD,SHORT (SENSOR)	1	MKA3B-67-290			5	127.80
8	RETAINER(LHS), REAR BUMPER	1	MKD53-50-2J1A			\$	32.40
9	RETAINER(RHS), REAR BUMPER	1	MKD53-50-2H1A			5	32.40
10	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	\$	5.10	\$	5.10
11	REFLECTOR LHS	1	MKD31-51-5M0			\$	101.20
12	REFLECTOR RHS	1	MKD31-51-5L0			\$	101.20
13	COVER(LHS), TOWING	1	MKD53-50-EL1A	\$	2.50	\$	2.50
14	COVER(RHS), TOWING	1	MKD53-50-EK1A	\$	2.50	Ś	2.50
15	REAR REINFORCEMENT	1	MKD53-50-260D	\$	495.20	\$	495.20
16	STAY, REAR REINFORCEMENT	2	MKD53-52-B22A	\$	32.80	\$	32.80
17	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$	6.60	5	6.60
18	FASTENER, REAR BUMPER	2	M845A-56-146A	\$	5.60	5	5.60
19	CLIP, REAR BUMPER	2	MC274-50-133	\$	7.00	\$	7.00
20	RIVET, REAR BUMPER	4	ML33X-13-209	\$	11.20	\$	11.20
21	GROMMET, REAR BUMPER	6	MBHN1-50-0Z1A	\$	15.00	\$	15.00
22	PANEL, REAR END	1	MK0Y0-70-75Z			S	473.90
23	TAILGATE	1	MKDZ1-62-02XD	\$	1,321.40	\$	1,321.40
24	TRIM LOWER, TAILGATE	1	MKA0G-68-960			5	267.10
25	WEATHERSTRIP, TAILGATE	1	MKD53-62-761A			\$	174.50
26	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867			ŝ	22.80
27	LOCK, TAILGATE	1	MG33M-62-310B			Ś	256.40
28	TAPE PROTECTOR, TAILGATE	2	MBR5S-56-994	\$	14.40	\$	14.40
29	TAPE PROTECTOR, TAILGATE	2	MG043-62-864A	\$	6.60	\$	6.60
30	SWITCH, OPEN	1	MKD53-62-480A		3232	\$	94.80
31	GARNISH, TAILGATE	1	MKD46-50-810AE4	s	363.20	\$	363.20

32	MAZDA, EMBLEN	1	1	MKD53-51-721	\$	45.30	\$	45.30
33	SKYACTIV, EMBLI	M	1	MKD53-51-771	\$	71.60	\$	71.60
34	FASTENER, REAR	WINDSCREEN	2	MCS13-50-896	\$	15.60	\$	15.60
35	FASTENER, REAR	WINDSCREEN	2	MD204-50-896A	\$	5.20	\$	5.20
36	SPACER, REAR W	INDSCREEN	3	MGJ6A-50-897	\$	36.30	\$	36.3
37	PIN STUD, REAR	WINDSCREEN	1	MGR48-63-938	\$	11.40	\$	11.4
38	PROTECTOR, REA	AR SPOILER	2	MKD53-51-954	\$	6.00	\$	6.0
39	PROTECTOR, REA	AR SPOILER	2	MKD54-51-954	\$	5.00	\$	5.00
40	PROTECTOR, REA	AR SPOILER	3	MD01G-51-979	\$	37.80	\$	37.8
41	PROTECTOR, REA	AR SPOILER	2	MKD53-51-979A	\$	5.00	\$	5.0
42	PROTECTOR, REA	AR SPOILER	2	MKD45-51-979	\$	5.00	\$	5.0
43	PROTECTOR, REA	AR SPOILER	4	M8BN9-51-972	\$	9.20	\$	9.2
44	CLIP, REAR SPOIL	ER	1	MKD53-51-0B6B	\$	2.50	\$	2.5
45	CLIP, REAR SPOIL	ER	2	MKDY3-51-0A6B	\$	21.60	\$	21.6
46	FASTENER, REAR	SPOILER	3	MEG21-51-146	\$	17.70	\$	17.7
47	CLIP, REAR SPOIL		2	MEG21-51-SJ3	\$	10.80	\$	10.8
48	ANTENNA, KEYLE	SS	1	MKD47-67-6NXA	\$	105.80	\$	105.8
49	CLIP, ANTENNA		1	MKD45-67-6NYA	\$	2.50	\$	2.5
50	GASKET(LHS), TA	ILLAMP	1	MKD54-51-163A	\$	35.20	\$	35.2
51	GASKET(RHS), TA	ILLAMP	1	MKD54-51-153A	\$	35.20	\$	35.2
52	FASTENER, TAILL	AMP	2	MKD53-51-146B	\$	7.80	\$	7.8
53	GROMMET, TAIL	LAMP	2	MGJ6A-51-14Y	\$	29.80	\$	29.8
54	GASKET(LHS), TA	ILGATE LAMP	1	MKD53-51-3J8A	\$	43.70	\$	43.7
55	GASKET(RHS), TA	ILGATE LAMP	1	MKD53-51-3H8A	\$	43.70	\$	43.7
56	LAMP, LICENSE		2	MGJ6A-51-270C			\$	90.6
57	CAMERA-BACK N	MONITOR	1	MK015-67-RC0A			\$	790.5
58	LAMP, BOOTLID		1	MKA0G-51-3G0C	\$	466.60	5	466.6
				TOTAL PARTS	\$	4,620.40	\$	7,970.2
				LESS 10%	\$	462.04	\$	797.0
				TOTAL PARTS COST	\$	//	\$	7,173.1
			Labour Descript	ion	-			
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR TAILGATE REPAIR ALL AREAS AFFE			\$	1,890.00	\$	3,780.0
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR	REINFORCEMENT, I	REAR END PANEL AND TAILGATE.	\$	1,500.00	\$	3,000.0
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEAL	ANT ON THE CUTTII	NG			\$	350.0
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRES	SERVATION.		\$	150.00	\$	250.0
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRI REPAIR ON THE REAR SECTION.	MS ON THE REAR SI	ECTION TO GIVE WAY TO THE	\$	315.00	\$	630.0
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCR	EEN GLASS		\$	560.00	ς	560.0

7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS		\$	120.00	40	120.0
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$	315.00	5	630.0
9	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.		\$	315.00	\$	630.0
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE,				\$	70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$	150.00	\$	250.0
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$	180.00	\$	350.0
13	MZ-BR-SUNDRI	SUNDRIES.		\$	30.00	\$	100.0
			TOTAL LABOUR	\$	5,525.00	\$	10,720.0
			TOTAL PARTS	\$	4,158.36	\$	7,173.1
			TOTAL	\$	9,683.36	\$	17,893.1
			LESS EXCESS	\$		\$	1 14
			TOTAL AFTER EXCESS	\$	9,683.36		
			GST 7%	\$	677.84	\$	-
			GRAND TOTAL	\$	10,361.20	\$	175

REMARKS: SGA6166C

8 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

From:

catherinechua@eurokars.com.sg

Sent:

Friday, 2 February 2018 4:15 PM

To:

Guo Qiang (LKKAuto)

Cc:

CS A Team; Admin A; jess.francis@eurokars.com.sg

Subject:

SGA6166C - FINALISATION OF COR

Attachments:

0983_001.pdf

Dear Guo Qiang

Please find our computation attached for your agreement.

COR: \$9683.36before GST

8 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121

DID: 6603 6121 FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]

Sent: Friday, February 2, 2018 4:01 PM

To: Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>

Subject: Attached Image

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: Our ref: VC010890

CC4/QBE17022461/Gpa3

Date:

06.12.2017

The Motor Claims Department

M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGA 6166C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.11.2017 at the premises of M/s <u>Trans Eurokars Pte Ltd (Ubi)</u> and have the following to report:-

Workshop Estimate Amount	: S\$	17,473.24
Revised Estimate Amount	: S\$	8,720.27
"Check" Items Amount	: S\$	2,489.30
Market Value	: S\$	4
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the

Rear Portion

rear front offside

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

7-8 days

Yours faithfully,

XING GUO QIANG

Licensed Appraiser

1210.00	344.40	1890.00	1890.00			
1218.00	385.80	1500.00	1500.00			
37.00 5.10	34.60	150.00	350.00			
2.50	19.40	315.00	100.00			
2.50	127.30	560.00	315.00			
32.80	32.40	120.00	315.00			
		315.00	315.00			
6.60	32.40					
5.60	101.20	315.00	70.00			
7.00	101.20	150.00	100.00	0.00		
11.20	495.20	180.00	170.00	0.00		
15.00	473.90	30.00	70.00			
1321.40	267.10					
14.40	174.50				0.00	0.00
6.60	22.80				0.00	0.00
363.20	256.40					
45.30	94.80					
71.60	0د.105					
15.60	2,50	5525.00	5195.00			
5.20	90.60					
36.30	790.50					
11.40	3953.30					
6.00						
5.00						
37.80						
5.00						
5.00						
9.20						
2.50						
21.60						
17.70						
10.80						
35.20						
35.20						
7.80						
29.80						
43.70						
43.70						

3550.30		
7503.60	10720.00	350.00
3550.30	5525.00	180.00
3953.30	5195.00	170.00

3550.30

355.03 3195.27 5525.00

8720.27

344.40 34.60 127.80 495.20 473.90 267.10 174.50 256.40 94.80 105.80 2.50 2377.00 237.70 2139.30 350.00

2489.30

CHECK ITEM

Catherine Chong (LKK Auto)

From:

Jenny Toh <jenny.toh@qbe.com>

Sent:

Thursday, 23 November, 2017 2:09 PM

To:

assignments@lkkauto.com

Cc:

Jenny Toh

Subject:

New Assignment :YOUR REF: GT7803R / OUR REF: SGA6166C THIRD PARTY CLAIM

(REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Attachments:

1650 001.pdf

Our ref: VC010890

Dear Madam

Kindly survey the TP Claim :-

Insured: GT7803R TP Vehicle: SGA6166C

Date of accident:10/11/2017

Contact: as below


JOS YUN NU IN DOS FILLS

Kindly acknowledge receipt

Jenny Toh Senior Assistant, Claims QBE Emerging Markets - Singapore

QBE Insurance (Singapore) Pte Ltd Phone: +65 6477 1225 Email: jenny.toh@qbe.com

Visit us on the web at www.gbe.com.sg



From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]

Sent: Thursday, 23 November, 2017 11:11 AM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: kevin.lee@eurokars.com.sg; ronald.yap@eurokars.com.sg

Subject: RE: YOUR REF: GT7803R / OUR REF: SGA6166C THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A

DIRECT SETTLEMENT)

Hi Jenny,

Kindly refer to the necessary documents for this case.

Let us have the appointed surveyor for our arrangement.

Thanks & regards.

Jess Francis Carlos

Insurance Claim Executive

TRANS EUROKARS PTE LTD

5 Ubi Close Singapore 408605

DID: +6563957874

From: Jenny Toh [mailto:jenny.toh@qbe.com]
Sent: Thursday, 23 November 2017 8:59 AM
To: Jess Francis < jess.francis@eurokars.com.sg>

Cc: Jenny Toh < jenny.toh@gbe.com>

Subject: RE: YOUR REF: GT7803R / OUR REF: SGA6166C THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A

DIRECT SETTLEMENT)

Hi Jess

Joyce Heng no longer with us.

Can kindly re-forward estimate and SAS report to us.

Thank

Jenny Toh Senior Assistant, Claims QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd Phone: +65 6477 1225 Email: jenny.toh@qbe.com Visit us on the web at www.qbe.com.sq



From: jess.francis@eurokars.com.sg [mailto:]
Sent: Wednesday, 22 November, 2017 6:29 PM

To: joyce.heng@qbe.com; Joyce Foo <joyce.foo@qbe.com>

Cc: ronald.yap@eurokars.com.sg; vion.lim@eurokars.com.sg; catherinechua@eurokars.com.sg;

kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg

Subject: RE: YOUR REF: GT7803R / OUR REF: SGA6166C THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A

DIRECT SETTLEMENT)

Hi QBE,

Can we have the appointed surveyor for this case.

Thanks & regards.

Jess Francis Carlos

Insurance Claim Executive

TRANS EUROKARS PTE LTD

5 Ubi Close

Singapore 408605 DID: +6563957874

From: Eric Pau

Sent: Saturday, 11 November 2017 12:34 PM

To: joyce.heng@qbe.com; Jess Francis < jess.francis@eurokars.com.sg>

Cc: Ronald Yap < ronald.yap@eurokars.com.sg >; Vion Lim < vion.lim@eurokars.com.sg >; Siew Guek Catherine Chua

catherinechua@eurokars.com.sg; Kevin Lee kevin.lee@eurokars.com.sg;

Subject: YOUR REF: GT7803R / OUR REF: SGA6166C THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT

SETTLEMENT)

YOUR REF: GT7803R / OUR REF: SGA6166C THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Joyce,

Kindly arrange the survey of our client's vehicle.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Liaise with Jess for survey arrangement.

Best Regards,

Eric Pau

Insurance Claims Officer

TRANS EUROKARS PTE LTD

5 Ubi Close, Singapore 408605 **D**: (65) 6395 8685 **H**: (65) 9618 5991 **E**: eric.pau@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]

Sent: Saturday, November 11, 2017 12:41 PM To: Eric Pau <eric.pau@eurokars.com.sg>

Subject: Attached Image

IMPORTANT NOTICE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of

this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 19 December, 2017 4:11 PM

To:

eric.pau@eurokars.com.sg

Cc:

'jess.francis@eurokars.com.sg'; Admin A

Subject:

Your Ref: SGA 6166C *Our Ref: CC4/QBE17022461/Gpa3 [ACCIDENT INVOLVING GT

7803R(QBE) & SGA 6166C ON 10/11/2017]

Your Ref: SGA 6166C

Without Prejudice

Our Ref: CC4/QBE17022461/Gpa3

Dear Sirs/Madam,

ACCIDENT INVOLVING GT 7803R(QBE) & SGA 6166C ON 10/11/2017

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hsiao Tong (LKKAuto)

Sent:

Monday, 5 February 2018 10:50 AM

To:

catherinechua@eurokars.com.sg

Cc:

Guo Qiang (LKKAuto); Admin A; Zaini (LKK Auto)

Subject:

RE: SGA6166C - FINALISATION OF COR *LKK REF: CC4/QBE17022461/Gpa3

Attachments:

0983_001.pdf

Without Prejudice

Hi Catherine,

We refer to your below email.

For COR, finalise amount at P/P \$9,683.36(before GST) with 8days.

*** Kindly forward your LOD with all the relevant documents (ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]

Sent: Friday, 2 February 2018 4:15 PM

To: Guo Qiang (LKKAuto) < Guo Qiang@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; jess.francis@eurokars.com.sg

Subject: SGA6166C - FINALISATION OF COR

Dear Guo Qiang

Please find our computation attached for your agreement.

COR: \$9683.36before GST

8 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thanks n Regards

Catherine Chua Insurance Claims Executive Trans Eurokars Pte Ltd DID: 6603 6121

FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]

Sent: Friday, February 2, 2018 4:01 PM

To: Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>

Subject: Attached Image

From:

jen.lim@eurokars.com.sg

Sent:

Monday, 26 March 2018 11:26 AM

To:

Hsiao Tong (LKKAuto)

Cc:

jessicahs@eurokars.com.sg Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017

Subject: Attachments:

3049_001.pdf

"Without Prejudice"

Dear Hsiao Tong,

Attached is the covering letter, Repair Tax Invoice, Rental Invoice, GIA Search Fee, Letter of Authority & Discharge voucher signed by client for your perusal.

Await to hear from you with your offer of settlement as soon as possible.

Thank you very much.

Note: Documents send by email only.

Best Regards,
Jenny Lim
Admin Assistant

TRANS EUROKARS PTE LTD

12 Sungei Kadut Avenue Singapore 729648

Tel: +65 63633003 DID: +65 63602444 Fax: +65 63602899

From:

Hsiao Tong (LKKAuto)

Sent:

Monday, 26 March 2018 5:13 PM

To:

Syaheeda Nacah Binte Mohamed Othman; Joyce Foo

Cc:

Jenny Toh; Zaini (LKK Auto); Admin A

Subject:

<Seek Mandate> Your Ref: VC010890 *LKK REF: CC4/QBE17022461/Gpa3s2

[ACCIDENT INVOLVING GT7803R(OI) & SGA6166C(TP) ON 10/11/2017]

Attachments:

LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey

Photos.pdf; TP LOD_SGA 6166C.pdf

Your ref: VC010890

Our ref: CC4/QBE17022461/Gpa3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GT7803R(OI) & SGA6166C(TP) ON 10/11/2017

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our insured driver's favour.

We seek your approval to offer Third Party repairer "TRANS EUROKARS PTE LTD" at \$11,219.20(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$19,145.70 \$10,361.20	
2. Loss of Rental (8days x \$100.00) (w/GST)	\$ 856.00	\$ 856.00(8days x \$100.00)(w/GST)
3. Loss of Use (2days PRI x \$100.00)	\$ 200.00	\$ -
4. LTA/GIA search fee	\$ 2.00	\$ 2.00
Total	\$20,203.70	\$11,219.20

^{**08}days recommendation for repair.

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Syaheeda Nacah Binte Mohamed Othman [mailto:syaheeda.othman@qbe.com]

Sent: Wednesday, 6 December 2017 2:08 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 27 March 2018 12:48 PM

To:

jen.lim@eurokars.com.sg

Cc:

jessicahs@eurokars.com.sg

Subject:

RE: Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017 *LKK REF:

CC4/QBE17022461/Gpa3s2

Without Prejudice

Hi Jenny,

We refer to the above matter.

We propose settlement as follows: -

Total	\$11,219.20
3. LTA/GIA search fee	\$ 2.00
2. Loss of Rental (8days x \$100.00) (w/GST)	\$ 856.00
1. Cost of Repair (w/GST)	\$10,361.20

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jen.lim@eurokars.com.sg [mailto:jen.lim@eurokars.com.sg]

Sent: Monday, 26 March 2018 11:26 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: jessicahs@eurokars.com.sg

Subject: Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017

"Without Prejudice"

Dear Hsiao Tong,

From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 28 March 2018 11:46 AM

To:

'jen.lim@eurokars.com.sg'

Cc:

jessicahs@eurokars.com.sg

Subject:

RE: Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017 *LKK REF:

CC4/QBE17022461/Gpa3s2

Attachments:

DV_SGA6166C.pdf

Without Prejudice

Hi Jenny,

Thank you for your acceptance.

Please duly sign the DV enclosed and return together with the following document to us(LKK) for our necessary action: -

- Original LOD
- Original Repair Tax Invoice
- Original Authorisation to Act signed by your client, Ng Ching Fah
- Original Rental Receipt

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jen.lim@eurokars.com.sg [mailto:jen.lim@eurokars.com.sg]

Sent: Tuesday, 27 March 2018 2:54 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: jessicahs@eurokars.com.sg

Subject: RE: Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017 *LKK REF: CC4/QBE17022461/Gpa3s2

Hi Hsiao Tong,

Please let us have your DV.

· Thanks you.

Best Regards,

Jenny Lim

Admin Assistant

TRANS EUROKARS PTE LTD

12 Sungei Kadut Avenue Singapore 729648

Tel: +65 63633003 DID: +65 63602444 Fax: +65 63602899

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Tuesday, March 27, 2018 12:48 PM To: Jen Lim < jen.lim@eurokars.com.sg>

Cc: Jessica Harry Shastri < jessicahs@eurokars.com.sg>

Subject: RE: Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017 *LKK REF: CC4/QBE17022461/Gpa3s2

Without Prejudice

Hi Jenny,

We refer to the above matter.

We propose settlement as follows: -

Total	\$11,219.20
3. LTA/GIA search fee	\$ 2.00
2. Loss of Rental (8days x \$100.00) (w/GST)	\$ 856.00
1. Cost of Repair (w/GST)	\$10,361.20

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jen.lim@eurokars.com.sg [mailto:jen.lim@eurokars.com.sg]

Sent: Monday, 26 March 2018 11:26 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: jessicahs@eurokars.com.sg

Subject: Your ref: GT7803R Our ref: SGA6166C DOA: 10/11/2017

"Without Prejudice"

Dear Hsiao Tong,

Attached is the covering letter, Repair Tax Invoice, Rental Invoice, GIA Search Fee, Letter of Authority & Discharge voucher signed by client for your perusal.

Await to hear from you with your offer of settlement as soon as possible.

Thank you very much.

Note: Documents send by email only.

Best Regards,
Jenny Lim
Admin Assistant
TRANS EUROKARS PTE LTD

12 Sungei Kadut Avenue Singapore 729648

Tel: +65 63633003 DID: +65 63602444 Fax: +65 63602899

From:

Joyce Foo <joyce.foo@qbe.com>

Sent:

Thursday, 19 April 2018 1:26 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A; Joy Irene (LKKAuto); Asher Sng (LKKAuto)

Subject:

RE: TP SURVEY - SGA6166C - OUR INSURED GT7803R - DOA 10.11.2017 *** LKK

REF: CC4/QBE17022461/Gpa3s2

Our Ref. VC010890

Hi Hsiao Tong

We have received the DV and relevant documents from TP's workshop. Please let us have your survey report to proceed with settlement.

Thank You & Best Regards

Joyce Foo Senior Assistant - Claims QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd Phone: +65 6477 1184 Email: joyce foo@qbe.com Visit us on the web at www.qbe.com.sg



From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Thursday, 19 April, 2018 12:09 PM To: Joyce Foo <joyce.foo@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto)

<AsherSng@lkkauto.com>

Subject: RE: TP SURVEY - SGA6166C - OUR INSURED GT7803R - DOA 10.11.2017 *** LKK REF:

CC4/QBE17022461/Gpa3s2

Hi Joyce,

We refer to your below email.

We have settled the matter at \$11,219.20(all-in) with third party repairer.

We are currently pending for signed DV from third party. Attached here with a copy of email correspondence with third party for your easy reference.

Please call us if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Thursday, 19 April 2018 11:59 AM

To: Joyce Foo <joyce.foo@qbe.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto)

<AsherSng@lkkauto.com>

Subject: RE: TP SURVEY - SGA6166C - OUR INSURED GT7803R - DOA 10.11.2017 *** LKK REF:

CC4/QBE17022461/Gpa3s2

Dear Joyce,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

By copy to Hsiao Tong.

FYI and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [mailto:joyce.foo@qbe.com]
Sent: Thursday, 19 April, 2018 11:40 AM
To: Admin A <admin-a@lkkauto.com>

Subject: TP SURVEY - SGA6166C - OUR INSURED GT7803R - DOA 10.11.2017

Your Ref. TBA

Our Ref. VC010890

Dear Sir/Madam


We refer to our assignment on 23.11.2017.

. Todate we did not receive your survey report. Please expedite

Thank You & Best Regards

Joyce Foo Senior Assistant - Claims QBE Asia Pacific - Singapore

OBE Insurance (Singapore) Pte Ltd Phone: +65 6477 1184 Email: joyce foo@gbe.com Visit us on the web at www.qbe.com.sg



IMPORTANT NOTICE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

HEVEL .		Affiliated to Federation Intern	nationale Des Experts En Autom	obile
QBE IN	SURANCE (SIN	IGAPORE) PTE LTD	Ref : CC4/QBE17022	2461/Gpa3s2
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date: 20-04-2018 Code: QBE		
1.	West Published	Policy Particul	ars :- THIRD PARTY CLAI	M
	nsured Veh.	GT 7803R	Veh. Inspected	SGA 6166C
-	olicy No.	8-V0016264-MVA	Coverage (\$)	0.00
_	laim No.	VC010890	Excess (\$)	0.00
A	ssign From	JOYCE FOO	Assign Date	24/11/2017
2.		Vehicle P	articulars & Condition	
	Make & Model	MAZDA CX-5	c.c	2488
E	ngine No.	HIDDEN	Year of Reg.	2015
-	Chassis No.	JM6KE1032G0345043	Colour	SILVER
C	Odometer	38016	Steering	IN ORDER
В	Brakes	IN ORDER	Modification	SPORTS RIM
G	Seneral	GOOD		
3.	A STATE OF	Col	nditions of Tyres	
		Size	Make	Balance
F	R/H Front Tyre	225/55R19	тоуо	6 mm
L	JH Front Tyre	225/55R19	тоуо	6 mm
F	R/H Rear Tyre	225/55R19	тоуо	6 mm
L	/H Rear Tyre	225/55R19	TOYO	6 mm
4.		Desc	ription of Damages	
Т	THE VEHICLE SU	STAINED DAMAGES AT TH	E REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Ge	neral Information	
1	Accident Date	10/11/2017	Inspection Date	24/11/2017
5	Survey held at	TRANS EUROKARS PTE I	_TD	
		NO 5 UBI CLOSE SINGAPORE 408605		
5a.	Fire A		Remarks	
A F	A)THE INSPECTION	ON WAS CONDUCTED ON A	A"WITHOUT PREJUDICE" BA NS, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.
5b.	Estimate Days of Repair			

ESTIMATED NORMAL PERIOD FOR REPAIR:

8 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 6166C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,218.00	1,218.00
2	SENSOR, ULTRASONIC (CENTER)	NOT NECESSARY	344.40	-
	SENSOR, ULTRASONIC (SIDE)	NOT NECESSARY	385.80	75
	RETAINER CENTER, SENSOR	NOT NECESSARY	34.60	-
2	RETAINER SIDE, SENSOR	NOT NECESSARY	19.40	-
5	TAPE PROTECTOR, SENSOR	NECESSARY	37.00	37.00
	CORD, SHORT (SENSOR)	NOT NECESSARY	127.80	-
	RETAINER (LHS), REAR BUMPER	NOT NECESSARY	32.40	-
4	RETAINER (RHS), REAR BUMPER	NOT NECESSARY	32.40	
1	BRACKET CENTER, REAR BUMPER	NECESSARY	5.10	5.10
1	REFLECTOR LHS	NOT NECESSARY	101.20	-
1	REFLECTOR RHS	NOT NECESSARY	101.20	-
1	COVER (LHS), TOWING	CUT	2.50	2.50
1	COVER (RHS), TOWING	сит	2.50	2.50
1	REAR REINFORCEMENT	BENT	495.20	495.20
2	STAY, REAR REINFORCEMENT	NECESSARY	32.80	32.80
	TAPE PROTECTOR, REAR BUMPER	NECESSARY	6.60	6.60
2	FASTENER, REAR BUMPER	NECESSARY	5.60	5.60
	CLIP. REAR BUMPER	NECESSARY	7.00	7.00
	RIVET, REAR BUMPER	NECESSARY	11.20	11.20
6	GROMMET, REAR BUMPER	NECESSARY	15.00	15.00
1	PANEL, REAR END	NOT NECESSARY	473.90	
1	TAILGATE	BUCKLED	1,321.40	1,321.40
1	TRIM LOWER, TAILGATE	NOT NECESSARY	267.10	
	WEATHERSTRIP, TAILGATE	NOT NECESSARY	174.50)
	VALVE ONEWAY, TAILGATE	NOT NECESSARY	22.80	
	LOCK, TAILGATE	NOT NECESSARY	256.40	
	TAPE PROTECTOR, TAILGATE	NECESSARY	14.40	14.40
	TAPE PROTECTOR, TAILGATE	NECESSARY	6.60	6.60
	SWITCH, OPEN	NOT NECESSARY	94.80	
	GARNISH, TAILGATE	DEFORMED	363.20	363.20

Report Ref No. CC4/QBE17022461/Gpa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	MAZDA, EMBLEM	NECESSARY	45.30	45.30
1	SKYACTIVE, EMBLEM	NECESSARY	71.60	71.60
2	FASTENER, REAR WINDSCREEN	NECESSARY	15.60	15.60
2	FASTENER, REAR WINDSCREEN	NECESSARY	5.20	5.20
3	SPACER, REAR WINDSCREEN	NECESSARY	36.30	36.30
1	PIN STUD, REAR WINDSCREEN	NECESSARY	11.40	11.40
2	PROTECTOR, REAR SPOILER	NECESSARY	6.00	6.00
2	PROTECTOR, REAR SPOILER	NECESSARY	5.00	5.00
3	PROTECTOR, REAR SPOILER	NECESSARY	37.80	37.80
2	PROTECTOR, REAR SPOILER	NECESSARY	5.00	5.00
2	PROTECTOR, REAR SPOILER	NECESSARY	5.00	5.00
4	PROTECTOR, REAR SPOILER	NECESSARY	9.20	9.20
1	CLIP, REAR SPOILER	NECESSARY	2.50	2.50
	CLIP, REAR SPOILER	NECESSARY	21.60	21.60
3	FASTENER, REAR SPOILER	NECESSARY	17.70	17.70
	CLIP. REAR SPOILER	NECESSARY	10.80	10.80
1	ANTENNA, KEYLESS	DAMAGED	105.80	105.80
1	CLIP, ANTENNA	NECESSARY	2.50	2.50
1	GASKET (LHS), TAILLAMP	NECESSARY	35.20	35.20
1	GASKET (RHS), TAILLAMP	NECESSARY	35.20	35.20
	FASTENER, TAILLAMP	NECESSARY	7.80	7.80
	GROMMET, TAILLAMP	NECESSARY	29.80	29.80
1	GASKET (LHS), TAILGATE LAMP	NECESSARY	43.70	43.70
1	GASKET (RHS), TAILGATE LAMP	NECESSARY	43.70	43.70
	LAMP, LICENCE	NOT NECESSARY	90.60	
	CAMERA - BACK MONITOR	NOT NECESSARY	790,50	
1	LAMP BOOTLID	CRACKED	466.60	466.6
	LESS 10% DISCOUNT		-797.02	-462.0
			7,173.18	4,158.3
	SPECIAL NETT ITEMS			
1	NUMBER PLATE (SN)	NOT NECESSARY	70.00	

Report Ref No. CC4/QBE17022461/Gpa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

9,683.36

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
	36		170.00	30.00
	LABOUR			
	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		3,780.00	1,890.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, AND TAILGATE. TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.		3,000.00	1,500.00
		NOT NECESSARY	350.00	
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
SEC	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		630.00	315.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		120.00	120.00
	TO TRANSFER REVERSE CAMERA.		630.00	315.00
	TO TRANSFER REVERSE SENSORS.		630.00	315.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	1054097
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			10,550.00	5,495.00
	GRAND TOTAL		17,893.18	9,683.36

Report Ref No. CC4/QBE17022461/Gpa3s2

W

XING GUO QIANG

M.MATAI, AMSAE-A

RECOMMENDED COST OF REPAIRS

Amorit

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.