

ASS. REC. BY:

REF:

CS/AXA/7022501/Gibber

Special Instruction:

Surveyor:

GQ

Smart Claim

ASSIGNMENT (Office)

From (Person):

Yvonne Any

of

AXA

Date/Time:

27-11-2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 5889C

Insured:

at Workshop m/s

Anlim Motor

Tel:

6483 1244

of

81k 10 Amk md Park JA #01-09

Policy No:

Claim No:

97M004R9

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

24-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27/11/2017 1:25pm

Person Contacted:

Elgine

Vehicle IN OUT

Date/Time

Action/Instruction

(✓) Estimate

SKZ 5889C - X

28/11/17

Send preli revised by SMART claim

7/12/18

Final fig \$7423 (Red 4531, 38%) confirmed by email

REF:

AAA

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SK85889C Yr Regn: 28 Jan 2016

Type: ☒ M.Cas / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier cc 1986

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

27073

T. Radio:

Insured / Std / NI / NA

Eng No:

C/No:

8SU600070127

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/65 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

27-11-17

Survey held at

w/s

5:30pm

Des. of Damages ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 DEC 2017

Date/Time. File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time. File Return to?

2) 7/2 - typist

Report Format :

SMART claim

Lump Sum / I.B.I. (\$) :

7423 p

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)
☐ :

Survey Fee:

Transportation

) \$ + RS. \$:

Photos

Others

TOTAL

250

250

Survey Department Check List (Case Handler)

Reference No.: CS/AXA 17022501/6VB

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 7/2/18
Case Handler Date

*C: Critical *N: Nor-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CS/AXA17022501/Gvb		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 27-11-2017		
		Code : AXA2		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKZ 5889C
Policy No.		Coverage (\$)		0.00
Claim No. S7M004R9		Excess (\$)		500.00
Assign From SMART CLAIM (YVONNE ANG)		Assign Date		27/11/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c 0		
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 24/11/2017		Inspection Date 27/11/2017		
Survey held at AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047				
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



Service Request Details

Claim

S7M004R9

Reference

None 

Loss Date

November 24, 2017

Request Date

November 27, 2017

Due Date

December 4, 2017

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKZ5889C

Make

TOYOTA

Model

HARRIER 2.0

10 Ang Mo Kio Ind. Park 2A, , , 568047

Primary Contact/Insured

SENG CHYE TOK

BLK 421 #11-483, FAJAR ROAD, 670421, Singapore, Singapore

96694021

SHERVONNESEM@EASECREATIVE.COM

Claim Handler

Yvonne ANG

6568804461

yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 500

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

New Message

LKK AUTO CONSULTANTS PTE LTD (OD) ▾

Type *

☒ Message

Subject *

PRELIMINARY ADVICE OF VEHICLE NO SKZ 5889C

Message *

Repairer's Estimate (Gross) : S\$11,914.00

Revised Estimate Amount : S\$6,327.00

" Check" Items Amount : S\$2,905.00

Total : S\$9,232.00

Market Value : S\$114,000.00

COE/PARF Rebate : S\$63,658.00

Nett Value : S\$50,342.00

The vehicle sustained damages at the front portion.

Survey date and time: 27/11/2017 at 5.30PM

We have authorize repair.

No of days:5 days

Best Regards,

Veron Chen

Cancel

Send

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	8142E

Vehicle Details

Vehicle No.	SKZ5889C
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	HARRIER ELEGANCE 2.0 CVT ABS D/AIRBAG
Primary Colour	Black
Manufacturing Year	2015
Engine No.	3ZRB712159
Chassis No.	ZSU600070127
Maximum Power Output	111.0 kW (148 bhp)
Open Market Value	\$27,148.00
Original Registration Date	28 Jan 2016
First Registration Date	28 Jan 2016
Transfer Count	0
Actual ARF Paid	\$25,008.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Jan 2026
PARF Rebate Amount	\$18,756.00

Intended COE Rebate Details

COE Expiry Date	27 Jan 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$55,001.00
COE Rebate Amount	\$44,902.00
Total Rebate Amount	\$63,658.00

The information contained herein is correct as at 28 Nov 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	8142E

Vehicle Details

Vehicle No.	SKZ5889C
Vehicle to be Exported	Yes
Intended De-registration Date	25 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	HARRIER ELEGANCE 2.0 CVT ABS D/AIRBAG
Primary Colour	Black
Manufacturing Year	2015
Engine No.	3ZRB712159
Chassis No.	ZSU600070127
Maximum Power Output	111.0 kW (148 bhp)
Open Market Value	\$27,148.00
Original Registration Date	28 Jan 2016
First Registration Date	28 Jan 2016
Transfer Count	0
Actual ARF Paid	\$25,008.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Jan 2026
PARF Rebate Amount	\$18,756.00

Intended COE Rebate Details

COE Expiry Date	27 Jan 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$55,001.00
COE Rebate Amount	\$44,000.00
Total Rebate Amount	\$62,756.00

The information contained herein is correct as at 25 Nov 2017

OK

► Toyota Harrier Used Vehicle List (17 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Harrier 2.0A Premium Panoramic	\$119,800	\$12,960 /yr	11-Jan-2016	1,986 cc	20,000 km	Ocean Cars Prestige Pte Ltd	Available

Just Like New. Very Low Mileage. 3 Digit Old Number Plate. Immaculate Condition. 10%-20% Down Payment Scheme Available. Call/ SMS For More Details And Viewing Now.

Office No. - 64633378

Jason Lim - 93881975 | Blue Cheng - 94383844 | Chester Lee - 90676766 | Alson - 97497050

Toyota Harrier 2.0A Elegance Panoramic	\$114,500	\$12,590 /yr	15-Jan-2016	1,986 cc	29,000 km	Go-Go Carz Pte Ltd	Available
---	------------------	---------------------	--------------------	-----------------	------------------	---------------------------	------------------

New Arrival! Breaking News. Offer For The Month. Free Insurance For All Customer With 40% NCD And Above. Low Mileage Done. Cheapest In Town! Getting A Safety, Superb Handling, Comfortable Luxury SUV W...

Office No. - -

Kobi Sim - 88236623

Toyota Harrier 2.0A G's Panoramic	\$163,888	\$18,300 /yr	04-Feb-2016	1,986 cc	-	JCWC Automobile	Available
--	------------------	---------------------	--------------------	-----------------	----------	------------------------	------------------

Toyota Harrier Elegance G's Panoramic Package, 3 Years Or 100,000 Km Warranty Provided, Ultimate Finance Packages Available At Competitive Rates, In House/Loan Can Be Arranged, Do Call Before Viewing ...

Office No. - 65696969

Terence - 90025913 | Ace - 90707117 | Romen - 91512330

Toyota Harrier 2.0A Elegance Panoramic	\$115,800	\$12,530 /yr	19-Feb-2016	1,986 cc	26,844 km	Select By Performance Premium Selection	Available
---	------------------	---------------------	--------------------	-----------------	------------------	--	------------------

Popular Harrier SUV Equipped With 2L Engine Providing Adequate Daily Power! Spacious Cabin For 5 Adults To Lounge In Comfort! Panoramic Roof Give You A Sense Of Spaciousness In The Cabin! Large Boot C...

Office No. - 65074866

Johanna Lim - 90996112 | Fiona Neo - 98488890 | Han - 96644456 | Gerald - 96809729

Toyota Harrier 2.0A Premium Panoramic	\$122,500	\$13,020 /yr	29-Mar-2016	1,986 cc	35,000 km	Motor Universe Credit Pte Ltd	Available
--	------------------	---------------------	--------------------	-----------------	------------------	--------------------------------------	------------------

Interest Rate From 1.99%! Still Under Warranty. In House Loan Available! Come With Build In GPS And Power Tailgate, 100% Accident Free. Well Maintained. Immaculate Condition. Welcome Trade In. Please C...

Office No. - 64655595

Jackson - 82012885 | Benson Hu - 97997507 | John - 98895558 | Johnson - 97376599

Toyota Harrier 2.0A Premium	\$128,800	\$13,750 /yr	29-Mar-2016	1,986 cc	16,300 km	Prime Motor & Leasing	Available
------------------------------------	------------------	---------------------	--------------------	-----------------	------------------	----------------------------------	------------------

Elegant Silver SUV, Premium Model With High Specifications, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available.

Office No. - 68723113

Jack - 91096509 | Eliz - 88680011 | Larry - 96861029

Toyota Harrier 2.0A Elegance	\$133,800	\$14,840 /yr	01-Apr-2016	1,995 cc	-	Tan Motor Car Enterprise	Available
-------------------------------------	------------------	---------------------	--------------------	-----------------	----------	---------------------------------	------------------

Guaranteed Delivery. No Top Up Required. Flexible Loan Available. No Hidden Cost. 3 Years Warranty Available! High Loan And Interest Rate 2.78% Available! High Spec With Moonroof, Electric Seats. Imme...

Office No. - 64577328

Terence - 97876217 | Sunny - 90883671 | Joseph - 82288908

Toyota Harrier 2.0A Premium Panoramic	\$124,800	\$13,080 /yr	13-Apr-2016	1,986 cc	-	Universe Motoring	Available
--	------------------	---------------------	--------------------	-----------------	----------	--------------------------	------------------

Up To 90% Loan! Flexible Repayment With In House Financing. Our Vehicle Inspected By Professional Team For Highest Quality With Option Extended Warranty Available. Owning A Car Is So Much Easier With ...

Office No. - 64631729

Leonard - 83337808 | Davis - 98265151 | Jason - 98157511 | Alex - 85007794

Toyota Harrier 2.0A Elegance	\$158,000	\$17,180 /yr	25-Apr-2016	1,986 cc	-	K-Auto Express	Available
-------------------------------------	------------------	---------------------	--------------------	-----------------	----------	-----------------------	------------------

Very Low Mileage, Well Maintained And Very Well Kept By Owner. Please Call Our Sales Consultant For Viewing Arrangement Or Test Drive Right Now.

Office No. - -

Khoo - 85228863

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2017 12:12
Date Of Accident	24/11/2017 13:10
Exact Location Of Accident	BLK 421 FAJAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ5889C
Insured/Policyholder	
Name Of Registered Owner	TOK SENG CHYE
NRIC No	S1488142E
Email Address	SHERVONNESEM@EASECREATIVE.COM
Mobile Phone No	(LOCAL) +65-96800560
Alternative Phone No	OTHERS-96694021

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 ELEGANCE (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA151662/1
Cover Note Number	28/01/2017 - 27/01/2018

Driver

Name of Driver	SHERVONNE SEM HUI HUI
NRIC No	S7136925J
Date Of Birth	20/10/1971
Occupation	INDOOR
Date Of Driving Pass	21/07/2014
Driving Experience	3 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96694021
Fax Number	
Contact Number	OTHERS-96800560
Email Address	SHERVONNESEM@EASECREATIVE.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

x 

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2:23 PM

4G 77%



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

account number
03926

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 159)-Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960-
 -Motor Vehicles (Third-Party Risks) Rules, 1999 (Malaysia)-

Policy details

Policyholder name	TOK SENG CHYE	Certificate number	GA151662 / 1
Cover	Comprehensive	Chassis number	ZSU600070127
Plan name	Essential	Engine number	3ZRB712159
NCD applicable	20%		
Vehicle registration number	SKZ5889C		
Period of insurance	from 28/01/2017 to 27/01/2018 (both dates inclusive)		
Finance loan company	UNITED OVERSEAS BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any Named Driver as stated in the Policy:
 1. SHERVONNE SEM HUI HUI
 (c) Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Mot permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods of with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-me

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 159) and Section (Malaysia), are not to be included under these headings

EXCESS	Basic Own Damage Excess	SGD 500.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorized Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Compensation Act, (Chapter 159) and Part IV of the Road Transport Act, 1997 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must transfer the Certificate of Insurance and the Policy to the insured Insurance has been lost or destroyed a Statutory Declaration to this effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 159).
 The Premium Warranty Clause requires the premium to be paid in full with a specified period of time, when there would be no liability under endorsement etc

AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 3

VA1 / GA151662

Claims procedure

A. At the Accident Site

1. Exchange particulars with all parties involved in the accident including name, NRIC/FIN number, telephone number company.
2. Take note of the third party vehicle numbers. Please also take digital photographs (e.g. MMS) of all the third party accident and a view of the accident scene. These are to be included in the accident report to be filed later.
3. If there are witnesses, note down their names, NRIC/FIN numbers, telephone numbers and addresses.

B. What to do immediately after

1. Call our Customer Helpline at 1800-880-4741 or AXA's Premium Workshops listed below for further advice/assistance
2. Report the accident to one of AXA's Premium Workshops listed below, with your vehicle (whether damaged or not) or by the next working day. AXA's Premium Workshops are authorised to assist our policyholders for accident report
3. Lodge a police report for the following motor accident cases:-
 - injury case;
 - non-injury case involving a government vehicle or damage to government property;
 - non-injury case involving a foreign vehicle;
 - non-injury case involving a pedestrian or cyclist;
 - any accident outside of Singapore.
4. Avoid all unauthorised tow-truck operators or repair workshops.
5. Forward all letters and communications received from third parties concerning the accident to AXA Insurance Pte

AXA Premium Workshops

NORTH / CENTRAL ZONE

Ah Lim Motor Company (Main)
 40, Telok Ayer St, #01-02, Telok Ayer St, Singapore 068557. Tel: 6333 1344. Fax: 6333 4170

Sketch Plan Pg. 5

To Whom It May Concern,


Accident involving my vehicle no. SK25889 C on 24/11/2017 (date) with
SMIS SSC (other vehicle no) along FARM ROAD

I, Toke Seng Chye Nric No. S14881122

Owner of vehicle no. SK25889 C am aware of the accident of my vehicle on
24/11/2017 (Date) while car was driven by SHERLINE SEM HUI HUI

Nric No. S1169253. I hereby, authorise him/ her to make the report.

X




Name TOKE SENG CHYE

Date: 25/11/2017

.....
..
To fill in if there is a OD claim

I am aware of the circumstances and agreeable to claim my own insurance for the
above accident.

X



Name TOKE SENG CHYE

Date: 25/11/2017



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

LIC Auto.

Estimate No: MC0912620

Date: 25 Nov 2017

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C

Claim Type: Own Damage

Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET X Repair - Blue		1 PC	530.00	
2 FRONT BONNET HINGE LH & RH X		2 PC	60.00	
3 FRONT BONNET ABSORBER LH & RH X SNN		2 PC	180.00	
4 FRONT BONNET LOCK - BT		1 PC	50.00	
5 FRONT BONNET LOCK CABLE X SNN		1 PC	22.00	
6 FRONT BONNET INSULATOR CLIPS X SNN		9 PC	9.00	
7 FRONT BONNET CHROME MOULDING OUTER - Cut		1 PC	90.00	
8 FRONT GRILLE - BR		1 PC	200.00	
9 FRONT GRILLE CLIPS - AC		8 PC	8.00	
10 HEADLAMP WITH HID LH & RH - CRA		2 PC	1,800.00	
11 HEADLAMP LOWER BEAM LH & RH - CHECK PRICE < LH? RH - BT		2 PC	0.0000	
12 HEADLAMP CLIPS X NN		4 PC	4.00	
13 HEADLAMP TOP SIDE PANEL LH & RH X Repair.		2 PC	130.00	
14 FRONT BUMPER - Dis		1 PC	530.00	
15 FRONT BUMPER SIDE RETAINER LH & RH - AC		2 PC	76.00	
16 FRONT BUMPER CLIPS - AC		12 PC	12.00	
17 FRONT BUMPER INNER TOP BEAM CTR - BT		1 PC	100.00	
18 FRONT BUMPER INNER TOP SIDE BRACKET LH & RH ?		2 PC	90.00	
19 FRONT BUMPER REINFORCEMENT - BT		1 PC	145.00	
20 FRONT BUMPER REINFORCEMENT BRACKET LH & RH X NN		2 PC	160.00	
21 FRONT BUMPER SPONGE CTR BIG - CRA		1 PC	40.00	
22 FRONT BUMPER SIDE SPONGE SMALL LH & RH		2 PC	36.00	
23 FRONT BUMPER TOW COVER LH & RH < LH? RH - Dis		2 PC	24.00	
24 FRONT BUMPER LOWER GRILLE CTR - Cut		1 PC	85.00	
25 FRONT BUMPER LOWER COVER ?		1 PC	45.00	
26 FRONT BUMPER LOWER SPOILER BLACK S - CRA		1 PC	100.00	
27 ENGINE UNDER COVER CTR ?		1 PC	60.00	
28 FOGLAMP < LH? RH - CRA		2 PC	230.00	
29 FOGLAMP COVER OUTER LH & RH < LH? RH - AC		2 PC	80.00	
30 RADIATOR SUPPORT PANEL X Repair. < LH? RH - NN		1 PC	320.00	
31 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG LH & RH < LH? RH - AC		2 PC	90.00	
32 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE SMALL LH & RH ?		2 PC	90.00	
33 RADIATOR SUPPORT PANEL TOP GARNISH - AC		1 PC	135.00	
34 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS - AC		12 PC	18.00	
35 BRACE PANEL - BT		1 PC	75.00	
36 HORN X NN		2 PC	100.00	
37 AIR CON CONDENSER ASSY ORI ?		1 PC	530.00	
38 AIR CON CONDENSER PIPE (COND-VALVE) ?		1 PC	200.00	
39 AIR CON CONDENSER PIPE (COND-COMP) ?		1 PC	135.00	





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 25 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
40 AIR CON CONDENSER FAN MOTOR ?		1 PC	160.00	
41 AIR CON CONDENSER FAN BLADE ?		1 PC	65.00	
42 RADIATOR ASSY ORI ?		1 PC	480.00	
43 RADIATOR FAN BLADE ?		1 PC	60.00	
44 RADIATOR FAN MOTOR ?		1 PC	160.00	
45 RADIATOR FAN COWLING ?		1 PC	125.00	
46 RADIATOR SPARE TANK X		1 PC	130.00	
47 WIPER WASHER TANK RH		1 PC	65.00	
48 FRONT FENDER LH & RH - true LH ?		2 PC	580.00	
49 FRONT FENDER COWLING - RH - true		2 PC	310.00	
50 FRONT FENDER COWLING CLIPS - MCC.		20 PC	30.00	
				8,754.00

Special Nett

51 RADIATOR COOLANT ?	1 PC	35.00
52 NUMBER PLATE X NN	1 PC	35.00

70.00

LABOUR

53 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20
54 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	100
55 TO REMOVE & REINSTALL FRONT ENGINE MOUNTING, GEARBOX MOUNTING	1 PC	150.00	?
56 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT - AIR BAG LIGHT & ENGINE LIGHT.	1 PC	180.00	?
57 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, BRACE PANEL, FRONT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, SIDE BRACKET, HEADLAMP TOP PANEL. TO KNOCK & REPAIR FRT DOOR, FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME.	1 PC	1,200.00	600
58 TO SPRAY FRT BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, FRT BUMPER SIDE BRACKET, BRACE PANEL, RADIATOR SUPPORT PANEL, HEADLAMP TOP PANEL, FRT FENDER, FRT DOOR, FRT CHASSIS FRAME, FRT WHEELHOUSE PANEL.	1 PC	1,400.00	600





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 25 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
				3,090.00

Amount Before Excess	S\$ 11,914.00
Add GST @ 7%	833.98
Total Amount payable	S\$ 12,747.98

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SEVEN HUNDRED FORTY SEVEN AND CENTS NINETY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

Excess : \$500
Authorised.
part by part.
before paint photos.
5 Days.

27/11/17

Gue Qiamy - 82880282

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

LIC AL 10.

Estimate No: MC0912620

Date: 25 Nov 2017

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C

Claim Type: Own Damage

Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET X repair - BUC		1 PC	530.00	✓
2 FRONT BONNET HINGE LH & RH X		2 PC	60.00	
3 FRONT BONNET ABSORBER LH & RH X SNN		2 PC	180.00	
4 FRONT BONNET LOCK / BT		1 PC	50.00	✓
5 FRONT BONNET LOCK CABLE X SNN		1 PC	22.00	
6 FRONT BONNET INSULATOR CLIPS X SNN		9 PC	9.00	
7 FRONT BONNET CHROME MOULDING OUTER - Cut		1 PC	90.00	✓
8 FRONT GRILLE / PR		1 PC	200.00	✓
9 FRONT GRILLE CLIPS / ALC		8 PC	8.00	✓
10 HEADLAMP WITH HID LH & RH - CRA		2 PC	1,800.00	✓
11 HEADLAMP LOWER BEAM LH & RH - CHECK PRICE SEH BT X NN		2 PC	0.0000	X
12 HEADLAMP CLIPS X NN		4 PC	4.00	
13 HEADLAMP TOP SIDE PANEL LH & RH X repair - BT		2 PC	130.00	✓
14 FRONT BUMPER / D's		1 PC	530.00	✓
15 FRONT BUMPER SIDE RETAINER LH & RH - ALC		2 PC	76.00	✓
16 FRONT BUMPER CLIPS / ALC		12 PC	12.00	18
17 FRONT BUMPER INNER TOP BEAM CTR - BT		1 PC	100.00	✓
18 FRONT BUMPER INNER TOP SIDE BRACKET LH & RH X NN		2 PC	90.00	X
19 FRONT BUMPER REINFORCEMENT - BT		1 PC	145.00	✓
20 FRONT BUMPER REINFORCEMENT BRACKET LH & RH X NN		2 PC	160.00	
21 FRONT BUMPER SPONGE CTR BIG / CRA		1 PC	40.00	✓
22 FRONT BUMPER SIDE SPONGE SMALL LH & RH		2 PC	36.00	✓
23 FRONT BUMPER TOW COVER LH & RH X NN D's		12 PC	24.00	12
24 FRONT BUMPER LOWER GRILLE CTR X NN - mis		1 PC	85.00	✓
25 FRONT BUMPER LOWER COVER X NN		1 PC	45.00	X
26 FRONT BUMPER LOWER SPOILER BLACK X - CRA		1 PC	100.00	✓
27 ENGINE UNDER COVER CTR X - ee		1 PC	60.00	✓
28 FOGLAMP X NN - CRA		1 2PC	230.00	115
29 FOGLAMP COVER OUTER LH & RH X NN - ee		2 PC	80.00	40
30 RADIATOR SUPPORT PANEL X repair - BT		1 PC	320.00	✓
31 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG LH & RH X NN - ee		2 PC	90.00	45
32 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE SMALL LH & RH X NN		2 PC	90.00	X
33 RADIATOR SUPPORT PANEL TOP GARNISH / ee		1 PC	135.00	✓
34 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS / ee		12 PC	18.00	✓
35 BRACE PANEL / BT		1 PC	75.00	✓
36 HORN X NN		2 PC	100.00	
37 AIR CON CONDENSER ASSY ORI X NN		1 PC	530.00	X
38 AIR CON CONDENSER PIPE (COND-VALVE) X BT		1 PC	200.00	✓
39 AIR CON CONDENSER PIPE (COND-COMP) X NN		1 PC	135.00	X





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 25 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 AIR CON CONDENSER FAN MOTOR		1 PC	160.00	
41 AIR CON CONDENSER FAN BLADE		1 PC	65.00	
42 RADIATOR ASSY ORI		1 PC	480.00	
43 RADIATOR FAN-BLADE		1 PC	60.00	
44 RADIATOR FAN MOTOR		1 PC	160.00	
45 RADIATOR FAN COWLING		1 PC	125.00	
46 RADIATOR SPARE TANK		1 PC	130.00	
47 WIPER WASHER TANK RH		1 PC	65.00	
48 FRONT FENDER LH & RH		2 PC	580.00	✓
49 FRONT FENDER COWLING		1/2 PC	310.00	155
50 FRONT FENDER COWLING CLIPS		20 PC	30.00	✓

8,754.00

Special Nett

51 RADIATOR COOLANT	1 PC	35.00	✓
52 NUMBER PLATE	1 PC	35.00	✓

70.00

LABOUR

53 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20 ✓
54 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	100 ✓
55 TO REMOVE & REINSTALL FRONT ENGINE MOUNTING, GEARBOX MOUNTING	1 PC	150.00	✓ NN
56 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT - AIR BAG LIGHT & ENGINE LIGHT.	1 PC	180.00	✓ 700
57 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, BRACE PANEL, FRONT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, SIDE BRACKET, HEADLAMP TOP PANEL. TO KNOCK & REPAIR FRT DOOR, FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME.	1 PC	1,200.00	800 ✓
58 TO SPRAY FRT BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, FRT BUMPER SIDE BRACKET, BRACE PANEL, RADIATOR SUPPORT PANEL, HEADLAMP TOP PANEL, FRT FENDER, FRT DOOR, FRT CHASSIS FRAME, FRT WHEELHOUSE PANEL.	1 PC	1,400.00	600 700 ✓



Guo Qiang - 82880282



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 30 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: S7M004R9
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
-------------	---------	----------	-------------	---------------

Supplementary Parts to Repair

SPARE PARTS

1 RADIATOR SUPPORT SIDE GARNISH RH	1 PC	20.00	✓	
2 WIPER GRILLE SIDE GARNISH RH	1 PC	20.00	✓	
				40.00

Amount Before Excess	S\$ 40.00
GST Amount	S\$ 2.80
Total Amount payable	S\$ 42.80

The above vehicle was surveyed by GUO XIANG - LKK on 27/11/2017

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

Guo Xiang
20/11/17



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC0912620

Ref No: MF0910815

Date: 31 Jan 2018

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: S7M004R9
 Claim Type: Own Damage
 Accident Date: 24/11/2017

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET		1 PC	530.00	
2 FRONT BONNET LOCK		1 PC	50.00	
3 FRONT BONNET CHROME MOULDING OUTER		1 PC	90.00	
4 FRONT GRILLE		1 PC	200.00	
5 FRONT GRILLE CLIPS		8 PC	8.00	
6 HEADLAMP WITH HID LH & RH		2 PC	1,800.00	
7 HEADLAMP TOP SIDE PANEL LH & RH		2 PC	130.00	
8 FRONT BUMPER		1 PC	530.00	
9 FRONT BUMPER SIDE RETAINER LH & RH		2 PC	76.00	
10 FRONT BUMPER CLIPS		10 PC	18.00	
11 FRONT BUMPER INNER TOP BEAM CTR		1 PC	100.00	
12 FRONT BUMPER REINFORCEMENT		1 PC	145.00	
13 FRONT BUMPER SPONGE CTR BIG		1 PC	40.00	
14 FRONT BUMPER SIDE SPONGE SMALL LH & RH		2 PC	36.00	
15 FRONT BUMPER TOW COVER RH		1 PC	12.00	
16 FRONT BUMPER LOWER GRILLE CTR		1 PC	85.00	
17 FRONT BUMPER LOWER SPOILER BLACK		1 PC	100.00	
18 ENGINE UNDER COVER CTR		1 PC	65.00	
19 FOGLAMP RH		1 PC	115.00	
20 FOGLAMP COVER OUTER RH		1 PC	40.00	
21 RADIATOR SUPPORT PANEL		1 PC	320.00	
22 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG RH		1 PC	45.00	
23 RADIATOR SUPPORT PANEL TOP GARNISH		1 PC	135.00	
24 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS		12 PC	18.00	
25 BRACE PANEL		1 PC	75.00	
26 AIR CON CONDENSER PIPE (COND-VALVE)		1 PC	200.00	
27 FRONT FENDER LH & RH		2 PC	580.00	
28 FRONT FENDER COWLING RH		1 PC	155.00	
29 FRONT FENDER COWLING CLIPS		20 PC	30.00	
30 RADIATOR SUPPORT SIDE GARNISH RH		1 PC	20.00	
31 WIPER GRILLE SIDE GARNISH RH		1 PC	20.00	
				5,768.00
Special Nett				
32 RADIATOR COOLANT		1 PC	35.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288
ATTN: Motor Claim Department

FAX: 63382522

Claim No: MC0912620
Ref No: MF0910815
Date: 31 Jan 2018
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: S7M004R9
Claim Type: Own Damage
Accident Date: 24/11/2017

Repair Cost to Vehicle No (For Finalization):SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
				35.00
LABOUR				
33 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
34 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
35 TO DISMANTLE ALL DAMAGED PARTS.T0 CUT & WELD RADIATOR SUPPORT PANEL,BRACE PANEL,FRONT BUMPER REINFORCEMENT,FRT BUMPER TOP BEAM CTR,SIDE BRACKET,HEADLAMP TOP PANEL.TO KNOCK & REPAIR FRT DOOR,FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME.		1 PC	800.00	
36 TO SPRAY FRT BONNET,FRT BUMPER,FRT BUMPER REINFORCEMENT,FRT BUMPER TOP BEAM CTR,FRT BUMPER SIDE BRACKET,BRACE PANEL,RADIATOR SUPPORT PANEL,HEADLAMP TOP PANEL,FRT FENDER, FRT DOOR,FRT CHASSIS FRAME,FRT WHEELHOUSE PANEL.		1 PC	700.00	
				1,620.00

Amount Before Excess	S\$ 7,423.00
Less Excess	S\$ 500.00
Amount Before GST	S\$ 6,923.00
Add GST @ 7%	484.61
Total Amount payable	S\$ 7,407.61

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED AND SEVEN AND CENTS SIXTY ONE ONLY

The above vehicle was surveyed by GUO XIANG - LKK on 27/11/2017

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

LICK AUTO.

Estimate No: MC0912620

Date: 25 Nov 2017

Policy No: GA151662/1

Veh Reg No: SKZ5889C

Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C

Claim Type: Own Damage

Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BONNET X Repair - buc		1 PC	530.00	
2 FRONT BONNET HINGE LH & RH X		2 PC	60.00	
3 FRONT BONNET ABSORBER LH & RH X 5NN		2 PC	180.00	
4 FRONT BONNET LOCK / BT		1 PC	50.00	
5 FRONT BONNET LOCK CABLE X 5NN		1 PC	22.00	
6 FRONT BONNET INSULATOR CLIPS X		9 PC	9.00	
7 FRONT BONNET CHROME MOULDING OUTER - Cat		1 PC	90.00	
8 FRONT GRILLE / PR		1 PC	200.00	
9 FRONT GRILLE CLIPS / PL		8 PC	8.00	
10 HEADLAMP WITH HID LH & RH - CCA		2 PC	1,800.00	
11 HEADLAMP LOWER BEAM LH & RH - CHECK PRICE < LH? RH - BT		2 PC	0.0000	
12 HEADLAMP CLIPS X 5NN		4 PC	4.00	
13 HEADLAMP TOP SIDE PANEL LH & RH X Repair - BT		2 PC	130.00	
14 FRONT BUMPER / O's		1 PC	530.00	
15 FRONT BUMPER SIDE RETAINER LH & RH - PL		2 PC	76.00	
16 FRONT BUMPER CLIPS / PL		12 PC	12.00	
17 FRONT BUMPER INNER TOP BEAM CTR - BT		1 PC	100.00	
18 FRONT BUMPER INNER TOP SIDE BRACKET LH & RH X		2 PC	90.00	
19 FRONT BUMPER REINFORCEMENT / BT		1 PC	145.00	
20 FRONT BUMPER REINFORCEMENT BRACKET LH & RH X 5NN		2 PC	160.00	
21 FRONT BUMPER SPONGE CTR BIG / CCA		1 PC	40.00	
22 FRONT BUMPER SIDE SPONGE SMALL LH & RH O's		2 PC	36.00	
23 FRONT BUMPER TOW COVER LH & RH < LH X 5NN RH X 5NN		1/2 PC	24.00	
24 FRONT BUMPER LOWER GRILLE CTR X Repair - mis		1 PC	85.00	
25 FRONT BUMPER LOWER COVER X		1 PC	45.00	
26 FRONT BUMPER LOWER SPOILER BLACK X - CCA		1 PC	100.00	
27 ENGINE UNDER COVER CTR X - PL		1 PC	60.00	
28 FOGLAMP < LH? CCA		1/2 PC	230.00	
29 FOGLAMP COVER OUTER LH & RH < LH X RH - PL		2 PC	80.00	
30 RADIATOR SUPPORT PANEL X Repair - BT		1 PC	320.00	
31 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG LH & RH < LH X RH - PL		2 PC	90.00	
32 RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE SMALL LH & RH X		2 PC	90.00	
33 RADIATOR SUPPORT PANEL TOP GARNISH / PL		1 PC	135.00	
34 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS / PL		12 PC	18.00	
35 BRACE PANEL / BT		1 PC	75.00	
36 HORN X 5NN		2 PC	100.00	
37 AIR CON CONDENSER ASSY ORI X		1 PC	530.00	
38 AIR CON CONDENSER PIPE (COND-VALVE) X - BT		1 PC	200.00	
39 AIR CON CONDENSER PIPE (COND-COMP) X		1 PC	135.00	





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 25 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 AIR CON CONDENSER-FAN MOTOR		1 PC	160.00	
41 AIR CON CONDENSER-FAN BLADE		1 PC	65.00	
42 RADIATOR ASSY ORI		1 PC	480.00	
43 RADIATOR FAN BLADE		1 PC	60.00	
44 RADIATOR FAN MOTOR		1 PC	160.00	
45 RADIATOR FAN COWLING		1 PC	125.00	
46 RADIATOR SPARE TANK		1 PC	130.00	
47 WIPER WASHER-TANK RH		1 PC	65.00	
48 FRONT FENDER LH & RH		2 PC	580.00	
49 FRONT FENDER COWLING		1 PC	310.00	
50 FRONT FENDER COWLING CLIPS		20 PC	30.00	

8,754.00

Special Nett

51 RADIATOR COOLANT	1 PC	35.00
52 NUMBER PLATE	1 PC	35.00

70.00

LABOUR

53 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00
54 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00
55 TO REMOVE & REINSTALL FRONT-ENGINE-MOUNTING, GEARBOX MOUNTING	1 PC	150.00
56 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT - AIR BAG LIGHT & ENGINE LIGHT.	1 PC	180.00
57 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL, BRACE PANEL, FRONT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, SIDE BRACKET, HEADLAMP TOP PANEL TO KNOCK & REPAIR FRT DOOR, FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME.	1 PC	1,200.00
58 TO SPRAY FRT BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, FRT BUMPER SIDE BRACKET, BRACE PANEL, RADIATOR SUPPORT PANEL, HEADLAMP TOP PANEL, FRT FENDER, FRT DOOR, FRT CHASSIS FRAME, FRT WHEELHOUSE PANEL.	1 PC	1,400.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimunc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 25 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: SKZ5889C
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
				3,090.00

Amount Before Excess S\$ 11,914.00

Add GST @ 7% 833.98

Total Amount payable S\$ 12,747.98

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SEVEN HUNDRED FORTY SEVEN AND CENTS NINETY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

Excess : \$500
Authorized.
part by part.
before print photos.
5 Days.

27/11/17

Gue Qiamy - 82880282

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912620
Date: 30 Nov 2017
Policy No: GA151662/1
Veh Reg No: SKZ5889C
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Your Ref No: S7M004R9
Claim Type: Own Damage
Accident Date: 24/11/2017

Estimate Repair Cost to Vehicle No :SKZ5889C

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 RADIATOR SUPPORT SIDE GARNISH RH / <i>De</i>		1 PC	20.00	
2 WIPER GRILLE SIDE GARNISH RH / <i>At</i>		1 PC	20.00	
				40.00

Amount Before Excess	S\$ 40.00
GST Amount	S\$ 2.80
Total Amount payable	S\$ 42.80

The above vehicle was surveyed by GUO XIANG - LKK on 27/11/2017

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

Guo Xiang
20/11/17



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 0745 9333



Dept Direct: 6305 0610

Dept Direct: 6305 0011

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-17760
DATE : 30/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5839C
TERMS : 30 days
PO NO.
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID
1 T90467-07220
ZYX10

DESCRIPTION
CLIP,

StkLoc
U1

SUPPLIER

QTY : 10
UPRICE : 1.80
AMOUNT : 18.00

pages

SUB-TOTAL : 18.00
ADD GST 10.0% : 1.26

E & OE

TOTAL AMOUNT SGD : 19.26

[P] 30/11/2017 10:35:16AM

[E] 30/11/2017 10:34:05AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



* AR 20 17 11 - 177 60 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

=====
AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blades, Saipen (Made in Korea),
Forch (Made in Germany))

Spark plug: Nippon Denso, NGK (Made in Japan)

=====
TAX INVOICE AR201711-16612
DATE 28/11/2017
CUSTOMER ID AHL008
VEH REG. NO. SKZ5889C
TERMS 30 days
PO NO.
PAGE NO. Page 1 of 2
CURR. SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53510-48230 ZSU60 AVU65	FRT BONNET LOCK	U1 I.2-D5-D	1	50.00 ✓	50.00
2. T52029-48010 ZSU60 AVU65	FRT BUMPER UPPER REINF	U1 I.1-D31	1	100.00 ✓	100.00
3. T52614-48040 ZSU60 AVU65	FRT BUMPER SPONGE	U1 I.2-A14	1	40.00 ✓	40.00
4. T81210-48050 ZSU60 AVU65	FOG LAMP RH	U1 I.2-E1	1	115.00 ✓	115.00
5. T81431-48190 ZSU60 AVU65	FOG LAMP COVER RH	U1 I.2-D5-G	1	40.00 ✓	40.00
6. T53205-48030 ZSU60 AVU65	RAD SUPPORT PANEL	U1 I.1-D9	1	320.00 ✓	320.00
7. T52618-48010 ZSU60 AVU65	FRT BUMPER LWR GARNISH	U1 I.2-A13	1	65.00 ✓	65.00
8. T53301-48170 ZSU60 AVU65	FRT BONNET	U1 SUPPLIER	1	530.00 ✓	530.00
9. T53101-48720/2 ZSU60	RAD GRILLE (PREMIUM)	U1 SUPPLIER	1	200.00 ✓	200.00
10. T52119-48C60-C1 ZSU60	FRT BUMPER	U1 SUPPLIER	1	530.00 ✓	530.00
11. T53875-48120 ZSU60 AVU65	FRT FENDER LINER RH	U1 SUPPLIER	1	155.00 ✓	155.00
12. T53289-48020 ZSU60 AVU65	SUPPORT TOP GARNISH	U1 SUPPLIER	1	135.00 ✓	135.00

Page 4

CONTINUE NEXT PAGE
ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)
WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 8029



Wiper blade: NWD (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-16612
DATE : 28/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5889C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR. : SGD

SQ STOCKID	DESCRIPTION	StrLoc	QTY	UPRICE	AMOUNT
------------	-------------	--------	-----	--------	--------

SUB-TOTAL : 2,280.00
ADD GST 7.00 % 159.60

E & O E TOTAL AMOUNT SGD : 2,439.60

[P] 28/11/2017 3:55:23PM


[E] 28/11/2017 3:17:13PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



* AR201711-16612 *

Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WIPERBLADES
Dept Direct: 6417 9701 / 6745 6836



Dept Direct: 6305 8610

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9755

Dept Direct: 6417 9795

Dept Direct: 6417 9793

Wiper blade: NWD (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-16705
DATE : 28/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5889C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	SKLoc	QTY	U/PRICE	AMOUNT
1	T52555-48040 ZSU60 AVU65	FRT BUMPER S/RETAINER RH	U1 SUPPLIER	1	38.00	38.00
2	T52536-48030 ZSU60 AVU65	FRT BUMPER S/RETAINER LH	U1 SUPPLIER	1	38.00	38.00

Handwritten signature/initials

SUB-TOTAL : 76.00
ADD GST 7.00 % 5.32

E & O.E TOTAL AMOUNT SGD : 81.32

[P] 28/11/2017 4:23:23PM

[E] 28/11/2017 4:22:57PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



AR201711-16705

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Handwritten signature



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WIPACER GLASS
Dept Direct: 6417 9781 / 6745 9030



Dept Direct: 6305 9010

Dept Direct: 6305 9011

Dept Direct: 6417 9782



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9786

Dept Direct: 6417 9703

Wiper blade: NWD (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-16770
DATE : 28/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5889C
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1. T52021-48040	FRY BUMPER REINFORCEMENT U1		1	145.00	145.00
ZSU60					

SUPPLIER

JAFAN

READY ✓

Page 2

SUB-TOTAL : 145.00
ADD GST 7.00 % 10.15

E & O.E TOTAL AMOUNT SGD : 155.15

[F] 28/11/2017 5:31:24PM


[E] 28/11/2017 5:30:51PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



* AR201711-16770 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received In Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPAC
Dept Direct: 6417 9791 / 6745 9330

Arrange By

Driver

MLC



Dept Direct: 6305 9010

Dept Direct: 8305 9011

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWS (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201711-16606
DATE : 28/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5889C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 3
CURR : SGD

SQ STOCKID

1. T75770-48030

ZSU60 AVU65

2. T52161-16010ROC

ALL MODEL

3. T52611-48170

ZSU60 AVU65

4. T52612-48030

ZSU60 AVU65

5. T53285-48020-CU

ZSU60 AVU65

6. T52411-48020

ZSU60 AVU65

7. T16691-37010

ZSU60

DESCRIPTION

FRT BONET MLDG

BUMPER CLIP

FRT BUMPER SPONGE RH

FRT BUMPER SPONGE LH

FRT BUMPER HOLE COVER RH

FRT BUMPER LWR GUARD

RAD SUPPORT GARNISH RH (SMALL)

StkLoc

PA

PL2-A1-231

PA

PL2-N1-04A

PA

PL2-Q1-08B

PA

PL2-Q1-08A

PA

PL2-A1-203

PA

PL2-E1-01S

PA

PL2-N1-09A

QTY

1

8

1

1

1

1

1

U/PRICE

90.00

1.00

18.00

18.00

12.00

100.00

20.00

AMOUNT

90.00

8.00

18.00

18.00

12.00

100.00

20.00

CONTINUE NEXT PAGE

[P] 28/11/2017 3:38:05PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 28/11/2017 3:1337PM

Pass page



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9038



Dept Direct: 6305 6610

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201711-16606
DATE : 28/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5889C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 3
CURR : SGD

NO	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
8.	T16693-36010 ZSU60 AVU65	SUPPORT AIR GUIDE RH (BIG)	PA PL2-Q1-08B	1	45.00	45.00
9.	T16697-36010 ZSU60 AVU65	SUPPORT AIR GUIDE LH (BIG)	PA PL2-Q1-07B	1	45.00	45.00
10.	T52537-48010/20 ZSU60 AVU65	FRT BUMPER TOP BEAM RH	PA PL2-F1-06B	1	65.00	65.00
11.	T52538-48010/20 ZSU60 AVU65	FRT BUMPER TOP BEAM LH	PA PL2-H1-05B	1	65.00	65.00
12.	T90467-07217	CLIP	PA PL2-K1-06I	12	1.50	18.00
13.	T53208-48090 ZSU60 AVU65	BRACE PANEL	PA PL2-F1-06B	1	75.00	75.00
14.	T53812-48190 ZSU60 AVU65	FRT FENDER LH	PA PL2-C1-12B	1	290.00	290.00

CONTINUE NEXT PAGE

[P] 28/11/2017 3:38:05PM

[E] 28/11/2017 3:13:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDO GREEN GLASS
Dept Direct: 6417 9791 / 9745 9939



Dept Direct: 6303 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201711-16606
DATE : 28/11/2017
CUSTOMER ID : AHL008
VEH REG. NO. : SKZ5889C
TERMS : 30 days
PO NO. :
PAGE NO. : Page 3 of 3
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
15. T53811-48210 ZSU60 AVU65	FRT FENDER RH	PA PL2-B1-06B	1	290.00	290.00
16. T90467-07166 JB33/ACV30/31R	CLIP FOR SHIELD	PA PL2-K1-06J	20	1.50	30.00
17. T53866-48070 ZSU60 AVU65	WIPER GARNISH S/COVER RH	PA PL2-J1-03E	1	20.00	20.00
18. T88706-48010 ZSU60	LIQUID PIPE ASSY	PA PL2-J1-04S	1	200.00	200.00
19. T81110-48440 ZSU60 AVU65	HEAD LAMP RH ASSY	PA NEW	1	900.00	900.00
20. T81150-48890 ZSU60 AVU65	HEAD LAMP LH ASSY	PA NEW	1	900.00	900.00
21. T53112-48150 ZSU60 AVU65	FRT BUMPER LWR GRILLE	PA NEW	1	85.00	85.00

SUB-TOTAL : 3,294.00
ADD GST 7.00 % 230.58

E & OE

TOTAL AMOUNT SGD: 3,524.58

[P] 28/11/2017 3:38:05PM

[E] 28/11/2017 3:13:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN

This is computer generated document.
No signature is required.



* A R 2 0 1 7 1 1 1 6 6 0 6 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 February 2018 9:32 AM
To: Mei Kwan (LKKAUTO); muihong@ahlimmotor.com.sg; Guo Qiang (LKKAUTO)
Cc: Admin A; SUR
Subject: RE: Draft Finalisation - SKZ5889C - S7M004R9 *** LKK REF: CS/AXA17022501/Gvb

Dear Mui Hong,

Confirmed finalize amount \$7423 before excess \$500

No of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 6 February 2018 8:58 AM
To: muihong@ahlimmotor.com.sg; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Draft Finalisation - SKZ5889C - S7M004R9 *** LKK REF: CS/AXA17022501/Gvb

Dear Mui Hong,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/AXA17022501/Gvb	Veron

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg [mailto:muihong@ahlimmotor.com.sg]
Sent: Monday, 5 February, 2018 3:03 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Admin-B <admin-b@lkkauto.com>; Admin A <admin-a@lkkauto.com>

a@lkkauto.com>

Subject: Draft Finalisation - SKZ5889C - S7M004R9

Dear Guo Qiang,

Pls see attached the Draft Finalisation – SKZ5889C for your approval.

Pls request your admin to return assessment for us to key in the supplementary parts. Pls do drop us an email to inform when assessment is returned.

Pls advise.

Thanks !

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170