

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Flossie Ang

Date: 27 Nov 2017

Preliminary Advice

Insured Vehicle No : GR2925R

TP Vehicle No : SJG8741L

Make : SUBARU LEGACY

Date of Inspection : 27/11/2017

Inspection At : Tan Lim Motor Pte Ltd (Defu)
51 Defu Lane 10
Singapore 539216

Accident Date : 22/11/2017

Assignment Date : 23/11/2017

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,885.10
Revised Amount	:S\$	2,750.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,750.00
Lump Sum Repair	:S\$	2,750.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.