

INS. CASE OWNER

Kiao Chuan

CC 4 / AIG170 22518

LKK

IDAC

Surveyor:

Sebastian

DOI

22/11/17

Date / Time:

27/11/17

Registered in Merimen:

27/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKK 30355

Name of Insured:

TEH KA HAK

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

23/10/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

163958040059

Policy No.:

2100371165

Make / Model:

VOLVO (3.0-2.0 C1)

Place of Accident:

JIN OF CLEMENTE RD & ULU PANDAN RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SGR 95200



INSRS:

WSP: long sheng

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

28/11/17 (HT)

SGR 95200 - X ; SKK 30355 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

28/11/17 11/11/17

After call ltr to OI:

28/11/17 11/11/17

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

8/12/17

EC instruction: Ask tp to finalise the claim & submit Ltr. Then we will offer 80% & 15% basis.

9/1/18

File pass to Mei Kuan to close

RECEIVED 9 JAN 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:		Confirm with:		Confirm by:	
Repair Cost:		\$S	() days	Reduction:		%		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:	Confirm with:		Email:		Call:	
Final Liability:		%	(Agreed / Assessed) BOLA S/N No.:		NIL		IFMO or B 28, Ass. Lia:	
Repair Cost:		8350 @ 90%	\$S 7515.00					
Loss of Rental (LOR):		\$S	() days					
Loss of Use (LOU):		\$S 675.00	(50 x 15 days)					
Loss of Income (LOI):		\$S	(5 x days)					
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>		LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		(Tick only one)				
GIA/LTA Search		\$S						
Medical:		\$S						
Disbursement:		\$S	(e.g. Tow/ Independent)					
Legal Cost		\$S						
Total:		\$S 8190.00	Global Sum \$S:		8000.00			
FINAL PAYMENT		Date/Time:	Confirm with:		Email:		Call:	
Payee 1:		\$S 8000.00	Name 1:		Long Sheng Motor Service			
Payee 2: (Strike if N.A.)		\$S	Name 2:					
Payee 3: (Strike if N.A.)		\$S	Name 3:					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17022518/Spa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-11-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKK 3035S	Veh. Inspected	SGR 9520D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/10/2017	Inspection Date	27/11/2017
Survey held at	LONG SHENG MOTOR SERVICE BLK 6, NO. 399-G, WOODLANDS RD YEW TEE IND. ESTATE SINGAPORE 678007.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nett #83W

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	1211I
Vehicle Details	
Vehicle No.	SGR9520D
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	HONDA
Vehicle Model	JAZZ 1.4A
Primary Colour	Blue
Manufacturing Year	2006
Engine No.	L13A54000891
Chassis No.	JHMGD18507S208074
Maximum Power Output	60.0 kW (80 bhp)
Open Market Value	\$14,312.00
Original Registration Date	27 Feb 2007
First Registration Date	27 Feb 2007
Transfer Count	0
Actual ARF Paid	\$15,744.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	26 Feb 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$25,197.00
COE Rebate Amount	\$21,428.00
Total Rebate Amount	\$21,428.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Nov 2017

1576 RE: 832
9w
9w
C: 832
W
= 832

Username / Email Add
password
Connect Sign Up New Account
Forgot Password

HONDA JAZZ Price Range Depreciation 2007 Vehicle Type

Advanced Search

Home » Used Cars » Platinum Auto » Honda Jazz 1.3A (COE till 02/2022)

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Rental



Honda Jazz 1.3A (COE till 02/2022)

Overview Financial Accessories Similar Research Photos Map

CONSIGNMENT

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$29,800	
Depreciation	\$7,070 /yr View models with similar depreciation	?
Reg Date	14-Feb-2007 (4yrs 2mths 16days COE left)	
Manufactured	2007	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,339 cc	
Road Tax	\$590 /yr	?
Power	60.0 kW (80 bhp) View specs of the Honda Jazz (2002-2006)	?
Curb Weight	1,040 kg	?
Features	Powerful 1.4 I-VTEC Engine, ABS, 2 x Airbag, 5 Speed Auto Transmission, Electric Retractable Side Mirror.	
Accessories	Leather Seats, Sports Rim, Factory Fitted Audio System, Reverse Sensors.	
Description	100% Accident Free, Looking For Affordable Japan Car, Honda Jazz Is The Best Choice, Very Low Depreciation Per Day Only \$18, Everyone Can Afford To Own This Car, Cheaper Than Rent A Car, Bank And In House Loan Available, Fast And Easy Approval, Excellent Condition, Well Kept By Previous Owner, Call Us Now For Viewing, Trade In Welcome.	
COE	\$25,197	?
OMV	\$13,874	?
ARF	\$13,344	?
Dereg Value	\$21,235 as of today (change)	?
No. of Owners	2	?
Type of Veh	Hatchback	
Category	COE Car, Consignment Car	
Availability	Available	CONSIGNMENT

Add to Shortlist Add to Compare Add a Note

Posted on: 25-Nov-2017 | Last Updated on: 25-Nov-2017

Tags: Honda Jazz, Honda Jazz, 2007 Honda Jazz, 2007 Honda Jazz, Honda, Jazz, Jazz, Used Honda

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- List of owner consignment cars
- List of consignment agents



Seller Information

Company	Platinum Auto » dealer's pricelist » 32 vehs sold 57 vehs available
Address	8 Kaki Bukit Avenue 4 #04-06 Search cars nearby this location
Location	Premier @ Kaki Bukit
Office No	63864184
Contact Person(s)	Richard 98173682

Useful Services

STA Make sure of this car condition with STA Evaluation.
Vehicle Evaluation

Free Valuation Find out the market value for your car. Get a free Car Valuation.

Upfront Payment

» more financial info

Transfer Fee	\$11	?
Down Payment	\$8,940 (change)	Maximum 70% Loan ?

龙胜汽车服务

LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Date: 25.11.2017

Page 1/3

Owner: Chua Kok Khuan

Attention: AIG Asia Pacific Insurance Pte.Ltd

RE: Accident to vehicle SGR 9520D - Honda Jazz 1.4 Auto (2006) on 23.10.2017

Estimated cost of repair of the above mentioned vehicle.

Replacement Parts:-

1pcs	Bonnet ✓ PUN	\$	561.90 ✓
2pcs	Bonnet Rubber @ 17.50 ✓ NEC.	\$	35.00 ✓
2pcs	Bonnet Hinge @ 39.10 ✓ BT	\$	78.20 ✓
1pcs	Bonnet Lock ✓ BT	\$	95.10 ✓
1pcs	Front Wiper Garnish ? X NN	\$	235.80 X
2pcs	Front Wiper Side Garnish @ 41.60 ? X NN	\$	83.20 X
2pcs	Headlamp Assy L/R @ 794.60 ✓ CRK.	\$	1,589.20 ✓
2pcs	Headlamp Lower Beam L/R @ 112.30 ✓ MS	\$	224.60 ✓
2pcs	Front Fender L/R @ 429.10 ✓ Defam.	\$	858.20 ✓
2pcs	Front Fender Inner Panel L/R @ 419.60 ✓ BT	\$	839.20 ✓
2pcs	Front Fender Inner Garnish L/R @ 96.30 ✓ Defam.	\$	192.60 ✓
1pcs	Front Bumper Assy ✓ MS	\$	627.60 ✓
2pcs	Front Bumper Side Retainer L/R @ 31.90 ✓ MS	\$	63.80 ✓
1pcs	Front Bumper Reinforcement ✓ BT	\$	281.90 ✓
1pcs	Front Bumper Lower Grille ✓ MS	\$	121.90 ✓
2pcs	Front Bumper Fog Lamp L/R @ 327.60 ✓ MS	\$	655.20 ✓
1pcs	Towing Cover ✓ MS	\$	23.90 ✓
1pcs	Front Support Panel ✓ BT	\$	510.10 ✓
1pcs	Front Grille ✓ MS	\$	169.70 ✓
1pcs	Front Grille Emblem ✓ MS	\$	33.10 ✓
1pcs	Rear Door RH ✓ BT.	\$	797.10 ✓
2pcs	Rear Door Hinges R/H @ 96.30 ? X NN	\$	192.60 X
1pcs	Rear Door Glass Outer Moulding RH ✓ NEC	\$	85.70 ✓
1pcs	Rear Door Outer Handle RH X NN	\$	81.20 X
1pcs	Rear Door Rubber RH ✓ NEC	\$	135.90 ✓
1pcs	Rear Door Frame Sticker RH ✓ NEC.	\$	98.30 ✓
1pcs	Front Door RH ✓ BT	\$	897.10 ✓
2pcs	Front Door Hinges RH @ 96.30 ✓ BT	\$	192.60 ✓
1pcs	Front Door Glass Outer Moulding RH ✓ NEC.	\$	85.70 ✓
1pcs	Front Door Inner Trim Board RH ? X NN	\$	498.20 X
1pcs	Front Door Inner Lock RH ? X NN	\$	261.70 X
1pcs	Front Door Frame Sticker RH ✓ NEC	\$	98.30 ✓
1pcs	Front Door Outer Handle RH X NN	\$	81.20 X
1pcs	Front Door Gear Regulator RH ? X NN	\$	373.10 X
3pcs	Alloy Rim (Rear & Front) @ 391.60 cut	\$	1,174.80 391.60
1pcs	A.B.S Pump ✓ CRK.	\$	1,819.10 ✓
		\$	14,152.80

龙胜汽车服务

LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Page 2/3

SGR 9520D

<u>B/Balance</u>		\$	14,152.80
1pcs	Front Door Rubber RH ✓ NEC	\$	135.90 ✓
1pcs	Front Windscreen Pillar RH R	\$	619.70 X
1pcs	Front Windscreen Pillar Garnish RH ? X NN	\$	162.90 X
1pcs	Rear Fender RH ✓ DT	\$	719.60 ✓
1pcs	Rear Bumper R	\$	476.10 X
2pcs	Rear Bumper Side Retainer L/R @ 31.90 ? X NN	\$	63.80 X
10pcs	Rear Bumper Clip @ 3.80 ✓ NEC	\$	38.00 ✓
2pcs	Side Under Spoiler L/R @ 316.70 ✓ Deform	\$	633.40 ✓
1pcs	Air-Con Condenser ? X	\$	516.60 X
1pcs	Air-Con Pipe ? X	\$	309.10 X
1pcs	Air-Con Hose ? X	\$	381.60 X
1pcs	Radiator Assembly	\$	988.30 ✓
1pcs	Engine Mounting - Frt ? X	\$	367.30 X
1pcs	Engine Mounting - LH ? X	\$	489.10 ✓
1pcs	Engine Mounting - RH ? X	\$	531.90 ✓
2pcs	Front Shock Absorber L/R @ 387.40 ? X	\$	774.80 X
2pcs	Front Shock Absorber Mounting L/R @ 103.70 ? X	\$	207.40 X
2pcs	Front Lower Arm L/R @ 382.50 ? X	\$	765.00 X
1pcs	Engine Cross Member ? X	\$	833.90 X
1pcs	Front Stabiliser Bar ? X	\$	321.70 X
2pcs	Front Stabiliser Linkage L/R @ 93.10 ? X	\$	186.20 X
2pcs	Front Kunkle Arm L/R @ 391.70 ? X	\$	783.40 X
2pcs	Front Kunkle Bearing L/R @ 329.10 ? X	\$	658.20 ✓
1pcs	Rear Shock Absorber RH ? X	\$	303.50 X
1pcs	Wiper Tank ✓ PWD	\$	179.30 ✓
1pcs		\$	25,599.50
	Less 20%	\$	(5,119.90)
		\$	20,479.60

龙胜汽车服务

LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Page 3/3

SGR 9520D

<u>B/Balance</u>		\$	20,479.60	
<u>Special Nett:</u>				
1pcs	Front Windscreen Sealant ✓ NEC	\$	80.00	40
1pcs	Radiator Coolant ✓ NEC	\$	60.00	50
1pcs	Front Number Plate ✓ MS	\$	60.00	40
		\$	200.00	
<u>ADD:</u>				
	Labour Charges	\$	1,850.00	1500
	Spray Painting	\$	1,850.00	1350
	To Check Wiring	\$	80.00	40
	Wheel Alignment	\$	120.00	80
	Anti Rust Treatment	\$	100.00	60
	To Remove & Transfer Both Door Fittings Proper Functions @ 80.00	\$	160.00	100
	To Remove & Refit Air-Con Condenser To Facilitate Repair	\$	120.00	80
	To Remove & Replace Both Front & Rear Suspension Components	\$	680.00	400
	To Carry Out Chassis Alignment & To Reset Setting	\$	250.00	200
		\$	5,210.00	

Total Amount : \$ 25,889.60

15 days.

Sebastian.
28/11/2017.

- Lump Sum Repair.
 - Question Mark Item Photo.
 - Photo After Paint
- 90036121

sebastianyang@hkauto.com

HK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 7 December, 2017 5:58 PM
To: 'LSMTYC'
Subject: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Your Ref: **SGR 9520D** Without Prejudice
Our Ref: CC4/AIG17022518/Spa3

Dear Sirs,

ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017

We refer to the above matter.

We attached here with a copy of our insured accident report for your easy reference. We have spoken to our insured and he mentioned that he was making a right turn with green arrow.

Brief Details.

On 23/10/2017 at 1530hrs I was driving my vehicle, V1 SKK3035S along Clementi road. Subsequently, I was waiting to turn into Ulu Pandan Road at the junction between Clementi road and Ulu Pandan road once there was the green arrow shown on the traffic light, the bus in front of me made a right turn into Pandan road and I followed behind the bus. As I was making the turn suddenly a vehicle, V2 SGF from the opposite lane hit onto my front portion of my vehicle, V1. I came out of my vehicle, made a first aid kit and helped the driver of V2 come out of his vehicle. Subsequently traffic police and ambulance arrived at the scene and both the driver and the passenger of V2 were conveyed by ambulance. Due to the accident, my vehicle, V1's front was badly damaged and V2's front was also damaged. I have an in-car camera in my vehicle and the traffic police took the memory card of the in-car camera so that he could view the accident. On 23/10/2017 at 1700hrs I went to Ng Teng Fong Hospital as I was having body pains and was admitted on the same day and was discharged on 24/10/2017. The doctor also gave me a Medical Certificate (MC).

We have also informed Ms Sim from your good office that we are reviewing the matter and will get back to you **by next week**.

Thank you for your patience and understanding in this matter.

Please call the undersigned if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 12 December, 2017 4:31 PM
To: 'LSMTYC'
Subject: RE: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Without Prejudice

Hi,

We refer to the above matter.

We propose settlement at a global sum of \$8,000.00(all-in).

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 7 December, 2017 5:59 PM
To: 'LSMTYC' <lsmstyc@singnet.com.sg>
Subject: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Your Ref: **SGR 9520D** Without Prejudice
Our Ref: CC4/AIG17022518/Spa3

Dear Sirs,

ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017

We refer to the above matter.

We attached here with a copy of our insured accident report for your easy reference. We have spoken to our insured and he mentioned that he was making a right turn with green arrow.

Brief Details.

On 23/10/2017 at 1530hrs I was driving my vehicle, V1 SKK3035S along Clementi road. Subsequently, I was waiting to turn into Ulu Pandan Road at the junction between Clementi road and Ulu Pandan Road once there was the green arrow shown on the traffic light, the bus in front of me made a right turn onto Ulu Pandan road and I followed behind the bus. As I was making the turn suddenly a vehicle, V2 SGF from the opposite lane hit onto my front portion of my vehicle, V1. I came out of my vehicle, made first aid and helped the driver of V2 come out of his vehicle. Subsequently traffic police and ambulance arrived at the scene and both the driver and the passenger of V2 were conveyed by ambulance. Due to the accident, my vehicle, V1's front was badly damaged and V2's front was also damaged. I have an in-car camera in my vehicle and the traffic police took the memory card of the in-car camera so that he could view the accident. On 23/10/2017 at 1700hrs I went to Ng Teng Fong Hospital as I was having body pains and was admitted on the same day and was discharged on 24/10/2017. The doctor also gave me a traffic accident report (MC).

We have also informed Ms Sim from your good office that we are reviewing the matter and will get back to you **by next week**.

Thank you for your patience and understanding in this matter.

Please call the undersigned if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: LSMTYC <lsmstyc@singnet.com.sg>
Sent: Wednesday, 27 December, 2017 10:37 AM
To: Hsiao Tong (LKKAUTO)
Subject: FW: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]
Attachments: 9c23c5d3-824a-420e-8a53-b5cc35241021.jpg; 79f58fbe-0ff2-4735-8dde-daec8638cf92.jpg; ab8ebdbd-867e-4a8e-975f-d7d851bac517.jpg; 3eaaeadeb-e96d-45f7-9feb-db988f6aaa48.jpg; 5ce57e97-5a31-47f9-9420-811e03c7e9d9.jpg; 8c81e4c2-046f-4855-984e-055a390c9654.jpg; 27122017100349.pdf

From: LSMTYC [mailto:lsmstyc@singnet.com.sg]
Sent: Wednesday, 27 December 2017 10:34 AM
To: 'LSMTYC' <lsmstyc@singnet.com.sg>
Subject: RE: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Dear Hsiao Tong ,

Please refer attachment of vehicle SGR9520D documents & after repair photo.
Kindly let us have your DV soonest. Thanks

Have a good days.....



*Best Regards,
Apple Sim*

*Long Sheng Motor Service
Blk 6 , No.399-G , Woodlands Road ,
Yew Tee Industrial Estate ,
Singapore 678007 .
Tel : +65 6763 9733
Fax: +65 6763 9866
Email : lsmstyc@singnet.com.sg*

From: LSMTYC [mailto:lsmstyc@singnet.com.sg]
Sent: Tuesday, 12 December 2017 4:39 PM
To: 'Hsiao Tong (LKKAUTO)' <chewht@lkkauto.com>
Subject: RE: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Dear Hsiao Tong ,

Refer to the above matter.

We acceptance your offer global sum of S\$ 8,000.00 (All in)

Have a good days.....



*Best Regards,
Apple Sim*

*Long Sheng Motor Service
Blk 6 , No.399-G , Woodlands Road ,
Yew Tee Industrial Estate ,
Singapore 678007 .
Tel : +65 6763 9733
Fax: +65 6763 9866
Email : lsmsstyc@singnet.com.sg*

From: Hsiao Tong (LKKAUTO) [<mailto:chewht@lkkauto.com>]

Sent: Tuesday, 12 December 2017 4:31 PM

To: LSMTYC <lsmsstyc@singnet.com.sg>

Subject: RE: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Without Prejudice

Hi,

We refer to the above matter.

We propose settlement at a global sum of \$8,000.00(all-in).

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 7 December, 2017 5:59 PM

To: 'LSMTYC' <lsmstyc@singnet.com.sg>

Subject: Your Ref: SGR 9520D *Our Ref: CC4/AIG17022518/Spa3 [ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017]

Your Ref: **SGR 9520D**

Without Prejudice

Our Ref: CC4/AIG17022518/Spa3

Dear Sirs,

ACCIDENT INVOLVING SKK 3035S(AIG) & SGR 9520D ON 23/10/2017

We refer to the above matter.

We attached here with a copy of our insured accident report for your easy reference. We have spoken to our insured and he mentioned that he was making a right turn with green arrow.

Brief Details.

On 23/10/2017 at 1530hrs I was driving my vehicle, V1 SKK3035S along Clementi road. Subsequently I was waiting to turn into Ulu Pandan Road at the junction between Clementi road and Ulu Pandan road once there was the green arrow shown on the traffic light, the bus in front of me made a right turn into Pandan road and I followed behind the bus. As I was making the turn suddenly a vehicle, V2 SGF from the opposite lane hit onto my front portion of my vehicle, V1. I came out of my vehicle, made a first aid and helped the driver of V2 come out of his vehicle. Subsequently traffic police and ambulance arrived at the scene and both the driver and the passenger of V2 were conveyed by ambulance. Due to the accident my vehicle, V1's front was badly damaged and V2's front was also damaged. I have an in-car camera in my vehicle and the traffic police took the memory card of the in-car camera so that he could view the accident. On 23/10/2017 at 1700hrs I went to Ng Teng Fong Hospital as I was having body pains and was admitted on the same day and was discharged on 24/10/2017. The doctor also gave me a traffic accident report (TAR).

We have also informed Ms Sim from your good office that we are reviewing the matter and will get back to you **by next week**.

Thank you for your patience and understanding in this matter.

Please call the undersigned if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007 (Reg.No: 52840117C)

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Our Ref : SGR 9520D

Page 1/2

Your Ref: CC4/AIG17022518/Spa3

Date : 27.12.2017

To : LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park
Ubi Avenue 1, #02-25 Singapore 408933

Attn : **Hsiao Tong, Chew**

Remark : **Third Party Claims (TPPD)**

Dear Sirs,

Accident Involving Vehicle No: SGR 9520D & SKK 3035S
Along Celeменти Road & Pandan Road Junction
On 23.10.2017 At 15.1 Hours

We act for Chua Kok Khuan, the owner of vehicle No. SGR 9520D was
involved in the above accident on 23.10.2017 where your insured's vehicle No.
SKK 3035S is the sole cause of the accident.

I/We hereby claim for loss damages and expenses suffered.
I/We append below our claim as follows ;

Costs Of Repair (All In)	S \$ 8,000.00
Loss Of Use	S -
Car Rental Fees	S -
Survey Report Fees	S -
Towing Fees	S -
L.T.A Search / Police Report Fees	S -
Document Disbursements / Liability Contribution	S -
Total	S \$ 8,000.00

SGD : **Eight Thousand Dollars Only.**

Kindly let us hear from you within fourteen (14) days from the date hereof , or alternatively, let us
have your full and final settlement of SGD **\$ 8,000.00** of our claim, failing which our
shall have to resort to legal actions to recover losses without further references to you .
In that event, we shall also be claiming for legal costs and interests due to us.

龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate
Singapore 678007 (Reg.No: 52840117C)
Tel: 67639733 Fax: 67639866
Email: lsmstyc@singnet.com.sg

Page 2/2

Our Ref : SGR 9520D
Your Ref: CC4/AIG17022518/Spa3

Date : 27.12.2017

To : LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park
Ubi Avenue 1, #02-25 Singapore 408933

Attn : Hsiao Tong, Chew

Remark : Third Party Claims (TPPD)

We enclose a copy of each of the following documents for your consideration :-

- | | |
|-------------------------------------|---|
| <input checked="" type="checkbox"/> | Breakdown of claim |
| <input type="checkbox"/> | A copy of motor registration card |
| <input type="checkbox"/> | A copy of insurance certificate & policy schedule |
| <input type="checkbox"/> | Copies of owner's I/C and driving licence |
| <input type="checkbox"/> | Copies of driver's I/C and driving licence |
| <input type="checkbox"/> | A copy of our insured police report |
| <input type="checkbox"/> | A copy of police sketch plan / police investigation result |
| <input type="checkbox"/> | Original adjuster report , photographs and receipt |
| <input checked="" type="checkbox"/> | Original Long Sheng Motor Service invoice No. 4098 |
| <input type="checkbox"/> | A copy your insured police report |
| <input type="checkbox"/> | Original our insured car rental agreement , invoice and receipt |
| <input checked="" type="checkbox"/> | Original authorisation letter and payment authorisation letter |
| <input type="checkbox"/> | A copy of our insured GIA report |
| <input type="checkbox"/> | A copy of our insured ARCA company |
| <input type="checkbox"/> | A copy of your insured I/C , driving licence , work permit , passport |
| <input type="checkbox"/> | A copy of your insured JPJ search |
| <input type="checkbox"/> | Original receipt for policy excess fee |
| <input type="checkbox"/> | A copy of your insured I-Search report |
| <input type="checkbox"/> | Our insured vehicle after repair photographs |
| <input type="checkbox"/> | Other revevant documents to substantiate our client's claim |

Please revert back as soon as possible.

Thanks a lot

Yours Faithfully



Name _____
Address _____

PAYMENT AUTHORISATION LETTER

Your ref:

Date: 27.12.2017

To,

AIQ Asia Pacific Insurance Pte. Ltd.

.....
.....
.....

Dear Sir/Madam,

RE: ACCIDENT ON 23.10.2017 BETWEEN VEHICLE NO SGR 9520 D
AND YOUR INSURED VEHICLE NO SKK 3035 D

I refer to the above matter, and wish to notify your good selves that I have taken possession of the said vehicle, and I am completely satisfied with the repairs undertaken by **LONG SHENG MOTOR SERVICE**. (Repairer)

Please kindly release payments due to directly to M/s **LONGSHENG MOTOR SERVICE**, Blk. 6, No.399-G, Woodlands Road, Yew Tee Industrial Estate, Singapore 678007.

Your cooperation on the above matter is much appreciated.

Thank You.

Yours faithfully,


.....
Name: Chua Kok Khuan
I/C No. S72012112
.....

c.c M/s Long Sheng Motor Service



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG17022518/pa3

04 DECEMBER 2017

THE KA HAK
BLK 286C TOH GUAN ROAD
#08-22
SINGAPORE 603286

Dear Sir/Madam,

ACCIDENT INVOLVING SKK 3035S & SGR 9520D ON 23/10/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SGR 9520D against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To: Long Sheng Motor Service
Singapore

RE: ACCIDENT INVOLVING VEHICLE NOS. SRR 9520 D + SKK 30355
ALONG/AT Celestenti Road + Pandan Road Junction
ON 23.10.2017 @ 15.10 Pm


I/We Chua Kok Huan (NRIC No. S7201241 I)
of Apt. B11, 651 Seng Guan Road #08-276 Singapore 670615
the owner of vehicle No. SRR 9520 D hereby authorise you to commence repair of the
said vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request, I/We hereby
authorise you to demand claim settle receive whatever amount settled/payable by the insurance company
and/or third party or to commence legal proceedings, if necessary, in my name, for the cost of repairs and
loss of use, etc and to you appointing any Solicitor to act for me in respect of the said accident/claim and all
and any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the
whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on
my/our behalf) shall accept this as my/our irrevocable authorization to pay the amount compensated direct
to you after deduction of their costs on Solicitor & Client basis. I/We undertake to co-operate fully with
you and my/our Solicitor appointed as my/our behalf without claiming my/our expenses or time losses or
incidental charges etc to see the claim to a successful conclusion. In the event the payment of the settlement
sum is made in my favour, I shall attend your workshop and give you a replacement cheque or cash (less
off the deposit, if any), within 14 days of being notified by you. If I/We fail to do the above, I shall be
liable to you for the sum of repair, legal costs and other costs/expenses incurred by you. I/We undertake to
ensure that my/our cheque shall be honoured upon presentation by you. In the event that my/our cheque is
dishonoured, for whatever reason, you may proceed to lodge a police complaint against me for this criminal
act and may proceed to sue me/us for this breach.

I/we undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the 3rd
party's insurance company communicate with me/us directly orally or in writing and I/we further undertake
not to accept any monies or offer settlement from the 3rd party's insurance without first communicating
with you and obtaining your consent.

In the event of any of the aforesaid breach, I/We shall have totally no deface to your action/claim against
me/us and I/We will have to bear your legal costs incurred on an indemnity basis for any legal action may
arise against me/us including your damages, expenses and other incidental charges.

My/Our Insurers is/are TOKIO MARINE Insurance Singapore Limited
Policy No MU 001209 Excess Expiry date

Dated this 24 day of Nov 20 17


Owner's Signature
Company stamp


Witness's signature
Name:

Interpreter's signature

Interpreted in English/Chinese/Malay

Name:

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, LONG SHENG MOTOR SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$8,000.00 (Global Sum) for vehicle no. SGR 9520D that was damaged pursuant to the accident which occurred on 23/10/2017 (date) along CLEMENTI ROAD & ULU PANDAN ROAD JUNCTION involving vehicle no/s SKK 3035S.

This is pursuant to the inspection conducted on 27/11/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHUA KOK KHUAN ("the third party claimant") of vehicle no. SGR 9520D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGR 9520D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 08 (day) of JAN (month) 2018 (year)



yuk

Signed by appointed surveyor

Long Sheng Motor Service
Blk 6, No. 399-G, Woodlands Road
Yew Tee Industrial Estate
Singapore 678007
Tel: 6783 9799 Fax: 6763 9866

Signed by "the workshop" (with chop)

龍勝汽車服務
LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate,
Singapore 678007

Tel: 6763 9733 Fax: 6763 9866
(Reg. No: 52840117C)

No. 4098

M/s. AIG Asia Pacific Insurance Pte.Ltd

Date: 27.12.2017

SGR 9520D - Honda Jazz 1.4 Auto (2006)

Global Sum

\$ 8,000.00

- Including cost of repair and loss of use.

\$ 8,000.00

SGD: Eight Thousand Dollar Only

* as per surveyor's recommendation *

TP Claim Against - SKK 30355
D.O.A : 23.10.2017

LONG SHENG MOTOR SERVICE



龍勝汽車服務 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate,
Singapore 678007

Tel: 6763 9733 Fax: 6763 9866

(Reg. No: 52840117C)

No. 4098

M/s. AIG Asia Pacific Insurance Pte Ltd

Date

27.12.2017

SGR 9520D - Honda Jazz 1.4 Auto (2006)

Cost of Repair (Global Sum)

\$ 8,000.00

\$ 8,000.00

SGD: Eight Thousand Dollar Only

* as per surveyor's recommendation *

TP Claim Against - SKK 3035S

D.O.A : 23.10.2017

LONG SHENG MOTOR SERVICE



.....

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017 Edit Reg		27 Nov 2017 00:00 Edit Adj Rpt	S\$8,350.00 Edit Estimates	S\$8,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TEH KA HAK, ID: S1790795F		
Main Claimant:	CHUA KOK KHUAN, ID: S72012111		
Vehicle Reg. No.:	SGR9520D	Date of Loss:	23/10/2017 00:00 - :59
Claim Type:	TP / 1639580400SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKK30355	Policy No. (Claimant):	MU001209
	Excess:		
Repairer:	Long Sheng Motor Service (HQ) 399G, 6 Woodlands Road,, Yew Tee Industrial, 678007 Woodlands - Tel: 6763 9733		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Chuan] Kian-Chuan.Chan@aig.com		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 06/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)































- AIG_SG (28/11/2017): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGR9520D (1639580400SG)
[SKK3035S]
TP
CHUA KOK KHUAN
Oct 23 2017 12:00AM
[TEH KA HAK]
Long Sheng Motor Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser <input type="button" value="v"/>		
Letters/Correspondences												1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown												Edit			
Photos/Images												3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
2	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
3	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
4	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
5	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
6	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
7	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
8	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
9	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
10	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
11	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
12	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
13	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
14	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
15	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
16	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
17	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
18	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
19	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
20	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
21	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
22	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
23	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
24	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
25	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
26	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
27	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
28	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
29	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
30	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
31	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			
32	08/01/18 09:19	General View												Load JPG <input checked="" type="checkbox"/>			

33	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
61	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
62	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
63	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
64	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
65	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
66	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
67	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
68	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
69	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
70	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
71	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
72	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
73	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
74	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
75	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
76	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
77	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
78	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
79	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
80	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
81	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
82	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>

83	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
84	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
85	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
86	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
87	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
88	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
89	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
90	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
91	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
92	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
93	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
94	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
95	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
96	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
97	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
98	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
99	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
100	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
101	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
102	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
103	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
104	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
105	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
106	08/01/18 09:19	General View	1	Load JPG	<input checked="" type="checkbox"/>
107	08/01/18 09:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
108	08/01/18 09:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
109	08/01/18 09:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
110	08/01/18 09:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
111	08/01/18 09:19	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation1 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 15:35	ACKNOWLEDGEMENT EMAIL TO AIG DD 25.11.2017	1	Load PDF	
2	27/11/17 15:35	EMAIL FROM AIG DD 24.11.2017	1	Load PDF	
3	28/11/17 16:36	TP GIA REPORT	1	Load PDF	
4	05/12/17 10:36	TP ESTIMATE- MARKED	1	Load PDF	
5	09/01/18 16:50	WORKSHOP INVOICE	1	Load PDF	
6	15/01/18 11:20	Release Voucher	1	Load PDF	
7	15/01/18 11:20	AUTHORISATION TO ACT FORM	1	Load PDF	
8	15/01/18 11:20	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	28/11/17 09:16	OI GIA report	1	Load PDF	

Documents Checklist**DOCUMENTS CHECKLIST**

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK3035S (Insd veh)	Model:	HONDA JAZZ 1.4 (A)
	SGR9520D (TP veh)		
Date of Accident:	23/10/2017		

Global Sum Settlement	: <input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No
Repair Estimate	: \$	25,889.60
Final Repair Cost	: \$	8,000.00
Loss of Use	: \$	15.00 days at \$50.00 per day
Rental (if any)	: \$	days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (Global Sum)	: \$	8,000.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 90 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Long Sheng Motor Service	: \$	8,000.00
2)		: \$	

JOANNE LEE KHANG MIN

15 Jan
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022518/SPA3Q2

Date: 15/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: SGR9520D

Insured Vehicle No: SKK3035S

Date of Loss: 23/10/2017

Nature of Claim: TP

Claim No: 1639580400SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGR9520D

Make & Model: HONDA JAZZ, 1.4 (A)

Engine No: L13A54000891

Reg. Date: 27/02/2007 (Man. Year: 2006)

Chassis No: JHMGD18507S208074

Colour: Blue

Odometer: 187811 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,679.60	10,745.04	9,934.56	48.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	3,810.00	1,400.00	26.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,889.60	14,555.04	11,334.56	43.78
Approved Total (Overridden) (S\$)		8,350.00		
Nett Amount (S\$)	25,889.60	8,350.00	17,539.60	67.75
+ Loss of Use (15.0 x S\$50.00/day) (S\$)		750.00		
		(S\$) 9,100.00		
Liabile Amount (90.00%) (S\$)		8,190.00		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

Long Sheng Motor Service (HQ)
399G, 6 Woodlands Road., Yew Tee
Industrial
Singapore 678007

Estimated Period of Repair: 15.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Punctured	561.90 FL	*561.90 FL
2	2		*BONNET RUBBER	Necessary	35.00 FL	*35.00 FL
3	2		*BONNET HINGE	Bent	78.20 FL	*78.20 FL
4	1		*BONNET LOCK	Bent	95.10 FL	*95.10 FL
5	1		*FRONT WIPER GARNISH	Not Necessary	235.80 FL	*- FL
6	2		*FRONT WIPER SIDE GARNISH	Not Necessary	83.20 FL	*- FL
7	2		*HEADLAMP ASSY L/R	Cracked	1,589.20 FL	*1,589.20 FL
8	2		*HEADLAMP LOWER BEAM L/R	Missing	224.60 FL	*224.60 FL
9	2		*FRONT FENDER L/R	Deformed	858.20 FL	*858.20 FL
10	2		*FRONT FENDER INNER PANEL L/R	Bent	839.20 FL	*839.20 FL
11	2		*FRONT FENDER INNER GARNISH L/R	Deformed	192.60 FL	*192.60 FL
12	1		*FRONT BUMPER ASSY	Missing	627.60 FL	*627.60 FL
13	2		*FRONT BUMPER SIDE RETAINER L/R	Missing	63.80 FL	*63.80 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	281.90 FL	*281.90 FL
15	1		*FRONT BUMPER LOWER GRILLE	Missing	121.90 FL	*121.90 FL
16	2		*FRONT BUMPER FOG LAMP L/R	Missing	655.20 FL	*655.20 FL
17	1		*TOWING COVER	Missing	23.90 FL	*23.90 FL
18	1		*FRONT SUPPORT PANEL	Bent	510.10 FL	*510.10 FL
19	1		*FRONT GRILLE	Missing	169.70 FL	*169.70 FL
20	1		*FRONT GRILLE EMBLEM	Missing	33.10 FL	*33.10 FL
21	1		*REAR DOOR RH	Bent	797.10 FL	*797.10 FL
22	2		*REAR DOOR HINGES R/H	Not Necessary	192.60 FL	*- FL
23	1		*REAR DOOR GLASS OUTER MOULDING RH	Necessary	85.70 FL	*85.70 FL
24	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	81.20 FL	*- FL
25	1		*REAR DOOR RUBBER RH	Necessary	135.90 FL	*135.90 FL
26	1		*REAR DOOR FRAME STICKER RH	Necessary	98.30 FL	*98.30 FL
27	1		*FRONT DOOR RH	Dented	897.10 FL	*897.10 FL
28	2		*FRONT DOOR HINGE RH	Bent	192.60 FL	*192.60 FL
29	1		*FRONT DOOR GLASS OUTER MOULDING RH	Necessary	85.70 FL	*85.70 FL
30	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	498.20 FL	*- FL
31	1		*FRONT DOOR INNER LOCK RH	Not Necessary	261.70 FL	*- FL
32	1		*FRONT DOOR FRAME STICKER RH	Necessary	98.30 FL	*98.30 FL
33	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	81.20 FL	*- FL
34	1		*FRONT DOOR GEAR REGULATOR RH	Not Necessary	373.10 FL	*- FL
35	1		*ALLOY RIM (REAR & FRONT) (3 PCS)	Cut (1 PCS ONLY)	1,174.80 FL	*391.60 FL
36	1		*A.B.S PUMP	Cracked	1,819.10 FL	*1,819.10 FL
37	1		*FRONT DOOR RUBBER RH	Necessary	135.90 FL	*135.90 FL
38	1		*FRONT WINDSCREEN PILLAR RH	Repair	619.70 FL	*- FL
39	1		*FRONT WINDSCREEN PILLAR GARNISH RH	Not Necessary	162.90 FL	*- FL
40	1		*REAR FENDER RH	Dented	719.60 FL	*719.60 FL
41	1		*REAR BUMPER	Repair	476.10 FL	*- FL
42	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	63.80 FL	*- FL
43	10		*REAR BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
44	2		*SIDE UNDER SPOILER L/R	Deformed	633.40 FL	*633.40 FL
45	1		*AIR-CON CONDENSER	Not Necessary	516.60 FL	*- FL
46	1		*AIR-CON PIPE	Not Necessary	309.10 FL	*- FL
47	1		*AIR-CON HOSE	Not Necessary	381.60 FL	*- FL
48	1		*RADIATOR ASSEMBLY	Not Necessary	988.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*ENGINE MOUNTING -FRT	Not Necessary	367.30 FL	*- FL
50	1		*ENGINE MOUNTING -LH	Not Necessary	489.10 FL	*- FL
51	1		*ENGINE MOUNTING -RH	Not Necessary	531.90 FL	*- FL
52	2		*FRONT SHOCK ABSORBER L/R	Not Necessary	774.80 FL	*- FL
53	2		*FRONT SHOCK ABSORBER MOUNTING L/R	Not Necessary	207.40 FL	*- FL
54	2		*FRONT LOWER ARM L/R	Not Necessary	765.00 FL	*- FL
55	1		*ENGINE CROSS MEMBER	Not Necessary	833.90 FL	*- FL
56	1		*FRONT STABILIZER BAR	Not Necessary	321.70 FL	*- FL
57	2		*FRONT STABILIZER LINKAGE L/R	Not Necessary	186.20 FL	*- FL
58	2		*FRONT KNUCKLE ARM L/R	Not Necessary	783.40 FL	*- FL
59	2		*FRONT KNUCKLE BEARING L/R	Not Necessary	658.20 FL	*- FL
60	1		*REAR SHOCK ABSORBER RH	Not Necessary	303.50 FL	*- FL
61	1		*WIPER TANK	Punctured	179.30 FL	*179.30 FL
62	1		*FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
63	1		*RADIATOR COOLANT	Necessary	60.00 FS	*50.00 FS
64	1		*FRONT NUMBER PLATE	Missing	60.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	25,799.50	13,398.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,119.90	2,653.76

Total Parts (\$\$)	20,679.60	10,745.04
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	1,850.00	1,500.00
2	SPRAY PAINTING	New	1,850.00	1,350.00
3	TO CHECK WIRING	New	80.00	40.00
4	WHEEL ALIGNMENT	New	120.00	80.00
5	ANTI RUST TREATMENT	New	100.00	60.00
6	TO REMOVE & TRANSFER BOTH DOOR FITTINGS PROPER FUNCTIONS	New	160.00	100.00
7	TO REMOVE & REFIT AIR-CON CONDENSER TO FACILITATE REPAIR	New	120.00	80.00
8	TO REMOVE & REPLACE BOTH FRONT & REAR SUSPENSION COMPONENTS	New	680.00	400.00
9	TO CARRY OUT CHASSIS ALIGNMENT & TO RESET SETTING	New	250.00	200.00
Gross Labour Cost (S\$)			5,210.00	3,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >