

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

24 NOV 2017

Estimate No. : b1 44958
Date Estimated : 24/11/2017
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Yu Yah Leng (Yu YaLin)
103 Ah Hood Road
#09-08

Singapore 320103

- ACCOUNT - 163385

FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA2749M	D829183	26/02/2016	520ia	0

DESCRIPTION**VALUE**

To replace front bumper, front left fender including attachments etc and to knock out dented area caused by accident

1700 2,550.00

To paint front bumper and front left fender

1730 1,923.00

To replace left or right headlight including program and conduct tests for proper function.

451 531.00

To remove old FDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

7 150.00

Total Labour 1: **5,626.00****DESCRIPTION****QTY****PRIC****VALUE**

FRT LH 2 SIDE PANEL BRACKET ?

1

31.35

31.35

FRT LH 3 SIDE PANEL BRACKET ?

1

31.35

31.35

FRT LH 4 SIDE PANEL BRACKET ?

1

31.35

31.35

FRT LH 1 SIDE PANEL BRACKET ?

1

67.45

67.45

FRT LH FENDER b1

1

842.30

842.30

FRT LH BOTTOM DEFORMATION ELEMENT ?

1

99.25

99.25

FRT BUMPER CARRIER ?

1

668.10

668.10

FRT BUMPER BOTTOM MOUNT ?

1

153.65

153.65

FRT BUMPER LH SPACER na

1

9.20

9.20

GRILLE AIR INLET MIDDLE ?

1

80.65

80.65

LH GRILLE AIR INLET PARTLY CLOSED cut

1

74.25

74.25

SHOCK ABSORBER FRONT ?

1

46.80

46.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44958
Date Estimated : 24/11/2017
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA2749M	D829183	26/02/2016	520ia	0

DESCRIPTION

FRT BUMPER LH PROTECTIVE RUBBER STR *de*
FRT BUMPER PANEL PRIMED (PDC) *de*
COVERING PRIMEND LH *ne*
EMBLEM GROMMET *ne*
BMW EMBLEM *ne*
LH BI XENON HEADLIGHT *no*
DECOUPLING RING PDC TORQUE CONVERTE *ne*

QTY	PRIC	VALUE
1	21.75	21.75
1	1,246.40	1,246.40
1	39.10	39.10
2	0.80	1.60
1	67.80	67.80
1	2,566.95	2,566.95
4	4.95	19.80

Total Parts : 6,099.10

Claims ☒ 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 27/11/17 09:16 Excess S\$ 800

Surveyor's Name Tan Jun Sign Tan Jun

Surveyor's Tel 9744874 Authorised Yes / No _____

Authorised Date 27/11/17 Time _____

RESURVEY PARTS PHOTO BY SURVEYOR ☒ Yes / No PML Yes / No _____

Surveyor's E-mail tanjun@shant.com

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,626.00
Parts	:	6,099.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	820.76
Grand Total	:	12,545.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **