

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Elite AM Pte Ltd/SKR3814Z/01/12/2017 10:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450516 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@paciflc.net.sg

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

WIPER BLADES
Dept Direct: 6417 9701 / 6415 9803



Dept Direct: 6306 9610

Dept Direct: 6306 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blades: NNB (Nippon Wiper blade), Sliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso NGK (Made in Japan)

TAX INVOICE : AR201711-16972
DATE : 29/11/2017
CUSTOMER ID : AXA001
VEH REG. NO. : SKR3814Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	JJ5908A108	LATCH.HOOD (2)	PA	1	40.00	40.00 ✓
2.	JJMR200300	CLIP.BUMPER (7)	PL3-N1-06B PA	10	2.00	20.00 ✓
3.	JJ6400F879	BRACKET.FR BUMPER LH	PL3-N1-02E PA	1	10.00	10.00 ✓
4.	JJ6400F880	BRACKET.FR BUMPER RH	PL3-P1-03C PA	1	10.00	10.00 ✓
5.	JJ6402A233	GRILLE.FR BUMPER	PL3-P1-03C PA	1	100.00	100.00 ✓
6.	JJ5256B523/5256C259	PANEL,H/LAMP SUPPORT,UPR LH	PL3-P1-010 PA	1	35.00	35.00 X
7.	JJ5256B524/5256C260	PANEL,H/LAMP SUPPORT,UPR RH	PL3-P1-08B PA	1	35.00	35.00 X
8.	JJ5256B516	PANEL,H/LAMP SUPPORT,LWR	PL3-P1-09B PA	1	55.00	55.00 X
9.	JJ6400G164	GARNISH,FR BUMPER RH	PL3-Q1-08B PA	1	16.00	16.00 X
10.	JJ6400G234	GARNISH,FR FOG LAMP,RH (3)	PL3-P1-04A PA	1	24.00	24.00 ✓
11.	JJMR288150	SUPPORT PANEL UPP GARNISH CLIPS (13)	PL3-N1-09A PA	9	2.00	18.00 ✓
12.	JJ7407A316	MOULDING,FR BUMPER RH (20) Bumper bracket	PL2-N1-04A PA PL3-P1-04A	1	55.00	55.00

CONTINUE NEXT PAGE
ORIGINAL

total: 84535

11/11/2017
9799 979 5772



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
AXA Tower #24-01

SINGAPORE 068811
TEL: 68804635(GARNET) FAX: 8804838
ATTN: GARNET

WINDSCREEN GLASS
Dept Direct: 6417 5191 / 6745 0608



Dept Direct: 6305 8610

Dept Direct: 6305 8611

Dept Direct: 6417 8792



Dept Direct: 6417 8784

Dept Direct: 6417 8793

Dept Direct: 6417 8796

Dept Direct: 6417 8793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-16972
DATE : 29/11/2017
CUSTOMER ID : AXA001
VEH REG. NO. : SKR3814Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
------------	-------------	--------	-----	---------	--------

SUB-TOTAL : 418.00

ADD GST 7.00 % 29.26

E. & O.E TOTAL AMOUNT SGD : 447.26

[P] 30/11/2017 2:54:25PM

[E] 29/11/2017 10:21:56AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HUAT



* AR201711-16972 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450516 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3, CO. REG. NO.: 188307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 8745 9838



Wiper blade: NWB (Nippon Wiper blade), Silber (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-17022

DATE : 29/11/2017

CUSTOMER ID : AXA001

VEH REG. NO. : SKR3814Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 2

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	JJ5900A739	BONNET	SG	1	500.00	500.00 ✓
			C3-5			
2.	JJ5902A140	WEATHERSTRIP,HOOD	SG	1	70.00	70.00 ✓
			S3-1B			
3.	JJ8301C525	HEADLAMP UNIT LH(HID)	SG	1	520.00	520.00 ✓
			R3-2			
4.	JJ8301C526	HEADLAMP UNIT RH(HID)	SG	1	520.00	520.00 ✓
			Q3-10			
5.	JJ6400G281	FACE.FR BUMPER	SG	1	540.00	540.00 ✓
			H4-2			
6.	JJ5256B735/B515	PANEL,H/LAMP SUPPORT,UPR	SG	1	95.00	95.00 ✓
			L3-5B			
7.	JJ5215A423	PANEL,H/LAMP SUPPORT,LH	SG	1	30.00	30.00 ✗
			N3-1A			
8.	JJ5215A424	PANEL,H/LAMP SUPPORT,RH	SG	1	30.00	30.00 ✗
			K3-1A			
9.	JJ5220K649/H029	PANEL,H/LAMP SUPPORT,LWR	SG	1	80.00	80.00 ✗
		LH				
			O3-1A			
10.	JJ5220H030	PANEL,H/LAMP SUPPORT,LWR	SG	1	80.00	80.00 ✗
		RH				
			K3-1A			
11.	JJMR288150	SUPPORT PANEL UPP GARNISH	SG	1	2.00	2.00 ✓
		CLIPS				
			D3-1B			
12.	JJMU488006	BUMPER CLIPS	SG	10	2.00	20.00 ✓
			S3-5B			

CONTINUE NEXT PAGE

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3D18 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGAI KADUT AVE SINGAPORE 720672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO. M2-0119201-3 CO. REG. NO. 199307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way


AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

AMERICAN GLASS
Dept Direct: 6417 9791 / 6745 9629



Dept Direct: 6417 9791

Dept Direct: 6417 9791

Dept Direct: 6417 9791

Dept Direct: 6417 9791

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso NGK (Made in Japan)

TAX INVOICE : AR201711-17022

DATE : 29/11/2017

CUSTOMER ID : AXA001

VEH REG. NO. : SKR3814Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 2

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
----	---------	-------------	--------	-----	---------	--------

SUB-TOTAL : 2,487.00

ADD GST 7.00 % 174.09

E. & O.E TOTAL AMOUNT SGD : 2,661.09

[P] 30/11/2017 3:19:59PM

[E] 29/11/2017 10:42:28AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive HUAT



* AR201711-17022 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 723072

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL: 68804635 (GARNET) FAX: 8804838

ATTN: GARNET


W. A. SCHREINER GLASS
Dept Direct: 6417 9795 / 6745 9809



Dept Direct: 6305 9615

Dept Direct: 6305 9611

Dept Direct: 6417 9793



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-17624

DATE : 30/11/2017

CUSTOMER ID : AXA001

VEH REG. NO. : SKR3814Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. JJ7450A959	FRONT GRILLE & LOGO	SG N3-4	1	190.00	190.00 ✓
2. JJ6400F231/H568	REINFORCE, FR BUMPER	SG P3-5A	1	350.00	350.00 ✓
3. JJ7450A753	(14) COVER, HEADLAMP SUPPORT UPR support top cover	SG	1	25.00	25.00
4. JJ6405A194	(16) FRONT BUMPER WXTENSION lower 1.0 bumper (1.0 bumper)	K3-5B SG AA3-10	1	185.00	185.00 ✓
5. JJ1350A601	RADIATOR ASSY	SG R3-2	1	560.00	560.00 ✓
6. JJ7812A220	A/C CONDENSER ASSY	SG P3-12	1	450.00	450.00 ✓

SUB-TOTAL : 1,760.00
ADD GST 7.00 % 123.20

E. & O.E

TOTAL AMOUNT SGD : 1,883.20

[P] 02/12/2017 11:02:30AM

[E] 30/11/2017 9:12:39AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: EDWARD



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

WIPER BLADE
Dept Direct: 6417 8781 / 8742 9030



Dept Direct: 6417 8781

Dept Direct: 6417 8786

Dept Direct: 6417 8786

Dept Direct: 6417 8786

Wiper blade: NWB (Nippon Wiper blade), Super (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201711-17696
DATE : 30/11/2017
CUSTOMER ID : AXA001
VEH REG. NO. : SKR3814Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. JJMR597328	INSULATOR,RAD SUPPORT,UPR	MO	1	5.00	5.00

① tank bulber A
② 6A
radiator top moulding

SUB-TOTAL : 5.00
ADD GST 7.00 % 0.35

E. & O.E

TOTAL AMOUNT SGD : 5.35

[P] 02/12/2017 11:02:42AM

[E] 30/11/2017 9:58:24AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDWARD



* AR 201711-17696 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

WIPERBLADES
Dept Direct: 6417 9191 / 6745 9930



Dept Direct: 6417 9191

Dept Direct: 6417 9191

Dept Direct: 6417 9191

Dept Direct: 6417 9191

Wiper blade: NWB (Nippon Wiper blade), Siper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201712-00396

DATE : 01/12/2017

CUSTOMER ID : AXA001

VEH REG. NO. : SKR3814Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	JJMR597328	INSULATOR,RAD SUPPORT,UPR	MO	1	5.00	5.00
	CW5 CY2 CY4		2A25			

red cap
⑤
②②

SUB-TOTAL : 5.00
ADD GST 7.00 % 0.35

E. & O.E

TOTAL AMOUNT SGD : 5.35

[P] 02/12/2017 11:02:53AM

[E] 01/12/2017 12:29:23PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDWARD



* A R 2 0 1 7 1 2 - 0 0 3 9 6 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG NO: M2-01182013 CO-REG NO: 198307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

HINDSHELL 4-42
Dept Direct: 6417 8791 / 6745 9028

Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8797

Dept Direct: 6417 8798

Dept Direct: 6417 8799

Dept Direct: 6417 8800

Dept Direct: 6417 8801

Dept Direct: 6417 8802

Dept Direct: 6417 8803

Dept Direct: 6417 8804

Dept Direct: 6417 8805

Dept Direct: 6417 8806

Wiper blade: NWB (Nippon Wiper blade), Silver (Made in Korea)

Spark plug: Nippon Denso NGK (Made in Japan)

TAX INVOICE : AR201712-00398

DATE : 01/12/2017

CUSTOMER ID : AXA001

VEH REG. NO. : SKR3814Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. JJ6400G576	FR BUMPER TOP BEAM	PA	1	85.00	85.00 ✓
		PL3-P1-09B			
2. JJ6400D581	FR BUMPER INR BRACKET LH	PA	1	45.00	45.00 ✓
		PL3-P1-08B			
3. JJ6400D582	FR BUMPER INR BRACKET RH	PA	1	45.00	45.00 ✓
		PL3-P1-09B			
4. JJ6400D977	FR BUMPER INNER STAY	PA	2	15.00	30.00 ✓
		PL3-P1-07A			

SUB-TOTAL : 205.00
ADD GST 7.00 % 14.35

E. & O.E

TOTAL AMOUNT SGD : 219.35

[P] 07/12/2017 11:12:49AM

[E] 01/12/2017 12:30:29PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDWARD



* A R 2 0 1 7 1 2 - 0 0 3 9 8 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

AXA Tower #24-01

SINGAPORE 068811

TEL : 68804635(GARNET) FAX : 8804838

ATTN : GARNET

REFER AR201711-16972

WINDSHIELD GLASS
Dept Direct: 6417 8791 / 8746 9938



Dept Direct: 6305 9940

Arrange By

Driver



Dept Direct: 6417 8791

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct:

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

CREDIT NOTE : DC201712-00111

DATE : 04/12/2017

CUSTOMER ID : AXA001

VEH REG. NO. : SKR3814Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	JJ5256B523/5256C259	PANEL,H/LAMP SUPPORT,UPR LH	PA	-1	35.00	-35.00
2.	JJ5256B524/5256C260	PANEL,H/LAMP SUPPORT,UPR RH	PA	-1	35.00	-35.00
3.	JJ5256B516	PANEL,H/LAMP SUPPORT,LWR	PA	-1	55.00	-55.00

SUB-TOTAL : -125.00

ADD GST 7.00 % -8.75

E. & O.E

TOTAL AMOUNT SGD : -133.75

[P] 28/12/2017 10:33:03AM

[E] 04/12/2017 2:37:43PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HUAT



* D C 2 0 1 7 1 2 - 0 0 1 1 1 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGAI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO-REG. NO.: 189307741M

WIPER BLADES
Dept Direct: 6417 9791 / 6145 9030



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct:

Wiper blade: NWS (Nippon Wiper Blade), Silper (Made in Korea)
Forch (Made in Germany)
Spartan (Nippon Denso) (Made in Japan)

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
AXA Tower #24-01

SINGAPORE 068811
TEL : 68804635(GARNET) FAX : 8804838
ATTN : GARNET

REFER AR201711-17022

CREDIT NOTE : DC201712-00303
DATE : 07/12/2017
CUSTOMER ID : AXA001
VEH REG. NO. : SKR3814Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	JJ5215A423	PANEL,H/LAMP SUPPORT,LH	SG N3-1A	-1	30.00	-30.00
2.	JJ5215A424	PANEL,H/LAMP SUPPORT,RH	SG K3-1A	-1	30.00	-30.00
3.	JJ5220K649/H029	PANEL,H/LAMP SUPPORT,LWR LH	SG O3-1A	-1	80.00	-80.00
4.	JJ5220H030	PANEL,H/LAMP SUPPORT,LWR RH	SG K3-1A	-1	80.00	-80.00

SUB-TOTAL : -220.00
ADD GST 7.00 % -15.40

E. & O.E TOTAL AMOUNT SGD : -235.40

[P] 07/12/2017 11:13:02AM

[E] 07/12/2017 9:32:22AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte, Ltd.

Sales Executive : HUAT



* 0 0 2 0 1 7 1 2 - 0 0 3 0 3 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2017 13:40	25 Nov 2017 11:25	27 Nov 2017 13:40	S\$2,030.00	S\$2,030.00		Pending for Survey Report
	Sendback Est	S\$14,381.00	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	01 Dec 2017 10:28	01 Dec 2017 10:58	01 Dec 2017 10:58			(Combined)	Combined with Main Uncombine Suppl.
		S\$0.00					

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHUA YEW HUA, ID: S1814949D, Tel: +6596571691, Email: james.chua86@yahoo.com.sg		
Vehicle Reg. No.:	SKR3814Z	Date of Loss:	17/11/2017 16:00 - :59 [33 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / C0460351	Policy/Cover Note No.:	P1740188 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Elite AM Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands, 757322 Woodlands - Tel: 63346276		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Kitty Teo - 6880 4602]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 06/12/2017]		
Driver/Custodian:	CHUA YEW HUA (50 / Male), NRIC: S1814949D, Tel: +6596571691		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (02/07/2018): **URGENT - PLEASE ADVISE STATUS**
- AXA_SG (28/06/2018): **FINALIZATION**
- AXA_SG (19/06/2018): **PART INVOICES**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKR3814Z (C0460351)

OD

Nov 17 2017 4:00PM

[CHUA YEW HUA]

Elite AM Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser ▼](#)

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	25/11/17 11:25	Repairer Estimates	 Load HTM	☐
2	01/12/17 10:58	Repairer Estimates Suppl. #1	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 09:17	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/12/17 12:36	SKR 3814Z DISMANTLE	 Load PDF	☐
2	01/12/17 12:36	SKR 3814Z INSPECTION	 Load PDF	☐
3	31/05/18 17:44	General View	 Load JPG ☒	☒
4	31/05/18 17:44	General View	 Load JPG ☒	☒
5	31/05/18 17:44	General View	 Load JPG ☒	☒
6	31/05/18 17:44	General View	 Load JPG ☒	☒
7	31/05/18 17:44	General View	 Load JPG ☒	☒
8	31/05/18 17:44	General View	 Load JPG ☒	☒
9	31/05/18 17:44	General View	 Load JPG ☒	☒
10	31/05/18 17:44	General View	 Load JPG ☒	☒
11	31/05/18 17:44	General View	 Load JPG ☒	☒
12	31/05/18 17:44	General View	 Load JPG ☒	☒
13	31/05/18 17:44	General View	 Load JPG ☒	☒
14	31/05/18 17:44	General View	 Load JPG ☒	☒
15	31/05/18 17:44	General View	 Load JPG ☒	☒
16	31/05/18 17:44	General View	 Load JPG ☒	☒
17	31/05/18 17:44	General View	 Load JPG ☒	☒
18	31/05/18 17:44	General View	 Load JPG ☒	☒
19	31/05/18 17:44	General View	 Load JPG ☒	☒
20	31/05/18 17:44	General View	 Load JPG ☒	☒
21	31/05/18 17:44	General View	 Load JPG ☒	☒
22	31/05/18 17:44	General View	 Load JPG ☒	☒
23	31/05/18 17:44	General View	 Load JPG ☒	☒
24	31/05/18 17:44	General View	 Load JPG ☒	☒
25	31/05/18 17:44	General View	 Load JPG ☒	☒
26	31/05/18 17:44	General View	 Load JPG ☒	☒
27	31/05/18 17:44	General View	 Load JPG ☒	☒
28	31/05/18 17:44	General View	 Load JPG ☒	☒
29	31/05/18 17:44	General View	 Load JPG ☒	☒
30	31/05/18 17:44	General View	 Load JPG ☒	☒
31	31/05/18 17:44	General View	 Load JPG ☒	☒

Assessment Reports			1 per page ▼	☑
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
32	31/05/18 17:44	General View	 Load JPG	☑
33	31/05/18 17:44	General View	 Load JPG	☑
34	31/05/18 17:44	General View	 Load JPG	☑
35	31/05/18 17:44	General View	 Load JPG	☑
36	31/05/18 17:44	General View	 Load JPG	☑
37	31/05/18 17:44	General View	 Load JPG	☑
38	31/05/18 17:44	General View	 Load JPG	☑
39	31/05/18 17:44	General View	 Load JPG	☑
40	31/05/18 17:44	General View	 Load JPG	☑
41	31/05/18 17:44	General View	 Load JPG	☑
42	31/05/18 17:44	General View	 Load JPG	☑
43	31/05/18 17:44	General View	 Load JPG	☑
44	31/05/18 17:44	General View	 Load JPG	☑
45	31/05/18 17:44	General View	 Load JPG	☑
46	31/05/18 17:44	General View	 Load JPG	☑
47	31/05/18 17:44	General View	 Load JPG	☑
48	31/05/18 17:44	General View	 Load JPG	☑
49	31/05/18 17:44	General View	 Load JPG	☑
50	31/05/18 17:44	General View	 Load JPG	☑
51	31/05/18 17:44	General View	 Load JPG	☑
52	31/05/18 17:44	General View	 Load JPG	☑
53	31/05/18 17:44	General View	 Load JPG	☑
54	31/05/18 17:44	General View	 Load JPG	☑
55	31/05/18 17:44	General View	 Load JPG	☑
56	31/05/18 17:44	General View	 Load JPG	☑
57	31/05/18 17:44	General View	 Load JPG	☑
58	31/05/18 17:44	General View	 Load JPG	☑
59	31/05/18 17:44	General View	 Load JPG	☑
60	31/05/18 17:44	General View	 Load JPG	☑
61	31/05/18 17:44	General View	 Load JPG	☑
62	31/05/18 17:44	General View	 Load JPG	☑
63	31/05/18 17:44	General View	 Load JPG	☑
64	31/05/18 17:44	General View	 Load JPG	☑
65	31/05/18 17:44	General View	 Load JPG	☑
66	31/05/18 17:44	General View	 Load JPG	☑
67	31/05/18 17:44	General View	 Load JPG	☑
68	31/05/18 17:44	General View	 Load JPG	☑
69	31/05/18 17:44	General View	 Load JPG	☑
70	31/05/18 17:44	Chassis Number	 Load JPG	☑
71	31/05/18 17:44	Odometer Reading	 Load JPG	☑
72	31/05/18 17:44	General View	 Load JPG	☑
73	31/05/18 17:44	General View	 Load JPG	☑
74	31/05/18 17:44	General View	 Load JPG	☑
75	31/05/18 17:44	General View	 Load JPG	☑
76	31/05/18 17:44	General View	 Load JPG	☑
77	31/05/18 17:44	Reinspection Photo	 Load JPG	☑
78	31/05/18 17:44	Reinspection Photo	 Load JPG	☑
79	31/05/18 17:44	Reinspection Photo	 Load JPG	☑

Assessment Reports			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
80	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
81	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
82	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
83	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
84	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
85	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
86	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
87	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
88	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
89	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
90	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
91	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
92	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
93	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
94	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
95	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
96	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
97	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
98	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
99	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
100	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
101	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
102	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
103	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
104	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
105	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
106	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
107	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
108	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
109	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
110	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
111	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
112	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
113	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
114	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
115	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
116	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
117	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
118	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
119	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
120	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
121	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
122	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
123	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
124	31/05/18 17:44	Reinspection Photo	 Load JPG	☒
125	31/05/18 17:44	Reinspection Photo	Load JPG	☒
126	31/05/18 17:44	Reinspection Photo	Load JPG	☒
127	31/05/18 17:44	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
128	31/05/18 17:44	Reinspection Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/06/18 16:12	PART INVOICES	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 15:57	PARTS INVOICE	 Load PDF	
2	24/08/18 15:57	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	18/11/17 13:40	Accident Statement	 Load HTM	
2	23/11/17 16:16	Addendum Sheet	 Load JPG	☒
3	23/11/17 16:18	Accident Statement Addm. #1	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	18/11/17 13:26	ACCIDENT SCENE PHOTO 1	 Load JPG	☒
2	18/11/17 13:26	ACCIDENT SCENE PHOTO 2	 Load JPG	☒
3	18/11/17 13:26	ACCIDENT SCENE PHOTO 3	 Load JPG	☒
4	18/11/17 13:26	ACCIDENT SCENE PHOTO 4	 Load JPG	☒
5	18/11/17 13:26	ACCIDENT SCENE PHOTO 5	 Load JPG	☒
6	18/11/17 13:34	ACCIDENT PHOTO 1	 Load JPG	☒
7	18/11/17 13:34	ACCIDENT PHOTO 2	 Load JPG	☒
8	18/11/17 13:34	ACCIDENT PHOTO 3	 Load JPG	☒
9	18/11/17 13:34	ACCIDENT PHOTO 4	 Load JPG	☒
10	18/11/17 13:34	ACCIDENT PHOTO 5	 Load JPG	☒
11	18/11/17 13:34	ACCIDENT PHOTO 6	 Load JPG	☒
12	18/11/17 13:34	ACCIDENT PHOTO 7	 Load JPG	☒
13	18/11/17 13:34	ACCIDENT PHOTO 8	 Load JPG	☒
14	18/11/17 13:34	ACCIDENT PHOTO 9	 Load JPG	☒
15	18/11/17 13:34	ACCIDENT PHOTO 10	 Load JPG	☒
16	18/11/17 13:34	ACCIDENT PHOTO 11	 Load JPG	☒
17	18/11/17 13:34	ACCIDENT PHOTO 12	 Load JPG	☒
18	18/11/17 13:34	ACCIDENT PHOTO 13	 Load JPG	☒
19	18/11/17 13:34	ACCIDENT PHOTO 14	 Load JPG	☒
20	18/11/17 13:34	ACCIDENT PHOTO 15	 Load JPG	☒
21	18/11/17 13:34	ACCIDENT PHOTO 16	 Load JPG	☒
22	18/11/17 13:34	ACCIDENT PHOTO 17	 Load JPG	☒
23	18/11/17 13:34	ACCIDENT PHOTO 18	 Load JPG	☒
24	18/11/17 13:34	ACCIDENT PHOTO 19	 Load JPG	☒
25	18/11/17 13:34	ACCIDENT PHOTO 20	 Load JPG	☒
26	18/11/17 13:34	ODOMETER READING	 Load JPG	☒
27	18/11/17 13:34	CHASSIS NUMBER	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	18/11/17 13:23	Accident Sketch Plan	 Load TIF	

Assessment Reports				1 per page ▾	✓
No	Finalized On	Elite AM Pte Ltd (HQ)		Thumbnail	Print
2	18/11/17 13:23	DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	1	Load JPG	✓
3	18/11/17 13:23	INSURANCE COVER NOTE	1	Load TIF	
4	18/11/17 13:25	OWNER IC & DRIVING LICENCE (FRONT)	i	Load JPG	✓
5	18/11/17 13:25	OWNER IC & DRIVING LICENCE (BACK)	1	Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17022536/SRBS2

Date: 24/08/2018

REFERENCE

Insured/Claimant:	CHUA YEW HUA	Policy No:	P1740188	
Date of Loss:	17/11/2017	Nature of Claim:	OD	Claim No: C0460351

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR3814Z	Engine No:	4B12PG7340
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT (A)	Chassis No:	JMYXTGF3WFZ001603
Reg. Date:	03/02/2015 (Man. Year: 2014)	Odometer:	60808 km
Colour:	Black		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	S\$107,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,791.00	0.00	9,791.00	100.00
Miscellaneous Items	60.00	40.00	20.00	33.33
Labour	4,530.00	1,990.00	2,540.00	56.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,381.00	2,030.00	12,351.00	85.88
- Excess (S\$)	400.00	0.00	400.00	100.00
(S\$)	13,981.00	2,030.00	11,951.00	85.48
+ GST 7.00/7.00% (S\$)	978.67	142.10	836.57	85.48
Nett Amount (S\$)	14,959.67	2,172.10	12,787.57	85.48

INSPECTION

Date of Assignment:	27/11/2017 Present Location:	Elite AM Pte Ltd (HQ) Elite AM Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands Singapore 757322
Date Inspected:	28/11/2017 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2018)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR3814Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (CONSISTENT)	Bent	550.00 F	*- F
2	1		*BONNET OUTER MOULDING (CONSISTENT)	Cut	30.00 F	*- F
3	1		*BONNET LOCK (CONSISTENT)	Jammed	50.00 F	*- F
4	2		*HEADLAMP LHS & RHS (CONSISTENT)	Cracked	1,200.00 F	*- F
5	1		*FRONT BUMPER (CONSISTENT)	Cracked	600.00 F	*- F
6	1		*FRONT GRILLE & LOGO (CONSISTENT)	Necessary	300.00 F	*- F
7	10		*FRONT GRILLE CLIPS (CONSISTENT)	Cut	30.00 F	*- F
8	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	400.00 F	*- F
9	2		*FRONT BUMPER RETAINER LHS & RHS (CONSISTENT)	Necessary	40.00 F	*- F
10	1		*FRONT BUMPER CENTRE GRILLE (CONSISTENT)	Cracked	130.00 F	*- F
11	1		*WASHER COVER (CONSISTENT)	Serviceable	30.00 F	*- F
12	1		*WASHER COVER MOTOR (CONSISTENT)	Serviceable	150.00 F	*- F
13	1		*SUPPORT PANEL (CONSISTENT)	Not Necessary	500.00 F	*- F
14	1		*SUPPORT PANEL UPPER GARNISH (CONSISTENT)	Dented	45.00 F	*- F
15	10		*SUPPORT PANEL UPPER GARNISH CLIPS (CONSISTENT)	Necessary	30.00 F	*- F
16	1		*FRONT BUMPER LOWER LID (CONSISTENT)	Scratched	300.00 F	*- F
17	1		*FOG LAMP COVER RHS (CONSISTENT)	Missing	25.00 F	*- F
18	1		*FOG LAMP RHS (CONSISTENT)	Scratched	40.00 F	*- F
19	10		*FRONT BUMPER CLIPS (CONSISTENT)	Necessary	3,000.00 F	*- F
20	1		*WHEEL ARCH RHS (BLACK) (CONSISTENT)	Cut	3.00 F	*- F
21	1		*RADIATOR (CONSISTENT)	Bent	100.00 F	*- F
22	1		*AIRCON CONDENSER (CONSISTENT)	Bent	650.00 F	*- F
23	2		*RADIATOR TOP MOUNTING (CONSISTENT)	Necessary	1,100.00 F	*- F
24	1		*RADIATOR ELECTRIC FAN C/W COWLING ASSY (CONSISTENT)	Serviceable	8.00 F	*- F
25	1		*A/C HOSE (CONSISTENT)	Serviceable	150.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*A/C SUCTION HOSE (CONSISTENT)	Serviceable	180.00 F	*- F
27	1		*A/C DISCHARGE HOSE (CONSISTENT)	Serviceable	150.00 F	*- F
28	1		*PARTS SUPPLIED BY AXA'S SUPPLIER \$4,535.00		-	-
Supplementary #1						
29	1		*FRONT BUMPER TOP BEAM (CONSISTENT)	Dented	-	*- F
30	1		*FRONT BUMPER INNER BRACKET LH (CONSISTENT)	Necessary	-	*- F
31	1		*FRONT BUMPER INNER BRACKET RH (CONSISTENT)	Necessary	-	*- F
32	2		*FRONT BUMPER INNER STAY (CONSISTENT)	Necessary	-	*- F
F=Franchise part.				Total Parts (S\$)	9,791.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (BENT) (CONSISTENT)	60.00	40.00
Sub Total (S\$)			60.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove and replace the above front damaged parts	New	2,000.00	800.00
2	To spray painting on the replace and repair parts, LHS & RHS fender, front bumper, bonnet (inner & outer), LHS & RHS wheelhousing, front upper panel, LHS & RHS headlamps panels, front chassis members, LHS & RHS radiator vertical panels, front LHS door.	New	2,000.00	1,000.00
3	To remove & replace A/C condenser & A/C parts as listed above; to vacuum & charge up gas	New	150.00	100.00
4	To remove & replace radiator, electric fan assy and refix hoses; to pressurize cooling system	New	80.00	50.00
5	To check electrical wirings & focus headlights	New	50.00	40.00
6	To jack, straighten & align front chassis members according to factory specification	New	250.00	0.00
Gross Labour Cost (S\$)			4,530.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >