



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

HITACHI CAPITAL ASIA PACIFIC PTE LTD
111 SOMERSET ROAD
#11-05
Singapore 238164

*Not Authorized
1. B.1
Repairing B4 point*

Dear sir

Estimate cost of repair to vehicle no. SLB 5274R

To supply

1. Front bumper	<i>my car</i>	580.00	—
2. Front bumper retainersx2	<i>clsp.1</i>	100.00	+
3. Head lamp		980.00	?
4. Head lamp bracket	<i>sn</i>	55.00	X
5. Fog lamp	<i>sn</i>	350.00	X
6. Fog lamp cover	<i>sn</i>	65.00	X
7. Front fender	<i>sn</i>	380.00	X
8. Front fender inner garish	<i>sn</i>	125.00	X
9. Wheel rim	<i>1. x 15</i>	1,015.00	<i>8000</i>
10. Chips for garish and bumper x15	<i>sn</i>	22.50	—
11. Door mirror		750.00	?
12. Lower arm		338.00	?
13. Knuckle arm		350.00	?
14. Shock absorber	<i>2 of</i>	300.00	?

Labour charges

Rust proofing	<i>sn</i>	80.00	X
Panel beating		880.00	<i>400</i>
Spray painting		800.00	<i>500</i>
To remove and refit undercarriages		350.00	?
Wheel alignment			

Total

75050

Your faithfully

Albert Poon

ALBERT POON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: