

REPAIR ESTIMATE*

VEHICLE NO : SHA 7449T

DATE 24/11/2017 15:37

MAKE :

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Bracket, Frt/LH/RH ?		\$ 95.00	\$ 190.00
	Bumper Absorber, Frt/LH/RH ?		\$ 207.00	\$ 414.00
	Radiator Grille ✓			\$ 1,220.00
	<i>Front Bumper x Repair</i>			
	SUB TOTAL			\$ 1,824.00
	LESS 20%			\$ 364.80
	DISCOUNTED TOTAL			\$ 1,459.20
	Labour Charge			
	Panel Beating- Repair Frt Bumper			\$ 400.00 <i>200</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 2,109.20
<p><i>1/Calan 10/11/17</i></p> <p><i>24/11/17 1540hrs</i></p> <p><i>2 Days</i></p> <p><i>P/P</i></p> <p><i>After Rep & Photo</i></p>				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party surveys on a "No Fault & Prejudice" basis • No illegal modifications is allowed • Supplementary items must be reviewed and is subject to final approval from Insurance Company. <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				