COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHD 3269G

MAKE

DATE 27/11/2017 11:11

HINA

MODEL	: HYUNDAI i40		25 7 25 7			1
Qty	Parts Description/ Labour	Type	Unit Price		75.00	ļ.,
	Front Door Comfort Logo (LH)			\$	73.00	Nett
	Front Pour (CH) x Legal					
	Front Poor (CH) × tegalt Front Fix de (CH) × response					
	prod fra					
	Labour Charge	V.				
	Labour Charge Panel Beating			\$	350.00	36
	Spray Painting Charge			\$ 4	200.00	36
	Tuff Kote			\$	50,00	† ×
				•	600.00	4
	TOTAL LABOUR			\$	600.00	1
	ESTIMATE TOTAL			\$	675.00]
	1					
	Calvin CK14					
	1(a/vin 1CK14) 1 27/1/2 1420 hr.					
	1/ 24/1/4 /42					
	2 Pays. P/P AHar Rywiphoho					
	0/0	LKKA	to Consultants hence not	fv		
	1/2	Ine Re	vairer of the following: rvey before iffer turay out fing			
	After Ry in photo	· lo dist	By damaged part and result	Nev		
		• Third o	rices are subject to confirm than acty seems on a tWin — Engli	re" ha	ie I	
		• No illes	Hi illoumestor (s. is a			
		is subje	mentary (jem/s) must be resurved to find	red and to compa	ny	
			dged by Repairer			
		Signature Date:	2			
		- 3101				
	This is an initial estimate based on a visual inspection of the	ne above ve	chicle. The final repair q	uantum	will	1
	be prepared after the vehicle is surveyed by a motor Surve					