

LKK-
IDAC

Date / Time :

Registered in Merimen:



Insured Vehicle No. :

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : SIM BOW HONG

Claim No. _____

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers Liability		
4. Employment Practices Liability		
5. Fidelity and Bonding		
6. Commercial Automobile		
7. Aircraft and Helicopter		
8. Marine		
9. Umbrella		
10. Other		

Driver Tel No. :

(V/L: YES/NO)

GA 7547X



INSRS:

WSP:

Tel: 011 44 1223 323434

RMKS:



INSRS:

WSP:

Tel: +353 1 434 2000
Fax: +353 1 434 2001
E-mail: info@hse.ie
Web: www.hse.ie

RMKS:



INSRS:

WSP:

Tel:

DMKS.



INSRS:

WSP:

Tel :

NAME _____

Date/Time		STAGE	DATE / PIC
20/1/18	49754XX - Y	Non-Reporting ltr (1st):	NA
20/1/18	49754XX - Y	Non-Reporting ltr (2nd):	
20/1/18	49754XX - Y	Non-Reporting ltr (Final):	
20/1/18	49754XX - Y	Notification ltr (if non-pickup):	
19-1-18	FILE RECEIVED FROM ZATER	Call Of:	20/2-3-18
26-3-18 @	1140 W/OIC MS. ENG. SHE CONFIRMED ACC. AGREED TO SETTLE AWARE NCD ISSUE.	After call ltr to Of:	
21-5-18	FOR MANDATE	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	☒
		After call ltr to Of:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GLA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☐
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	days) Reduction:	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 6-9-18	Confirm with: RSCONE	Email ☐ Call ☐
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.: 9a	If NO or B 28, Ass. Lia:
Repair Cost: GST	SS 8,774		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS 780 (\$ 60 x 13 days)		
Loss of Income (LOI):	SS (\$ x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS 8		
Medical:	SS -		1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS -	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	SS -		3) Survey fee:
Total:	SS 9,562	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 9,362	Name 1:	CHENG HOE MOTOR PTE LTD
Payee 2: (Strike if N.A.)	SS X	Name 2:	X
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY:

REF:

A.G.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GQ 7547X Yr Regn: 04, 99

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Lite c.c. 1781Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 19624 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KR 42 0027980Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: CenterR: Merida 165R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 27/4/17Survey held at ✓

Rear

R/Bal. 3 mmL/Bal. 3 mmD.O.I. 28/11/17Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop orC/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/11 File pass to Carhume112m 8820d Carhume E 8rd 9Car (11+2x60)R (16,254.27 / 43%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC4/AIG17022630/Kzb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 28-11-2017	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 6614A	Veh. Inspected	GQ 7547X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/11/2017	Inspection Date	28/11/2017	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GA 7547X

TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 27/11/2017

TP Veh Reg No: GBC6614A

Estimate No: ES1791350

Date: 28 Nov 2017

Policy No: D17MTPCVE000954

Veh Reg No: GQ7547X

Make/Model: TOYOTA LITEACE 5DRS

Chassis No: KR420027980

Engine No: 7K0239151

Reg. Date: 08/04/1999

Estimate Repair Cost to Vehicle No :GQ7547X

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 RH HEAD LAMP RIM	111.86	1 PCS	111.86	—
2 FRONT BUMPER	382.68	1 PC	382.68	—
3 FRONT BUMPER RH SIDE RETAINER	18.00	1 PC	18.00	—
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	—
5 FRONT RH FENDER	361.20	1 PC	361.20	—
6 FRONT RH FENDER INNER SHIELD	145.30	1 PC	145.30	—
7 FRONT RH FENDER INNER SHIELD CLIPS	3.00	6 PCS	18.00	—
8 FRONT RH FENDER LAMP	51.30	1 PC	51.30	—
9 FRONT WINDSCREEN GLASS	1,070.80	1 PC	1,070.80	—
10 FRONT WINDSCREEN GLASS MOULDING	80.00	1 PC	80.00	—
11 FRONT RH MUD FLAP	126.34	1 PCS	126.34	—
12 FRONT RH MUD FLAP CLIPS	3.50	2 PCS	7.00	—
13 FRONT RH DOOR	718.50	1 PC	718.50	—
14 FRONT RH DOOR SIDE MIRROR	207.70	1 PC	207.70	—
15 FRONT RH DOOR OUTER HANDLE	134.30	1 PC	134.30	—
16 FRONT RH DOOR GLASS	443.40	1 PC	443.40	—
17 FRONT RH DOOR GLASS MOULDING	109.00	1 PC	109.00	—
18 FRONT RH DOOR TOP HINGE	78.00	1 PC	78.00	—
19 FRONT RH DOOR BOTTOM HINGE	78.00	1 PC	78.00	—
20 FRONT RH DOOR INNER LOCK	280.00	1 PC	280.00	—
21 FRONT RH DOOR INNER RUBBER	197.30	1 PCS	197.30	—
22 FRONT RH WINDSCREEN PILLAR	505.53	1 PC	505.53	—
23 FUEL DOOR PANEL	448.50	1 PC	448.50	—
24 RH SLIDING DOOR	1,127.60	1 PC	1,127.60	—
25 RH SLIDING DOOR OUTER HANDLE	165.06	1 PC	165.06	—
26 RH SLIDING DOOR INNER BOARD	130.80	1 PCS	130.80	—
27 RH SLIDING DOOR ROLLER TRUCK	272.86	1 PCS	272.86	—
28 RH SLIDING DOOR ROLLER	119.80	1 PCS	119.80	—
29 RH SLIDING DOOR INNER LOCK	303.00	1 PCS	303.00	—
30 REAR RH SIDE PANEL	1,147.40	1 PC	1,147.40	—
31 REAR RH TYRE RIM	256.80	1 PCS	256.80	—
32 REAR RH WHEEL BEARING	100.30	1 PC	100.30	—
33 FRONT RH TOP ARM	686.50	1 PC	686.50	—
34 FRONT RH KNUCKLE ARM	296.09	1 PC	296.09	—
35 FRONT RH WHEEL BEARING	98.30	1 PC	98.30	—
			10,298.22	
			Less 25%	2,574.56
				7,723.67

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be submitted and is subject to final approval from Ins. Co. before repair.

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374-382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 27/11/2017

TP Veh Reg No: GBC6614A

Estimate No: ES1791350

Date: 28 Nov 2017

Policy No: D17MTPCVE000954

Veh Reg No: GQ7547X

Make/Model: TOYOTA LITEACE 5DRS

Chassis No: KR420027980

Engine No: 7K0239151

Reg. Date: 08/04/1999

Estimate Repair Cost to Vehicle No :GQ7547X

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Special Net				
36 FRONT WINDSCREEN GUM	40.00	1 PC	40.00	✓
37 ERP BRACKET	25.00	1 PC	25.00	✓
38 FRONT RH DOOR COY STICKER	20.00	1 PCS	20.00	✓
39 REAR RH TYRE	160.00	1 PC	160.00	300.00
			245.00	245.00
Labour				
40 TOWING	50.00	1 LA	50.00	✓
41 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓
42 REMOVE AND REFIX FRONT BUMPER ASSY, FRONT RH FENDER, HEAD LAMP, RH SLIDING DOOR AND ATTACHMENT, FRONT RH DOOR AND ATTACHMENT, TO CUTTING, WELDING AND RENEW FRONT RH W/SCREEN PILLAR, RH DOOR PILLAR OUTER, REAR RH SIDE PANEL TO KNOCK AND REPAIR FRONT RH WHEEL HOUSING, REAR RH FLOOR BOARD PANEL, RH DOOR PILLAR INNER AND REALIGN THE SAME	2,500.00	1 LA	2,500.00	2100
43 REMOVE AND REFIX DASH BOARD, METER ASSY AND CHECK WIRING	250.00	1 LA	250.00	✓
44 REMOVE AND REFIX AIRCON,CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
45 PUTTY AND RESPRAY ON FRONT BUMPER, BONNET, FRONT RH FENDER, WHEEL HOUSING, FRONT RH DOOR, SLIDING DOOR, REAR RH SIDE PANEL, W/SCREEN PILLAR, DOOR PILLAR, ALL AFFECTED AREA	1,800.00	1 LA	1,800.00	1600
46 REMOVE AND REFIX TOP ROOF LINING, SEAT, CARPET ETC	120.00	1 LA	120.00	✓
47 REMOVE AND REFIX FRONT RH DOOR GLASS	60.00	1 LA	60.00	✓
48 REMOVE AND REFIX FRONT AND REAR UNDER CARRIAGE	380.00	1 LA	380.00	1000
49 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
50 RUSTPROOFING	100.00	1 LA	100.00	✓
			5,540.00	5,540.00
Total				SS 13,508.67
Add GST @ 7%				945.61
Total Amount Payable				SS 14,454.28

For Cheng Hoe Motor Pte Ltd


 AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	5350C
Vehicle Details	
Vehicle No.	GQ7547X
Vehicle to be Exported	Yes
Intended De-registration Date	27 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	LITEACE 5 DR
Primary Colour	Beige
Manufacturing Year	1999
Engine No.	7K0239151
Chassis No.	KR420027980
Maximum Power Output	-
Open Market Value	\$16,201.00
Original Registration Date	08 Apr 1999
First Registration Date	08 Apr 1999
Transfer Count	1
Actual ARF Paid	\$811.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	31 Mar 2019
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$3,733.00
COE Rebate Amount	\$501.00
Total Rebate Amount	\$501.00

The information contained herein is correct as at 27 Nov 2017

OK

Sign up & Get \$50 free gift pack!
 Email Add: _____
 Submit Qu
 Sign Up New Account
 Forgot Password

TOYOTA LITEACE

Price Range

Depreciation

Year Reg

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Carz World Pte Ltd > Toyota Liteace (COE till 02/2019)

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Leasing



BLACK FRIDAY PROMOTION
 4-DAY OFFER ONLY
 24th - 27th Nov 2017

Receive a
\$S100
 CapitaVoucher
 upon Card approval

Apply Now
 T&Cs apply

Toyota Liteace (COE till 02/2019)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$8,988**Depreciation** \$7,610 /yr

View models with similar depreciation

Reg Date 02-Feb-1999
(1yr 2mths 5days COE left)**Lifespan** 01-Feb-2019**Manufactured** 1998**Mileage** -**Transmission** Auto**Engine Cap** 1,781 cc**Curb Weight** 1,180 kg**Fuel type** Petrol**Features** Reliable Toyota Diesel Engine. 5 Doors For Easy Loading/Unloading Of Goods. Power Steering.**Accessories** Brand New Leather Upholstery.**Description** Reliable Liteace Van! Diesel Engine. Practical Cabin. Space To Suit Your Daily Business Needs! 5 Doors For Easy Access. Previously Personal Use For Some Light Goods. Regularly Maintained. COE Till Feb 2019. Sell As It Is Condition. Call Us For Viewing Today!**COE** \$5,116**OMV** \$15,370**ARF** \$769**Dereg Value** \$604 as of today (change)**No. of Owners** 3**Type of Veh** Van**Category** COE Car, Premium Ad Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Printed on: 25-Nov-2017 | Last Updated on: 26-Nov-2017

Tags: Toyota Townace, Toyota Liteace, Toyota Liteace, 1999 Toyota Liteace, 1999 Toyota Liteace, Toyota, Liteace, Liteace, Used Toyota

Upfront Payment

+ more Financial info

Transfer Fee \$11**Down Payment** \$899 (change)

Maximum 90% Loan

1st Instalment \$600**Total Upfront Payment** \$1,518 (excluding insurance)

Estimates based on 90% loan at 4.3% interest rate. Check with seller for exact figure.

Items for Toyota Liteace

+ View All

**Sprint Booster Throttle Controller**
From \$188**Window View**
\$43**Boot Cover**
\$100**Luxury Leather Upholstery (With Car...**
From \$50**Wheel Seal (x) 90311-42801**
\$12**Bibbed Carpets For Sale**
\$5,888

View All

Compare

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 16512

Date: 27/11/17

寶號

Messrs: 清河

車號

Vehicle No: GQ 7547 X

由

From: Tai Seng AUE

時間 (日/夜)

Time (day/night):

其他

Others: Acc

CASH \$: 30

CHEQUE:

經手人

Authorised by: [Signature]

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

CMS expands in Asia

Visit our website and learn more about our new office in Hong Kong!

[OPEN](#)
 Username
 password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Volkswagen Sharan 2.0L TSI Turbo 2013 Meteorite Black.



One Lady Owner, Low Mileage,
 Covered Basement Parking,
 Never Been To Malaysia
 Direct Owner StarAd


[Browse by Category](#)
[Sort by Date Posted](#)

9 vehicles

[Advanced Search](#)


	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh 1
Search Selection	Toyota Liteace		Any	Any	> 10 year(s) old	1,601cc - 2,000cc	Any	
	Toyota Liteace (COE till 07/2022)		\$37,800	\$8,160 /yr	17-Jul-2007	1,781 cc	-	
	Fuel Type: Petrol Very Good Condition Auto Transmission Toyota Liteace. The Most Reliable Van In The Market. Engine And Gearbox In Tip-Top Condition. Vn Believe. Call Now For Viewing And Test Drive Today! Car (S) Pte Ltd Posted: 18-Nov-2017 Tags: Toyota Townace, 2007 Toyota Liteace, 2007 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Used Toyota							
	Toyota Liteace (COE till 05/2022)		\$36,800	\$8,250 /yr	17-May-2007	1,781 cc	-	
	Fuel Type: Petrol 1 Owner, Most Popular Mid-Sized Van With Auto Transmission. Engine And Gearbox In Excellent Condition. New Leather Seats And Paintwork Servicing And Wear And Tear Done Up. Trade In Welcome. Car (S) Pte Ltd Posted: 18-Nov-2017 Tags: Toyota Townace, 2007 Toyota Liteace, 2007 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Used Toyota							
	Toyota Liteace (COE till 02/2019)		\$8,988	\$7,650 /yr	02-Feb-1999	1,781 cc	-	
	Fuel Type: Petrol Reliable Liteace Van! Diesel Engine. Practical Cabin Space To Suit Your Daily Business Needs! 5 Doors For Easy Access. Previously Personal Use. Some Light Goods. Regularly Maintained. COE Till Feb ... Posted: 27-Nov-2017 Tags: Toyota Townace, 1999 Toyota Liteace, 1999 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Used Toyota							
	Toyota Liteace (COE till 09/2020)		\$14,800	\$5,210 /yr	12-Oct-2000	1,781 cc	-	
	Fuel Type: Petrol Cheapest In Market, Low Depreciation At \$5.1k. Well Kept. Good Condition. High Trade In. In House Loan Available. Selling Near Scarp Valley. Posted: 22-Nov-2017 Tags: Toyota Townace, 2000 Toyota Liteace, 2000 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Used Toyota							
Car Buying			Car Selling			Car Aftermarket		
Car Ownership			On The Move			Lifestyle		
	Toyota Liteace (COE till 06/2019)		\$9,800	\$6,190 /yr	08-Jul-1999	1,781 cc	-	
	Fuel Type: Petrol Regular Servicing Done, Well Maintained, Loan Available, Price Negotiable, Call For Viewing. The Most Cheapest Liteace In Town To Bring You In Your Everyday Life!							

[Buy Tyres Online](#)
[Latest Special Offers from 7](#)

ABWIN Bus Pte Ltd

Posted: 21-Nov-2017

Tags: Toyota Townace, 1999 Toyota Liteace, 1999 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Liteace, Used Toyota

**Toyota Liteace (COE till 03/2019)**

\$11,800

\$8,840 /yr

20-Apr-1999

1,781 cc

Fuel Type: Petrol

This Commercial Van Is In An Extremely Good Condition. Very Well Taken Care By It's Ex-Owner. Quiet Engine And Low Maintenance.

Car (S) Pte Ltd

Posted: 06-Nov-2017

Tags: Toyota Townace, 1999 Toyota Liteace, 1999 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Liteace, Used Toyota

**Toyota Liteace (COE till 03/2022)**

\$25,800

\$5,950 /yr

13-Jun-2000

1,781 cc

Fuel Type: Petrol

Still Have 4.4 Years To Drive! Only 1 Owner. New Paintwork And New Seats. No Repairs Needed Just Drive And Go. No Hassle And Reliable Your Smooth Running Of Business. Ideal For Small Start Up ...

Posted: 02-Nov-2017

Tags: Toyota Townace, 2000 Toyota Liteace, 2000 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Liteace, Used Toyota

**Toyota Liteace (COE till 03/2022)**

\$22,888

\$5,280 /yr

04-May-2000

1,781 cc

Fuel Type: Petrol

Use Till End Of Vehicle Expiry Still Can Take Back (\$9,324) From The COE Rebate! Please Call To Arrange For Viewing, Thanks.

Posted: 23-Oct-2017

Tags: Toyota Townace, 2000 Toyota Liteace, 2000 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Liteace, Used Toyota

**Toyota Liteace (COE till 03/2020)**

\$16,800

\$7,190 /yr

23-May-2000

1,781 cc

Fuel Type: Petrol

Most Popular Mid-Sized Van. Engine And Gearbox In Excellent Condition.

Posted: 06-Oct-2017

Tags: Toyota Townace, 2000 Toyota Liteace, 2000 Toyota Liteace, Toyota Liteace, Toyota Liteace, Toyota Liteace, Liteace, Liteace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh T
------	-------	-------	--------------	----------	---------	---------	-------

For old advertisements, view [Expired ads](#).

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Toyota Liteace Singapore, used Toyota Liteace Singapore, used Toyota Liteace, used vehicles Singapore or even buy used Toyota Liteace Singapore. We have new car dealers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore, estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance is made that the information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

© 2004-2017 sgCarMart. All rights reserved.

- Terms of
- Privacy P
- Personal

Compare

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	:	GBC6614A
Claimant Vehicle No.	:	GQ7547X
Date of Accident	:	27/11/2017
Traffic Accident involving vehicle/s No.	:	ALONG TAI SENG AVE

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 8,774.00	
2	Loss of Use	\$ 780.00	\$60 X 13 days
3	LTA Search	\$ 8.00	
TOTAL		\$ 9,562.00	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 26 March 2018 11:42 AM
To: 'sorhong@supertron.cm.sg'
Cc: Admin A
Subject: ACCIDENT INVOLVING GBC 6614A AND GQ 7547X ON 27/11/2017

Our ref: CC4/AIG17022630/Kjb3

SINTEBROS CORPORATION PTE LTD

Policy Holder

ATTENTION: Ms. Eng (Officer-In-Charge)

Dear Madam,

ACCIDENT INVOLVING GBC 6614A AND GQ 7547X ON 27/11/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT

I, MAC Technical Service (the third party claimant) of 22 Lentor Green
Singapore 789271 (address), owner of GQ7547X (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. GQ7547X that
was damaged pursuant to the accident which occurred on 27/11/2017 (date) along Tai Seng Ave
(location) involving vehicle no/s GBC6614A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 27 (day) of Nov (month) 20 17 (year)

MAC TECHNICAL SERVICE
22 LENTOR GREEN
SINGAPORE 789271
TEL: 6482 2161 FAX: 6481 6894

Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, **CHENG HOE MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK** **AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8774.00** (Repair Cost), **S\$780.00** (Loss of Use), **S\$8.00** (Disbursement), for vehicle no **GQ7547X** that was damaged pursuant to the accident which occurred **27/11/2017** (date) along **Tai Seng Ave** (location) involving vehicle no/s **GBC6614A**. This is pursuant to the inspection conducted on **28/11/2017** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **MAC Technical Service** ("the third party claimant") of vehicle no. **GQ7547X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage **GQ7547X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 6 (day) of SEPT. (month) 2018 (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP-AIG
Claim Type: Third Party
Accident Date: 27/11/2017
TP Veh Reg No: GBC6614A

NO: CL8180904
Date: 21 Aug 2018
Policy No: D17MTPCVE000954
Veh Reg No: GQ7547X
Make/Model: TOYOTA LITEACE
5DRS
Job No: JC1598098

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	SS 8,200.00	SS 8,200.00

Total	SS 8,200.00
Add GST @ 7%	574.00
Total Amount payable	SS 8,774.00

For Cheng Hoe Motor Pte Ltd

E. & O. E.



AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358
TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B078/2017	
YOUR REF:			
OUR REF : ACS.CH.LTA.2017 (NOV 2017)		DATE : 11/12/17	
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusal, attendance preparation examination of documents relating thereto, correspondence, attendance, perusal's, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.			
LTANET SEARCHES FOR THE MONTH NOV 2017			
S/NO	TP NO.	CHM	DOA
			sub-total b/f
			\$ 175.00
23	24/11/2017	SJL9040A	SDU6000C
24	25/11/2017	SJX5770D	SKL9090L
25	27/11/2017	GX2086E	SLM8775J
26	27/11/2017	SJH111G	SKG3869J
27	27/11/2017	GBC6514A	GQ7547X
28	4/5/2017	SCJ6565D	SGD1872P
29	21/3/2017	GZ7368Z	SJA6418R
30	17/5/2017	SKN5123Y	SKB835S
			\$ 64.00
30 searches @\$8.00 per search			Total:
			\$ 240.00
[SINGAPORE DOLLARS: TWO HUNDRED & FORTY-ONLY.]			
			
M/s. A.C. SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE			
We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.			

Print Received Message

This mail is associated with :

***GQ7547X (4104331153SG)**
[GBC6614A]

TP

MAC TECHNICAL SERVICE

Nov 27 2017 12:00AM

[Sintebros Corporation Pte Ltd]

Cheng Hoe Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/09/2018 14:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9562.00) - GQ7547X - Claim Handler: Wui, Shawn-KJ

Approved:9562.00:Please see email from Shawn to Joy on 04/09/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2017 Edit Reg		28 Nov 2017 00:00 Edit Adj Rpt	S\$8,200.00 Edit Estimates	S\$8,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Sintebros Corporation Pte Ltd, Co. Reg. No.: 200300005D								
Main Claimant:	MAC TECHNICAL SERVICE, Co. Reg. No.: 53125350C								
Vehicle Reg. No.:	GQ7547X	Date of Loss:	27/11/2017 00:00 - :59 [223 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4104331153SG	Policy/Cover Note No.:	2100343304						
Vehicle Reg. No. (Insured):	GBC6614A	Policy No. (Claimant):	D17MTPCVE000954						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (06/09/2018): Alert - Adj Mandate Approved (S\$9562.00) - GQ7547X - Claim Handler: Wui, Shawn-K... - AIG_SG_EXPRESS (04/09/2018): Alert - Adj Mandate Maintained - GQ7547X - Claim Handler: Wui, Shawn-KJ - AIG_SG (29/11/2017): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GQ7547X (4104331153SG)
[GBC6614A]
TP
MAC TECHNICAL SERVICE
Nov 27 2017 12:00AM
[Sintebros Corporation Pte Ltd]
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
Assessment Reports															1 per page					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print			
1	29/11/17 11:17		Accident Statement From: SC – Reg. No: G8C6614A, Claimant: SINTEBROS CORPORATION PTE LTD												1	Load HTM				
Photos/Images															3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	04/09/18 13:30		General View												1	Load JPG				
2	04/09/18 13:30		General View												1	Load JPG				
3	04/09/18 13:30		General View												1	Load JPG				
4	04/09/18 13:30		General View												1	Load JPG				
5	04/09/18 13:30		General View												1	Load JPG				
6	04/09/18 13:30		General View												1	Load JPG				
7	04/09/18 13:30		General View												1	Load JPG				
8	04/09/18 13:30		General View												1	Load JPG				
9	04/09/18 13:30		General View												1	Load JPG				
10	04/09/18 13:30		General View												1	Load JPG				
11	04/09/18 13:30		General View												1	Load JPG				
12	04/09/18 13:30		General View												1	Load JPG				
13	04/09/18 13:30		General View												1	Load JPG				
14	04/09/18 13:30		General View												1	Load JPG				
15	04/09/18 13:30		General View												1	Load JPG				
16	04/09/18 13:30		General View												1	Load JPG				
17	04/09/18 13:30		General View												1	Load JPG				
18	04/09/18 13:30		General View												1	Load JPG				
19	04/09/18 13:30		General View												1	Load JPG				
20	04/09/18 13:30		General View												1	Load JPG				
21	04/09/18 13:30		General View												1	Load JPG				
22	04/09/18 13:30		General View												1	Load JPG				
23	04/09/18 13:30		General View												1	Load JPG				
24	04/09/18 13:30		General View												1	Load JPG				
25	04/09/18 13:30		General View												1	Load JPG				
26	04/09/18 13:30		General View												1	Load JPG				
27	04/09/18 13:30		General View												1	Load JPG				
28	04/09/18 13:30		General View												1	Load JPG				
29	04/09/18 13:30		General View												1	Load JPG				
30	04/09/18 13:30		General View												1	Load JPG				

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
31	04/09/18 13:30	General View		Load JPG ☒
32	04/09/18 13:40	Photo After Spray		Load JPG ☒
33	04/09/18 13:40	Photo After Spray		Load JPG ☒
34	04/09/18 13:40	Photo After Spray		Load JPG ☒
35	04/09/18 13:40	Photo After Spray		Load JPG ☒
36	04/09/18 13:40	Photo After Spray		Load JPG ☒
37	04/09/18 13:40	Photo After Spray		Load JPG ☒
38	04/09/18 13:40	Photo After Spray		Load JPG ☒
39	04/09/18 13:40	Photo After Spray		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/11/17 15:43	EMAIL FROM AIG DD 28112017		Load PDF
2	29/11/17 18:28	TP ESTIMATE- MARKED		Load PDF
3	29/11/17 18:28	TP GIA REPORT		Load PDF
4	04/09/18 13:36	LTA SEARCH		Load PDF
5	05/09/18 10:24	TOWING-MV-LREBATE		Load PDF
6	10/09/18 11:23	LETTER TO INSURED		Load PDF
7	12/09/18 11:14	WORKSHOP INVOICE		Load PDF
8	12/09/18 11:14	AUTHORISATION TO ACT FORM		Load PDF
9	12/09/18 11:14	Release Voucher		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBC6614A (Insd veh)	Model:	TOYOTA LITEACE 1.5 (M)
	GQ7547X (TP veh)		
Date of Accident:	27/11/2017		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$	14,454.27	
Final Repair Cost	: \$	8,774.00	
Loss of Use	: \$	780.00	13.00 days at \$60.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	8.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	9,562.00	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	: \$	9,562.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

12 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022630/KJB3Q2

Date: 12/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100343304

Claimant Vehicle
No : GQ7547X

Insured Vehicle No : GBC6614A

Date of Loss: 27/11/2017

Nature of Claim: TP

Claim No: 4104331153SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GQ7547X

Make & Model: TOYOTA LITEACE, 1.5 (M)

Engine No: 7K0239151

Reg. Date: 08/04/1999 (Man. Year: 1999)

Chassis No: KR420027980

Colour: Silver

Odometer: 196241 km

Engine Capacity: 1781 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165 R13

Rear Tyre Size: 165 R13

Front Left Side: Condor 9 mm

Rear Left Side: West Lake 3 mm

Front Right Side: Condor 9 mm

Rear Right Side: West Lake 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,968.66	6,971.35	997.31	12.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	4,660.00	880.00	15.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,508.66	11,631.35	1,877.31	13.90
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	13,508.66	8,200.00	5,308.66	39.30
+ GST 7.00/7.00% (S\$)	945.61	574.00	371.61	39.30
Nett Amount (S\$)	14,454.27	8,774.00	5,680.27	39.30
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		9,562.00		

INSPECTION

Date of Assignment: 28/11/2017

Date Inspected: 28/11/2017 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial

Park A
Singapore 768761

Estimated Period of Repair: 11.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEAD LAMP RIM	Dented	111.86 FL	*111.86 FL
2	1		*FRONT BUMPER	Buckled	382.68 FL	*382.68 FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	18.00 FL	*18.00 FL
4	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*FRONT RH FENDER	Bent	361.20 FL	*361.20 FL
6	1		*FRONT RH FENDER INNER SHIELD	Distorted	145.30 FL	*145.30 FL
7	6		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	18.00 FL	*18.00 FL
8	1		*FRONT RH FENDER LAMP	Broken	51.30 FL	*51.30 FL
9	1		*FRONT WINDSCREEN GLASS	Cracked	1,070.80 FL	*1,070.80 FL
10	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	80.00 FL	*80.00 FL
11	1		*FRONT RH MUD FLAP	Dented	126.34 FL	*126.34 FL
12	2		*FRONT RH MUD FLAP CLIPS	Necessary	7.00 FL	*7.00 FL
13	1		*FRONT RH DOOR	Bent	718.50 FL	*718.50 FL
14	1		*FRONT RH DOOR SIDE MIRROR	Broken	207.70 FL	*207.70 FL
15	1		*FRONT RH DOOR OUTER HANDLE	Dented	134.30 FL	*134.30 FL
16	1		*FRONT RH DOOR GLASS	Cut	443.40 FL	*443.40 FL
17	1		*FRONT RH DOOR GLASS MOULDING	Dented	109.00 FL	*109.00 FL
18	1		*FRONT RH DOOR TOP HINGE	Bent	78.00 FL	*78.00 FL
19	1		*FRONT RH DOOR BOTTOM HINGE	Bent	78.00 FL	*78.00 FL
20	1		*FRONT RH DOOR INNER LOCK	Repair	280.00 FL	*- FL
21	1		*FRONT RH DOOR INNER RUBBER (50%)	Cut	147.97 FS	*98.65 FS
22	1		*FRONT RH WINDSCREEN PILLAR	Bent	505.53 FL	*505.53 FL
23	1		*FUEL DOOR PANEL	Bent	448.50 FL	*448.50 FL
24	1		*RH SLIDING DOOR	Bent	1,127.60 FL	*1,127.60 FL
25	1		*RH SLIDING DOOR OUTER HANDLE	Dented	165.06 FL	*165.06 FL
26	1		*RH SLIDING DOOR INNER BOARD	Serviceable	130.80 FL	*- FL
27	1		*RH SLIDING DOOR ROLLER TRUCK	Dented	272.86 FL	*272.86 FL
28	1		*RH SLIDING DOOR ROLLER	Serviceable	119.80 FL	*- FL
29	1		*RH SLIDING DOOR INNER LOCK	Dented	303.00 FL	*303.00 FL
30	1		*REAR RH SIDE PANEL	Bent	1,147.40 FL	*1,147.40 FL
31	1		*REAR RH TYRE RIM (80%)	Punctured	192.60 FS	*205.44 FS
32	1		*REAR RH WHEEL BEARING	Necessary	100.30 FL	*100.30 FL
33	1		*FRONT RH TOP ARM	Serviceable	686.50 FL	*- FL
34	1		*FRONT RH KNUCKLE ARM	Bent	296.09 FL	*296.09 FL
35	1		*FRONT RH WHEEL BEARING	Necessary	98.30 FL	*98.30 FL
36	1		*FRONT WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
37	1		*ERP BRACKET	Necessary	25.00 FS	*25.00 FS
38	1		*FRONT RH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
39	1		*REAR RH TYRE (30%)	Cut	160.00 FS	*112.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	10,429.69	9,128.11
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,461.03	2,156.76
Total Parts (\$\$)	7,968.66	6,971.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE AND REFIX FRONT BUMPER ASSY ,FRONT RH FENDER ,HEAD LAMP ,RH SLIDING DOOR AND ATTACHMENT ,FRONT RH DOOR AND ATTACHMENT .TO CUTTING ,WELDING AND RENEW FRONT RH W/SCREEN PILLAR ,RH DOOR PILLAR OUTER ,REAR RH SIDE PANEL)	New	2,500.00	2,100.00
4	TO KNOCK AND REPAIR FRONT RH WHEEL HOUSING ,REAR RH FLOOR BOARD PANEL,RH DOOR PILLAR INNER AND REALIGN THE SAME)	New	-	-
5	REMOVE AND REFIX DASH BOARD ,METER ASSY AND CHECK WIRING	New	250.00	250.00
6	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
7	PUTTY AND RESPRAY ON FRONT BUMPER ,BONNET ,FRONT RH FENDER ,WHEEL HOUSING ,FRONT RH DOOR ,SLIDING DOOR ,REAR RH SIDE PANEL ,W/SCREEN PILLAR ,DOOR PILLAR ,ALL AFFECTED AREA	New	1,800.00	1,600.00
8	REMOVE AND REFIX TOP ROOF LINING SEAT ,CARPET ETC	New	120.00	120.00
9	REMOVE AND REFIX FRONT RH DOOR GLASS	New	60.00	60.00
10	REMOVE AND REFIX FRONT AND REAR UNDER CARRIAGE	New	380.00	100.00
11	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
12	RUSTPROOFING	New	100.00	100.00
Gross Labour Cost (\$\$)			5,540.00	4,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >