

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jas Tan

Date: 29 Nov 2017

## **Preliminary Advice**

Vehicle No	: SGB5369K	Accident Date	: 21/11/2017
Make	: MITSUBISHI LANCER	Policy No.	: GA080020
Assignment Date	: 28/11/2017	Excess	: S\$0.00
Date of Inspection	: 28/11/2017	Est. Duration of Repair	: 4.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,954.00
Revised Amount	:S\$	1,497.00
Check Items (Estimated)	:S\$	1,278.00
Total	:S\$	2,775.00

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	16,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,010.00

## **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Survey date and time: 28/11/2017 at 4.30PM  
We have authorise repair.