



Your Ref : M1705581

Date: 18th December 2017

Our Ref : CS/TMI17022639/Dtbs2

M/s Tokio Marine Insurance Singapore Ltd

20 Mccallum Street #09-01

Tokio Marine Centre

Singapore 069046

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLM 1200Y
ACCIDENT ON 30/10/2017**

Instruction was received to inspect the vehicle Reg. No. SLM 1200Y. The inspection was conducted on 30/11/2017 at the premises of M/s Ah Lim Motor Company, 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SLM 1200Y
Make/Model	: Toyota Corolla Altis
Year of Registration	: 2009
Body Colour	: Silver
Chassis Number	: MR053ZEE106145252
Engine Capacity	: 1598cc

The vehicle caught fire. Cause of fire likely due to electrical nature. Pending investigations.
(Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 22,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 10,000.00)
Nett Liability	<u>S\$ 12,000.00</u>

Vehicle Inspected By:



ANG BRYAN TANI
Automotive Assessor / Investigator



K.K.LAU CPT (RET)
*BEng(Hons), B.Bus, MBA, PEng(UK), PE(USA),
MASME(USA), MInstAEA(UK), MIRTE, MCI Arb
REGD Auto Consultant-SAE, Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.