

ASS. REC. BY:

REF: CS/FCI/7022772/Ggbn2 Special Instruction:

SUPERVISOR:

GQ

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

FCI

Date/Time: 11:39am @ 30/11/2017

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 2823P

Insured:

SHD 3420K

at Workshop m/s

Tan Him Motor

Tel:

68685151

of

51 Defu Lane 10

Policy No:

Claim No:

D17611006 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A 25/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 11:47am @ 30/11/17

Person Contacted:

Ling Ling

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJW 2823P-X

SHD 3420K-CC3 / ICR 17011103 / H1W9392-D.O.A. 1/06/2017

SYNOPSIS

XMR.

REF:

Fci

ASSIGNMENT

(2019)

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s Tan lim

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$22K.

Record only

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJW2823P

Yr Regn:

23 Dec 2009

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

chevrolet Cruze c.c 1598

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

64273

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KL13A 6961A K 5849 55

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

continental

Front

Rear

R/Bal.

45

mm

R/Bal.

45

mm

L/Bal.

45

mm

L/Bal.

45

mm

D.O.A.

D.O.I.

30-11-17

Survey held at

w/s

2:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12/17

email preli to May.

13/12

Finalized \$4300 with Boss.

(Red: 662.33, 61%).

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation

(\$ + RS \$)

Photos

Others

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL

170

50

50

39

309

Report Format: Tip

Lump Sum / I.B.I: (\$ 4300)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022772/Ggb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3420K	Veh. Inspected	SJW 2823P
Policy No.		Coverage (\$)	0.00
Claim No.	D17011006MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	30/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/11/2017	Inspection Date	29/11/2017
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	28-11-2017	Our Ref No. D17011006MFSH
Accident Date	25-11-2017	Claim Type. Third Party
Insured Vehicle	SHD3420K	Third Party Vehicle. SJW2823P
Survey Location	51 DEFU LANE 10	
Contact Person.	LING LING	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231160)



PRI Documents



Close



PRI Header Details

Claim No	D17011006MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TAN LIM M
Workshop Name	TAN LIM MOTOR PTE LTD (Contact Person : LING LING)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68585151 , Fax: 68580877 EmailId: LINGLING@TLMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3420K	TP Vehicle No	SJW2823P
PRI Recieved Date	28-11-2017 07:47:46 PM	Surveyor Appointed Date	30-11-2017 11:38:27 AM	Surveyor Accept Date	30-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-11-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Friday, 1 December, 2017 12:47 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011006MFSH/1
Attachments: SJW 2823P.pdf

Dear May,

Enclosed herewith preliminary advise of vehicle SJW 2823P.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 30 November, 2017 12:09 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011006MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 30 November, 2017 11:38 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; MAYCHUA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011006MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011006MFSH

Date: 01-12-2017

Our Ref: CS/FCI17022772/Ggb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJW 2823P

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29-11-2017 at the premises of M/s TAN LIM MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 10,962.33
Revised Estimate Amount	: S\$ 4,208.10
"Check" Items Amount	: S\$ 562.23
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Yours faithfully

Xing Guo Qiang
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4076J
Vehicle Details	
Vehicle No.	SJW2823P
Vehicle to be Exported	Yes
Intended De-registration Date	27 Nov 2017
Vehicle Make	CHEVROLET
Vehicle Model	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour	Black
Manufacturing Year	2009
Engine No.	F16D35145261
Chassis No.	KL1JA6961AK584955
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$12,482.00
Original Registration Date	23 Dec 2009
First Registration Date	23 Dec 2009
Transfer Count	2
Actual ARF Paid	\$12,482.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	22 Dec 2019
PARF Rebate Amount	\$7,489.00
Intended COE Rebate Details	
COE Expiry Date	22 Dec 2019
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$6,281.00
COE Rebate Amount	\$3,553.00
Total Rebate Amount	\$11,042.00

The information contained herein is correct as at 27 Nov 2017

OK

► Cruze Used Vehicle List (15 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Chevrolet Cruze 1.6A	\$22,000	\$8,510 /yr	29-Sep-2009	1,598 cc	163,000 km		Available

Office No. - -

Peter - 98550121

Full Bodykit With 17" Rims. Excellent Condition. No Repairs Required. Selling As Car Is No More Needed. Loan And Insurance Can Be Arranged. No Dealers Please.

Chevrolet Cruze 1.6A	\$25,800	\$9,420 /yr	29-Dec-2009	1,598 cc	140,000 km		Available
----------------------	----------	-------------	-------------	----------	------------	--	-----------

Monthly Repayment \$613! Price Further Reduced To Sell! \$6k Drive Away Or Monthly \$844, Low Depreciation At \$26 Per Day Only, Cheaper Than Car Rental, No Repairs Required, Low Downpayment Available, Do...

Office No. - -

Roy - 97959866 | Gary - 90092442 | Won - 85894765 | Stanley - 90391156

Chevrolet Cruze 1.6A	\$22,800	\$7,980 /yr	28-Dec-2009	1,598 cc	138,000 km	Zenith Motoring	Available
----------------------	----------	-------------	-------------	----------	------------	-----------------	-----------

Office No. - 64403350

Daniel - 96922249 | Shawn - 97713161

Chevrolet Cruze 1.6A	\$24,800	\$9,010 /yr	24-Dec-2009	1,598 cc	-	Car Design Motor	Available
----------------------	----------	-------------	-------------	----------	---	------------------	-----------

Well Maintained And Service, Ease Of Drive, Safety And Reliability. Pristine Condition. No Repair Needed. Very Low Depreciation, Check With Our Friendly Consultants For More Information. In House Loan...

Office No. - 67468820

Sunny Ang - 90468282 | Anson - 88183368 | Roy Ong - 81888837 | Simon Tan - 91261801

Chevrolet Cruze 1.6A (OPC)	\$20,888	\$7,130 /yr	22-Dec-2009	1,598 cc	88,000 km		Available
----------------------------	----------	-------------	-------------	----------	-----------	--	-----------

Normal Conversion Available! Warranty For Engine Till May 2018. Low Mileage 88,000 Km! Car Only Use On Weekends! Price Negotiable! Call/SMS For Viewing!

Office No. - -

YH Tan - 96422398

Chevrolet Cruze 1.6A	\$24,900	\$9,120 /yr	17-Dec-2009	1,598 cc	-	SG Car Consign Pte Ltd	Available
----------------------	----------	-------------	-------------	----------	---	------------------------	-----------

Trendy Knight White Chevrolet Cruze 1.6A Sports With Premium Black Leather Upholstery Owned By Executive Owner Selling Due To Under Usage. 100% Accident Free! Well Maintained By Pervious Owner With Re...

Office No. - 61000200

Joey Kwan - 91191515

Chevrolet Cruze 1.6M	\$20,999	\$7,520 /yr	15-Dec-2009	1,598 cc	-	99 Motor Trading	Available
----------------------	----------	-------------	-------------	----------	---	------------------	-----------

No Regrets! Price Negotiable, Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.

Office No. - 62844922

Mr Nah - 81896183 | Bobby Geh - 96365598 | Ah Wong - 98533943 | Raymond Tang - 81850016

Chevrolet Cruze 1.6A (OPC)	\$22,800	\$8,310 /yr	30-Nov-2009	1,598 cc	69,891 km	Yong Lee Seng Motor	Available
----------------------------	----------	-------------	-------------	----------	-----------	---------------------	-----------

Evaluated By Vicom, Free 6 Months Maintenance And 1 Grooming.

Office No. - 68440123

Raymond Tang - 96250045 | Richmond Tang - 96200045

Chevrolet Cruze 1.6M	\$20,000	\$7,150 /yr	20-Nov-2009	1,598 cc	180,000 km	Motorist Pte Ltd	Available
----------------------	----------	-------------	-------------	----------	------------	------------------	-----------

No Regrets! Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.

Office No. - 65898800

Joseph - 81899232

Chevrolet Cruze 1.6A	\$22,800	\$8,550 /yr	30-Oct-2009	1,598 cc	104,112 km	Jet E Motor Trading	Available
----------------------	----------	-------------	-------------	----------	------------	---------------------	-----------

Low Down Payment, In House Finance Avail, Low Mileage Of Only 13000kms Travelled Yearly! Maintained And Serviced Regularly By Previous Owner, Call Before Sell.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

First Capital Insured's Veh No : SHD3420K

Date of Accident : 25 November 2017

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Kee Jia Min Agatha (Ji Jiamin)

Date : 28 November 2017

req: LKK.

Guoqiang

29-11-2017

2145hrs.

Supplementary To Repair SJW2823P - Chevrolet CRUZE 1.6L AUTO ABS D/AB 2WD 4

Chassis No : KL1JA6961AK584955

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s rear door / <i>Buc</i>	\$ 1,283.00
02	1 pc	n/s rear door power window motor with regulator <i>BT</i>	\$ 269.00
03	1 pc	rear door inner trimboard <i>CRA</i>	\$ 355.70
04	1 pc	rear door inner lock <i>X</i>	\$ 261.00
05	1 pc	rear door inner lock staker <i>X</i>	\$ 18.00
06	1 pc	rear door window glass channel weatherstrip <i>X</i>	\$ 323.00
07	1 pc	rear door outer weatherstrip moulding <i>X</i>	\$ 156.00
08	1 pc	rear door 1/4 glass pillar <i>X</i>	\$ 124.00
09	1 pc	rear door 1/4 glass weatherstrip <i>X</i>	\$ 104.00
10	1 pc	rear door weatherstrip <i>X</i>	\$ 130.00
11	1 pc	rear door hinge top <i>X</i>	\$ 41.00
12	1 pc	rear door hinge bottom <i>X</i>	\$ 41.00
13	1 pc	rear door checker / arrestor <i>X</i>	\$ 55.00
14	1 pc	rear fender <i>X</i> <i>Buc</i>	\$ 1,757.00
15	1 pc	rear fender inner cowlings <i>X</i>	\$ 85.00
16	6 pc	rear fender inner cowlings clips @ \$2.50 <i>X</i>	\$ 15.00
17	1 pc	rear fender 1/4 garnish <i>X</i>	\$ 35.00
18	1 pc	rear bumper <i>Cut</i>	\$ 1,151.00
19	1 pc	n/s rear bumper side retainer <i>Mc</i>	\$ 16.00
20	1 pc	rear windshield glass weatherstrip <i>X</i> <i>Mc</i>	\$ 65.00
21	1 pc	n/s rear shock absorber <i>X</i> <i>NN</i>	\$ 170.00
22	1 pc	rear wheel bearing with hub <i>Mc</i>	\$ 459.00
			\$ 6,913.70
		Less 10 %	\$ 691.37
			\$ 6,222.33
		<u>SPECIAL NETT ITEMS</u>	
23	1 pc	rear windshield glass sealant <i>X</i> <i>Mc</i>	\$ 180.00
24	1 pc	rear windshield glass sponge <i>X</i> <i>NN</i>	\$ 100.00
25	1 pc	n/s rear wheel rim <i>X</i>	\$ 300.00
26	1 pc	rear wheel tyre <i>SUR</i>	\$ 380.00
			\$ 960.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of n/s rear door fittings and perform water seepage test.	\$ 150.00
02		To remove and refit rear windscreen glass.	\$ 180.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00

985.3

185

1194

733

2993

3593.7

40

120

160

60

X MV

60



陳林厚喺私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

First Capital Insured's Veh No : SHD3420K

Date of Accident : 25 November 2017

Miss Kee Jia Min Agatha (Ji Jiamin)

Date : 28 November 2017

Supplementary To Repair SJW2823P - Chevrolet CRUZE 1.6L AUTO ABS D/AB 2WD 4
Chassis No : KL1JA6961AK584955

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
04		To rust-proofing of the affected areas.	\$ 150.00
05		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 450.00
06		To transfer of tyre, rim and on wheel balancing.	\$ 50.00
07		To check steering geometry and computer wheel alignment.	\$ 120.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
09		Putty and spray painting of the affected portion.	\$ 1,500.00
			\$ 3,780.00
		Total	\$ 10,962.33

60
x NN
30
60
600 800
600
1670

6 Days.
lumpsum repair
After repair photos.
Guo Qiang - 82880282
29/11/17

Guo Qiang
11/12/17

5423.7
20%: 4300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022772/Ggbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3420K	Veh. Inspected	SJW 2823P	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011006MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	30/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET CRUZE	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KL1JA6961AK584955	Colour	BLACK	
Odometer	64273	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	5 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	5 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	5 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/11/2017	Inspection Date	30/11/2017	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 2823P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S REAR DOOR	BUCKLED	1,283.00	985.30
1	N/S REAR DOOR POWER WINDOW MOTOR WITH REGULATOR	BENT	269.00	185.00
1	REAR DOOR INNER TRIMBOARD	CRACKED	355.70	355.70
1	REAR DOOR INNER LOCK	NOT NECESSARY	261.00	-
1	REAR DOOR INNER LOCK STUKER	NOT NECESSARY	18.00	-
1	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	323.00	-
1	REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	156.00	-
1	REAR DOOR 1/4 GLASS PILLAR	NOT NECESSARY	124.00	-
1	REAR DOOR 1/4 GLASS WEATHERSTRIP	NOT NECESSARY	104.00	-
1	REAR DOOR WEATHERSTRIP	NOT NECESSARY	130.00	-
1	REAR DOOR HINGE TOP	NOT NECESSARY	41.00	-
1	REAR DOOR HINGE BOTTOM	NOT NECESSARY	41.00	-
1	REAR DOOR CHECKER/ARRESTOR	NOT NECESSARY	55.00	-
1	REAR FENDER	BUCKLED	1,757.00	1,194.00
1	REAR FENDER INNER COWLING	NOT NECESSARY	85.00	-
6	REAR FENDER INNER COWLING CLIPS @\$2.50	NOT NECESSARY	15.00	-
1	REAR FENDER 1/4 GARNISH	NOT NECESSARY	35.00	-
1	REAR BUMPER	CUT	1,151.00	733.00
1	N/S REAR BUMPER SIDE RETAINER	NECESSARY	16.00	16.00
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NECESSARY	65.00	65.00
1	N/S REAR SHOCK ABSORBER	NOT NECESSARY	170.00	-
1	REAR WHEEL BEARING WITH HUB	NECESSARY	459.00	459.00
	LESS 10% DISCOUNT		-691.37	-399.30
			6,222.33	3,593.70
SPECIAL NETT ITEMS				
1	REAR WINDSHIELD GLASS SEALANT (SN)	NECESSARY	180.00	40.00
1	REAR WINDSHIELD GLASS SPONGE (SN)	NOT NECESSARY	100.00	-
1	N/S REAR WHEEL RIM (SN)	NOT NECESSARY	300.00	-

Report Ref No. CS/FCI17022772/Ggbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL TYRE (SN)	SCRATCHED	380.00	120.00
			960.00	160.00
	LABOUR			
	TO TRANSFER OF N/S REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.		150.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		180.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		150.00	60.00
	TO DROP REAR AXLE AND SUSPENSION ASSY, REMOVE AND RENEWAL OF NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING.	NOT NECESSARY	450.00	-
	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING.		50.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		120.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		1,000.00	800.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,500.00	600.00
			3,780.00	1,670.00
GRAND TOTAL			10,962.33	5,423.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CS/FCI17022772/Ggbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.