



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/11/2018

### Survey Details:

Date of loss	28-Nov-17
Date of appointment	30-Nov-17
Date of survey	30-Nov-17
Location of survey	ESTEEM PERFORMANCE PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SJC 7066E
Make and Model	TOYOTA VIOS 1.5E AUTO 1497cc
Date of registration	27-Feb-08
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

### Repair details:

Initial Estimate	\$ 9,759.36
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 3,447.61
Check items (estimate)	\$ -
Labour	\$ 2,570.00
<b>Total</b>	<b>\$ 6,017.61</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 4,800.00</b>

Number of days for repair	<u>9 DAY</u>
---------------------------	--------------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

### **Remarks:**

*We have not authorized repairs. Insured Driver Mr Wong (Transcab taxi) reported that he rear-ended TP. An email was sent out to Insured to notify TP claim. No feedback from Insured till date. TP LOD IN. For mandate approval.*

### **Mandate:**

Liability(TP)	100%	
Proposed Repair Cost	\$ 5,136.00	w/gst
Loss of Use	\$ 720.00	\$60 x 12 days
Loss of Rental (w/gst)	\$ -	no. of days
Loss of Income	\$ -	no. of days
LTA search fees	\$ 5.35	
Others	\$ -	
<b>Proposed Total</b>	<b>\$ 5,861.35</b>	

\*\*\*TBC - To Be Confirmed