

China

F2

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8519T

DATE 11/30/2017 14:34

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ?			\$ 225.00	
	Rear Bumper Clips 10 pcs ✓			\$ 22.00	
	SUB TOTAL			\$ 1,858.35	
	LESS 20%			\$ 371.67	
	DISCOUNTED TOTAL			\$ 1,486.68	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 200.00	200
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 30.00	x
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 550.00	
	ESTIMATE TOTAL			\$ 2,222.38	
Kalun (KKK) ✓ 30/11/17 1435hrs 2 Days. PRP Before Paint photo.					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____