LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd From: LKK Auto Consultants Pte Ltd

8 Shenton Way #24-01 51 Ubi Ave 1 #01-25 AXA Tower Paya Ubi Industrial Park Singapore 068811 Singapore 408933

Attn: Tan Wancong Date: 08 Dec 2017

Preliminary Advice

Insured Vehicle No : SGZ721H

TP Vehicle No : SLQ2420B Accident Date : 30/11/2017

Make : HONDA CITY Assignment Date : 04/12/2017

Date of Inspection : 01/12/2017 Est. Duration of Repair : 12 days

Inspection At : T & T Auto Services Pte Ltd (160 Sin Ming) (HQ)

BLK 160 SIN MING DRIVE, #08-14 SIN MÍNG AUTOCITY

Singapore 575722

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear and front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,027.92
Revised Amount	:S\$	7,602.85
Check Items (Estimated)	:S\$	1,296.56
Total	:S\$	8,899.41

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.