

ESTIMATE RC AUTO

Not Authorised
L1 by 87
Purvey After Paint
5 days

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

GBA 6396 P

Date : 1/12/2017

Toyota townace

Quantity	Description/Particular	Unit Price	Amount	
1 PC	Tailgate	\$ 1620	00	✓
1 PC	Tailgate Lock	\$ 120	00	✓
1 pc	Rear Bumper	\$ 490	00	✓
1 pc	Rear Panel	\$ 380	00	✓
1 pc	Rear Windscreen Moulding	\$ 114	00	✓
		Total\$	2724	00
		less 25	2043	00
	To transfer tailgate accessories	\$ 60	00	✓
	To reinstate windscreen	\$ 120	00	✓
	To replace above parts	\$ 800	00	600
	To respray job	\$ 500	00	✓
1 set	Reverse Sensor	\$ 250	00	2000
	70km/h sticker	\$ 20	00	1500
		Total\$	3793	00

Received the above goods in good order and condition

for RC AUTO

Received by

E.&O.E.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: