

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Rempang Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

04 DEC 2017

Estimate No. : b1 45040
Date Estimated : 04/12/2017
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Kee Song Wei
34 Hartley Grove

Singapore 457896

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ1288D	V791718	24/01/2017	216d CAT	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

850 1,700.00

Spray painting rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To replace rear PDC sensor wire harness including reset and checks for proper function.

226 266.00

Sundries.

? 80.00

Total Labour 1: 3,261.00

DESCRIPTION

REAR BUMPER PANEL PRIMED (PDC)

RR BUMPER RH SIDE GUIDE

REAR BUMPER CARRIER

SUPPORT

LEFT PROTECT

RIGHT PROTEC

REAR FLAP TOWING EYE PRIMED

Trim, drip r

RR RH LIGHT IN THE TRUNK LID

RR RH LIGHT IN THE SIDE PANEL

DECOUPING RING PDC TORQUE CONVERTER

DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	942.75	942.75
1	46.65	46.65
1	413.45	413.45
1	36.40	36.40
1	1.95	1.95
1	1.95	1.95
1	27.10	27.10
1	47.05	47.05
1	239.85	239.85
1	342.60	342.60
3/4	4.95	19.80
1	4.95	19.80

Total Parts : 2,139.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45040
Date Estimated : 04/12/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ1288D	V791718	24/01/2017	216d CAT	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>12/12/17 @ 1415</u>	Excess S\$ _____
Surveyor's Name <u>Ram</u>	Sign _____
Surveyor's Tel <u>90060068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Resurvey 64 pint

Labour 1	:	3,261.00
Parts	:	2,139.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	378.02
Grand Total	:	<u>5,778.37</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **