

INS. CASE OWNER:

CC6 / CTI1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

PTE 1125

SGP 88484

SFJ 6841K



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / CIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

ost-Repair Photos:

Others:

Confirm by: (then) TO CLAIM LAST VEHICLE

Email

Call

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

If NO or B 28. Ass. Lia:

Email

Call

REPAIR COST:	SS	() days	Reduction:	%
GLOBAL SETTLEMENT	Date/Time:	Confirm with	Email	Call
Insured Liability:	%	(Agreed / Assessed)	BOLA S/N No.:	
Repair Cost:	SS			
Loss of Rental (LOR):	SS	() days		
Loss of Use (LOU):	SS	(\$ x days)		
Loss of Income (LOI):	SS	(\$ x days)		
LOI only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]
GR/LTA Search:	SS			
Medical:	SS			
Disbursement:	SS	(e.g. Tow/ Independent)		
Legal Cost:	SS			
Total:	SS	Global Sum \$S:		
GLOBAL PAYMENT	Date/Time:	Confirm with:	Email	Call
Payee 1:	SS	Name 1:		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPIES SENT
7/3/2018

Summary

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SFI6899K Yr Regn 2008 oct
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make Toyota Alphard C.C. 2362
 Colour Black A/C Insured / Std / NI / NA
 Sp. Reading 178376 T. Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No. ANH208010797

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18
 R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.L. <u>04/12/17</u>

Survey held at Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Chrm.</u>
	<u>4/1 - \$1800 (Reel \$5931.10 / 771)</u>

Date/Time, File Pass to? ☐ : Prel. Report

File ☐ : Final Report

Date/Time, File Return to?

to

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

_____ \$ - \$0.00

Photo

Other 924

Total

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech Insp \$

☐ Weekend \$

Report Format :

Lump Sum / I.B./I: \$

\$254



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17022960/Ahb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGP 8858Y	Veh. Inspected	SFJ 6899K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/11/2017	Inspection Date	04/12/2017
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SFJ689

Toyota AI

ANH208c

Rear Bumper

Rear Bumper 1

Rear Bumper

Rear Bumper 1

Rear Bumper

Reverse Sensor

Rear End 1

Tailgate

Tailgate Lock

Tailgate GL

Tailgate Glass Sealant

Toyota Logo

Alphard Wordley

0.10

1.379. +

30. +

130. +

45. +

58.1 +

78.9 =

1.731. x

1.731. x

75. x

1.298.25 +

200. +

200. +

300. +

400. +

30. +

50. +

50. =

830. x

1.298.25 +

200. +

830. =

2.328.25 x

2.328.25 x

80. x

1.860.5 x

0.10

1.860.5 x

1379 ✓

30 ✓

65x2 = 130 ✓

45x2 = 90 45

68.3x2 = 136.60 +

280 (SN) 200 (SN)

762.80 +

1593 +

399.10 +

193.60 +

60 (SN) +

68.10 ✓

78.90 ✓

1731

SN: 400

1298.45

SFJ6899K

Panel Beating

Spray Painting,

Wiring.

To undersoil

To remove reverse sensor

To transfer tailgate fitting

To remove tailgate glass

To remove upholstery.

~~1500~~ 3.00

~~800~~ 4.00

~~55~~ 3.0

100 x

~~100~~ 50

150 x

180 x

~~150~~ 50

830

total 2328.25

4/5 1.8K

03000

Consultants hence notify
 Repairer of the following:
 • Survey before/after spray painting
 • Display damaged part(s) during resurvey
 • Prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Shu Pei (LKKAUTO)

From: Joel Goh <joel.goh@sg.cntaiping.com>
Sent: Monday, 11 December, 2017 11:02 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SGP8858Y (OI : CTI - SNM17D06921C02/8) and SFJ6899K (TP : LKK REF - CC6/CTI17022960/hb3) on 25.11.2017

Dear Shu Pei

Our insured have not reported this accident.

Best Regards

Joel Goh
Claims Executive (Motor Division)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02
Springleaf Tower Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6184
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
joel.goh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 11 December, 2017 10:46 AM
To: Joel Goh <joel.goh@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SGP8858Y (OI : CTI - SNM17D06921C02/8) and SFJ6899K (TP : LKK REF - CC6/CTI17022960/hb3) on 25.11.2017

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [<mailto:joel.goh@sg.cntaiping.com>]

Sent: Tuesday, 5 December, 2017 11:25 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SGP8858Y (OI : CTI - SHM17D06921C02/8) and SFJ6899K (TP : LKK REF - CC6/CTI17022960/hb3) on 25.11.2017

Dear Shu Pei

Our insured have not reported this accident.
Attached our letter sent to insured today.

Best Regards

Joel Goh
Claims Executive (Motor Division)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02

Springleaf Tower Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6184

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

joel.goh@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Monday, 4 December, 2017 4:17 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Joel Goh <joel.goh@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving SGP8858Y (OI : CTI - TBA) and SFJ6899K (TP : LKK REF - CC6/CTI17022960/hb3) on 25.11.2017

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case from M/s Modern Automotive Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeij@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079908
Tel: 6399 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208394E

Our Reference: **SNM17D06921/C02/8**

Date : **05 DECEMBER 2017**

via Ordinary & Registered Mail

**TAN CHIN YANG (NON-DRIVER)
BLK 114 BUKIT PURMEI ROAD
#09-235
SINGAPORE 090114**

Dear Sir / Madam

**ACCIDENT INVOLVING SGP8858Y AND SFJ6899K ON 25 NOVEMBER 2017
ALONG TUAS LINK 2 TOWARDS MALAYSIA CHECKPOINT**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SFJ6899K**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of **our authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIC
Ref : CC6/CTI17022960/hb3
Contact No : 6841 2096
via Email : vicalpeh@lkkauto.com

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F02/LKKDSANR-2013



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/CTII7022960/Ahb3

12th December 2017

TAN CHIN YANG
BLK 114 BUKIT PURMEI ROAD
#09-235
SINGAPORE 090114

Dear Sir / Madam,

**ACCIDENT INVOLVING SGP 8858Y AND SEJ 6899K ON 25TH NOVEMBER 2017
ALONG/AT TUAS LINK 2 TOWARDS MALAYSIA CHECKPOINT**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a **THIRD PARTY** claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** dated 05 DECEMBER 2017.

To enable us to look into the matter immediately, please let us hear from you within **seven (7)** days from date of this letter (by 19TH December 2017).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/CTI17022960/Ahb3

15th JANUARY 2018

TAN CHIN YANG (NON DRIVER)
BLOCK 114 BUKIT PURMEI ROAD
#09-235
SINGAPORE 090114

Dear Sir / Madam,

**ACCIDENT INVOLVING SGP 8858Y AND SFJ 6899K ON 25th NOVEMBER 2017
ALONG TUAS LINK 2 TOWARDS MALAYSIA CHECKPOINT**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD** to settle a **THIRD PARTY** claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from **CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD** dated 05th December 2017.

To enable us to look into the matter immediately, please let us hear from you within **seven (7) days** from date of this letter (by 25th January 2018).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,


Vic Alpeh Sanghilan
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

To : Traffic Police – Deputy Head, Investigations Department
Fax : 65474885

ONLY FOR ACCIDENTS IN SINGAPORE

NON-INJURY MOTOR ACCIDENT REPORT SCHEME
FORM ON NON-REPORTING BY INSURED

Please be informed that we have yet to receive a motor accident report from our insured with regard to a non-injury motor accident as follows:-

Date of accident : 25/11/2017
Time of accident : 1130HRS
Place of accident : Along TUAS LINK 2 TOWARDS MALAYSIA
Third Party's name : MR ANTHONY TENG
Third Party's vehicle number : SFJ 6899K
Our insured's name : TAN CHIN YANG (NON-DRIVER)
Our insured's vehicle number : SGP 8858Y
Our insured's NRIC number : TBA
Our insured's address : BLOCK 114 BUKIT PURMEI ROAD
#09-235
SINGAPORE 090114

Our Insured's telephone number : TBA

A letter dated **(05/12/2017 and 12/12/2017)** was sent to remind our insured to report the non-injury motor accident to us. No report has yet been made.

Please do not hesitate to contact the following for any clarification on the matter.
(Please cite our reference number: **CC6/CTI17022960/Ahb3**)

Name and address of insurance company: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079079909120

Name of contact person : Vic Sanghlan
Contact Number : 6256 3561 / Fax: 6741 4108
Date : 15/01/2018

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Thursday, 5 September 2019 3:19 PM
To: Claims Dept of CTI
Cc: Elaine Cheong
Subject: Your ref: SNM17D06921/C02/8 [ACCIDENT INVOLVING VEHICLES SGP8858Y AND SFJ6899K ON 25/11/2017]

Dear Sir/Mdm,

We have checked with Third Party and confirm that they decided to withdraw the claim.

We will proceed to close and submit WP report.

Thank you.

Best Regards,

Carlton Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



POSTING RECEIPT FOR REGISTERED ARTICLE(S)

¹ Seneca's focus was to be used for Insured and Non-Insured Registered Article.

- a) Separate forms are to be used for Insured and Non-Insured Registered Article.
 b) Please provide all information required and produce this receipt for all enquiries.
 c) Please tick where applicable. It shall be assumed no Advice of Receipt (AR) is required or delivery by air is requested if relevant * is left blank.
 d) Please indicate the return address on the item(s) to ensure prompt return in event of non-delivery to the addressee(s).
 e) Please post item(s) at the post office counter according to the sequence stated below.

For Official Use Only (Item numbers are printed in order of posting at counter)									
1. Name & Address of Addressee CONGRATULATE PEB USD 1 BAKER WHEEL CONCRETE #02-53 WICKGA WAREH C/O 688064 CON: 09010114 TO: 09010114		AIR*: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N		By*: () N		() AIR () SUR		R6 YSH Ref: 1936-037/00000000 Date: 17 Jan 2018 R6 Hrs: 1026123011356 R626123012796	
		Insurance*: () Y <input type="checkbox"/> SS							
		Contents:							
2. Name & Address of Addressee TAS GARD 4486 BANK 114 BAKER WHEEL RCD #09-735 C/O 090114 CON: 09010114 TO: 09010114		AIR*: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N		By*: () N		() AIR () SUR			
		Insurance*: () Y <input type="checkbox"/> SS							
		Contents:							

Sander's Agreement

I have read, understood and agreed to the terms and conditions of posting auralife. I accept the maximum liability payable for Registered Mail Service and certify that all information provided by me does not contain any hazardous or prohibited items.

Name & Signature

Date _____

is true
p.16

SINGAPORE POST
MACPHERSON RD
GST Reg. Add: SINGAPORE POST CENTRE
10 EUNOS ROAD 8
SINGAPORE 408600
GST Reg. No : M2-0105651-9
Date: 17 Jan 2018 Time: 10:43:43

Description	Amount (S\$)	GST@7%
-------------	--------------	--------

Ref. No: PSL01/1926/017/0046

Postage Label

LOCAL

31

3 X	2.54	7.62	0.50
-----	------	------	------

SUB TOTAL	7.62	0.50
-----------	------	------

TOTAL AMOUNT	7.62
--------------	------

GST COLLECTED BY SINGPOST	0.50
---------------------------	------

MOP : CASH : \$7.62

Collect a FREE HPB steps tracker at participating Post Offices located island-wide! Book an appointment now at stepschallenge-appointment.com! Terms & conditions apply.

Pay any bills on SAM and earn LinkPoints now! Terms & conditions apply

Thank you for visiting Singapore Post

#Zero-rated for GST

*Exempt

- +Out of Scope

**Supplier Item

Price inclusive of 7% GST where applicable

I have checked & confirmed the product is visually good, functional & performed within expectation.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17022960/Ada3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 05-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGP 8858Y	Veh. Inspected	SFJ 6899K
Policy No.		Coverage (\$)	0.00
Claim No.	SNM17D06921/C02/8	Excess (\$)	0.00
Assign From		Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALPHARD	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ANH208010797	Colour	BLACK
Odometer	178376	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	6 mm
L/H Front Tyre	235/50 R18	MICHELIN	6 mm
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/11/2017	Inspection Date	04/12/2017
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 6899K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,379.00	1,379.00
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER @\$65.00	NECESSARY	130.00	130.00
2	REAR BUMPER TOW COVER @\$45.00	N/S MISSING	90.00	45.00
2	REAR BUMPER REFLECTOR @\$68.30	NOT NECESSARY	136.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	762.80	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,593.00	-
1	TAILGATE LOCK	NOT NECESSARY	399.10	-
1	TAILGATE GLASS MOULDING	NOT NECESSARY	193.60	-
1	TOYOTA LOGO	NECESSARY	68.10	68.10
1	ALPHARD WORDING	NECESSARY	78.90	78.90
	LESS 25% DISCOUNT		-	-432.75
			4,861.10	1,298.25
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
			340.00	200.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND TAILGATE .		1,000.00	300.00
	SPRAY PAINTING.		800.00	400.00
	WIRING .		50.00	30.00
	TO UNDERSEAL .	NOT NECESSARY	100.00	-
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO TRANSFER TAILGATE FITTING.	NOT NECESSARY	150.00	-
	TO REMOVE TAILGATE GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE UPHOLSTERY.		150.00	50.00
			2,530.00	830.00
GRAND TOTAL			7,731.10	2,328.25

Report Ref No. CC6/CTI17022960/Ada3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	----------

Report Ref No. CC6/CTI17022960/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.