

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Ref:

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CS3/EQI17023044/Wbe2 18-04-2018

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND

COMPLEX SINGAPORE 069110

Date: 18-04-2018

			Code: EQI					
1.	Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	SJH 4052M	Veh. Inspected	GBE 815R				
	Policy No.		Coverage (\$)	0.00				
	Claim No.	DM17HO02700	Excess (\$)	0.00				
	Assign From	BAZLIN AHMAD	Assign Date	05/12/2017				
2.	Vehicle Particulars & Condition							
	Make & Model	TOYOTA DYNA	c.c	2982				
	Engine No.	HIDDEN	Year of Reg.	2015				
	Chassis No.	JTFAT35YX0K204893	Colour	SILVER				
	Odometer	109257 KM	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM				
	General	FAIR						
3.	Conditions of Tyres							
		Size	Make	Balance				
	R/H Front Tyre	195/75 R15	YOKOHAMA	4 mm				
	L/H Front Tyre	195/75 R15	YOKOHAMA	4 mm				
	R/H Rear Tyre	155 R12C	YOKOHAMA	4 mm				
	L/H Rear Tyre	155 R12C	YOKOHAMA	4 mm				
4. Description of Damages								
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.							
5.	General Information							
		05/44/0047		00/40/0047 / 44 00 004)				

5.	General Information						
	Accident Date	25/11/2017	Inspect Date / Time	06/12/2017 (11:06 AM)			
	Survey held at	SYNERGY MOTOR					
		53 UBI AVE 1 #01-45 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934					

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:

D FOR REPAIR: 4 Working Days

Report Ref No. CS3/EQI17023044/Wbe2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.