

ASSA REC. BY:

REF: CS/MSG17023045/Ktber

Special Instruction:

Surveyor:
Menmen

Kenneth

ASSIGNMENT (Office)

From (Person): Winnie Chua

of

MSG

Date/Time:

5/12/17 @ 11:07am

Estimated Cost:

Bill to:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV / ☐ CS

To Inspect Vehicle No:

SJT 360L

Insured:

at Workshop m/s

Lai Hui (Meng Kee)

Tel:

G4338110

of 160 Sin Ming Drive #01-01, 575722

Policy No:

288 22315AMX

Claim No:

538363

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

24/11/17

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:15am @ 5/12/17

Person Contacted:

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

5/12 -

SJT 360L - x
Revert via menmen

5/12 -

16:17 - Authorise by Jenny Ong

5/12 -

4:30pm inform Jenny authorise repair excess \$500.

ASS. REC. BY:

REF:

MSG /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$93k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.5% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJT 360L Yr Regn: 08.11

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: M. 250 cc 1796

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 124073 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2120478 A 410667

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: Inorder / ☒ Jammed / ☐ Leaked / ☐ Burnt orBrake: Inorder / ☒ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 245/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front: ☒ mmR/Bal. ☒ mmL/Bal. ☒ mm

D.O.A. 24/11/17 D.O.I. 5/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

M O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/12 File pass to Coroner

Confirmed \$9489.50; 7 days (Red 1344; 12%)

RECEIVED 24 AUG 2018

23/8/2018

Date/Time, File Pass to?

12412 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$9489.50)

☐ Prel. Report☐ Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17023045/Ktb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 05-12-2017	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected		SJT 360L
	Policy No.	28822315QMX	Coverage (\$)	0.00
	Claim No.	538363	Excess (\$)	500.00
	Assign From	MERIMEN (WINNIE CHUA)	Assign Date	05/12/2017
2. Vehicle Particulars & Condition				
	Make & Model	c.c		0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	24/11/2017	Inspection Date	05/12/2017
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Nov 2017 Sendback Est	05 Dec 2017 10:53 S\$10,428.70	05 Dec 2017 11:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	HO SHOK FONG, ID: S0161107J, Tel: +6591386298, Email: Hoshokfong51@yahoo.com.sg								
Vehicle Reg. No.:	SJT360L	Date of Loss:	24/11/2017 17:00 - :59						
Claim Type:	OD / 538363	Policy/Cover Note No.:	28822315QMX (Comprehensive) Coverage: 09/09/2016 - 26/12/2017						
		Excess:	S\$500.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/12/2017]								
Driver/Custodian:	HO SHOK FONG (64 / Male), NRIC: S0161107J, Tel: +6591386298								
Adj Asg. Remarks:	Please revert. OI continued to drive 53km after accident. Any Aggravated damages?								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2017 11:44
Date Of Accident	24/11/2017 17:30
Exact Location Of Accident	YISHUN STREET 81
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT360L
Insured/Policyholder	
Name Of Registered Owner	HO SHOK FONG
NRIC No	S0161107J
Email Address	HOSHOKFONG51@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91386298
Alternative Phone No	OFFICE-91386298
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E250-1.8 CGI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	82010456
Driver	
Name of Driver	HO SHOK FONG
NRIC No	S0161107J
Date Of Birth	31/12/1952
Occupation	INDOOR
Date Of Driving Pass	07/05/1979
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91386298
Fax Number	
Contact Number	OFFICE-91386298
Email Address	HOSHOKFONG51@YAHOO.COM.SG

Address	BLK 180 BUKIT BATOK WEST AVENUE 8 #08-191
Postcode	650180
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-
General Information of the Accident	
Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY
Other Information	
Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1
Details of Police Action	
Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	
Circumstances of Accident	
Attachment(s)	
Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO EXTRACT OR COPY VIDEO FROM CAMERA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBB7003L
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	

Email Address

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FB87003L

Were seat belts worn?

NO

Was injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: MD Shabir
NIC/ITN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached police report.

Video has been submitted to traffic police

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Moshobir
NRIC/PIN No.:



**SINGAPORE
POLICE FORCE**



T/20171124/2146

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

1 of 3

Report No. T/20171124/2146

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/11/2017 19:52		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: HO SHOK FONG			Address: APT BLK 180 BT BATOK WEST AVE 8 #08-191 HDB-BUKIT BATOK SINGAPORE 650180		
ID Type / ID No.: NRIC NO / S0161107J			Contact No.: Home/Office: Mobile: 91386298		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 31/12/1952	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Chef			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 24/11/2017 17:30	Type of Location:
Location: Junction of Road 1 and Road 2 YISHUN CENTRAL YISHUN STREET 81				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBB7003L	Motorcycle				Totally Damaged	0
SJT360L	Car				Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171124/2148

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

2 of 3

Report No. T/20171124/2148

CONTINUATION OF REPORT

DRIVER			
Name	HO SHOK FONG	ID No.	S0161107J
Related Vehicle	NIL	Contact No.	91366298
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

AT THE ABOVE STATED TIME, DATE AND LOCATION.

I WAS COMING OUT FROM YISHUN HOSPITAL CARPARK, I TURNED LEFT AND THE TRAFFIC LIGHT WAS RED AND THERE WAS ONE VEHICLE IN FRONT OF ME ON THE FIRST LANE. AS SOON AS IT TURNED GREEN, THE VEHICLE STARTED MOVING OFF SLOWLY. THE VEHICLE IN FRONT OF ME WANTED TO MAKE A RIGHT TURN, WHICH IS WHAT I INTENDED TO DO. AS SOON AS THE CAR IN FRONT OF ME STARTED TURNING RIGHT, I FOLLOWED THE CAR. A MOTORCYCLE CAME FROM THE OTHER SIDE AND BANGED INTO THE FRONT AND RIGHT SIDE OF MY VEHICLE AND HE FELL OFF HIS BIKE. ABOUT 15 MINS AFTER THE ACCIDENT, AMBULANCE ARRIVED TO SCENE FOLLOWED BY TRAFFIC POLICE.

THE RIDER WAS BROUGHT BACK TO KHOO TECK PUAT HOSPITAL AS HE WAS INJURED. THE POLICE ADVISED ME TO HEAD DOWN TO TRAFFIC POLICE HQ TO MAKE A REPORT AND MEET IO BEI FENG. THAT'S ALL.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171124/2146

3 of 3

Report No. T/20171124/2146

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / KHALED AMR HASSAN MOHSEN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sgt 3 LIM ENG KUAN, CLARENCE Contact No.: 65476195

Authentication Stamp
NP168

Signature Of Informant:
Date/Time: 24/11/2017 19:52
Classification Of Case:
SINGAPORE POLICE FORCE Signature:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0161107J



Name
HO SHOK FONG
何灼芳
Race
CHINESE
Date of birth
31-12-1952
Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: **S0161107J**
Name
HO SHOK FONG
Exp. Date: **31 Dec 1952**
Valid Date: **03 Apr 2003**



4842248



License No: **S0161107J**



Date of issue
13-03-2010

Address
**APT BLK 180 BUKIT BATOK WEST AVENUE 8
#06-191
SINGAPORE 850180**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

	PASS DATE
• Class 10 Motorcycles not exceeding 200 cc	07 Jul 1988
• Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms	07 May 1979

NT 426A

License No: **S0161107J**





MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412213G GST Reg. No. 20-0412212G

MOTOR INSURANCE COVER NOTE

Cover Note No. 82010456

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Agent No. : 190102
Name of Insured : Ho Shok Fong
Make and Description of Vehicle : Mercedes Benz E250CGI
Vehicle Registration No. : SJT360L
Year of Manufacture : 2011
Engine No. : 27186030211357
Chassis No. : WDD2120472A410667
Capacity : 1,796 Cubic Capacity
Cover Type : Comprehensive
Sum Insured (SGD) : Market Value
Period of Insurance : 09/09/2017 to 26/12/2017
Excess (SGD) : 600

I/We hereby certify that this Covering note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the
Company's Authorised Representative

MSIG Insurance (Singapore) Pte. Ltd.
Authorised Insurers

Authorised Representative

Amy Ler
Senior Vice President, Agencies

Date of Issue : 16/06/2017

This covering note is valid for 30 days from the date of issue.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	1107J

Vehicle Details

Vehicle No.	SJT360L
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	MERCEDES BENZ
Vehicle Model	E 250CGI
Primary Colour	Silver
Manufacturing Year	2011
Engine No.	27186030211357
Chassis No.	WDD2120472A410667
Maximum Power Output	150.0 kW (201 bhp)
Open Market Value	\$53,854.00
Original Registration Date	27 Jun 2011
First Registration Date	27 Jun 2011
Transfer Count	2
Actual ARF Paid	\$53,854.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	26 Jun 2021
PARF Rebate Amount	\$35,005.00

Intended COE Rebate Details

COE Expiry Date	26 Jun 2021
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$67,700.00
COE Rebate Amount	\$24,238.00
Total Rebate Amount	\$59,243.00

The Information contained herein is correct as at 28 Nov 2017

OK

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg
UEN: 199407592C

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	69044
Policy No:	28822315QMX	Date of Loss:	24/11/2017
Vehicle Reg. No.:	SJT360L	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	HO SHOK FONG	Contact No:	+6591386298
Driver:	HO SHOK FONG		

Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	01/01/2011
Vehicle Colour:	Silver		
Engine No:	27186030211357	Chassis No:	WDD2120472A410667
Odometer:	124073 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

10/7 days

for oil



*Not Attracted
1.2,
Repairing B4 paint
Ex \$500*

Description of Accident/Loss: OI TURNED RIGHT AND COLLIDED WITH TP

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / VICTOR FAN

COST OF CLAIMS

	Amount
Parts	8,578.70
Miscellaneous Items	0.00
Labour	1,000.00
Paintwork Labour	850.00
Towing	0.00

Calculated Gross Total (S\$)	10,428.70
- Excess (S\$)	500.00
(S\$)	9,928.70
+ GST 7.00% (S\$)	695.01
Nett Amount (S\$)	10,623.71

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)
 Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJT360L/05/12/2017 10:53
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Bonnet	R ₁ 0.00	0.00	*1,135.00 F	✓
2	1		*Bonnet hinge RH	D ₁ 0.00	0.00	*72.00 F	✓
3	1		*Bonnet hinge actuator LH	Sm 0.00	0.00	*182.00 F	?
4	1		*Bonnet hinge actuator RH	Act 0.00	0.00	*182.00 F	✓
5	1		*Bonnet rubber seal	Gr 0.00	0.00	*12.00 F	✓
6	1		*Bonnet spring stopper LH	Sm 0.00	0.00	*12.00 F	?
7	1		*Bonnet spring stopper RH	Gr 0.00	0.00	*12.00 F	✓
8	1		*Bonnet lock RH (lower)	R ₂ 0.00	0.00	*35.00 F	X
9	1		*Bonnet latch striker	R ₁ 0.00	0.00	*35.00 F	✓
10	1		*Front bumper	CM 0.00	0.00	*725.00 F	✓
11	1		*Front bumper reinforcement	R ₁ 0.00	0.00	*260.00 F	✓
12	1		*Front bumper centre grille	D ₁ 0.00	0.00	*35.00 F	✓
13	1		*Front bumper inner frame centre	CM 0.00	0.00	*35.00 F	✓
14	1		*Front bumper sponge RH	Gr 0.00	0.00	*26.00 F	✓
15	1		*Front bumper sponge (centre)	CM 0.00	0.00	*52.00 F	✓
16	1		*Front bumper tow hook cover	Gr 0.00	0.00	*28.00 F	✓
17	1		*Front bumper top clip LH	Gr 0.00	0.00	*5.00 F	✓
18	1		*Front bumper top clip RH	Gr 0.00	0.00	*5.00 F	✓
19	1		*Front bumper reinforcement side beam RH	D ₁ 0.00	0.00	*25.00 F	✓
20	1		*Front bumper lower bracket RH	D ₁ 0.00	0.00	*30.00 F	✓
21	1		*Radiator grille	CM 0.00	0.00	*555.00 F	✓
22	1		*Front fender RH	R ₁ 0.00	0.00	*500.00 F	✓
23	1		*Front fender chrome moulding RH	Sm 0.00	0.00	*19.00 F	✓
24	1		*Front fender inner shield RH (front)	CM 0.00	0.00	*80.00 F	✓
25	2		*Front fender inner shield clips RH	Gr 0.00	0.00	*7.00 F	✓
26	1		*Front bumper parking sensor wire harness	Sm 0.00	0.00	*108.00 F	?
27	1		*Front headlamp RH (used parts) S/N 12-58	R ₂ 0.00	0.00	*1,610.00 F	✓
28	1		*Front headlamp nozzle RH	Sm 0.00	0.00	*100.00 F	✓
29	1		*Engine lower cover	CM 0.00	0.00	*120.00 F	✓
30	1		*Front centre top panel	R ₁ 0.00	0.00	*75.00 F	✓
31	1		*Front headlamp panel RH	R ₁ 0.00	0.00	*125.00 F	✓
32	1		*Front headlamp panel support bracket RH	D ₁ 0.00	0.00	*16.00 F	✓
33	1		*Front daylight lamp RH	Gr 0.00	0.00	*250.00 F	✓
34	1		*Front daylight chrome cover RH	Gr 0.00	0.00	*62.00 F	✓
35	1		*Front daylight base cover RH	Sm 0.00	0.00	*32.00 F	✓
36	1		*Front air con air guide, top	CM 0.00	0.00	*33.00 F	✓
37	1		*Front air con air guide, lower	CM 0.00	0.00	*77.00 F	?
38	1		*Front centre top panel cover	CM 0.00	0.00	*65.00 F	?
39	1		*Front number plate garnish	D ₁ 0.00	0.00	*87.00 F	✓
40	1		*Front parking sensor RH, inner	D ₁ 0.00	0.00	*138.00 F	✓
41	1		*Front parking sensor RH, outer	Sm 0.00	0.00	*138.00 F	?
42	1		*Air con condenser	R ₁ 0.00	0.00	*633.00 F	✓
43	1		*Radiator top lock pin LH	Gr 0.00	0.00	*20.00 F	✓
44	1		*AC decal	R ₁ 0.00	0.00	*14.00 F	✓
45	1		*Front number plate	Gr 0.00	0.00	*35.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)

7,802.00

+ Margin on L,N Items 10.00% (S\$) 776.70

Total Parts (S\$) 8,578.70

Lai Huat (Meng Kee) Motor Pte Ltd/SJT360L/05/12/2017 10:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (including front windscreen pillar RH)	New	850.00
<u>Labour Items</u>			
2	To check wheel alignment	New	60.00
3	To remove + refix roof top moulding RH	New	60.00
4	To remove + renew air con condenser and refill gas	New	120.00
5	Using diagnostic equipment to erase/check fault codes	New	60.00
6	To straighten front body, to knock dents on front wheelhouse top panel RH and renew of parts	New	700.00
Gross Labour Cost (\$\$)			1,850.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJT360L/05/12/2017 10:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LUK Auto Consultants hereby notify the Repairer of the following:

- To receive the vehicle only during
- To supply a 24-hour emergency towing service
- Parts prices are subject to price increase
- Third party claims are on a "Without Prejudice" basis
- No Rega claim involved is allowed
- Supplemental claims for uninsured loss is subject to the insurance company

Accepted by Repairer

Signature:

Date:

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Apr 2018)
 Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJT360L/01/04/2018 22:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper reinforcement bracket	0.00	0.00	138.00 F
2	1		*Power steering cooling pipe	0.00	0.00	160.00 F
3	1		*Power steering fluid	0.00	0.00	32.00 F
4	1		*Bonnet U-shaped striker	0.00	0.00	20.00 F
5	1		*Front engine hood catch	0.00	0.00	18.00 F
Sub Total (S\$)						368.00
+ Margin on L,N Items 10.00% (S\$)						36.80
Total Parts (S\$)						404.80

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SJT360L/01/04/2018 22:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD. TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089722

DATE	05/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan.Tan
CUSTOMER REF.	SJT360L	OUR REF.	41845

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUATI TIME:16:48
 LAI HUAT (MENG KEE) MOTOR PTE LTD
 160, SIN MING DRIVE
 #04-01/#04-02 AND #07-03
 SIN MING AUTOCITY
 SINGAPORE 575722
 Telephone No : 4533757, A4598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD
 160, SIN MING DRIVE
 #04-01/#04-02 AND #07-03
 SIN MING AUTOCITY
 SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 M2A212 880 10 83 9040	1. FRONT GRILLE AVANTGARD 21	1D-8L	1 PC	555.00	✓ 555.00
2 M2A212 880 01 57	2. ENGINE HOOD W212 '10-'12 1	6B-7A	1 PC	1,135.00	✓ 1,135.00
3 M2A204 880 02 28	3. HENGE 2	1A-07E	1 PC	72.00	✓ 72.00
4 M2A212 906 63 01	4. ACTUATOR A	1E-10A	1 PC	182.00	✓ 182.00
5 M2A212 887 00 98	5. GASRET 5	1C-3F	1 PC	12.00	✓ 12.00
6 M2A204 880 02 27	6. ENGINE HOOD SPRING 7	1B-03F	1 PC	12.00	✓ 12.00
7 M2A212 880 12 18	7. BENDER 22	3B-2E	1 PC	500.00	✓ 500.00
8 M2A212 880 19 40	8. FRONT BUMPER W212 AVANTGARDE 10	6I-2	1 PC	725.00	✓ 725.00
9 M2A212 620 15 00	9. CROSS MEMBER FRT 11	3B-02D	1 PC	260.00	✓ 260.00
10 M2A212 885 05 23	10. FR BUMPER LWR GRILLE W212 12	1AA-1I	1 PC	35.00	✓ 35.00
11 M2A212 620 11 00	11. SPRING 30	3B-01B	1 PC	75.00	✓ 75.00
12 M2A212 620 02 91 64	12. M2A212 620 02 91/FRAME 31	3B-3B	1 PC	125.00	✓ 125.00
13 M2A212 880 01 60	13. FASTENER 9	1B-04G	1 PC	35.00	✓ 35.00
14 M2A212 620 00 28	14. BRACING 32	1A-2G	1 PC	16.00	✓ 16.00
15 M2A204 906 90 00	15. DAYTIME RUNNING LIGHT 33	1C-06F	1 PC	250.00	✓ 250.00
16 M2A212 885 18 23	16. COVER BUMPER AREA 34	1E-11I	1 PC	62.00	✓ 62.00
17 M2A212 505 14 30	17. AIR BUFFLE 36	1D-4I	1 PC	33.00	✓ 33.00

4084

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor



C.S. JOINT MADE IN JAPAN

Stockists

TOTAL

ADD GST

AMOUNT DUE



SIGN & COMPANY'S STAMP

DATE

ALL CHECKS MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

Signature of Alan Tan

FOR MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.
 Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
 Singapore 339564.
 Tel: 6298 3888 Fax: 6297 0863 (Accounts)
 E-mail : info@minghee.com
 Website : http://www.minghee.com

TAX INVOICE

INV NO : 8089722

DATE	05/12/2017	PAGE	2
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF	41845

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 16:48

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 4533757, 44598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
18	FR. INNER FENDER RH, FR W2 34	1A-81	1 PC	77.00	✓ 77.00
19	SENDER UNIT 40	3A-2A	1 PC	80.00	✓ 80.00
20	BEARING 43	1C-9A	1 PC	138.00	✓ 138.00
21	BEARING 43	1B-6J	1 PC	87.00	✓ 87.00
22	CONDENSOR 42	6B-1C	1 PC	633.00	✓ 633.00
23	NATURAL COOLER	6B-2C	1 PC	442.00	✓ 442.00
24	CLIP 25	1B-13C	1 PC	6.00	✓ 6.00
25	BEARING 43	1E-13C	1 PC	14.00	✓ 14.00
26	IMPACT ABSORBER 15	1A-05K	1 PC	52.00	✓ 52.00
27	BUMPER TOW COVER W212 16	1B-03H	1 PC	28.00	✓ 28.00
28	SHOCK HOOK	1B-3F	1 PC	35.00	✓ 35.00
29	CABLE HANGING	1C-08B	1 PC	100.00	✓ 100.00
30	ROTARY CATCH 17, 18	1E-10C	2 PCS	5.00	✓ 10.00
31	STRUT 19	1E-7C	1 PC	25.00	✓ 25.00
32	BASIC MOUNTING FOR BUMPER 20	1C-07F	1 PC	30.00	✓ 30.00
					1180

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOI'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor



G.U. JOINT MADE IN JAPAN

Stockists

SIGN & COMPANY'S STAMP

DATE

MOTOWA Mercedes-Benz BMW HONDA TOYOTA

KIA HYUNDAI

FUCHS KANAE bisAFE₃

AMOUNT DUE

ADD GST

TOTAL

STN

ALL CHECKS MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089831

DATE	06/12/2017	PAGE
TERM	30 Days Net	SALESMAN Alan Tan
CUSTOMER REF.	SJT360L	OUR REF 42319

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 13:31 ROUTE

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 4533757, 44598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
12-12C	12-12C	12-12C	4 PCS	4.00	16.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK

CLV JOINT VENTURE

MADE IN JAPAN

Stockists



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 9853 (Accounts)

E-mail : info@mingghee.com

Website : http://www.mingghee.com

INV NO : 8090187

DATE	09/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF.	43505

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ROUTE

ACCOUNT NUMBER: LAIHUAT1 TIME: 09:38

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 4533757, A4598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1. M2A212 520 23 23	UNDER COVER FRT 29	1D-4II	1 PC	120.00	✓ 120.00
2. M2A212 500 02 55	LEAN SHROUD ✓ 38	1D-4K	1 PC	65.00	✓ 65.00
3. M2A204 817 49 20	GUIDE SIGN ✓ 44	1B-06H	1 PC	14.00	✓ 14.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor

HDK

C.V. JOINT

MADE IN JAPAN

Stockists

SIGN & COMPANY'S STAMP



DATE

ALL CHECKS MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司

MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6298 3888 Fax: 6297 0663 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089901

DATE	07/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF.	42572

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER:

LAIHUAT1 TIME: 09:42

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 4533757, 4598162

ROUTE

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722



PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 M8A212 885 27 65	BASIC MOUNTING FOR BUMPER	1AAL11	1 PC	35.00	35.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE

*OVERDUE ACCOUNTS SHALL

BEAR INTEREST AT UOB'S PREVAILING

LENDING RATE

*CASH INVOICES MUST BE

PAID WITHIN 7 DAYS

FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK

C. J. JOHNSON

MADE IN JAPAN

Stockists



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 338564.

Tel: 6298 3888 Fax: 6297 8863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8089793

DATE	06/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF.	42203.

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 11:39
LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 4533757, 44598162

DELIVER TO:
LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA212 898 02 32	SHOCK STRIKER S4	1B-04G	1 PC	20.00	✓ 20.00
2 MBA212 880 00 60	ENGINE HOOD CATCH S5	1B-04G	1 PC	18.00	✓ 18.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT USDBS PREVAILING LENDING RATE


*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor



MADE IN JAPAN

Stockists



SIGN & COMPANY'S STAMP

TOTAL SIN
ADD GST 7%
AMOUNT DUE SIN

DATE

ALL CHECKS MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD. TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089735

DATE	05/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF.	42025

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 17:41
LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 4533757, A4598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MEX212 620 08 95	PERSONER S1	3B-1CC	1 PC	138.00	✓ 138.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT LOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor



MADE IN JAPAN

Stockists

DATE

DATE

ALL CHECKS MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.



Signature of Alan Tan

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lembah Kaitang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6298 3888 Fax: 6297 0853 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089808

DATE	06/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF.	42246

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 12:08
LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 4533757, A4598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA204 460 26 24	COOLING PIPE 52	IC-081	1 PC	160.00	✓ 160.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT USDS PREVAILING
LENDING RATE

*CASH INVOICE MUST BE
PAID WITHIN 7 DAYS
FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK
C.V. ADIT
MADE IN JAPAN

Stockists



DATE

ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lembuh Kallang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6298 3888 Fax: 6297 0883 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089851

DATE	06/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SJT360L	OUR REF	42093

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 14:57
LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 4533757, 44598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD
160, SIN MING DRIVE
#04-01/#04-02 AND #07-03
SIN MING AUTOCITY
SINGAPORE 575722



PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBX212 885 06 37	LA-05K	1 PC	33.00	✓ 33.00	

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE.
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor



Stockists

SIGN & COMPANY'S STAMP

Signature



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lambiah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8089862

DATE	06/12/2017	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.		OUR REF	42446

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: LAIHUAT1 TIME: 15:52

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 4533757, A4598162

DELIVER TO:

LAI HUAT (MENG KEE) MOTOR PTE LTD

160, SIN MING DRIVE

#04-01/#04-02 AND #07-03

SIN MING AUTOCITY

SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 HEA001 989 24 03 10	BW83-29 0 429 576 A/P/S F S3	1A-08B	1 PC	32.00	32.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE.

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor

HDK
JCV JOINT
MADE IN JAPAN

Stockists

SIGN & COMPANY'S STAMP

(Signature)



DATE
ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iris Auth'd	Status
Main	25 Nov 2017 Sendback Est	05 Dec 2017 10:53 \$510,428.70	05 Dec 2017 11:07 Edit Adj Rpt	\$59,489.50 Edit Estimates	\$59,489.50 View Rpt		Pending for Survey Report Cancel Case
Supp #1	11 Jan 2018 01:12	01 Apr 2018 22:50 \$5404.80	01 Apr 2018 22:50			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	HO SHOK FONG, ID: S01611073, Tel: +6591386298, Email: Hoshokfong51@yahoo.com.sg			
Vehicle Reg. No.:	SJT360L	Date of Loss:	24/11/2017 17:00 - :59 [76 Months and 28 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 538363	Policy/Cover Note No.:	28822315QMX (Comprehensive) Coverage: 09/09/2016 - 26/12/2017	
		Excess:	\$500.00	
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/01/2018]			
Driver/Custodian:	HO SHOK FONG (64 / Male), NRIC: S01611073, Tel: +6591386298			
Adj Asg. Remarks:	Please revert. OI continued to drive 53km after accident. Any Aggravated damages?			

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (23/08/2018): Alert - Adj Mandate Approved (\$59489.50) - SJT360L - Claim Handler: Winnie Chua ...
- MSIG_SG (05/12/2017): Alert - Adj Mandate Approved (\$59461.00) - SJT360L - Claim Handler: Winnie Chua ...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJT360L (538363)
OD
Nov 24 2017 5:00PM
[HO SHOK FONG]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports										1 per page	☒
No	Finalized On	Regent Motors (HQ)								Thumbnail	Print
1	25/11/17 11:57	Accident Statement								Load HTM	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	05/12/17 10:53	Repairer Estimates								Load HTM	
2	01/04/18 22:50	Repairer Estimates Suppl. #1								Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	05/12/17 15:59	Adjuster Immediate Advice								Load HTM	
2	20/08/18 14:17	Adjuster Immediate Advice								Load HTM	

Photos/Images

3 per page

☒

No	Finalized On	Regent Motors (HQ)								Thumbnail	Print
1	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
2	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
3	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
4	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
5	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
6	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
7	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
8	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
9	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
10	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
11	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
12	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
13	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
14	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
15	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
16	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
17	25/11/17 11:56	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	05/12/17 10:32	Front View								Load JPG	☒
2	05/12/17 10:32	Front View Left								Load JPG	☒
3	05/12/17 10:32	Front View Right								Load JPG	☒
4	05/12/17 10:32	Odometer Reading								Load JPG	☒
5	05/12/17 10:32	Chassis Number								Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	05/12/17 16:02	WORKSHOP ESTIMATE								Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
2	20/08/18 14:19	General View	 Load JPG	☒
3	20/08/18 14:19	General View	 Load JPG	☒
4	20/08/18 14:19	General View	 Load JPG	☒
5	20/08/18 14:19	General View	 Load JPG	☒
6	20/08/18 14:19	General View	 Load JPG	☒
7	20/08/18 14:19	General View	 Load JPG	☒
8	20/08/18 14:19	General View	 Load JPG	☒
9	20/08/18 14:19	General View	 Load JPG	☒
10	20/08/18 14:19	General View	 Load JPG	☒
11	20/08/18 14:19	General View	 Load JPG	☒
12	20/08/18 14:19	General View	 Load JPG	☒
13	20/08/18 14:19	General View	 Load JPG	☒
14	20/08/18 14:19	General View	 Load JPG	☒
15	20/08/18 14:19	General View	 Load JPG	☒
16	20/08/18 14:19	General View	 Load JPG	☒
17	20/08/18 14:19	General View	 Load JPG	☒
18	20/08/18 14:19	General View	 Load JPG	☒
19	20/08/18 14:19	General View	 Load JPG	☒
20	20/08/18 14:19	General View	 Load JPG	☒
21	20/08/18 14:19	General View	 Load JPG	☒
22	20/08/18 14:19	General View	 Load JPG	☒
23	20/08/18 14:19	General View	 Load JPG	☒
24	20/08/18 14:19	General View	 Load JPG	☒
25	20/08/18 14:19	General View	 Load JPG	☒
26	20/08/18 14:19	General View	 Load JPG	☒
27	20/08/18 14:19	General View	 Load JPG	☒
28	20/08/18 14:19	General View	 Load JPG	☒
29	20/08/18 14:19	General View	 Load JPG	☒
30	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
31	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
32	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
33	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
34	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
35	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
36	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
37	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
38	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
39	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
40	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
41	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
42	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
43	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
44	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
45	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
46	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
47	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
48	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
49	20/08/18 14:38	Reinspection Photo	 Load JPG	☒
50	20/08/18 14:39	Photo After Spray	 Load JPG	☒
51	20/08/18 14:39	Photo After Spray	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
52	20/08/18 14:39	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/18 12:55	tp police report	 Load PDF	
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
1	25/11/17 11:57	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	25/11/17 11:57	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	25/11/17 11:57	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	25/11/17 11:57	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	
5	25/11/17 11:57	Sketch Plan #5 [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	05/12/17 10:37	E-filed GIA report	 Load PDF	
2	05/12/17 10:37	Driver's NRIC + Driving License	 Load PDF	
3	05/12/17 10:37	Certificate of Insurance	 Load PDF	
4	05/12/17 10:37	Enquire PARF / COE Rebate for Registered Vehicle	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/18 16:42	estimate	 Load PDF	
2	20/08/18 16:42	supplementary	 Load PDF	
3	27/08/18 09:45	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
1	25/11/17 11:57	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
1	25/11/17 11:56	Accident Photo	 Load JPG	☒
2	25/11/17 11:56	Accident Photo	 Load JPG	☒
3	25/11/17 11:56	Accident Photo	 Load JPG	☒
4	25/11/17 11:56	Accident Photo	 Load JPG	☒
5	25/11/17 11:56	Accident Photo	 Load JPG	☒
6	25/11/17 11:56	Accident Photo	 Load JPG	☒
7	25/11/17 11:56	Accident Photo	 Load JPG	☒
8	25/11/17 11:56	Accident Photo	 Load JPG	☒
9	25/11/17 11:56	Accident Photo	 Load JPG	☒
10	25/11/17 11:56	Accident Photo	 Load JPG	☒
11	25/11/17 11:56	Accident Photo	 Load JPG	☒
12	25/11/17 11:56	Accident Photo	 Load JPG	☒
13	25/11/17 11:56	Accident Photo	 Load JPG	☒
14	25/11/17 11:56	Accident Photo	 Load JPG	☒
15	25/11/17 11:56	Accident Photo	 Load JPG	☒
16	25/11/17 11:56	Accident Photo	 Load JPG	☒
17	25/11/17 11:56	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
1	25/11/17 11:57	Sketch Plan	 Load TIF	
2	25/11/17 11:57	Sketch Plan #2	 Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	Regent Motors (HQ)	Thumbnail	Print
3	25/11/17 11:57	Sketch Plan #3	 Load TIF	
4	25/11/17 11:57	Sketch Plan #4	 Load TIF	
5	25/11/17 11:57	Sketch Plan #5	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17023045/KTBE2

Date: 28/08/2018

REFERENCE

Insured/Claimant:	HO SHOK FONG	Policy No:	28822315QMX	Claim No:	538363
Date of Loss:	24/11/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT360L	Engine No:	27186030211357
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2120472A410667
Reg. Date:	27/06/2011 (Man. Year: 2011)	Odometer:	124073 km
Colour:	Metallic Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	S\$93,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,983.50	7,829.50	1,154.00	12.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	860.00	140.00	14.00
Paintwork Labour	850.00	800.00	50.00	5.88
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,833.50	9,489.50	1,344.00	12.41
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	10,333.50	8,989.50	1,344.00	13.01
+ GST 7.00/7.00% (S\$)	723.35	629.27	94.08	13.01
Nett Amount (S\$)	11,056.85	9,618.77	1,438.08	13.01

INSPECTION

Date of Assignment:	05/12/2017 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	05/12/2017 Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2018)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT360L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Bent	1,135.00 F	*1,135.00 F
2	1		*Bonnet hinge RH (WCP)	Distorted	72.00 F	*72.00 F
3	1		*Bonnet hinge actuator LH (WCP)	Serviceable	182.00 F	*- F
4	1		*Bonnet hinge actuator RH (WCP)	Activated	182.00 F	*182.00 F
5	1		*Bonnet rubber seal (WCP)	Cut	12.00 F	*12.00 F
6	1		*Bonnet spring stopper LH (WCP)	Serviceable	12.00 F	*- F
7	1		*Bonnet spring stopper RH (WCP)	Missing	12.00 F	*12.00 F
8	1		*Bonnet lock RH (lower) (WCP)	Repair	35.00 F	*- F
9	1		*Bonnet latch striker (WCP)	Bent	35.00 F	*35.00 F
10	1		*Front bumper (WCP)	Cracked	725.00 F	*725.00 F
11	1		*Front bumper reinforcement (WCP)	Bent	260.00 F	*260.00 F
12	1		*Front bumper centre grille (WCP)	Dented	35.00 F	*35.00 F
13	1		*Front bumper inner frame centre (WCP)	Cracked	35.00 F	*35.00 F
14	1		*Front bumper sponge RH (WCP)	Missing	26.00 F	*33.00 F
15	1		*Front bumper sponge (centre) (WCP)	Cracked	52.00 F	*52.00 F
16	1		*Front bumper tow hook cover (WCP)	Missing	28.00 F	*28.00 F
17	1		*Front bumper top clip LH (WCP)	Missing	5.00 F	*5.00 F
18	1		*Front bumper top clip RH (WCP)	Missing	5.00 F	*5.00 F
19	1		*Front bumper reinforcement side beam RH (WCP)	Distorted	25.00 F	*25.00 F
20	1		*Front bumper lower bracket RH (WCP)	Distorted	30.00 F	*30.00 F
21	1		*Radiator grille (WCP)	Cracked	555.00 F	*555.00 F
22	1		*Front fender RH (WCP)	Bent	500.00 F	*500.00 F
23	1		*Front fender chrome moulding RH (WCP)	Serviceable	19.00 F	*- F
24	1			Cracked	80.00 F	*80.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*Front fender inner shield RH (front) (WCP)			
25	2		*Front fender inner shield clips RH (WCP)	Necessary	7.00 F	*22.00 F
26	1		*Front bumper parking sensor wire harness (WCP)	Serviceable	108.00 F	*- F
27	1		*Front headlamp RH	Broken	1,610.00 F	*1,288.00 FS
28	1		*Front headlamp nozzle RH (WCP)	Serviceable	100.00 F	*- F
29	1		*Engine lower cover (WCP)	Cracked	120.00 F	*120.00 F
30	1		*Front centre top panel (WCP)	Bent	75.00 F	*75.00 F
31	1		*Front headlamp panel RH (WCP)	Bent	125.00 F	*125.00 F
32	1		*Front headlamp panel support bracket RH (WCP)	Distorted	16.00 F	*16.00 F
33	1		*Front daylight lamp RH (WCP)	Missing	250.00 F	*250.00 F
34	1		*Front daylight chrome cover RH (WCP)	Missing	62.00 F	*62.00 F
35	1		*Front daylight base cover RH (WCP)	Serviceable	32.00 F	*- F
36	1		*Front air con air guide, top (WCP)	Cracked	33.00 F	*33.00 F
37	1		*Front air con air guide, lower (WCP)	Cracked	77.00 F	*77.00 F
38	1		*Front centre top panel cover (WCP)	Cracked	65.00 F	*65.00 F
39	1		*Front number plate garnish (WCP)	Dented	87.00 F	*87.00 F
40	1		*Front parking sensor RH, inner (WCP)	Dented	138.00 F	*138.00 F
41	1		*Front parking sensor RH, outer (WCP)	Serviceable	138.00 F	*- F
42	1		*Air con condenser (WCP)	Punctured	633.00 F	*633.00 F
43	1		*Radiator top lock pin LH (WCP)	Missing	20.00 F	*14.00 F
44	1		*AC decal (WCP)	Necessary	14.00 F	*14.00 F
45	1		*Front number plate	Missing	35.00 FS	*35.00 FS
Supplementary #1						
46	1		*Front bumper reinforcement bracket (WCP)	Bent	138.00 F	*138.00 F
47	1		*Power steering cooling pipe (WCP)	Dented	160.00 F	*160.00 F
48	1		*Power steering fluid (WCP)	Necessary	32.00 F	*32.00 F
49	1		*Bonnet U-shaped striker (WCP)	Distorted	20.00 F	*20.00 F
50	1		*Front engine hood catch (WCP)	Distorted	18.00 F	*18.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	8,170.00	7,238.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	813.50	591.50
Total Parts (\$\$)	8,983.50	7,829.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint (including front windscreen pillar RH)	New	850.00	800.00
<u>Labour Items</u>				
2	To check wheel alignment	New	60.00	0.00
3	To remove + refix roof top moulding RH	New	60.00	50.00
4	To remove + renew air con condenser and refill gas	New	120.00	100.00
5	Using diagnostic equipment to erase/check fault codes	New	60.00	60.00
6	To straighten front body, to knock dents on front wheelhouse top panel RH and renew of parts	New	700.00	650.00
Gross Labour Cost (\$\$)			1,850.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >