LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

8 Shenton Way #24-01 51 Ubi Ave 1 #01-25 AXA Tower Paya Ubi Industrial Park Singapore 068811 Singapore 408933

Attn: Winnie Ho Date: 06 Dec 2017

Preliminary Advice

Vehicle No : SLE5688P Accident Date : 03/12/2017 Make : MERCEDES-BENZ S320 Policy No. : GA267833 : 04/12/2017 **Excess** : S\$0.00 Assignment Date : 05/12/2017 Date of Inspection Est. Duration of Repair : 9.00

Inspection At : CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP)

188 PANDAN LOOP SINGAPORE 128378

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,139.76
Revised Amount	:S\$	18,763.63
Check Items (Estimated)	:S\$	0.00
Total	:S\$	18,763.63

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 341,000.00

 COE / PARF Rebate
 :S\$ 151,053.00

Salvage Value :S\$

Margin for Repair :S\$ 189,947.00

Remarks

(X)	The vehicle is	repairable at our	r adjusted amount.	We have also	confirmed	excess and pol	icy coverage.
-----	---	----------------	-------------------	--------------------	--------------	-----------	----------------	---------------

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Survey date and time:5/12/2017 at 2.50PM

We have authorise repair.