		A SECTOR	NMENT		
		1	CLIA	1485 L Yr Regn. POCH	2
From:	Date:				
Estimated Cost:		T)		Van / Lorry / Wil / Prime Mover	
OD / TP / WS / TP RES / OD	RES / EVA / INV / MV		Truck / Trailer or		
To Inspect Vehicle No.		M	ake: Hyun	Lr [70 0.0 A/C: Ins God / Std	5
at Workshop m/s		C	clour 5:/w	A/C: Ins G ≇d / Std	/ NL
of		S	p.Reading 1371	TiRadio: Instituted / Std	/ NI
Insured:		E	ng/No:		
Policy No.		C	No: T/	MAP2814VHJ,	14/
Claims No.		G	en. Cond: Good / Gir / Po	oor / Burnt	
Sum Insured:	Excess:	S	teering: Indrafer / Jammed	/Leaked/Burnt or	
(Client's Record)		В	rake: Ino@er / Jammed	/ Leaked / Burnt or	
Make of Veh:		N	lodi: Nil / S/Rim / ST€	A/Rim or	
		T	yre Size: F:	195/6515	
(Policy Condition)			R:	٠.	
Remark: The veh had comm	enced its	N/S O/S B	S / DUN / EXNOVA / GY /	FS / LIZA / MIC / OHTSU / PIR / SU	MI /
repair at the time of	of inspection.		TOYO / YOKO or	Hankale.	
Bal. or Market Value:		E	ront	Rear	
IDAC Accident Rport:	Consistent? : Yes	or No R	VBal. 7	nm R/Bal. 4	
GIA / PR Seen:	Consistent? : Yes o	or No L	/Bal. 7	nm L/Bal.	
Est. Repairs: L	days Res. Yes	or No D	OA 2/12/17	D.O.I. 4/2/12	
Lum Sum: ⊃o	% 3 Val.: Yes o	or No S	urvey held at	Prience	
CA / REV / REP. / 24	A LIDS	0	es. of Damages : Frt / Re	ear / O/Ş / N/S / U/C / Rooftop	or.
	1	Vehicle: IN / OUT		0/s Ren	
Date: Perso	n Contacted:		The U/C / Chassis fram	me / Body Structure affected due	0 00
Date / Time Action / Ins	struction			2 —.	
ile.	10- 7	- 501		(72	
451	91,900 (RBS14900	18 32.(-)			
	4				
Date/Time, File Pass to?	: Preli. Report	Da	ys Of Repair:		
11	: Final Report		survey No. of Trip:	Survey Fee:	_
Cate/Time, File Return to?	J. T. H. C. POST	1.00		Transportation:	
2)		Add Fee:	: Site Insp (\$)5 + RS5I	
		ī	Interview (\$	Photos	
			Finite MeA 1/4	1 :2:16/024	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Auton				
CHI	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI17023	050/K1ea3			
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 05-12-2017 Code: CTI				
1.		Policy Particul	Jars :- THIRD PARTY CLAIM				
	Insured Veh.	WC 5805Z	Veh. Inspected	SHD 1485L			
	Policy No.	DMCVSN1550971702	Coverage (\$)	0.00			
	Claim No.	SNM17D06964C02/5	Excess (\$)	0.00			
	Assign From		Assign Dato	05/12/2017			
2.		Vehicle P	articulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	귷	Steering				
	Brakes		Modification				
	General						
3.		Cor	nditions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre		-ê	mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre		#	mm			
4.		Desci	ription of Damages	REPORTE WAL			
5.		Ger	neral Information				
.00	Accident Date	02/12/2017	Inspection Date	04/12/2017			
	Survey held at	PREMIER AUTOMOTIVE S	ERVICES PTE LTD				
			UE 2 #01-02 SING/ PORE 486	6443			
5a.			Remarks				
	A)THE INSPECTION	ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BA	SIS.			
ļ	B)IN ACCORDANG	CE TO YOUR INSTRUCTION	S, WE HAVE NOT AUTHOR!	SEU KEPAIKS.			

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

4-Dec-17

ESTIMATE REPAIR BILL FOR HYUNDAI 130 (A) WAGON REGN NO: SHD 1485 L

1 pc	Rear o/s fender / //		s	1,575.23	
		-	\$	1,575.23	
	Les	ss 20%	\$	315.05	
S/NETT		1	\$	1,260.18	**
1 pc	Rear o/s fender sticker	13	\$	60.00	_
1 set	o/s door sticker		\$	100.00	_
	Sundry New		s	50.00	20
	To check wheel alignment		s	50.00 80.00	X
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s door	3	s	508 00	Van
	To putty and spray painting on the rear bumper, rear o/s fender, rear o/s door	37	5	690.00	5 Kz
	To apply rustproofing on the repaired and replaced panels		5	150.00	2.
	Total	3	5	2,800.18	
	(ALL THE REPAIR COSTS ARE SUBJECTED TO COT.)	_			

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

29/10/2 4 \$190/4 By,

Ple

Before Pathy ple

And residual and residual

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert

No.:

200304975H

Owner ID Type:

Company

Owner Name:

PREMIER TAXIS PTE. LTD.

Registered Address:

23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address:

.

Birth Date:

0.4

Vehicle Particulars

Vehicle No.:

SHD1485L

Previous Vehicle No.:

Effective Date of Ownership:

17 Oct 2017

Original Regn Date:

17 Oct 2017

Registration Date:

17 Oct 2017

Year of Manufacture:

2017

Vehicle Type:

Public Transport Taxi (Motor Car)

Vehicle Scheme:

Taxi (Company)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Make:

HYUNDAI

Vehicle Model:

130 GDH 1.6 TCI 5DR DCT

Primary Colour:

Silver

Secondary Colour:

Passenger Capacity:

5.05

4

Chassis No.:

TMAD281UVHJ141988

Engine No.:

D4FBHZ172981

Engine Capacity/Power

Rating:

1582 cc/-

Maximum Power Output:

100.0 kW (134 bhp)

Propellant:

Diesel

Max Unladen Weight:

1496 kg

Maximum Laden Weight:

1940 kg

Open Market Value:

\$20,019.00

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

4-Dec-17

ESTIMATE REPAIR BILL FOR HYUNDAI 130 (A) WAGON REGN NO: SHD 1485 L

1 pc	Rear o/s fender		\$	1,575.23
			\$	1,575.23
		Less 20%	\$	315.05
			\$	1,260.18
S/NETT	_			
1 pc	Rear o/s fender sticker		\$	60.00
1 set	o/s door sticker		\$	100.00 /
	Sundry		\$	50.00 20 80.00 X
	To check wheel alignment		s	89.00 ×
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s door		s	500.00 Kos
	To putty and spray painting on the rear bumper, rear o/s fender, rear o/s door		\$	500.00 Kos 600.00 5 Ks 150.00 2 0
	To apply rustproofing on the repaired and replaced panels		\$	150.00 2-
		Total	\$	2,800.18

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Calm (CCC)

4/2/r4 13304, the Ph. and I be translated to the P

Company Registration No. 199607198R

51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Your ref:

TBA

Date:

05.12.2017

Our ref:

CC3/CTI17023050/K1ea3

The Motor Claims Department M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1485L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>04.12.2017</u> at the premises of <u>M/s Premier Automotive Services Pte Ltd (Changi South)</u> and have the following to report:-

Workshop Estimate Amount	: S\$	2,800.18
Revised Estimate Amount	: S\$	2,400.18
"Check" Items Amount	: S\$	
Market Value	: S\$	•
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the

O/S Rear Portion

rear front offside

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

4.0 days


Yours faithfully,


KALVIN ANG

Licensed Appraiser

1575.23		60.00 100.00	30.00 80.00				
		20.00	100.00				
		400.00	60.00				
		540.00	130.00				
		20.00					
		1140.00					
		13321111100	400.00	5	0.00		
0.00							
						0.00	0.00
1575.23							
0.00		1540.00			0.00		
0.00		1140.00			0.00		
0.00		400.00			0.00		
1575.23							
315.05							
1260.18							
1140.00							
	0.00	1					
2400.18	0.00	ı					
	0.00	7	CHECK ITEM				
		J					
	0.00	-					
	0.00						
	0.00						
	0.00						

0.00





·----



MUHAMMAD FAISAL BIN JAFFAR

Histor

INDIAN Dale of both

11-04-1976 Country at birth SINGAPORE



11510809





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

PASS DATE .

C Class 28 Monterycles == 200 CC
C Class 24 Monterycles between 201 CC and 400 CC
C Class 2 Identify and make tractive-vehicles == 2500 kg
Class 4 Heavy morar cars and motior tractions == 2500 kg

36 Jul 2002 69 May 2006 17 Aug 2002

15 Zan 2000

S / No. 9000075905

Licence No: 576108091





VOCATIONAL LICENCE

Licence No.: 576108091

Name: MUHAMMAD FAISAL BIN JAFFAR

Issue Date : 16/10/2014

Please visit www.lta.gov.sg to check the status of this vocational licence

10/17/2017

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert

No.:

200304975H

Owner ID Type:

Company

Owner Name:

PREMIER TAXIS PTE, LTD.

Registered Address:

23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address:

-

Birth Date:

-

Vehicle Particulars

Vehicle No.:

SHD1485L

Previous Vehicle No.:

254

Effective Date of Ownership:

17 Oct 2017

Original Regn Date:

17 Oct 2017

Registration Date:

17 Oct 2017

Year of Manufacture:

2017

Vehicle Type:

Public Transport Taxi (Motor Car)

Vehicle Scheme:

Taxi (Company)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

.

Vehicle Attachment 3:

HYUNDAI

Vehicle Make: Vehicle Model:

130 GDH 1.6 TCI 5DR DCT

Primary Colour:

Silver

Secondary Colour:

.

Passenger Capacity:

4

Chassis No.:

TMAD281UVHJ141988

Engine No .:

D4FBHZ172981

Engine Capacity/Power

Rating:

1582 cc/-

Maximum Power Output:

100.0 kW (134 bhp)

Propellant:

Diesel

Max Unladen Weight:

1496 kg

Maximum Laden Weight:

1940 kg

Open Market Value:

\$20,019.00



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND MOTOR VEHICLES (THIRD PARTY RISKS AND ROAD TRANSPORT ACT, 1987 (MALAYSIA)	COMPENSATION) ACT (CHAPTER 189) COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)	COMPENSATION) RULES, 1960

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: SHD1485L

Chassis Number

: TMAD281UVHJ141988

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

- (b) Any licensed taxl driver driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to Use*
 - (a) Use as a Taxi.
 - (b) Use for social domestic and pleasure purposes.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled
 - * Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: 5\$3,500

INSURE WITH COE

HIRE PURCHASE COMPANY

: N/A : DBS BANK LTD

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue

: 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL:65446671 FAX:62141511 CO. REG:200707743D GST REG:200707743D

Our Ref: SHD1485L/GS

WITHOUT PREJUDICE

6th February 2018

(By Email Only)

Attn: The Motor Claims Department
China Taiping Insurance(Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Dear Sir/Madam

ACCIDENT INVOLVING SHD1485L & WC5805Z ALONG BEDOK NORTH ROAD ON 02.12.17

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHD1485L, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: WC5805Z at the material time of the accident with the driver of our client's vehicle, Mr Muhammad Faisal Bin Jaffar

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: WC5805Z, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of rappir	\$	2033.00 (Incl. GST)
(1) Cost of repair (2) Loss of Rental - 4Days @\$109.94per day	S	439.76
(3) Loss of Income – 4Days @\$100.00per day	\$	400.00
	\$	2.00
(4) GIA Search fee	S	2874.76

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHD1485L
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher, GIA search

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL:65446671 FAX:62141511 CO. REG:200707743D GST REG:200707743D

Our Ref: SHD1485L/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,

Claims Department - Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client - Premier Taxis Pte Ltd



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Our Ref: CC3/CTI17023050/K1ea3

08 FEB 2018

TS TRANSPORT & CONSTRUCTION PTE LTD 17 SUNGEL KADUT STREET 3 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729148

Dear Sir/Madam,

ACCIDENT INVOLVING WC 5805Z AND SHD 1485L ON 02/12/2017

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 day, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: ashersng@lkkauto.com

c.c. China Taiping Insurance (Singapore) Pte Ltd (Motor Claims Dept)

AUTHORIZATION TO ACT

I. PREMIER TAXIS PTE LTD (the third party claimant") of 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443 (address), owner of SHD 1485L (vehicle no.) hereby authorize PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHD 1485L that was damaged pursuant to the accident which occurred on 02/12/2017 (date) along BEDOK NORTH ROAD AFTER BEDOK RESERVOIR ROAD (location) involving vehicle no/s WC 5805Z ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Signed by "the third party claimant"

(with chop if applicable)

Signed by "the workshop" (with chop) " This Settlement excludes any bodily injuries arising out of the above said accident and pertains is property damage colu

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMCVSN1550971702

Claim No : SNM17D06964C02/5

Claimant : PREMIER TAXIS PTE LTD

Amount

: S\$1,318.38

DOLLARS ONE THOUSAND THREE HUNDRED EIGHTEEN AND CENTS

THIRTY EIGHT ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHD 1485L Insured Vehicle No. : WC 5805Z

Date of Loss

: 02/12/2017

Place of Accident

: BEDOK NOTH ROAD AFTER BEDOK RESERVOIR ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name

: IS TRANSPORT & CONSTRUCTION PTE LTD

Driver Name

: CUI JINZHU

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1)	General Damages	S\$		
(2)	Cost of Repair/ Encoss	55	1,016.50	
(3)	Loss of Use/Rental/ Earning	5\$	299.88	
(4)	GIA/Police Reports/		w ww	
	Investigation Results/Search Fees	5\$	2.00	
(5)	Medical Reports/Expenses	8\$		
(6)	Survey Fees/P.T. Fees	5\$		
(7)	Cost including Disbursement	5\$		

	TOTAL	. ss	1,318.38	

Claimant Name: PREMIER TAXIS PTE LTD

NRIC No : 200304975H

Signature



OFFICE 23 Changi South Avenue 2 #01-02 S(486443) TEL 65436676 / 65436689 FAX: 62141511

CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

TAX INVOICE

DATE

6-Feb-2018

PAGE

1 OF 1

PREMIER TAXIS PTE LTD 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443

TEM	Description Q1	ΓY	U.PRICE	А	MOUNT
TEM	FINAL REPAIR BILL FOR HYUNDAI 130 REGN NO: SHD 1485 L			\$	1,900.00
	TOTAL LUMP SUM REPAIR COSTS AS RECOMMEND	ED B	Y SURVEYOR GST @ 7% GRAND TOTAL		1,900.00 133.00 2,033.00

for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



08 December 2017

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Muhammad Faisal Bin Jaffar of NRIC Number S76108091 is a registered driver of SHD1485L. Muhammad Faisal Bin Jaffar is paying daily rental rate of \$109.94 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

Chin Bee Lian (Ms)

Assistant Vice President

Taxis Administration

Prepared By: SY

PREMIER TANIS PTE LTD 23 Changi South Avenue 2 #03-62 Singupore 486443 Telephone: +65 6214 8880 Fux: +65 6214 0330 www.premieriaxi.com Co. Reg. No. 200304975H PREMIER

CHECK IN / OUT VOUCHER

VEH NO			+	
VEH NO.	JC	8 NO.		
1	1 1	1 1	-31	11.

		CHECK			ANADE WEDE
DRIVER'S NAME MU	HAMMAD FA	ISAL BIN 3	AFFAR	INDICATE AREA OF I	
NRIC 8 76.1 0	The second secon	HANDPHONE & 7	420790	REAR	
TAXI REGN NO. S H		MAKE/MODEL 3	30 CA)		
DATE IN 0 4 14 21 14 7	TIME IN	D 9-1217	HAZS	mE	A M
KILOMETRES IN	FUEL IN E 1/4 1/2 3/4 F	KILOMETRES OUT	FUEL OUT E 1/4 1/2 3/4 F		
YES	NO CONFIRM THAT I HA	D D N M Y Y	MERFORVEHICLECTION H H M M OVE SAID VEHICLE AND ONLIN EVERY RESPECT		
TOGETHER WITH THE	THE TERM RENTAL AG	FOUS ON	VOUCHER IS USED IN		
DRIVER'S NAME	X 71214	DRIVER'S NAME		, @	
DRIVER'S SIGNATUR	E/DATE/TIME	DRIVER'S SIGNAT	(D)	BODY MARKINGS 1 – Light Dent 2 – Serious Dent	5 - Damaged 6 - Chip 7 - Crack
CHECKED IN BY (PREMIER'S AUTHOR	RISED WORKSHOP)	CHERRED OUT BY	Y HORISED WORKSHOP)	3 Light Scraich 4 Serious Scraich	8 - Peeling
SERVICE / REPAIRS			DRIVER'S REMARKS		
D SERVICING D T/BELT D AIRCON SYSTEM D TURBO D BRAKE SYSTEM CLUTCH SYSTE D BULB D UNDER CARRIA C CPF	ර 2 ව ව ව M	7 13 15			



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffies Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

Third Party Insurer Enquiry

Our Ref No:

GR-17-180359

Date of Request:

04/12/2017

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2

#01-02

Singapore 486443

Dear Sir/Madam,

Enquiry Date

04/12/2017

Enquiry By

GOH WEE DEK

TP Vehicle No. Accident Date

WC5805Z 02/12/2017

Enquiry Result		Period of insurance	Insurer Tel. No.
TD Vehicle No	Insurer		6389 6111
WC5805Z	China Taiping Insurance (Singapore) Pte. Ltd.	(4)11/2017	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

Our Ref No: Date of Request: GR-17-180359 04/12/2017

Your Ref No:

TAX INVOICE

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2 #01-02 Singapore 486443

Dear Sir/Madam,

Enquiry Date

04/12/2017

Enquiry By

GOH WEE DEK

TP Vehicle No.

WC5805Z

02/12/2017 Accident Date

	AMOUNT (S\$)
DESCRIPTION	1.87
TP Insurer Enquiry	0.13
GST Amount	2.00
Total Amount Due (GST Inclusive)	- L

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

[X] GIRO [] Cash [] Cheque

Asher Sng (LKKAuto)

From:

Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent:

Wednesday, 16 May 2018 4:11 PM

To: Cc: Asher Sng (LKKAuto); Admin A Elaine Cheong; Alfred Toh; Hwang Shiang Yi; xiaosi.tanss@ssgroup.sg;

ivy.limls@ssgroup.sg; ryan.pohlk@ssgroup.sg

Subject:

Accident Involving WC5805Z (OI: SNM17D06964C02/5) AND SHD1485L (TP: LKK REF -

CC3/CTI17023050/K1ea3) on 02/12/2017

Attachments:

LETTER TO OI.pdf; MSM117163817-WC5805Z.pdf; LKK Survey Photo.pdf; LKK Resurvey

Photo.pdf

LKK REF - CC3/CTI17023050/K1ea3 CTI REF - SNM17D06964C02/5 (WC5805Z)

Dear Asher

We are in receipt of your letter to Insured pertaining to the above matter.

You may proceed to negotiate the third party property damage claim at best possible terms.

Best Regards

Alfred Toh Senior Executive Claims Department China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: +65 6389 6183 FAX: +65 6224 7478/6224 7175

Email: claimsdept@sg.cntaiping.com alfred.toh@sg.cntaiping.com www.sg.cntaiping.com



This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]

Sent: Wednesday, May 16, 2018 3:21 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving WC5805Z (OI: SNM17D06964C02/5) AND SHD1485L (TP: LKK REF - CC3/CTI17023050/K1ea3) on 02/12/2017

Hi Elaine,

We refer the above matter.

Third party mention that there is no video or scene photo.

However insured mention that the driver did drive by the said location and agreed to let us settle at best.

Based on the photo taken by our surveyor third party vehicle was damaged on the right rear portion with blue paint mark which consistent with our insured vehicle colour paint.

In view on above, we propose to settle the case at best.

Thank You.

Best Regards.

Asher Sng | Case Handler LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkguto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Joel Goh [mailto:joel.goh@sg.cntaiping.com]
Sent: Thursday, 14 December 2017 10:01 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Asher Sng (LKKAuto) <<u>AsherSng@lkkauto.com</u>>; Vic (LKKAuto) <<u>vicalpeh@lkkauto.com</u>>; Admin A <<u>admin</u>

a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving WC5805Z (OI: CTI - SNM17D06964C02/5) AND SHD1485L (TP: LKK REF - CC3/CTI17023050/K1ea3) on 02/12/2017

Without Prejudice

Dear Shirley

Attached please find a copy of our insured's accident report for your attention.

Please assist to obtain third party video footage as our insured reported no contact / accident.

Best Regards

Joel Goh Claims Executive (Motor Division) Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 6389 6184

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com joel.goh@sg.cntaiping.com Website: www.sg.cntaiping.com

Disclaimer: This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Joel Goh

Sent: Thursday, 7 December, 2017 9:57 AM

To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>

Cc: Asher Sng (LKKAuto) < AsherSng@lkkauto.com>; Vic (LKKAuto) < vicalpeh@lkkauto.com>; Admin A < admin-

a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving WC5805Z (OI: CTI - SNM17D06964C02/5) AND SHD1485L (TP: LKK

REF - CC3/CTI17023050/K1ea3) on 02/12/2017

Dear Shirley

Our insured have not reported the accident. Attached our letter to insured for your attention.

Best Regards

Joel Goh Claims Executive (Motor Division) Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 6389 6184

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sq.cntaiping.com joel.goh@sg.cntaiping.com

Website: www.sg.cntaiplng.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Tuesday, 5 December, 2017 6:12 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Joel Goh < joel.goh@sg.cntaiping.com >; Asher Sng (LKKAuto) < AsherSng@lkkauto.com >; Vic (LKKAuto)

<vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving WC5805Z (OI: CTI - TBA) AND SHD1485L (TP: LKK REF -

CC3/CTI17023050/K1ea3) on 02/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SHD 1485L at M/s Premier Automotive Services Pte Ltd - Changi South. Enclosed for your perusal is: TP GIA report TP estimated cost of repair Preliminary advice Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action. Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051. To check availability of the case handler, you may contact the undersigned. Thank you. Best Regards, Shirley Hiew | Admin LKK Auto Consultants Pte Ltd Phone: 6366-0055 | email: ShirleyHjew@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit http://www.symanteccloud.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

СНІ	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI17023	050/K1ea3q2
	NSON ROAD #16-0	1,51,51		
		RSINGAPORE 079909	Date: 03-07-2018	
			Code: CTI	
1.	0.15	Policy Particula	ars :- THIRD PARTY CLAI	M
	Insured Veh.	WC 5805Z	Veh. Inspected	SHD 1485L
	Policy No.	DMCVSN1550971702	Coverage (\$)	0.00
	Claim No.	SNM17D06964C02/5	Excess (\$)	0.00
	Assign From		Assign Date	04/12/2017
2.		Vehicle Pa	articulars & Condition	
	Make & Model	HYUNDAI 130	c.c	1582
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	TMAD281UVHJ141988	Colour	SILVER
	Odometer	13718	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/65R15	HANKOOK	7 mm
	L/H Front Tyre	195/65R15	HANKOOK	7 mm
	R/H Rear Tyre	195/65R15	HANKOOK	7 mm
	L/H Rear Tyre	195/65R15	HANKOOK	7 mm
		Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	02/12/2017	Inspection Date	04/12/2017
	Survey held at	PREMIER AUTOMOTIVE SE	ERVICES PTE LTD	
		23 CHANGI SOUTH AVENU	E 2 #01-02 SINGAPORE 486	443
a.			Remarks	
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		
5b.		Estima	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Day	s



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1485L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR O/S FENDER	DENTED	1,575.23	1,575.23
	LESS 20% DISCOUNT	1-25-00-0-0	-315.05	-315.05
			1,260.18	1,260.18
	SPECIAL NETT ITEMS			
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
	M 12		210.00	180.00
	LABOUR			
	TO CHECK WHEEL ALIGNMENT .	NOT NECESSARY	80.00	
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK - OUT .STRAIGHTEN ,REPAIR,RESHAPE OF THE REAR O/S DOOR .		500.00	400.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,REAR O/S FENDER ,REAR O/S DOOR .		600.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	20.00
			1,330.00	960.00
	GRAND TOTAL		2,800.18	2,400.18

RECOMMENDED COST OF LUMP SUM REPAIRS	1,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/CTI17023050/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may made on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.