

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHA 3772K

MAKE :

MODEL : HYUNDAI i40

DATE 4/12/2017 17:10

LKK/Kalvin

L/Sum

Likee

AIG

| Qty                                                                                                                                                                                                                   | Parts Description/ Labour                     | Type | Unit Price | Amount             |      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|------|------------|--------------------|------|
|                                                                                                                                                                                                                       | Rear Bumper X Repair                          |      |            | \$ 603.60          |      |
|                                                                                                                                                                                                                       | Rear Bumper Clips 10 pcs X                    |      |            | \$ 22.00           |      |
|                                                                                                                                                                                                                       | Rear Fender (RH) X Repair                     |      |            | \$ 2,020.10        |      |
|                                                                                                                                                                                                                       | Rear Fender Inner Lining (RH) X               |      |            | \$ 164.40          |      |
|                                                                                                                                                                                                                       | Rear Windscreen Moulding X                    |      |            | \$ 60.00           |      |
|                                                                                                                                                                                                                       | Rear Door (RH) X Repair                       |      |            | \$ 1,351.10        |      |
|                                                                                                                                                                                                                       | Rocker Panel Outer Garnish (RH) X Repair      |      |            | \$ 483.60          |      |
|                                                                                                                                                                                                                       | Rear Wheel Hub-Cap (RH) ✓                     |      |            | \$ 150.70          |      |
|                                                                                                                                                                                                                       | <b>SUB TOTAL</b>                              |      |            | <b>\$ 4,855.50</b> |      |
|                                                                                                                                                                                                                       | <b>LESS 20%</b>                               |      |            | <b>\$ 971.10</b>   |      |
|                                                                                                                                                                                                                       | <b>DISCOUNTED TOTAL</b>                       |      |            | <b>\$ 3,884.40</b> |      |
|                                                                                                                                                                                                                       | <br>                                          |      |            |                    |      |
|                                                                                                                                                                                                                       | Rear Bumper Rubber Mat X                      |      |            | \$ 50.00           | Nett |
|                                                                                                                                                                                                                       | Rear Windscreen Sealant X                     |      |            | \$ 46.00           | Nett |
|                                                                                                                                                                                                                       | Rear Door Comfortdelgro & Apps Sticker (RH) ✓ |      |            | \$ 80.00           | Nett |
|                                                                                                                                                                                                                       | Front Door Coloured Comfort Logo (RH) ✓       |      |            | \$ 75.00           | Nett |
|                                                                                                                                                                                                                       |                                               |      |            | <b>\$ 251.00</b>   |      |
|                                                                                                                                                                                                                       | <br>                                          |      |            |                    |      |
|                                                                                                                                                                                                                       | <b>Labour Charge</b>                          |      |            |                    |      |
|                                                                                                                                                                                                                       | Panel Beating                                 |      |            | \$ 400             |      |
|                                                                                                                                                                                                                       | Spray Painting Charge                         |      |            | \$ 850.00          |      |
|                                                                                                                                                                                                                       | Wiring Charge                                 |      |            | \$ 1,000.00        | 900  |
|                                                                                                                                                                                                                       | Tuff Kote                                     |      |            | \$ 50.00           | X    |
|                                                                                                                                                                                                                       | Remove/Refix Cushion & Upholstery Rear        |      |            | \$ 50.00           | X    |
|                                                                                                                                                                                                                       | Remove/Refix Rear Windscreen Glass            |      |            | \$ 150.00          | X    |
|                                                                                                                                                                                                                       | Remove/Refix Reverse Sensor                   |      |            | \$ 120.00          | X    |
|                                                                                                                                                                                                                       | Transfer of Door                              |      |            | \$ 120.00          | 20   |
|                                                                                                                                                                                                                       | Rear Wheel Alignment                          |      |            | \$ 120.00          | X    |
|                                                                                                                                                                                                                       |                                               |      |            | \$ 80.00           | X    |
|                                                                                                                                                                                                                       | <b>TOTAL LABOUR</b>                           |      |            | <b>\$ 2,540.00</b> |      |
|                                                                                                                                                                                                                       | <b>ESTIMATE TOTAL</b>                         |      |            | <b>\$ 6,675.40</b> |      |
| <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p> |                                               |      |            |                    |      |

1/Calvin 16/11/17

4/12/17 1640hrs.

3 Pys.

4/5

After Repair photo

- To display damage on a scale of 1 to 5
- Parts prices are subject to confirmation
- Third party survey is subject to final approval
- No illegal modification
- Supplemental estimate is subject to final approval

Acknowledgement

Signature:

Date: