

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 860Z

DATE 4/12/2017 11:20

MAKE :

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt X			\$ 1,890.50
	Bumper Reinforcement, Frt X			\$ 1,158.00
	Bumper Bracket, Frt/LH/RH X		\$ 95.00	\$ 190.00
	Bumper Absorber, Frt/LH/RH X		\$ 207.00	\$ 414.00
	Bumper Side Beam, Frt/LH/RH X		\$ 26.90	\$ 53.80
	Bumper Sponge, Frt/Centre X			\$ 285.00
	Bumper Towing Cover, Frt X			\$ 62.50
	Bumper Grille, Frt/Centre X			\$ 290.50
	Bumper Inner Clip, Frt X			\$ 22.00
	Daylight (LH/RH) X		\$ 439.20	\$ 878.40
	Daylight Chrome Cover (LH/RH) X		\$ 78.00	\$ 156.00
	License Plate Trim Cover, Frt X			\$ 155.00
	Head Lamp Assy (LH/RH) X		\$ 2,380.00	\$ 4,760.00
	Head Lamp Bracket (LH/RH) X		\$ 300.00	\$ 600.00
	Radiator Top Panel, Frt X			\$ 330.50
	Head Lamp Panel (LH/RH) X		\$ 480.00	\$ 960.00
	Radiator Grille X			\$ 718.75
	Bonnet Assy X			\$ 2,850.60
	Bonnet Centre Lock X			\$ 95.00
	Bonnet Lock Lower X			\$ 92.00
	Radiator Assy X			\$ 1,345.00
	Radiator Fan Blower Assy X			\$ 1,385.40
	Radiator Shroud X			\$ 1,225.60
	Radiator Air Baffle, Top X			\$ 85.90
	Radiator Air Baffle, Lower X			\$ 125.90
	Radiator Overflow Hose X			\$ 186.40
	Radiator Mounting Lower X			\$ 7.50
	Radiator Mounting Top X			\$ 10.85
	Radiator Hose, Top X			\$ 73.35
	Radiator Hose Lower X			\$ 47.45
	Radiator Coolant X			\$ 60.00
	Aircon Condenser X			\$ 1,235.80
	Aircon Discharge Hose/Pipe X			\$ 372.55
	Turbo Charger Air Cooler X			\$ 1,053.80
	Turbo Charger Cooler Hose, RH X			\$ 313.60
	Turbo Charger Cooler Hose, LH X			\$ 75.45
	Turbo Charger Cooler Hose, Top X			\$ 92.50
	Water Pump Assy X			\$ 368.00
	Fan Belt (6Pk 2260) X			\$ 111.60
	Wheel Rim, RH /			\$ 1,250.00
	Mirror Glass, Frt/RH /			\$ 240.00
	Mirror Cover, Frt/RH /			\$ 70.00
	Mirror Housing W/Signal Lamp, Frt/RH /			\$ 414.00
	Mirror Motor Assy, Frt/RH /			\$ 860.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	SUB TOTAL			\$ 26,973.20	
	LESS 20%			\$ 5,394.64	
	DISCOUNTED TOTAL			\$ 21,578.56	
	Number Plate, Frt (Merc Taxi) X			\$ 50.00	Nett
	Front RH Door x repair				
	Front RH Fender x repair				
	Labour Charge			400	
	Panel Beating			\$ 1,500.00	
	Spray Painting Charge			\$ 1,500.00	400
	Wiring Charge			\$ 50.00	20
	Towing Charges			\$ 50.00	X
	Tuff Kote			\$ 50.00	X
	FRT Wheel Alignment			\$ 120.00	60
	Remove/Refix Aircon & Refill Gas			\$ 150.00	X
	TOTAL LABOUR			\$ 3,420.00	
	ESTIMATE TOTAL			\$ 25,048.56	
	1 call 1 LKK				
	5/12/17 1010hrs				
	28 Days				
	45				
	After Repair photo				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Corp. Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					