

22/03/2002

ASS. REC. BY:

REF: CS/EQ17023084/Gvb⁸⁴

Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Bazlin Ahmad

of

EQI

Date/Time: 5/12/17 @ 1:52pm

Estimated Cost:

Bill to:

☒ OD IP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN 6085J

Insured:

at Workshop m/s

Progressive Automotive

Tel:

67415336

of 81k 3022 A ubi Rd 1. # 01-45/46

Policy No: DMPPHQ17-0.03694

Claim No:

Sum Insured:

Excess:

\$ 250.00

Make of Veh:

D.O.A. 20/11/17

(Client's Record)

☒ CA / REV / REP. / REV 24 HRS wp/

H.O.D. Endorsement:

Date/Time: 2:05pm @ 5/12/17

Person Contacted:

Lily

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SGN 6085J - CS3/EQ17022286/T16 D.O.A. 20/11/17
15/1/18	Final dig \$ 4711.05 confirmed by email (Red 3564.05, 4310 No LS
18/1/18	Re-confirmed \$ 4799.05 by email (Red 3476.05, 4290)

REF: 60

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNV6085J

Yr Regn: 15 Jul 2011

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make:

chevrolet Cruze cc 1598

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

167125

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL1JA69E9B-K 187028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05-12-17

Survey held at:

w/s

5pm

Des. of Damages:

Fr

Rear

O/S

N/S

U/C

Rooftop

or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 JAN 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

16/1- typist

Report Format:

merimen

Lump Sum / I.B.I: (\$

4711.05

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS) \$

) Photos

) Others

TOTAL

160

[Signature]
15/1/2018

Survey Department Check List (Case Handler)

Reference No. : CS/EQI17023084/GVD

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 15/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI17023084/Gvb

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 05-12-2017



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGN 6085J
Policy No. DMPPHQ17-003694	Coverage (\$)	0.00
Claim No.	Excess (\$)	250.00
Assign From MERIMEN (BAZLIN AHMAD)	Assign Date	05/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 20/11/2017	Inspection Date 05/12/2017
Survey held at PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2017 10:43 Sendback Est	05 Dec 2017 11:39 S\$8,234.40	05 Dec 2017 13:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	QUEK YEOK CHAI WINSTON, ID: S8435257H, Tel: +6587495702		
Vehicle Reg. No.:	SGN6085J	Date of Loss:	20/11/2017 11:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	DMPPHQ17-003694 (Comprehensive)
		Excess:	S\$250.00
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/12/2017]		
Driver/Custodian:	QUEK YEOK CHAI WINSTON (/ Male), NRIC: S8435257H, Tel: +6587495702		
Adj Asg. Remarks:	EXCESS \$500 @ 50% DISCOUNT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SGN6085J
OD
Nov 20 2017 11:00AM
[QUEK YEOK CHAI WINSTON]
Progressive Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From EQ Insurance Company Ltd (HQ) (EQI_HQ), sent on **15/01/2018 13:36 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4711.05) - SGN6085J - Claim Handler: Bazlin Ahmad

Approved:4711.05.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd 5 Maxwell Road, #17-00 Tower Block MND Complex Singapore 069110	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Bazlin Ahmad	Date: 15 Jan 2018
<u>Preliminary Advice</u>	

Vehicle No	: SGN6085J	Accident Date	: 20/11/2017
Make	: CHEVROLET CRUZE	Policy No.	: DMPPHQ17-003694
Assignment Date	: 05/12/2017	Excess	: S\$250.00
Date of Inspection	: 5/12/2017	Est. Duration of Repair	: 5 days
Inspection At	: Progressive Automotive Pte Ltd		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,275.10
Revised Amount	:S\$	4,711.05
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,711.05
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	27,536.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,464.00

Remarks

- (☒) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (☐) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (☐) Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/11/2017 18:07
Date Of Accident	20/11/2017 11:00
Exact Location Of Accident	ALONG DUNMAN ROAD TOWARDS HAIG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN6085J
Insured/Policyholder	
Name Of Registered Owner	QUEK YEOK CHAI, WINSTON
NRIC No	S8435257H
Email Address	WINSTON682@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87433295
Alternative Phone No	OFFICE-87433295
Vehicle Particulars	
Manufacturer	CHEVROLET
Model	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-003694
Cover Note Number	N.A.

Driver

Name of Driver	QUEK YEOK CHAI, WINSTON
NRIC No	S8435257H
Date Of Birth	23/11/1984
Occupation	INDOOR
Date Of Driving Pass	27/09/2005
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87433295
Fax Number	
Contact Number	OFFICE-87433295
EMail Address	WINSTON682@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

Police Station Address

Police Station Contact

Was notice of intended Prosecution given? NO

If Yes, against whom?

JOO CHIAT NEIGHBOURHOOD POLICE POST

ROAD: 267 ONAN ROAD , POSTCODE: 424773 , COUNTRY: SINGAPORE

TEL NO: 1800-3459999 - FAX NO: 64474181

Circumstances of Accident

ON 20/11/2017 AT ABOUT 1100HRS, I WAS DRIVING MY VEHICLE SGN6085J ALONG DUNMAN ROAD AND WAS HEADING TOWARDS HAIG ROAD. THERE WAS ONE PASSENGER ON BOARD OF MY VEHICLE. AS THE TRAFFIC LIGHT LOCATED BEFORE HAIG ROAD SIGNALLED RED, I THEN STOP MY VEHICLE. I WISH TO INFORM THAT THERE WAS ONE VAN, GBB6369M IN FRONT OF MY VEHICLE. AS MY VEHICLE WAS SLOWING DOWN, A VEHICLE ON MY RIGHT THEN HONK TOWARDS ME. I THEN LOOK AT THE DRIVER OF THE VEHICLE, I THEN LOST MY FOCUS AND MY VEHICLE THEN CAME INTO CONTACT WITH THE REAR RIGHT BUMPER OF THE VAN. I THEN CAME DOWN OF MY VEHICLE AND OBSERVED MY FRONT LEFT HEAD LIGHT OF MY VEHICLE TO BE DAMAGED. MY FRONT BONNET WAS ALSO OBSERVED TO BE DENTED. I HAVE OBSERVED THE VAN'S REAR RIGHT SIDE DOOR TO BE DENTED. THE RIGHT TAIL LIGHT OF THE VAN WAS ALSO OBSERVED TO BE DAMAGED. AT THE MOMENT, I HAVE CHECKED WITH THE DRIVER AND THE 2 PASSENGER WHETHER THEY NEED ANY MEDICAL ATTENTION AND THEY TOLD ME THAT THEY WERE OKAY. I THEN EXCHANGED PARTICULARS WITH THE VAN DRIVER AND TOOK PHOOT OF THE DAMAGES OF BOTH VEHICLE. WE BOTH AGREED TO CLAIM THE DAMAGES THROUGH OUR OWN INSURANCE. I WISHED TO STATE THAT THERE WAS CCTV IN MY VEHICLE. I AM LODING THIS REPORT FOR INSURANCE CLAIM.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB6369M

Vehicle Make/Model/Colour TOYOTA/ HIACE

Details Of Properties NA

Name of Driver MUNIANDY A/L WAI OON @ PAH WAI ONN

NRIC/Passport Number G7195448Q

Contact Number 98310120

Address

NA
NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

**VERIFIED BY AJAX MARS
REPORTING OFFICER**

Muhammad Faizal


Bin Pabla

Witnessed by Reporting Centre
Personal

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800 3459999



T/20171129/2091

1 of 3

Report No. T/20171129/2091

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/11/2017 14:35	Vide Report No	Station Diary No. 21
--	----------------	-------------------------

Informant's Particulars

Name of Informant QUEK YEOK CHAI WINSTON		Address 95 STILL ROAD SINGAPORE 423987	
ID Type / ID No. NRIC NO / S8435257H		Contact No Home/Office	Mobile: 87433295
Nationality SINGAPORE CITIZEN		Email	
Sex Male	Age 33	Date of Birth 23/11/1984	Type of Informant Driver
Race Chinese		Language	Institution / School Name
Occupation self-employed		Driving Licence Information: Class Date of Expiry	

General Information of the Accident

Type of Accident	Non-Injury Others	Drink Drive No	Date/Time of Accident 20/11/2017 11:00	Type of Location Straight Road
Location Along Road 1 DUNMAN ROAD HAIG ROAD Along Dunman road towards Haig Road				
Weather Clear		Road Surface Dry	Road Speed Limit	
Traffic Flow One Way		Traffic Control Traffic Light - Working	Traffic Volume Moderate	
Type of Collision Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBB6369M	Van				Slightly Damaged	2
SGN6085J	Car	CHEVROLET	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR	Black	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
------------	-------------------	--------------	-----------	-------------

POLICE REPORT

**SINGAPORE
POLICE FORCE**

T/20171129/2091

2 of 3

Police Station Of Origin
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

Report No: T/20171129/2091

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SGN6085J	EQ INSURANCE COMPANY LTD	DMPPHQ17-003694	15/07/2017	14/07/2018

Brief Details.

On 20/11/2017 at about 1100hrs, I was driving my vehicle SGN6085J along Dunman road and was heading towards Haig road. There was one passenger on board of my vehicle. As the traffic light located before Haig road signaled red, I then stop my vehicle. I wished to inform that there was one Van, GBB6369M in front of my vehicle. As my vehicle was slowing down, a vehicle on my right then honk towards me. I then look at the driver of the vehicle. I then lost my focus and my vehicle then came into contact with the rear right bumper of the Van.

I then came down of my vehicle and observed my front left head light of my vehicle to be damaged. My front bonnet was also observed to be dented. I have observed the Van's rear right side door to be dented. The right tail light of the van was also observed to be damaged. At the moment, I have checked with the driver and the 2 passenger whether they need any medical attention and they told me that they were okay. I then exchange particulars with the van driver and took photo of the damages of both vehicle. We both agreed to claim the damages through our own insurance.

I wished to state that there was CCTV in my vehicle. I am lodging this report for insurance claim.

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20171129/2091

3 of 3

Report No. T/20171129/2091

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No: 1800-3459999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report.

G /

Staff Sgt TAY WEI SIANG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt TANG SIEW PING
Contact No: 65476430

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
29/11/2017 14:35

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	5257H

M.V Abt \$ 4800k

Vehicle Details

Vehicle No.	SGN6085J
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	CHEVROLET
Vehicle Model	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour	Black
Manufacturing Year	2011
Engine No.	F16D4271923KA
Chassis No.	KL1JA69E9BK187028
Maximum Power Output	91.0 kW (122 bhp)
Open Market Value	\$12,733.00
Original Registration Date	15 Jul 2011
First Registration Date	15 Jul 2011
Transfer Count	0
Actual ARF Paid	\$12,733.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 Jul 2021
PARF Rebate Amount	\$8,276.00

Intended COE Rebate Details

COE Expiry Date	14 Jul 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$53,390.00
COE Rebate Amount	\$19,260.00
Total Rebate Amount	\$27,536.00

The information contained herein is correct as at 05 Dec 2017

OK

Enquire Transfer Fee

Vehicle Details			
Vehicle No.	SGN6085J		
Vehicle Type	P10 - Passenger Motor Car		
Vehicle Attachment 1	No Attachment		
Vehicle Scheme	Normal		
Vehicle Make	CHEVROLET		
Vehicle Model	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR		
Chassis No.	KL1JA69E9BK187028		
Propellant	Petrol		
Engine No.	F16D4271923KA		
Engine Capacity	1598 cc		
Maximum Power Output	91.0 kW (122 bhp)		
Maximum Laden Weight	1844 kg		
Unladen Weight	1388 kg		
Year Of Manufacture	2011		
Original Registration Date	15 Jul 2011		
Lifespan Expiry Date	-		
COE Category	A - Car (1600cc & below)		
Quota Premium	\$53,390.00		
COE Expiry Date	14 Jul 2021		
Road Tax Expiry Date	14 Jan 2018		
PARF Eligibility Expiry Date	14 Jul 2021		
Inspection Due Date	14 Jul 2018		
Intended Transfer Date	06 Dec 2017		
CO2 Emission	-		
The current road tax expiry is 14 Jan 2018. You may renew the road tax from 15 Oct 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 14 Jan 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 15 Jan 2018 to 14 Jul 2018)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee	11.00	-	11.00



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

Date :

Our Ref :

I/We _____

Nric No _____ residing at

Owner of Vehicle No _____ hereby authorize

PROGRESSIVE AUTOMOTIVE PTE LTD

At Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 to proceed with the claim
on my insurance (OD / WS) to do repair of my vehicle.



SIGNATURE OF INSURED



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel:: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **EQ Insurance Company Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
 Policy No: DMPPHQ17-003694
 Vehicle Reg. No.: SGN6085J
 Driver Age/Info: / MALE
 TP Injury Involved? NO
 Insured/Claimant: QUEK YEOK CHAI WINSTON
 Driver: QUEK YEOK CHAI WINSTON

Ref. No: OD 1117-6247
 Date of Loss: 20/11/2017
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES
 Contact No: +6587495702

Make/Model: CHEVROLET CRUZE, 1.6 (A)
 Vehicle Colour: BLACK
 Engine No: F16D4271923KA
 Odometer: 167125 KM

Vehicle Reg. Date: 15/07/2011
 Chassis No: KL1JA69E9BK187028

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 6

Remarks: VEHICLE IS IN WORKSHOP
 Present Location: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	6,109.40
Miscellaneous Items	55.00
Labour	1,120.00
Paintwork Labour	950.00
Towing	0.00
	8,234.40
Gross Total (S\$)	8,234.40
+ GST 7.00% (S\$)	576.41
Nett Amount (S\$)	8,810.81

This claim is handled by: LILY LIM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)

Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER / CRA	0.00	0.00	*580.00 F ✓
2	10	NA	*FRONT BUMPER CLIPS - MC	0.00	0.00	*15.00 F ✓
3	2	NA	*FRONT BUMPER SIDE HOLDER - LH & RH - MC	0.00	0.00	*16.00 F ✓
4	1	NA	*FRONT BUMPER REINFORCEMENT X NN	0.00	0.00	*520.00 F X
5	2	NA	*FRONT BUMPER FOG LAMP UNIT - RH & LH X NN	0.00	0.00	*270.00 F X
6	2	NA	*FRONT BUMPER FOG LAMP COVER - RH & LH LH - CRA	0.00	0.00	*24.00 F 12
7	1	NA	*FRONT BUMPER LOWER SPOILER X CRA NN RH X NN	0.00	0.00	*40.00 F X
8	1	NA	*FRONT BUMPER GRILLE ASSY / Cut	0.00	0.00	*160.00 F ✓
9	1	NA	*FRONT BUMPER GRILLE LOGO X ABC	0.00	0.00	*F X
10	1	NA	*FRONT BUMPER TOP RUBBER X NN	0.00	0.00	*F X
11	1	NA	*BONNET - Blue	0.00	0.00	*850.00 F ✓
12	1	NA	*BONNET GRILLE / Cut	0.00	0.00	*120.00 F ✓
13	1	NA	*BONNET LOCK X NN	0.00	0.00	*F X
14	1	NA	*BONNET RUBBER - CENTRE - MC	0.00	0.00	*35.00 F ✓
15	2	NA	*BONNET RUBBER SIDE - RH & LH - MC	0.00	0.00	*20.00 F ✓
16	2	NA	*BONNET RUBBER; SMALL - RH & LH X NN	0.00	0.00	*F X
17	1	NA	*BONNET INSULATOR - MC	0.00	0.00	*85.00 F ✓
18	12	NA	*BONNET INSULATOR CLIPS - MC	0.00	0.00	10.5 *18.00 F ✓
19	1	NA	*SUPPORT PANEL X	0.00	0.00	*F X
20	1	NA	*CONDENSER X NN	0.00	0.00	*235.00 F X
21	1	NA	*RADIATOR X	0.00	0.00	*480.00 F X
22	1	NA	*RADIATOR FAN MOTOR X	0.00	0.00	*F X
23	1	NA	*RADIATOR FAN COWLING X	0.00	0.00	*185.00 F X
24	1	NA	*HEADLAMP UNIT - LH - CHA	0.00	0.00	*450.00 F ✓
25	1	NA	*HEADLAMP UNIT - RH X NN	0.00	0.00	*450.00 F X
26	1	NA	*WIPER TANK ASSY X NN	0.00	0.00	*85.00 F X
27	1	NA	*WIPER TANK MOTOR X	0.00	0.00	*48.00 F X
28	1	NA	*FRONT FENDER - LH - Blue	0.00	0.00	*450.00 F ✓
29	1	NA	*FRONT FENDER COWLING - LH X NN	0.00	0.00	*48.00 F X
30	10	NA	*FRONT FENDER COWLING CLIPS - LH - MC	0.00	0.00	*15.00 F ✓
31	1	NA	*HORN X	0.00	0.00	*42.00 F X
32	1	NA	*WIPER GARNISH - LH X NN	0.00	0.00	*38.00 F X
33	1	NA	*SUPPORT TOP PANEL X	0.00	0.00	*205.00 F X
34	1	NA	*SUPPORT PANEL HEADLAMP X	0.00	0.00	*70.00 F X

F=Franchise part.

Sub Total (\$\$)	5,554.00
+ Margin on L,N Items 10.00% (\$\$)	555.40
Total Parts (\$\$)	6,109.40

Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	COOLANT	X NN	20.00	X
2	1	FRONT NUMBER PLATE W/CASING	X NN	35.00	

Sub Total (S\$) 55.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	850	950.00
---	---------------------------------------	-----	-----	--------

Labour Items

2	TO KNOCK OUT DENTS ON LH FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	600-800	1,000.00
3	TO CHECK WIRING	New	/	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	/	100.00

Gross Labour Cost (S\$) 2,070.00

Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

5-6 Days.

Excess: \$250

Authorised.

part by part?

before paint photos.

Emo King - 8880282

05/12/17



6/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 18 January 2018 12:59 PM
To: 'Ray Progressive'
Cc: SUR
Subject: RE: SGN6085J - TO FINALIZE

Dear Ray,

Re-confirmed total amount \$4799.05 before excess \$250/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [mailto:ray@progauto.com.sg]
Sent: Wednesday, 17 January 2018 3:15 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SGN6085J - TO FINALIZE

Dear Veron,

As spoke, total amount should be \$4799.05 (add on front bump grille logo - \$80.00)

Regards,
Ray

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, January 15, 2018 12:09 PM
To: Ray Progressive
Cc: SUR; Guo Qiang (LKKAUTO); bhlm@progauto.com.sg; msho@progauto.com.sg; peiwen@progauto.com.sg; siewwei@proauto.com.sg
Subject: RE: SGN6085J - TO FINALIZE

Dear Ray,

Confirmed finalize amount \$4711.05 before excess \$250/-

No of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [mailto:ray@progauto.com.sg]

Sent: Monday, 15 January 2018 11:51 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: FW: SGN6085J - TO FINALIZE

Please see attached

From: Ray Progressive [mailto:ray@progauto.com.sg]

Sent: Wednesday, January 10, 2018 11:01 AM

To: 'Guo Qiang (LKKAuto)'; 'Veron Chen (LKKAuto)'

Cc: 'Wayne Lim'; 'bhlim@progauto.com.sg'; 'msho@progauto.com.sg'; 'Peiwen PROGAUTO';

'siewwei@progauto.com.sg'

Subject: SGN6085J - TO FINALIZE

Hi Guo Qiang/ Veron,

Please refer to finalize

Supp	\$40.70
Parts	\$3100.35
Lab	\$1570.00
Total	\$4711.05

Thank you

Best regard,

Ray

Progressive Automotive Pte Ltd

Tel: 6741-5336 Fax: 6741-7208

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 15 January 2018 12:09 PM
To: 'Ray Progressive'
Cc: SUR; Guo Qiang (LKKAUTO); bhlím@progauto.com.sg; msho@progauto.com.sg; peiwen@progauto.com.sg; 'siewwei@proauto.com.sg'
Subject: RE: SGN6085J - TO FINALIZE

Dear Ray,

Confirmed finalize amount \$4711.05 before excess \$250/-

No of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [mailto:ray@progauto.com.sg]
Sent: Monday, 15 January 2018 11:51 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SGN6085J - TO FINALIZE

Please see attached

From: Ray Progressive [mailto:ray@progauto.com.sg]
Sent: Wednesday, January 10, 2018 11:01 AM
To: 'Guo Qiang (LKKAUTO)'; 'Veron Chen (LKKAUTO)'
Cc: 'Wayne Lim'; 'bhlím@progauto.com.sg'; 'msho@progauto.com.sg'; 'Peiwen PROGAUTO'; 'siewwei@progauto.com.sg'
Subject: SGN6085J - TO FINALIZE

Hi Guo Qiang/ Veron,

Please refer to finalize

Supp	\$40.70
Parts	\$3100.35
Lab	\$1570.00
Total	\$4711.05

Thank you

Best regard,
Ray

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)
 Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER / CEA	0.00	0.00	*580.00 F ✓
2	10	NA	*FRONT BUMPER CLIPS / REC	0.00	0.00	*15.00 F ✓
3	2	NA	*FRONT BUMPER SIDE HOLDER - LH & RH / REC	0.00	0.00	*16.00 F ✓
4	1	NA	*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*520.00 F
5	2	NA	*FRONT BUMPER FOG LAMP UNIT - RH & LH ?	0.00	0.00	270.00 F
6	2	NA	*FRONT BUMPER FOG LAMP COVER - RH & LH < LH - CEA ✓	0.00	0.00	12 *24.00 F ✓
7	1	NA	*FRONT BUMPER LOWER SPOILER / CEA	0.00	0.00	*40.00 F
8	1	NA	*FRONT BUMPER GRILLE ASSY / CEA	0.00	0.00	*160.00 F ✓
9	1	NA	*FRONT BUMPER GRILLE LOGO / REC	0.00	0.00	-F
10	1	NA	*FRONT BUMPER TOP RUBBER ?	0.00	0.00	-F
11	1	NA	*BONNET / BUC	0.00	0.00	*850.00 F ✓
12	1	NA	*BONNET GRILLE / CEA	0.00	0.00	*120.00 F ✓
13	1	NA	*BONNET LOCK X NA	0.00	0.00	-F
14	1	NA	*BONNET RUBBER - CENTRE /	0.00	0.00	*35.00 F ✓
15	2	NA	*BONNET RUBBER SIDE - RH & LH / REC	0.00	0.00	*20.00 F ✓
16	2	NA	*BONNET RUBBER, SMALL - RH & LH /	0.00	0.00	-F
17	1	NA	*BONNET INSULATOR /	0.00	0.00	*85.00 F ✓
18	7	NA	*BONNET INSULATOR CLIPS / REC	0.00	0.00	10.50 *12.00 F ✓
19	1	NA	*SUPPORT PANEL ?	0.00	0.00	*235.00 F
20	1	NA	*CONDENSER ?	0.00	0.00	*480.00 F
21	1	NA	*RADIATOR ?	0.00	0.00	-F
22	1	NA	*RADIATOR FAN MOTOR ?	0.00	0.00	*185.00 F
23	1	NA	*RADIATOR FAN COWLING ?	0.00	0.00	*450.00 F ✓
24	1	NA	*HEADLAMP UNIT - LH / CEA	0.00	0.00	*150.00 F
25	1	NA	*HEADLAMP UNIT - RH /	0.00	0.00	*85.00 F
26	1	NA	*WIPER TANK ASSY ?	0.00	0.00	*48.00 F
27	1	NA	*WIPER TANK MOTOR ?	0.00	0.00	*450.00 F ✓
28	1	NA	*FRONT FENDER - LH / BUC	0.00	0.00	*48.00 F
29	1	NA	*FRONT FENDER COWLING - LH ?	0.00	0.00	*15.00 F ✓
30	10	NA	*FRONT FENDER COWLING CLIPS - LH / REC	0.00	0.00	*42.00 F
31	1	NA	*HORN ?	0.00	0.00	*38.00 F
32	1	NA	*WIPER GARNISH - LH X	0.00	0.00	*205.00 F
33	1	NA	*SUPPORT TOP PANEL ?	0.00	0.00	*70.00 F
34	1	NA	*SUPPORT PANEL HEADLAMP ?	0.00	0.00	

F=Franchise part.

Sub Total (S\$)

5,554.00

+ Margin on L,N Items 10.00% (S\$)

555.40

Total Parts (S\$)

6,109.40

Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	20.00
2	1	FRONT NUMBER PLATE W/ CASING	35.00
Sub Total (S\$)			55.00

006247

Estimates on Labour

No	Particulars	Lab. Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	850 / 950.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS ON LH FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	600 / 1,000.00
3	TO CHECK WIRING	New	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00
Gross Labour Cost (S\$)			2,070.00 1570

Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39 Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR O-LINE® MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs

5-6 Days.
Excess : \$250
- Authorized.
part by part ?
before panel photos.
Emo Riap - 8880282
05/12/17

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2017)
 Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SGN6085J/08/12/2017 13:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

006247

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET HINGE - LH / BT	0.00	0.00	*25.00 F ✓
2	2		*RADIATOR TOP BUSH / MC	0.00	0.00	*12.00 F ✓
Sub Total (S\$)						37.00
+ Margin on L,N Items 10.00% (S\$)						3.70
Total Parts (S\$)						40.70

Progressive Automotive Pte Ltd/SGN6085J/08/12/2017 13:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

SUPP 40.70

PARTS 3100.35

LAB 1570.00

4711.05



松義汽車機件私人有限公司 SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

00 6247

TAX INVOICE

REG NO: 200922006G
GST NO: 200922006G

PROGRESSIVE AUTOMOTIVE PTE LTD
BLK 3022A, UBI ROAD 1, #01-45/46.
SINGAPORE 408716

Invoice No: SAL17-081015
Date: 06/12/2017 11:56
Account No: P014
Sales person: STL
Order By: WENDY
Vehicle No: SGN 6085 J
P/O No:

Page 1 of 2

No.	Part No.	Description	Location	Qty	Price	Amount
1	C95022993	BUMPER COVER-FRONT	WH	1	580.00	580.00✓
2	C11589289	CLIP-BUMPER LWR	C21-26	10	1.50	15.00✓
3	C95291687	BRACKET-FRT BUMPER SIDE LH	D Frt Box	1	8.00	8.00✓
4	C95291688	BRACKET-FRT BUMPER SIDE RH	D Frt Box	1	8.00	8.00✓
5	C94831151	COVER-FOG LAMP LH	Box-70-Top	1	12.00	12.00✓
6	C96981093	GRILLE-RADIATOR (LWR) (GM)	WH	1	160.00	160.00✓
7	C94537888	BONNET (GM)	WH	1	850.00	850.00✓
8	C95931767	GRILLE-RADIATOR (UPR)	WH	1	120.00	120.00✓
9	C94787611	RUBBER-BONNET FRT	O/S-10	1	35.00	35.00✓
10	C94787612	RUBBER-BONNET LH	Box 69	1	10.00	10.00✓
11	C94787613	RUBBER-BONNET RH	Box 69	1	10.00	10.00✓
12	C95228989	PAD-BONNET INSULATION	WH	1	85.00	85.00✓
13	C11571159	CLIP-BONNET INSULATION	E2 Box	7	1.50	10.50✓
14	C95479486	HEAD LAMP ASSY-LH	WH	1	450.00	450.00✓
15	C94560509	FENDER-FRONT LH (+O)	WH	1	450.00	450.00✓
16	C11589292	CLIP-BUMPER (RR LWR)	C21-26	10	1.50	15.00✓
17	C96932077	HINGE-BONNET LH	G3-5	1	25.00	25.00✓

Issued By

Received By

2855.50

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

00 6247

PROGRESSIVE AUTOMOTIVE PTE LTD
BLK 3022A, UBI ROAD 1, #01-45/46.
SINGAPORE 408716

TAX INVOICE

REG NO: 200922086G
GST NO: 200922086G

Invoice No: SAL17-081015
Date: 06/12/2017 11:56
Account No: P014
Sales person: STL
Order By: WENDY
Vehicle No: SGN 6085 J
P/O No:

Page 2 of 2

No.	Part No.	Description	Location	Qty	Price	Amount
18	C13250318	BRACKET-RADIATOR UPR MTG	C21-25	1	6.00	6.00
Sub Total:						2,849.50
Add GST @7%:						199.47
Grand Total:						3,048.97

Issued By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received By

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

008247

PROGRESSIVE AUTOMOTIVE PTE LTD
BLK 3022A, UBI ROAD 1, #01-45/46.
SINGAPORE 408716

TAX INVOICE

REG NO: 200922086G
GST NO: 200922086G

Invoice No: SAL17-081022
Date: 06/12/2017 14:18
Account No: P014
Sales person: STL
Order By: WENDY
Vehicle No: SGN 6085 J
P/O No:

Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	C13250318	BRACKET-RADIATOR UPR MTG	C21-25	1	6.00	6.00 /
Sub Total:						6.00
Add GST (@7%):						0.42
Grand Total:						6.42

Issued By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received By

Received the above mentioned goods in order and good condition





松義汽車機件私人有限公司

SONG YI AUTO PARTS PTE LTD

Block 637, Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

TAX INVOICE

REG NO: 200922088G
GST NO: 200922088G

PROGRESSIVE AUTOMOTIVE PTE LTD
BLK 3022A, UBI ROAD 1, #01-45/46,
SINGAPORE 408716

Invoice No: SAL17-081070
Date: 08/12/2017 13:22
Account No: P014
Sales person: STL
Order By: WENDY
Vehicle No: SGN 6085 J
P/O No:

Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	C95032016	LOGO-RAD GRILLE	HHR	1	80.00	80.00

Sub Total: 80.00

CHASSIS NO: XL1JA69E9BK187028

Add GST @7%: 5.60

Grand Total: 85.60

Issued By

Received By

Goods sold returned are to be in full packaging
original condition within SEVEN working days

Received the above mentioned goods in order and good condition



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2017 10:43	05 Dec 2017 11:39	05 Dec 2017 13:52	S\$4,799.05	S\$4,799.05		Pending for Survey Report
	Sendback Est	S\$8,234.40	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	08 Dec 2017 13:31	08 Dec 2017 13:32	08 Dec 2017 13:32			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	QUEK YEOK CHAI WINSTON, ID: S8435257H, Tel: +6587495702		
Vehicle Reg. No.:	SGN6085J	Date of Loss:	20/11/2017 11:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	DMPPHQ17-003694 (Comprehensive)
		Excess:	S\$250.00
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/12/2017]		
Driver/Custodian:	QUEK YEOK CHAI WINSTON (/ Male), NRIC: S8435257H, Tel: +6587495702		
Adj Asg. Remarks:	EXCESS \$500 @ 50% DISCOUNT		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- EQI_HQ (15/01/2018): Alert - Adj Mandate Approved (S\$4711.05) - SGN6085J - Claim Handler: Bazlin Ahma...

ALL ASSOCIATED TASKS 

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGN6085J
OD
Nov 20 2017 11:00AM
[QUEK YEOK CHAI WINSTON]
Progressive Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)							Thumbnail	Print	
1	05/12/17 11:39	Repairer Estimates							Load HTM		
2	08/12/17 13:32	Repairer Estimates Suppl. #1							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	15/01/18 12:18	Adjuster Immediate Advice							Load HTM		
									3 per page		☒
Photos/Images										Thumbnail	Print
No	Finalized On	Progressive Automotive Pte Ltd (HQ)							Thumbnail	Print	
1	05/12/17 10:53	1							Load JPG	☒	
2	05/12/17 10:53	2							Load JPG	☒	
3	05/12/17 10:53	3							Load JPG	☒	
4	05/12/17 10:53	4							Load JPG	☒	
5	05/12/17 10:53	5							Load JPG	☒	
6	05/12/17 10:53	6							Load JPG	☒	
7	05/12/17 10:53	7							Load JPG	☒	
8	05/12/17 10:53	8							Load JPG	☒	
9	05/12/17 10:53	9							Load JPG	☒	
10	05/12/17 10:53	10							Load JPG	☒	
11	05/12/17 10:53	11							Load JPG	☒	
12	05/12/17 10:53	12							Load JPG	☒	
13	05/12/17 10:53	13							Load JPG	☒	
14	05/12/17 10:53	14							Load JPG	☒	
15	05/12/17 10:53	15							Load JPG	☒	
16	05/12/17 10:53	16							Load JPG	☒	
17	05/12/17 10:53	17							Load JPG	☒	
18	05/12/17 10:53	18							Load JPG	☒	
19	05/12/17 10:53	19							Load JPG	☒	
20	05/12/17 10:53	20							Load JPG	☒	
21	05/12/17 10:53	21							Load JPG	☒	
22	05/12/17 10:53	22							Load JPG	☒	
23	05/12/17 10:53	23							Load JPG	☒	
24	05/12/17 10:53	24							Load JPG	☒	
25	05/12/17 10:53	25							Load JPG	☒	
26	05/12/17 10:53	26							Load JPG	☒	
27	05/12/17 10:53	27							Load JPG	☒	
28	05/12/17 10:53	28							Load JPG	☒	
29	05/12/17 10:53	29							Load JPG	☒	
30	05/12/17 10:53	30							Load JPG	☒	
31	05/12/17 10:53	31							Load JPG	☒	

32	05/12/17 10:53	32	1	Load JPG	☒
33	05/12/17 10:53	33	1	Load JPG	☒
34	05/12/17 10:53	34	1	Load JPG	☒
35	05/12/17 10:53	35	1	Load JPG	☒
36	05/12/17 10:53	36	1	Load JPG	☒
37	05/12/17 10:53	37	1	Load JPG	☒
38	05/12/17 10:53	38	1	Load JPG	☒
39	05/12/17 10:53	39	1	Load JPG	☒
40	05/12/17 10:53	40	1	Load JPG	☒
41	05/12/17 10:53	41	1	Load JPG	☒
42	05/12/17 10:53	42	1	Load JPG	☒
43	05/12/17 10:53	43	1	Load JPG	☒
44	05/12/17 10:53	44	1	Load JPG	☒
45	05/12/17 10:53	45	1	Load JPG	☒
46	05/12/17 10:53	46	1	Load JPG	☒
47	05/12/17 10:53	47	1	Load JPG	☒
48	05/12/17 10:53	48	1	Load JPG	☒
49	05/12/17 10:53	49	1	Load JPG	☒
50	05/12/17 10:53	50	1	Load JPG	☒
51	05/12/17 10:53	51	1	Load JPG	☒
52	05/12/17 10:53	52	1	Load JPG	☒
53	05/12/17 10:53	53	1	Load JPG	☒
54	05/12/17 10:53	54	1	Load JPG	☒
55	05/12/17 10:53	55	1	Load JPG	☒
56	05/12/17 10:53	56	1	Load JPG	☒
57	05/12/17 10:53	57	1	Load JPG	☒
58	05/12/17 10:53	58	1	Load JPG	☒
59	05/12/17 10:53	59	1	Load JPG	☒
60	05/12/17 10:53	60	1	Load JPG	☒
61	05/12/17 10:53	61	1	Load JPG	☒
62	05/12/17 10:53	62	1	Load JPG	☒
63	05/12/17 10:53	63	1	Load JPG	☒
64	05/12/17 10:53	64	1	Load JPG	☒
65	05/12/17 10:53	65	1	Load JPG	☒
66	05/12/17 10:53	66	1	Load JPG	☒
67	05/12/17 10:53	67	1	Load JPG	☒
68	05/12/17 10:53	68	1	Load JPG	☒
69	05/12/17 10:53	69	1	Load JPG	☒
70	05/12/17 10:53	70	1	Load JPG	☒
71	05/12/17 10:53	71	1	Load JPG	☒
72	05/12/17 10:53	72	1	Load JPG	☒
73	05/12/17 10:53	73	1	Load JPG	☒
74	05/12/17 10:53	74	1	Load JPG	☒
75	05/12/17 10:53	75	1	Load JPG	☒
76	05/12/17 10:53	76	1	Load JPG	☒
77	05/12/17 10:53	77	1	Load JPG	☒
78	05/12/17 10:53	78	1	Load JPG	☒
79	05/12/17 10:53	79	1	Load JPG	☒
80	05/12/17 10:53	80	1	Load JPG	☒
81	05/12/17 10:53	81	1	Load JPG	☒

82	05/12/17 10:53	82	1	Load JPG	☒
83	05/12/17 10:53	83	1	Load JPG	☒
84	05/12/17 10:53	84	1	Load JPG	☒
85	05/12/17 10:53	85	1	Load JPG	☒
86	05/12/17 10:53	86	1	Load JPG	☒
87	05/12/17 10:53	87	1	Load JPG	☒
88	05/12/17 10:53	88	1	Load JPG	☒
89	05/12/17 10:53	89	1	Load JPG	☒
90	05/12/17 10:53	90	1	Load JPG	☒
91	05/12/17 10:53	91	1	Load JPG	☒
92	05/12/17 10:53	92	1	Load JPG	☒
93	05/12/17 10:53	93	1	Load JPG	☒
94	05/12/17 10:53	94	1	Load JPG	☒
95	05/12/17 10:53	95	1	Load JPG	☒
96	05/12/17 10:53	96	1	Load JPG	☒
97	05/12/17 10:53	97	1	Load JPG	☒
98	05/12/17 10:53	98	1	Load JPG	☒
99	05/12/17 10:53	99	1	Load JPG	☒
100	05/12/17 10:53	100	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/12/17 11:37	General View	1	Load JPG	☒
2	06/12/17 11:38	General View	1	Load JPG	☒
3	06/12/17 11:38	General View	1	Load JPG	☒
4	06/12/17 11:38	General View	1	Load JPG	☒
5	06/12/17 11:38	General View	1	Load JPG	☒
6	06/12/17 11:38	General View	1	Load JPG	☒
7	06/12/17 11:38	General View	1	Load JPG	☒
8	06/12/17 11:38	General View	1	Load JPG	☒
9	06/12/17 11:38	General View	1	Load JPG	☒
10	06/12/17 11:38	General View	1	Load JPG	☒
11	06/12/17 11:38	General View	1	Load JPG	☒
12	06/12/17 11:38	General View	1	Load JPG	☒
13	06/12/17 11:38	General View	1	Load JPG	☒
14	06/12/17 11:38	General View	1	Load JPG	☒
15	06/12/17 11:38	General View	1	Load JPG	☒
16	06/12/17 11:38	General View	1	Load JPG	☒
17	06/12/17 11:38	General View	1	Load JPG	☒
18	06/12/17 11:38	General View	1	Load JPG	☒
19	06/12/17 11:38	General View	1	Load JPG	☒
20	06/12/17 11:38	General View	1	Load JPG	☒
21	06/12/17 11:38	General View	1	Load JPG	☒
22	06/12/17 11:38	General View	1	Load JPG	☒
23	06/12/17 11:38	General View	1	Load JPG	☒
24	06/12/17 11:38	General View	1	Load JPG	☒
25	06/12/17 11:38	General View	1	Load JPG	☒
26	06/12/17 11:38	General View	1	Load JPG	☒
27	06/12/17 11:38	General View	1	Load JPG	☒
28	06/12/17 11:38	General View	1	Load JPG	☒
29	06/12/17 11:38	General View	1	Load JPG	☒
30	06/12/17 11:38	General View	1	Load JPG	☒

31	06/12/17 11:38	General View	1	Load JPG	☒
32	06/12/17 11:38	General View	1	Load JPG	☒
33	06/12/17 11:38	General View	1	Load JPG	☒
34	15/01/18 12:04	Reinspection Photo	1	Load JPG	☒
35	15/01/18 12:04	Reinspection Photo	1	Load JPG	☒
36	15/01/18 12:04	Reinspection Photo	1	Load JPG	☒
37	15/01/18 12:04	Reinspection Photo	1	Load JPG	☒
38	15/01/18 12:04	Reinspection Photo	1	Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	1	Load TIF	
1	05/12/17 10:54	Claimants NRIC & LIC	1	Load PDF	
2	05/12/17 10:54	E-filed GIA report		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF	
1	19/01/18 16:17	SUPPLEMENTARY	1	Load PDF	
2	19/01/18 16:17	PARTS INVOICE			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ17023084/GVBS2

Date: 22/01/2018

REFERENCE

Insured/Claimant: QUEK YEOK CHAI WINSTON
Date of Loss: 20/11/2017

Policy No: DMPPHQ17-003694
Nature of Claim: OD

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN6085J**
Make & Model: CHEVROLET CRUZE, 1.6 (A)
Reg. Date: 15/07/2011 (Man. Year: 2011)
Colour: Black
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$38,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: F16D4271923KA
Chassis No: KL1JA69E9BK187028
Odometer: 167125 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	6,150.10	3,229.05	2,921.05	47.50
Miscellaneous Items	55.00	0.00	55.00	100.00
Labour	1,120.00	720.00	400.00	35.71
Paintwork Labour	950.00	850.00	100.00	10.53
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,275.10	4,799.05	3,476.05	42.01
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	8,275.10	4,549.05	3,726.05	45.03
+ GST 7.00/7.00% (S\$)	579.26	318.43	260.83	45.03
Nett Amount (S\$)	8,854.36	4,867.48	3,986.88	45.03

INSPECTION

Date of Assignment: 05/12/2017 Present Location:
Date Inspected: 05/12/2017 Inspected At:

Progressive Automotive Pte Ltd (HQ)
Progressive Automotive Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2018)
Parts: 143	CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGN6085J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER (WCP)	Cracked	580.00 F	*580.00 F
2	10	NA	*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
3	2	NA	*FRONT BUMPER SIDE HOLDER - LH & RH (WCP)	Necessary	16.00 F	*16.00 F
4	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	520.00 F	*- F
5	2	NA	*FRONT BUMPER FOG LAMP UNIT - RH & LH (WCP)	Not Necessary	270.00 F	*- F
6	1	NA	*FRONT BUMPER FOGLAMP COVER - RH & LH (WCP)	N/s Cracked/O/s Not Necessary	24.00 F	*12.00 F
7	1	NA	*FRONT BUMPER LOWER SPOILER (WCP)	Not Necessary	40.00 F	*- F
8	1	NA	*FRONT BUMPER GRILLE ASSY (WCP)	Cut	160.00 F	*160.00 F
9	1	NA	*FRONT BUMPER GRILLE LOGO (WCP)	Necessary	0.00 F	*80.00 F
10	1	NA	*FRONT BUMPER TOP RUBBER (NPA) (WCP)	Not Necessary	0.00 F	*- F
11	1	NA	*BONNET (WCP)	Buckled	850.00 F	*850.00 F
12	1	NA	*BONNET GRILLE (WCP)	Cut	120.00 F	*120.00 F
13	1	NA	*BONNET LOCK (NPA) (WCP)	Not Necessary	0.00 F	*- F
14	1	NA	*BONNET RUBBER - CENTRE (WCP)	Necessary	35.00 F	*35.00 F
15	2	NA	*BONNET RUBBER SIDE - RH & LH (WCP)	Necessary	20.00 F	*20.00 F
16	2	NA	*BONNET RUBBER; SMALL - RH & LH (NPA) (WCP)	Not Necessary	0.00 F	*- F
17	1	NA	*BONNET INSULATOR (WCP)	Deformed	85.00 F	*85.00 F
18	1	NA	*BONNET INSULATOR CLIPS 12pcs (WCP)	Necessary	18.00 F	*10.50 F
19	1	NA	*SUPPORT PANEL (NPA) (WCP)	Not Necessary	0.00 F	*- F
20	1	NA	*CONDENSER (WCP)	Not Necessary	235.00 F	*- F
21	1	NA	*RADIATOR (WCP)	Not Necessary	480.00 F	*- F
22	1	NA	*RADIATOR FAN MOTOR (NPA) (WCP)	Not Necessary	0.00 F	*- F
23	1	NA		Not Necessary	185.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1	NA	*RADIATOR FAN COWLING (WCP) *HEADLAMP UNIT - LH (WCP)	Cracked	450.00 F	*450.00 F
25	1	NA	*HEADLAMP UNIT - RH (WCP)	Not Necessary	450.00 F	*- F
26	1	NA	*WIPER TANK ASSY (WCP)	Not Necessary	85.00 F	*- F
27	1	NA	*WIPER TANK MOTOR (WCP)	Not Necessary	48.00 F	*- F
28	1	NA	*FRONT FENDER - LH (WCP)	Buckled	450.00 F	*450.00 F
29	1	NA	*FRONT FENDER COWLING - LH (WCP)	Not Necessary	48.00 F	*- F
30	10	NA	*FRONT FENDER COWLING CLIPS - LH (WCP)	Necessary	15.00 F	*15.00 F
31	1	NA	*HORN (WCP)	Not Necessary	42.00 F	*- F
32	1	NA	*WIPER GARNISH - LH (WCP)	Not Necessary	38.00 F	*- F
33	1	NA	*SUPPORT TOP PANEL (WCP)	Not Necessary	205.00 F	*- F
34	1	NA	*SUPPORT PANEL HEADLAMP (WCP)	Not Necessary	70.00 F	*- F
Supplementary #1						
35	1		*BONNET HINGE - LH (WCP)	Bent	25.00 F	*25.00 F
36	2		*RADIATOR TOP BUSH (WCP)	Necessary	12.00 F	*12.00 F

F=Franchise part.

Sub Total (S\$)	5,591.00	2,935.50
+ Margin on L,N Items 10.00/10.00% (S\$)	559.10	293.55
Total Parts (S\$)	6,150.10	3,229.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	COOLANT (NOT NECESSARY)	20.00	0.00
2	1	FRONT NUMBER PLATE W/CASING (NOT NECESSARY)	35.00	0.00
Sub Total (S\$)			55.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	950.00	850.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS ON LH FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,000.00	600.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
Gross Labour Cost (S\$)			2,070.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >