

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023099/K1vbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 26-12-2017	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 8158T	Veh. Inspected	SH 8278X	
Policy No.	5082204587-01	Coverage (\$)	0.00	
Claim No.	MT/0972139-002	Excess (\$)	0.00	
Assign From		Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003561165	Colour	BLUE	
Odometer	53661	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2017	Inspection Date	05/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		